

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7c3"
    },
    "type": "CREDITOFFICER",
    "_id": "652fac137e32132d40944a01",
    "firstName": "Sushma",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9769571059",
    "email": "sbi01821@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500800",
    "discussWithPerson": "Sushma",
    "expectedFees": 4250.4,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7c3",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Churchgate (Mumbai) Branch",
  "email": "sbi.01821@sbi.co.in",
  "mobileNo": "022-22030017",
  "alternateMobileNo": "",
  "address": "\\The International \\, 17 Maharshi Karve Road, Churchgate, Mumbai -
400 020, State - Maharashtra, Country - India. \\r\\n",
  "ledgerName": "STATE BANK OF INDIA - CHURCHGATE",
  "fax": "022-22002752",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.30329711972126",
  "longitude": "73.2070311912668"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.2070311912668,
    19.30329711972126
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-11-16T13:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-17",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-17",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Titwala ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "34 & 35",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shri Ram Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Narayan Nagar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": " Jai Shree Ram Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "3/2/2 & 3/1(pt)",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 605",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Titwala (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
    "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
  },
  "finishing": {
```

```
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Narayan Nagar Road",
"west": "Ganga Apartment CHSL",
"south": "Ved Residency / Open Area ",
"east": "Open Plot"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
```

```
    "east": "",
    "south": "",
    "west": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Building Completion Certificate is received it may be assumed that the construction is as per Sanctioned Plan.\n\n",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "4900",
  "depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Titwala",
  "rate": "47500.00",
  "landRate": "11300",
  "igrImage": "cases/655600145586e00815886217/igr_1700547628609_Image.png",
  "squareMeterGuideLineRate": "45125.00",
  "squareFeetGuideLineRate": "4192.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "depreciationPercentage": "84",
  "rate": "3689.00",
  "squareFeetGuideLineRate": "3689.00",
  "squareMeterGuideLineRate": "39713.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Seller_Occupied",
"label": "Seller Occupied"
},
"monthlyRent": "6,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Customer No. 020070103304",
"meterCardHolderName": "Shri. Manoharlal Bhaiyalal Vishwakarma",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2007",
  "fullDate": "1/1/2007"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "5"
},
```



```
"finalPlinthArea": {
  "area": "570.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/655600145586e00815886217/
routeMap_1700291563164_Image.png",
    "routeLat": "19.296917",
    "routeLng": "73.217194",
    "stationName": "Titwala",
    "routeDistance": "2.2 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "saazj",
      "name": "saazj",
      "image": "cases/655600145586e00815886217/
routeMap_1700291432341_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2793000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2793000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2102730.00",
  "selectedBuildUpValue": "570.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "655761255586e008158a5953",
      "name":
"externallmg_1700225316919_WhatsApp_Image_20231117_at_50621_PM_1.jpeg",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316919_WhatsApp_Image_20231117_at_50621_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "655761255586e008158a595a",
      "name":
"externallmg_1700225316939_WhatsApp_Image_20231117_at_50621_PM_8.jpeg",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316939_WhatsApp_Image_20231117_at_50621_PM_8.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "655761255586e008158a5960",
    "name":
"externallmg_1700225316952_WhatsApp_Image_20231117_at_50621_PM.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316952_WhatsApp_Image_20231117_at_50621_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655761255586e008158a5955",
    "name":
"externallmg_1700225316925_WhatsApp_Image_20231117_at_50621_PM_3.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316925_WhatsApp_Image_20231117_at_50621_PM_3.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "655761255586e008158a5950",
    "name":
"externallmg_1700225316909_WhatsApp_Image_20231117_at_50621_PM_14.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316909_WhatsApp_Image_20231117_at_50621_PM_14.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "655761255586e008158a5958",
    "name": "Living Room",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316933_WhatsApp_Image_20231117_at_50621_PM_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655761255586e008158a595c",
    "name": "Living Room",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316943_WhatsApp_Image_20231117_at_50621_PM_10.jpeg",
    "orientation": "landscape"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "655761255586e008158a595e",
      "name": "Living Room",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316947_WhatsApp_Image_20231117_at_50621_PM_12.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "655761255586e008158a5956",
      "name": "Living Room",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316929_WhatsApp_Image_20231117_at_50621_PM_4.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "655761255586e008158a5957",
      "name": "Living Room",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316931_WhatsApp_Image_20231117_at_50621_PM_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "655761255586e008158a595d",
      "name": "Living Room",
      "path": "cases/655600145586e00815886217/
externallmg_1700225316945_WhatsApp_Image_20231117_at_50621_PM_11.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5714",
    "max": "6447"
  },
  "builtUpRateRange": {
    "min": "4762",
    "max": "5373"
  }
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
```

```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "570.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"audioRemarks": [],
"_id": "655600145586e00815886217",
"ownerName": "Mr. Dinesh Lakhan Sharma",
"ownerPhoneNo": "9869548836",
"appAddress": "101 1st floor\nJai shree Ram \nTitwala \nTa Kalyan Pin 421605",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
    "documentDate": "30/10/2023",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    }
  },
  "Vendor": "Mr. Rajiv Manohar Vishwakarma & Mr. Sanjiv Manohar Vishwakarma",
  "to": {
```

```
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Dinesh Lakhan Sharma & Mrs. Murti Dinesh Sharma",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "12769 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "634056",
"path": "cases/655600145586e00815886217/
document_1700134831511_1700134875097_20231106201250.pdf",
"fileName": "document_1700134831511_1700134875097_20231106201250.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "08/10/2002",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KDMC / NRV / BP / KV / 352-144"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700288867276_Commencement_Certificate.pdf",
  "path": "cases/655600145586e00815886217/
document_1700288867276_Commencement_Certificate.pdf",
  "id": "760999",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Sat Nov 18 2023 11:57:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
```

```
"label": "Building Completion Certificate"
},
"inputs": {
  "documentDate": "28/01/2007",
  "nameOfApprovingAuthority": {
    "value": "Kalyan_Dombivli_Municipal_Corporation",
    "label": "Kalyan Dombivli Municipal Corporation"
  },
  "remark": "(Number not readable)",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-"
},
"isHardCopy": false,
"displayStatus": true,
"id": "995006",
"path": "cases/655600145586e00815886217/
document_1700288983589_Building_Completion_Certificate.pdf",
"fileName": "document_1700288983589_Building_Completion_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "remark": " bearing Nos. 101 to 110 having 10 Shares of Rs. 50/- each
transferred dated 05.09.2021 in the name of Rajiv Manohar Vishwakarma and dated
10.10.2021 in the name of Sanjiv Manohar Vishwakarma by Jai Shree Ram Co-op.
Hsg. Soc. Ltd",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "11"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "224918",
  "path": "cases/655600145586e00815886217/
document_1700289513938_Share_Certificate.pdf",
  "fileName": "document_1700289513938_Share_Certificate.pdf"
},
{
```

```
"documentType": {
  "value": "6077c791395bc80714864a30",
  "label": "Electricity Bill"
},
"inputs": {
  "documentDate": "16/08/2022",
  "number": {
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": "020070103304"
},
"isHardCopy": false,
"displayStatus": true,
"id": "378690",
"path": "cases/655600145586e00815886217/
document_1700289711101_Electricity_Bill.pdf",
"fileName": "document_1700289711101_Electricity_Bill.pdf"
}
],
"caseNumber": "005045",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "442036",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 16 2023 17:12:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Dinesh Lakhan Sharma",
    "phone": "9869548836",
    "ownershipShare": "",
    "email": "",
    "id": "547249"
  },
  {
    "name": "Mrs. Murti Dinesh Sharma",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "452406"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "622522",
    "name": "Bedroom",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "90.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "90.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "7.17",
    "length1": "7",
    "length2": "2",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "64.50",
    "images": [],
    "extraAreas": [],
    "finalArea": "64.50"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "8",
    "name": "Passage",
```

```
"length": "",
"length1": "3",
"length2": "5",
"width": "",
"width1": "8",
"width2": "2",
"totalArea": "27.90",
"images": [],
"finalArea": "27.90",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Cupboard",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "3.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "3.00"
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Living Room",
  "length": "9.08",
  "length1": "9",
  "length2": "1",
  "width": "15.42",
  "width1": "15",
  "width2": "5",
  "totalArea": "140.03",
  "images": [],
  "finalArea": "140.03",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowered Area",
```



```
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "9",
  "length2": "00",
  "length": "9.00",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "18.00",
  "percentageBeforeTotal": "18.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "18"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "7",
  "width2": "10",
  "width": "7.83",
  "totalArea": "15.67",
  "percentageBeforeTotal": "15.67",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15.67"
```

```
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "8",
  "length2": "7",
  "length": "8.58",
  "width1": "6",
  "width2": "8",
  "width": "6.67",
  "totalArea": "57.22",
  "percentageBeforeTotal": "57.22",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "57.22"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "9",
  "length2": "00",
  "length": "9.00",
  "width1": "3",
```

```
"width2": "00",
"width": "3.00",
"totalArea": "27.00",
"percentageBeforeTotal": "27.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "27"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "272761",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "570",
  "squareMeterArea": "52.95",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "655c4c385586e008158e9f9d",
  "property": "Narayan Nagar, Titwala",
  "area": "490",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
```

```
    "expectedPrice": "2800000",
    "expectedRate": "5714.29",
    "builtUpExpectedRate": "4761.90",
    "image": "cases/655600145586e00815886217/
indicator_1700547185272_Image.png",
    "squareMeter": "45.52",
    "id": "351210"
  },
  {
    "printlnReport": true,
    "_id": "655c4c385586e008158e9f9e",
    "property": "Virat Heritage, Titwala",
    "area": "455",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "2800000",
    "expectedRate": "6153.85",
    "builtUpExpectedRate": "5128.21",
    "image": "cases/655600145586e00815886217/
indicator_1700547234605_Image.png",
    "squareMeter": "42.27",
    "id": "604816"
  },
  {
    "printlnReport": true,
    "_id": "655c4c385586e008158e9f9f",
    "property": "Narayan Nagar, Titwala",
    "area": "511",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "3000000",
    "expectedRate": "5870.84",
    "builtUpExpectedRate": "4892.37",
    "image": "cases/655600145586e00815886217/
indicator_1700547288748_Image.png",
    "squareMeter": "47.47",
    "id": "233905"
  },
}
```

```
{
  "printlnReport": true,
  "_id": "655c4c385586e008158e9fa0",
  "property": "Ved Residency, Titwala",
  "area": "380",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "7",
  "source": "Index_no.2",
  "expectedPrice": "2450000",
  "expectedRate": "6447.37",
  "builtUpExpectedRate": "5372.81",
  "image": "cases/655600145586e00815886217/
indicator_1700547383979_Image.png",
  "squareMeter": "35.30",
  "id": "117800"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5950",
    "name":
"externallmg_1700225316909_WhatsApp_Image_20231117_at_50621_PM_14.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316909_WhatsApp_Image_20231117_at_50621_PM_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5951",
    "name":
"externallmg_1700225316913_WhatsApp_Image_20231117_at_50621_PM_15.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316913_WhatsApp_Image_20231117_at_50621_PM_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5952",
    "name":
"externallmg_1700225316916_WhatsApp_Image_20231117_at_50622_PM.jpeg",
```

```
    "path": "cases/655600145586e00815886217/
externallmg_1700225316916_WhatsApp_Image_20231117_at_50622_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5953",
    "name":
"externallmg_1700225316919_WhatsApp_Image_20231117_at_50621_PM_1.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316919_WhatsApp_Image_20231117_at_50621_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5954",
    "name":
"externallmg_1700225316922_WhatsApp_Image_20231117_at_50621_PM_2.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316922_WhatsApp_Image_20231117_at_50621_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5955",
    "name":
"externallmg_1700225316925_WhatsApp_Image_20231117_at_50621_PM_3.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316925_WhatsApp_Image_20231117_at_50621_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5956",
    "name":
"externallmg_1700225316929_WhatsApp_Image_20231117_at_50621_PM_4.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316929_WhatsApp_Image_20231117_at_50621_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655761255586e008158a5957",
  "name":
"externallmg_1700225316931_WhatsApp_Image_20231117_at_50621_PM_5.jpeg",
  "path": "cases/655600145586e00815886217/
externallmg_1700225316931_WhatsApp_Image_20231117_at_50621_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655761255586e008158a5958",
  "name":
"externallmg_1700225316933_WhatsApp_Image_20231117_at_50621_PM_6.jpeg",
  "path": "cases/655600145586e00815886217/
externallmg_1700225316933_WhatsApp_Image_20231117_at_50621_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655761255586e008158a5959",
  "name":
"externallmg_1700225316936_WhatsApp_Image_20231117_at_50621_PM_7.jpeg",
  "path": "cases/655600145586e00815886217/
externallmg_1700225316936_WhatsApp_Image_20231117_at_50621_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655761255586e008158a595a",
  "name":
"externallmg_1700225316939_WhatsApp_Image_20231117_at_50621_PM_8.jpeg",
  "path": "cases/655600145586e00815886217/
externallmg_1700225316939_WhatsApp_Image_20231117_at_50621_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655761255586e008158a595b",
  "name":
"externallmg_1700225316941_WhatsApp_Image_20231117_at_50621_PM_9.jpeg",
  "path": "cases/655600145586e00815886217/
externallmg_1700225316941_WhatsApp_Image_20231117_at_50621_PM_9.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a595c",
    "name":
"externallmg_1700225316943_WhatsApp_Image_20231117_at_50621_PM_10.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316943_WhatsApp_Image_20231117_at_50621_PM_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a595d",
    "name":
"externallmg_1700225316945_WhatsApp_Image_20231117_at_50621_PM_11.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316945_WhatsApp_Image_20231117_at_50621_PM_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a595e",
    "name":
"externallmg_1700225316947_WhatsApp_Image_20231117_at_50621_PM_12.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316947_WhatsApp_Image_20231117_at_50621_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a595f",
    "name":
"externallmg_1700225316949_WhatsApp_Image_20231117_at_50621_PM_13.jpeg",
    "path": "cases/655600145586e00815886217/
externallmg_1700225316949_WhatsApp_Image_20231117_at_50621_PM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655761255586e008158a5960",
```



```
"name":
"externalImg_1700225316952_WhatsApp_Image_20231117_at_50621_PM.jpeg",
  "path": "cases/655600145586e00815886217/
externalImg_1700225316952_WhatsApp_Image_20231117_at_50621_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalName": "1700284280790_1697100715004_Calculation.xlsx",
  "filename": "1700547667609_1700284280790_1697100715004_Calculation.xlsx",
  "path": "cases/655600145586e00815886217/processingDocuments/170054766760
9_1700284280790_1697100715004_Calculation.xlsx",
  "size": "3049972",
  "createdAt": "Tue Nov 21 2023 11:51:09 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "655b4dcd5586e008158df50f",
  "note": "Rate done",
  "taskId": "655613745586e00815889706",
  "createdAt": "2023-11-20T12:15:09.911Z"
}
],
"createdAt": "2023-11-16T11:42:12.889Z",
"updatedAt": "2023-11-21T10:15:26.893Z",
"__v": 0,
"invoiceId": "655600155586e00815886220",
"updatedBy": "60f915d3f3dd69653a592199",
"fullAddress": "Residential Flat No. 101, 1st Floor, Shri Ram Apartment, Jai Shree
Ram Co-op. Hsg. Soc. Ltd., Plot No. 34 & 35, Narayan Nagar Road, Village - Titwala ,
```

Titwala (East), Taluka - Kalyan, District - Thane, PIN - 421 605, State - Maharashtra, India",

```
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Dipesh Sharma",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owners Son",
"siteVisitContactNo": "9869548836",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +
Cupboard + Bathroom",
"carpetTotal": "357.43",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "117.89",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "117.89",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "570.38",
"finalCarpetArea": "475.32",
"finalSalableArea": "570.38",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 357.43\nBalcony Area in Sq. Ft.
= 27.00\nFlowerbed Area in Sq. Ft. = 33.67\nAttached Terrace Area in Sq. Ft. =
57.22\n",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 570.00",
"reportGeneratedDate": "Tue Nov 21 2023 13:15:34 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-17",
"buildingServicesRate": "2500.00",
"flatRate": "5500.00",
"landOtherRate": "3000",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
```

```

},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Bedroom | 10'00" | 9'00" | 90.00 |
| Kitchen | 7'2" | 9'00" | 64.50 |
| Passage | 3'5" | 8'2" | 27.90 |
| WC | 4'00" | 3'00" | 12.00 |
| Cupboard | 3'00" | 1'00" | 3.00 |
| Bathroom | 5'00" | 4'00" | 20.00 |
| Living Room | 9'1" | 15'5" | 140.03 |
| Other Composition : | | | |
| Flowered Area | 9'00" | 2'00" | 18.00 |
| Flowered Area | 2'00" | 7'10" | 15.67 |
| Terrace Area | 8'7" | 6'8" | 57.22 |
| Balcony Area | 9'00" | 3'00" | 27.00 |