

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231032",
    "firstName": "Namrata ",
    "email": "racpc.sion@sbi.co.in",
    "mobileNo": "",
    "workMobileNo": "8879237774",
    "lastName": "Salvi"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Namrata ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kiroi Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6104f65764b190712161e4f2",
  "role": "SITEENGINEER",
  "firstName": "Hitesh ",
  "email": "hitsahu.123@gmail.com",
  "lastName": "Sahu",
  "mobileNo": "8080866497",
  "designation": "",
  "shortName": "HS",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.037786316169665",
  "longitude": "72.87227131621421"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87227131621421,
    19.037786316169665
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-16T13:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T13:00:00.000Z",
      "remark": ""
    }
  ]
},
],
```

```
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Antop Hill",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "3",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "MHADA Housing Scheme Code No. 350 (LIG)",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```



```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2/292, 378, 379, 380, 381 & 419",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "F/North",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 037",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Wadala (East)",
```

```
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  }
}
```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Open Plot",
  "west": "Open Plot",
  "south": "Slum Area",
  "east": "Ravji Ganatra Marg"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As MHADA itself is planning authority, building
construction permission is assumed to be available",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "7.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "14775",
  "depreciatedBuildingRate": "2775"
```

```
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "103570",
  "landRate": "47210",
  "igrImage": "cases/6556034e5586e00815886ac5/igr_1700204730338_Image.png",
  "squareMeterGuideLineRate": "103570.00",
  "squareFeetGuideLineRate": "9622.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "depreciationPercentage": "95",
  "rate": "9360.00",
  "squareFeetGuideLineRate": "9360.00",
  "squareMeterGuideLineRate": "100752.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "-",
    "label": "Others"
  },
  "monthlyRent": "10000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2018",
    "fullDate": "1/1/2018"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
```

```
"label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "5",
"totalLifeBuilding": "60",
"estimatedAge": "55",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "24",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Monorail",
      "label": "Monorail"
    },
    "routeMapImg": "cases/6556034e5586e00815886ac5/
routeMap_1700298521480_Image.png",
    "routeLat": "19.025841",
    "routeLng": "72.862217",
    "stationName": "Antop Hill",
    "routeDistance": "900 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ]
  }
}
```



```
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "swlxep",
      "name": "swlxep",
      "image": "cases/6556034e5586e00815886ac5/
routeMap_1700298327593_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4432500.00",
  "finalValue": "4432500.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3369600.00",
"selectedBuildUpValue": "360.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
}
```

```
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "655854cb5586e008158b097e",
      "name":
"externallmg_1700287691886_WhatsApp_Image_20231118_at_92048_AM.jpeg",
      "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691886_WhatsApp_Image_20231118_at_92048_AM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "655854cb5586e008158b097c",
      "name":
"externallmg_1700287691880_WhatsApp_Image_20231118_at_92048_AM_1.jpeg",
      "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691880_WhatsApp_Image_20231118_at_92048_AM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "655854cb5586e008158b097d",
      "name":
"externallmg_1700287691883_WhatsApp_Image_20231118_at_92048_AM_2.jpeg",
      "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691883_WhatsApp_Image_20231118_at_92048_AM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "655854cb5586e008158b097a",
      "name": "Living Room",
      "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691876_WhatsApp_Image_20231118_at_92047_AM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  {
```

```
    "status": false,
    "_id": "655854cb5586e008158b0978",
    "name": "Living Room",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691872_WhatsApp_Image_20231118_at_92046_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655854cb5586e008158b0977",
    "name": "Living Room",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691869_WhatsApp_Image_20231118_at_92046_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655854cb5586e008158b0974",
    "name": "Living Room",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691862_WhatsApp_Image_20231118_at_92045_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655854cb5586e008158b0973",
    "name": "Living Room",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691859_WhatsApp_Image_20231118_at_92044_AM.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14896",
    "max": "15000"
  },
  "builtUpRateRange": {
    "min": "13542",
    "max": "13637"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "300.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"audioRemarks": [],
"_id": "6556034e5586e00815886ac5",
"ownerName": "Ms. Janhavi Suresh Daware",
"ownerPhoneNo": "9768809299",
"appAddress": "Flat no. 102, 1st Floor, Building no. 3, Wing - B, Antop Hill Wadala ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12a4aa6d152c1801b497",
      "label": "MHADA Provisional Offer Letter"
    },
    "inputs": {
      "documentDate": "10/08/2023",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      },
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      }
    }
  }
],
```

```
    "Allottee": "2456/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "637108",
  "path": "cases/6556034e5586e00815886ac5/
document_1700135743213_1700135800210_MHADA_OFFER_LETTER_0001.pdf",
  "fileName":
"document_1700135743213_1700135800210_MHADA_OFFER_LETTER_0001.pdf"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b33a",
    "label": "No Objection Certificate "
  },
  "inputs": {
    "documentDate": "03/11/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    }
  }
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700297310648_document_1700135743213_17001358002
10_MHADA_OFFER_LETTER_0001.pdf",
  "path": "cases/6556034e5586e00815886ac5/document_1700297310648_document
_1700135743213_1700135800210_MHADA_OFFER_LETTER_0001.pdf",
  "id": "743755",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Sat Nov 18 2023 14:18:31 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005046",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "638246",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 16 2023 17:25:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Janhavi Suresh Daware",
```

```
"phone": "9768809299",
"ownershipShare": "",
"email": "",
"id": "555449"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "6",
"name": "Bedroom",
"length": "10.00",
"length1": "10",
"length2": "0",
"width": "8.67",
"width1": "8",
"width2": "8",
"totalArea": "86.67",
"images": [],
"finalArea": "86.67",
"extraAreas": []
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "5.17",
"width1": "5",
"width2": "2",
"totalArea": "51.67",
"images": [],
"extraAreas": [],
"finalArea": "51.67"
},
{

```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "6",
"name": "Toilet",
"length": "5.17",
"length1": "5",
"length2": "2",
"width": "2.25",
"width1": "2",
"width2": "3",
"totalArea": "11.62",
"images": [],
"finalArea": "11.62",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "",
  "length1": "7",
  "length2": "2",
  "width": "",
  "width1": "1",
  "width2": "10",
  "totalArea": "13.14",
  "images": [],
  "finalArea": "13.14",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "2.08",
```

```
"width1": "2",
"width2": "1",
"totalArea": "22.92",
"images": [],
"extraAreas": [],
"finalArea": "22.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "",
  "length1": "10",
  "length2": "0",
  "width": "",
  "width1": "11",
  "width2": "3",
  "totalArea": "112.50",
  "images": [],
  "finalArea": "112.50",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae12a4aa6d152c1801b497",
      "label": "MHADA Provisional Offer Letter"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "608109",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "300",
    "squareMeterArea": "27.87",
    "docFinalBuiltUp": "360",
    "docFinalBuiltUpSquareMeter": "33.444",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
```

```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "655711315586e008158962bd",
  "property": "1 BHK Flat In Swapnapurti Chs For Sale In Wadala East, Wadala",
  "area": "550.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "7500000.00",
  "expectedRate": "13636.36",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6556034e5586e00815886ac5/
indicator_1700204351050_Image.png",
  "squareMeter": "51.10",
  "id": "134091"
},
{
  "printlnReport": true,
  "_id": "655711315586e008158962be",
  "property": "1 BHK Flat In Antophill Mhada For Sale In Block-C, Nityanand Nagar,
Antop Hill, Mumbai",
  "area": "480.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "6500000.00",
  "expectedRate": "13541.67",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6556034e5586e00815886ac5/
indicator_1700204450252_Image.png",
  "squareMeter": "44.59",
  "id": "174980"
},
{
  "printlnReport": true,
  "_id": "6558938b5586e008158bd3b4",
```

```
"id": "3",
"property": "GTB Nagar, Mumbai",
"area": "350",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "4650000",
"expectedRate": "13285.71",
"builtUpExpectedRate": "12077.92",
"image": "cases/6556034e5586e00815886ac5/
indicator_1700303755355_Image.png"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b096f",
  "name":
"externallmg_1700287691842_WhatsApp_Image_20231118_at_92042_AM.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691842_WhatsApp_Image_20231118_at_92042_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0970",
  "name":
"externallmg_1700287691845_WhatsApp_Image_20231118_at_92043_AM_1.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691845_WhatsApp_Image_20231118_at_92043_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0971",
  "name":
"externallmg_1700287691850_WhatsApp_Image_20231118_at_92043_AM.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691850_WhatsApp_Image_20231118_at_92043_AM.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0972",
  "name":
"externallmg_1700287691854_WhatsApp_Image_20231118_at_92044_AM_1.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691854_WhatsApp_Image_20231118_at_92044_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0973",
  "name":
"externallmg_1700287691859_WhatsApp_Image_20231118_at_92044_AM.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691859_WhatsApp_Image_20231118_at_92044_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0974",
  "name":
"externallmg_1700287691862_WhatsApp_Image_20231118_at_92045_AM_1.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691862_WhatsApp_Image_20231118_at_92045_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0975",
  "name":
"externallmg_1700287691863_WhatsApp_Image_20231118_at_92045_AM_2.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691863_WhatsApp_Image_20231118_at_92045_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b0976",
  "name":
"externallmg_1700287691866_WhatsApp_Image_20231118_at_92045_AM.jpeg",
```



```
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691866_WhatsApp_Image_20231118_at_92045_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655854cb5586e008158b0977",
    "name":
"externallmg_1700287691869_WhatsApp_Image_20231118_at_92046_AM_1.jpeg",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691869_WhatsApp_Image_20231118_at_92046_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655854cb5586e008158b0978",
    "name":
"externallmg_1700287691872_WhatsApp_Image_20231118_at_92046_AM.jpeg",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691872_WhatsApp_Image_20231118_at_92046_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655854cb5586e008158b0979",
    "name":
"externallmg_1700287691874_WhatsApp_Image_20231118_at_92047_AM_1.jpeg",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691874_WhatsApp_Image_20231118_at_92047_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655854cb5586e008158b097a",
    "name":
"externallmg_1700287691876_WhatsApp_Image_20231118_at_92047_AM_2.jpeg",
    "path": "cases/6556034e5586e00815886ac5/
externallmg_1700287691876_WhatsApp_Image_20231118_at_92047_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655854cb5586e008158b097b",
  "name":
"externalImg_1700287691878_WhatsApp_Image_20231118_at_92047_AM.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externalImg_1700287691878_WhatsApp_Image_20231118_at_92047_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b097c",
  "name":
"externalImg_1700287691880_WhatsApp_Image_20231118_at_92048_AM_1.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externalImg_1700287691880_WhatsApp_Image_20231118_at_92048_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b097d",
  "name":
"externalImg_1700287691883_WhatsApp_Image_20231118_at_92048_AM_2.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externalImg_1700287691883_WhatsApp_Image_20231118_at_92048_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655854cb5586e008158b097e",
  "name":
"externalImg_1700287691886_WhatsApp_Image_20231118_at_92048_AM.jpeg",
  "path": "cases/6556034e5586e00815886ac5/
externalImg_1700287691886_WhatsApp_Image_20231118_at_92048_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"remarks": [],
"createdAt": "2023-11-16T11:55:58.817Z",
"updatedAt": "2023-11-18T10:41:41.733Z",
"__v": 0,
```

"invoiceId": "6556034e5586e00815886ace",  
"fullAddress": "Residential Flat No. 102, 1st Floor, Building No 3, Wing - B, MHADA  
Housing Scheme Code No. 350 (LIG), Village - Antop Hill, Municipality Ward No. F/  
North, Wadala (East), Mumbai, PIN Code - 400 037, State - Maharashtra, India",  
"updatedBy": "627221f4afd7d55eddeddcb4",  
"addressForMap": "",  
"caseReferredBy": "60b7177d2ffdf65bcd65882a",  
"contactPersonName": "Faizan Khan",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "Security Guard",  
"siteVisitContactNo": "9768809299",  
"buildingServicesRate": "3000",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": "MHADA Offer Letter",  
"finalBuiltUpPercentage": "20",  
"finalCarpetConvertToBuiltUpPer": "20",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 300.00",  
"flatRate": "15000.00",  
"landOtherRate": "12000",  
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet + Bathroom +  
Passage",  
"carpetTotal": "298.52000000000004",  
"otherCarpetTotal": "0.00",  
"builtupPercentage": "10",  
"finalBuiltupArea": "328.37",  
"finalCarpetArea": "298.52",  
"finalSalableArea": "361.21",  
"salablePercentage": "10",  
"toBeAdded": "",  
"extendOfSiteRemark": "",  
"siteMeasurementRemark": "",  
"finalSaleablePercentage": "",  
"landDetails": {  
 "holdType": {  
 "label": "Free Hold",  
 "value": "Free\_Hold"  
 },  
 "leaseDetails": {  
 "lessorName": "",  
 "lesseeName": "",  
 "leasePremium": "",

```

    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Bedroom	10'0"	8'8"	86.67
Kitchen	10'00"	5'2"	51.67
Toilet	5'2"	2'3"	11.62
Bathroom	7'2"	1'10"	13.14
Passage	11'00"	2'1"	22.92
Living Room	10'0"	11'3"	112.50
Other Composition :			