

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "648aa63dda662768e994f772",
    "firstName": "Saumita Chakraborty",
    "lastName": "Chakraborty",
    "mobileNo": "",
    "workMobileNo": "9167177426",
    "email": "Saumita.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Saumita Chakraborty",
  }
}
```

```
"expectedFees": 2500,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirod Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
```

```
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc4680ce84bf289ba9c7fc",
    "role": "SITEENGINEER",
    "firstName": "Nikhil ",
    "email": "valtechnical2022@gmail.com",
    "lastName": "Sonawane",
    "mobileNo": "9819470709",
    "designation": "",
    "shortName": "NS",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
    "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
```

```
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
```

```
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.298095246208845",
  "longitude": "73.22331368898062"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.22331368898062,
    19.298095246208845
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-11-18T02:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-18T02:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-18T02:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
```

```
"label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Titwala",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Titwala (East), Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Om Vinayak Darshan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Raviraj Hotel",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Goveli Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "112",
"label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "3",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 605",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
```

```

},
"flooring": {
  "value": "VerifiedTileFlooring",
  "label": "Vitrified Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
  "label": "Teak Wood Door frame with Solid door with safety door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
  "label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Valaram Ashish CHSL",

```

```
"west": "Wing B & Open Plot",
"south": "Open Plot",
"east": "Ekta Nagar Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "4387.5",
  "depreciatedBuildingRate": "2087.5"
},
"igrRate": {
  "propertyName": "Titwala",
  "rate": "47500",
  "landRate": "11300",
  "igrImage": "cases/655753585586e008158a232e/igr_1700566279975_Image.png",
  "squareMeterGuideLineRate": "45125.00",
```

```
"squareFeetGuideLineRate": "4192.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00",
  "depreciationPercentage": "89",
  "rate": "3847.00",
  "squareFeetGuideLineRate": "3847.00",
  "squareMeterGuideLineRate": "41404.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "5,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KDMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2012",
  "fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
}
```

```
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
```

```
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "Approx.",
    "label": "Approx."
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "49",
  "ageOfBuilding": "11",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "3",
  "flatFloorNo": "1",
  "noOfLifts": "",
  "noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "580.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/655753585586e008158a232e/
routeMap_1700632479940_Image.png",
    "routeLat": "19.297917",
    "routeLng": "73.223083",
    "stationName": "Titwala",
    "routeDistance": "2.5 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
```



```
"finalatlng": true
},
"locationMapImg": [
  {
    "id": "waoem",
    "name": "waoem",
    "image": "cases/655753585586e008158a232e/
routeMap_1700632370142_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2545040.00",
  "distressValuePercentage": "70",
  "realizableValuePercentage": "85",
  "bookValue": "0",
  "finalValue": "2545040.00"
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2231260.00",
"selectedBuildUpValue": "580.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "655c70b75586e008158f2977",
"name":
"externalimg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
```

```
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "655c70b75586e008158f2984",
    "name":
"externallmg_1700556983881_WhatsApp_Image_20231120_at_111919_AM_17.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983881_WhatsApp_Image_20231120_at_111919_AM_17.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "655c70b75586e008158f2974",
    "name":
"externallmg_1700556983827_WhatsApp_Image_20231120_at_111919_AM_1.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983827_WhatsApp_Image_20231120_at_111919_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655c70b75586e008158f2975",
    "name":
"externallmg_1700556983830_WhatsApp_Image_20231120_at_111919_AM_2.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983830_WhatsApp_Image_20231120_at_111919_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "655c70b75586e008158f2977",
    "name":
"externallmg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "655c70b75586e008158f297b",
    "name":
"externallmg_1700556983856_WhatsApp_Image_20231120_at_111919_AM_8.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983856_WhatsApp_Image_20231120_at_111919_AM_8.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "655c70b75586e008158f297a",
    "name":
"externallmg_1700556983852_WhatsApp_Image_20231120_at_111919_AM_7.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983852_WhatsApp_Image_20231120_at_111919_AM_7.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "655c70b75586e008158f2983",
    "name": "Bedroom",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983878_WhatsApp_Image_20231120_at_111919_AM_16.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655c70b75586e008158f2981",
    "name": "Bedroom",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983873_WhatsApp_Image_20231120_at_111919_AM_14.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "655c70b75586e008158f297f",
    "name": "Bedroom",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983868_WhatsApp_Image_20231120_at_111919_AM_12.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "status": false,
    "_id": "655c70b75586e008158f297e",
    "name": "Bedroom",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983866_WhatsApp_Image_20231120_at_111919_AM_11.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "4720",
    "max": "6458"
  },
  "builtUpRateRange": {
    "min": "4291",
    "max": "5382"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```



```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "580.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
```

```
"audioRemarks": [],
"_id": "655753585586e008158a232e",
"ownerName": "Mr. B. Ravishankar Aithal",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no. 101, 1st Floor, Wing - A, Om Vinayak Darshan CHS, Goweli
Road, Titwala East ",
"remark": "NPA Account ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "15/06/2012",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Laxmi Developers",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. B. Ravishankar Aithal",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "4376/2012"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "269991",
    "path": "cases/655753585586e008158a232e/document_1700221757890_17002218
16778_Racpc_Sion_Ravishankar_Aithal_NPA.pdf",
    "fileName": "document_1700221757890_1700221816778_Racpc_Sion_Ravishanka
r_Aithal_NPA.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/02/2011",
```

```
"nameOfApprovingAuthority": {
  "value": "Kalyan_Dombivli_Municipal_Corporation",
  "label": "Kalyan Dombivli Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "KDMP / NRV / BP / KV / 686 -333"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1700630970805_CC.pdf",
"path": "cases/655753585586e008158a232e/document_1700630970805_CC.pdf",
"id": "510139",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Wed Nov 22 2023 10:59:30 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1257aa6d152c1801b334",
    "label": "Rectification Deed"
  },
  "inputs": {
    "documentDate": "25/09/2012",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "M/s. Laxmi Developers",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. B. Ravishankar Aithal",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "5953/2012"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700631163906_retification_deed.pdf",
  "path": "cases/655753585586e008158a232e/
document_1700631163906_retification_deed.pdf",
```

```
"id": "669332",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Wed Nov 22 2023 11:02:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "23/08/2021",
    "remark": " issued by Er. G. V. Khot, Valuers & Consultant"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "528476",
  "path": "cases/655753585586e008158a232e/
document_1700631412502_khot__previ.pdf",
  "fileName": "document_1700631412502_khot__previ.pdf"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "29/08/2012",
    "remark": " issued by Yardi Prabhu Consultant & Valuers Pvt. Ltd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "248979",
  "path": "cases/655753585586e008158a232e/
document_1700631486487_yardi__previ.pdf",
  "fileName": "document_1700631486487_yardi__previ.pdf"
}
],
"caseNumber": "005087",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "584131",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Nov 17 2023 17:19:44 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. B. Ravishankar Aithal",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "380315"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "632128",
    "name": "Bedroom",
    "length": "9.00",
    "length1": "9",
    "length2": "00",
    "width": "11.00",
    "width1": "11",
    "width2": "00",
    "totalArea": "99.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "99.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "WC",
    "length": "4.00",
    "length1": "4",
    "length2": "00",
    "width": "3.00",
    "width1": "3",
    "width2": "00",
    "totalArea": "12.00",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "24.50",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "655d902a5586e00815901383",
      "name": "CP area ",
      "extraAreaType": "Add",
      "length": "4.17",
      "length1": "4",
      "length2": "2",
      "width": "1.75",
      "width1": "1",
      "width2": "9",
      "totalArea": "7.29"
    }
  ],
  "finalArea": "31.79"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "7.33",
```

```
"length1": "7",
"length2": "4",
"width": "8.25",
"width1": "8",
"width2": "3",
"totalArea": "60.50",
"images": [],
"extraAreas": [],
"finalArea": "60.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "135.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "135.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Cupboard",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "3",
    "length2": "5",
    "length": "3.42",
    "width1": "9",
    "width2": "4",
    "width": "9.33",
    "totalArea": "31.89",
    "percentageBeforeTotal": "49.89",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "_id": "655d907b5586e008159014c9",
  "name": "Living Balcony",
  "extraAreaType": "Add",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "18.00"
}
],
"percentage": "100",
"finalArea": "49.89"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "733508",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "580",
    "squareMeterArea": "53.88",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
```

```
  "_id": "655c955b5586e008158f900f",
  "property": "Goveli Road, Titwala",
  "area": "480",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "3100000",
  "expectedRate": "6458.33",
  "builtUpExpectedRate": "5381.94",
  "image": "cases/655753585586e008158a232e/
indicator_1700565905806_Image.png",
  "squareMeter": "44.59",
  "id": "166568"
},
{
  "printlnReport": true,
  "_id": "655c955b5586e008158f9010",
  "property": "Titwala Goveli Road, Titwala",
  "area": "460",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "2800000",
  "expectedRate": "6086.96",
  "builtUpExpectedRate": "5072.46",
  "image": "cases/655753585586e008158a232e/
indicator_1700565995998_Image.png",
  "squareMeter": "42.74",
  "id": "827133"
},
{
  "printlnReport": true,
  "_id": "655c955b5586e008158f9011",
  "property": "Umiya Complex, Titwala",
  "area": "415",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "2500000",
"expectedRate": "6024.10",
"builtUpExpectedRate": "5020.08",
"image": "cases/655753585586e008158a232e/
indicator_1700566115536_Image.png",
"squareMeter": "38.55",
"id": "171142"
},
{
"printlnReport": true,
"_id": "655c955b5586e008158f9012",
"property": "Goveli Road, Titwala",
"area": "585",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "3",
"source": "magic_bricks",
"expectedPrice": "2510000",
"expectedRate": "4290.60",
"builtUpExpectedRate": "0.00",
"image": "cases/655753585586e008158a232e/
indicator_1700566218307_Image.png",
"squareMeter": "54.35",
"id": "728111"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "655c70b75586e008158f2974",
"name":
"externalImg_1700556983827_WhatsApp_Image_20231120_at_111919_AM_1.jpeg",
"path": "cases/655753585586e008158a232e/
externalImg_1700556983827_WhatsApp_Image_20231120_at_111919_AM_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "655c70b75586e008158f2975",
"name":
"externalImg_1700556983830_WhatsApp_Image_20231120_at_111919_AM_2.jpeg",
```

```
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983830_WhatsApp_Image_20231120_at_111919_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2976",
    "name":
"externallmg_1700556983835_WhatsApp_Image_20231120_at_111919_AM_3.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983835_WhatsApp_Image_20231120_at_111919_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2977",
    "name":
"externallmg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983839_WhatsApp_Image_20231120_at_111919_AM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2978",
    "name":
"externallmg_1700556983843_WhatsApp_Image_20231120_at_111919_AM_5.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983843_WhatsApp_Image_20231120_at_111919_AM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2979",
    "name":
"externallmg_1700556983848_WhatsApp_Image_20231120_at_111919_AM_6.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983848_WhatsApp_Image_20231120_at_111919_AM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "655c70b75586e008158f297a",
  "name":
"externallmg_1700556983852_WhatsApp_Image_20231120_at_111919_AM_7.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983852_WhatsApp_Image_20231120_at_111919_AM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f297b",
  "name":
"externallmg_1700556983856_WhatsApp_Image_20231120_at_111919_AM_8.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983856_WhatsApp_Image_20231120_at_111919_AM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f297c",
  "name":
"externallmg_1700556983858_WhatsApp_Image_20231120_at_111919_AM_9.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983858_WhatsApp_Image_20231120_at_111919_AM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f297d",
  "name":
"externallmg_1700556983862_WhatsApp_Image_20231120_at_111919_AM_10.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983862_WhatsApp_Image_20231120_at_111919_AM_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f297e",
  "name":
"externallmg_1700556983866_WhatsApp_Image_20231120_at_111919_AM_11.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983866_WhatsApp_Image_20231120_at_111919_AM_11.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f297f",
    "name":
"externallmg_1700556983868_WhatsApp_Image_20231120_at_111919_AM_12.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983868_WhatsApp_Image_20231120_at_111919_AM_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2980",
    "name":
"externallmg_1700556983871_WhatsApp_Image_20231120_at_111919_AM_13.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983871_WhatsApp_Image_20231120_at_111919_AM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2981",
    "name":
"externallmg_1700556983873_WhatsApp_Image_20231120_at_111919_AM_14.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983873_WhatsApp_Image_20231120_at_111919_AM_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2982",
    "name":
"externallmg_1700556983876_WhatsApp_Image_20231120_at_111919_AM_15.jpeg",
    "path": "cases/655753585586e008158a232e/
externallmg_1700556983876_WhatsApp_Image_20231120_at_111919_AM_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655c70b75586e008158f2983",
```

```
    "name":
"externallmg_1700556983878_WhatsApp_Image_20231120_at_111919_AM_16.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983878_WhatsApp_Image_20231120_at_111919_AM_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f2984",
  "name":
"externallmg_1700556983881_WhatsApp_Image_20231120_at_111919_AM_17.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983881_WhatsApp_Image_20231120_at_111919_AM_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f2985",
  "name":
"externallmg_1700556983883_WhatsApp_Image_20231120_at_111919_AM_18.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983883_WhatsApp_Image_20231120_at_111919_AM_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f2986",
  "name":
"externallmg_1700556983885_WhatsApp_Image_20231120_at_111919_AM.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983885_WhatsApp_Image_20231120_at_111919_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655c70b75586e008158f2987",
  "name":
"externallmg_1700556983891_WhatsApp_Image_20231120_at_111920_AM.jpeg",
  "path": "cases/655753585586e008158a232e/
externallmg_1700556983891_WhatsApp_Image_20231120_at_111920_AM.jpeg",
  "orientation": "portrait"
}
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "Om Darshan.xlsx",
    "filename": "1700566352302_Om_Darshan.xlsx",
    "path": "cases/655753585586e008158a232e/
processingDocuments/1700566352302_Om_Darshan.xlsx",
    "size": "2427872",
    "createdAt": "Tue Nov 21 2023 17:02:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "655c69055586e008158f1088",
    "note": "ate Verification Done Pending for bank confirmation.",
    "taskId": "65582e645586e008158a6c90",
    "createdAt": "2023-11-21T08:23:33.687Z"
  },
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdfc2",
      "role": "FRONTDESK",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "655c706b5586e008158f26f8",
    "note": "Wrong Photo Upload (Task Reopen)",
  }
]
```



```
"taskId": "65582e645586e008158a6c97",
"createdAt": "2023-11-21T08:55:07.382Z"
}
],
"createdAt": "2023-11-17T11:49:44.748Z",
"updatedAt": "2023-11-22T06:00:54.958Z",
"__v": 0,
"invoiceId": "655753585586e008158a2337",
"fullAddress": "Residential Flat No. 101, 1st Floor, Wing - A, Om Vinayak Darshan Co-
op. Hsg. Soc. Ltd., Near Raviraj Hotel, Goveli Road, Village - Titwala, Taluka - Kalyan,
District - Thane, Titwala (East), Thane, PIN - 421 605, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Varsha Aithal ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's wife",
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 580.00",
"flatRate": "4800",
"landOtherRate": "2300",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Passage +
Bathroom + Cupboard",
"carpetTotal": "271.29",
"otherCarpetTotal": "50",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "49.89",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "462.20",
"finalCarpetArea": "420.18",
"finalSalableArea": "508.42",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "\nBuilt Up Area in Sq. Ft. = 550.00\nOpen Terrace Area in Sq.
Ft. = 30.00\n(Area as per Agreement for Sale)",
```

```

"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 370.00\nBalcony Area in Sq.
Ft. = 50.00\n(Area as per actual site measurement)",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Nov 22 2023 10:34:58 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-18"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	9'00"	11'00"	99.00
WC	4'00"	3'00"	12.00
Passage	8'2"	3'0"	24.50
Kitchen	7'4"	8'3"	60.50
Bathroom	5'00"	4'00"	20.00
Living Room	15'00"	9'00"	135.00
Cupboard	6'00"	2'00"	12.00
Other Composition :			
Balcony Area	3'5"	9'4"	31.89