

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "SITEENGINEER",
  "firstName": "Abhiraj",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.5425646219963",
  "longitude": "73.9360482681068"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.9360482681068,
    18.5425646219963
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-18T09:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-18T09:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Kharadi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "19",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Tower - E",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Haveli",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ganga Altus",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mundhwa - Kharadi Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "22/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1906",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 411 014",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Pune",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Pune_Municipal_Corporation",
"label": "Pune Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Pride Icon Building",
"west": "Open Plot & Road",
"south": "Road",
"east": "Under Construction Building"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
    },
    "extraDetailOfProperty": "",
    "dateOfIssusApprovePlan": " Copy of Approved Building Plan Document No.1539/21
Dated 06.09.2021 issued by Pune Municipal Corporation",
    "approvePlanVerified": "Building Under Construction",
    "empanelledOfApprovePlan": "N.A."
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "depreciatedCostOfConstruction": "",
    "depreciatedBuildingRate": ""
  },
  "igrRate": {
    "propertyName": "Residential ",
    "rate": "84770",
    "landRate": "28010",
    "igrImage": "cases/655886065586e008158ba338/igr_1700305987054_Image.png",
    "squareMeterGuideLineRate": "93247.00",
    "squareFeetGuideLineRate": "8663.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00",
    "depreciationPercentage": "0",
    "rate": "84770",
    "squareMeterGuideLineRate": "93247.00",
    "squareFeetGuideLineRate": "8663.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Building_Under_Construction",
      "label": "Building Under Construction"
    },
    "monthlyRent": "22000",
    "assessmentNo": "Details not available",
    "taxPaidHolderName": "Details not available",
```

```
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per Pune Municipal Corporation norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developing Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Along with Single Covered Car Parking at Ground i.e. No. 37",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
```

```
"fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Lower_Ground_+_Upper_Ground_Floor",
  "label": "Lower Ground + Upper Ground Floor"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "4",
"noOfAmenityFloors": "1",
"noOfFloors": "24",
"flatFloorNo": "19",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
```



```
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/655886065586e008158ba338/
routeMap_1700640496042_Image.png",
  "routeLat": "18.542764",
  "routeLng": "73.936289",
  "stationName": "Hadapsar (Pune)",
  "routeDistance": "3.1 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finalLatLng": true
},
"locationMapImg": [
  {
    "id": "60k4dn",
    "name": "60k4dn",
    "image": "cases/655886065586e008158ba338/
routeMap_1700640416504_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "10728000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "10728000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "24",
    "percentage": "30.967741935483872",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "24",
  "percentage": "5.42",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "24",
  "percentage": "5.42",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "24",
  "percentage": "2.71",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "54.52",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "8519194.00",
  "selectedBuildUpValue": "983.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "655d94625586e00815902032",
      "name":
"externallmg_1700631650715_WhatsApp_Image_20231122_at_110132_AM_1.jpeg",
      "path": "cases/655886065586e008158ba338/"
externallmg_1700631650715_WhatsApp_Image_20231122_at_110132_AM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "655d94625586e00815902036",
      "name":
"externallmg_1700631650726_WhatsApp_Image_20231122_at_110133_AM.jpeg",
      "path": "cases/655886065586e008158ba338/"
externallmg_1700631650726_WhatsApp_Image_20231122_at_110133_AM.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "655d94625586e00815902038",
      "name":
"externallmg_1700631650733_WhatsApp_Image_20231122_at_110134_AM.jpeg",
      "path": "cases/655886065586e008158ba338/"
externallmg_1700631650733_WhatsApp_Image_20231122_at_110134_AM.jpeg",
      "orientation": "landscape"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "655d94625586e00815902030",
  "name":
"externallmg_1700631650707_WhatsApp_Image_20231122_at_110131_AM_1.jpeg",
  "path": "cases/655886065586e008158ba338/
externallmg_1700631650707_WhatsApp_Image_20231122_at_110131_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "655d94625586e00815902031",
  "name":
"externallmg_1700631650712_WhatsApp_Image_20231122_at_110131_AM.jpeg",
  "path": "cases/655886065586e008158ba338/
externallmg_1700631650712_WhatsApp_Image_20231122_at_110131_AM.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "12000",
    "max": "13333"
  },
  "builtUpRateRange": {
    "min": "10910",
    "max": "12122"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```



```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "894.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "655886065586e008158ba338",
"audioRemarks": [],
"ownerName": "Kumar Gaurav ",
"ownerPhoneNo": "8698066096",
"appAddress": "Flat no. 1906, 19th Floor, Ganga Altus, Tower E, Village - Kharadi,
Pune",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae12a0aa6d152c1801b485",
      "label": "Agreement For Sale (6 pages from document)"
    },
    "inputs": {
      "documentDate": "09/11/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Goel Ganga India Private Limited",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Kumar Gaurav"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "619620",
    "path": "cases/655886065586e008158ba338/
document_1700300274224_1700300334009_CamScanner_11182023_141006.pdf",
    "fileName":
"document_1700300274224_1700300334009_CamScanner_11182023_141006.pdf"
```

```
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "05/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Pune_Municipal_Corporation",
      "label": "Pune Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KRD / DP / 0027 / 08"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700641405445_document_1700300274224_1700300334009_CamScanner_11182023_141006.pdf",
  "path": "cases/655886065586e008158ba338/document_1700641405445_document_1700300274224_1700300334009_CamScanner_11182023_141006.pdf",
  "id": "320489",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Nov 22 2023 13:53:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "06/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Pune_Municipal_Corporation",
      "label": "Pune Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "1539/21"
  },
  "isHardCopy": false,
```

```
"displayStatus": true,
"fileName": "document_1700664387823_58.pdf",
"path": "cases/655886065586e008158ba338/document_1700664387823_58.pdf",
"id": "886922",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Nov 22 2023 20:16:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P52100024713"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700664436226_P52100024713.pdf",
  "path": "cases/655886065586e008158ba338/
document_1700664436226_P52100024713.pdf",
  "id": "745536",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Nov 22 2023 20:17:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005108",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "751789",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Nov 18 2023 15:08:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Kumar Gaurav ",
"phone": "8698066096",
"ownershipShare": "",
"email": "",
"id": "772189"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "83.06",
  "totalAreaDocument": "894.00",
  "docBUILTUPPercentage": "10",
  "docFinalBUILTUP": "983.40",
  "docFinalBUILTUPSquareMeter": "91.36",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "674315"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65589c565586e008158c0030",
  "property": "Ganga Altus Kharadi, Pune, Maharashtra",
  "area": "786.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
}
```

```
"expectedPrice": "9432000.00",
"expectedRate": "12000.00",
"builtUpExpectedRate": "10909.09",
"image": "cases/655886065586e008158ba338/
indicator_1700305571272_Image.png",
"squareMeter": "73.02",
"id": "676124"
},
{
  "printlnReport": true,
  "_id": "65589c565586e008158c0031",
  "property": "Ganga Altus Kharadi, Pune, Maharashtra",
  "area": "750.00",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "10000000.00",
  "expectedRate": "13333.33",
  "builtUpExpectedRate": "12121.21",
  "image": "cases/655886065586e008158ba338/
indicator_1700305632572_Image.png",
  "squareMeter": "69.68",
  "id": "341930"
},
{
  "printlnReport": true,
  "_id": "65589c565586e008158c0032",
  "property": "Ganga Altus Kharadi, Pune, Maharashtra",
  "area": "950.0",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "11400000.00",
  "expectedRate": "12000.00",
  "builtUpExpectedRate": "10909.09",
  "image": "cases/655886065586e008158ba338/
indicator_1700305675134_Image.png",
  "squareMeter": "88.26",
  "id": "841429"
},
{
  "printlnReport": true,
```

```
    "_id": "65589c565586e008158c0033",
    "property": "Flat For Sale Ganga Altus EON Free Zone, Pune",
    "area": "693.00",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "9000000.00",
    "expectedRate": "12987.01",
    "builtUpExpectedRate": "11806.38",
    "image": "cases/655886065586e008158ba338/
indicator_1700305725120_Image.png",
    "squareMeter": "64.38",
    "id": "346236"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e0081590202f",
    "name":
"externallmg_1700631650704_WhatsApp_Image_20231122_at_110130_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650704_WhatsApp_Image_20231122_at_110130_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902030",
    "name":
"externallmg_1700631650707_WhatsApp_Image_20231122_at_110131_AM_1.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650707_WhatsApp_Image_20231122_at_110131_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902031",
    "name":
"externallmg_1700631650712_WhatsApp_Image_20231122_at_110131_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650712_WhatsApp_Image_20231122_at_110131_AM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902032",
    "name":
"externallmg_1700631650715_WhatsApp_Image_20231122_at_110132_AM_1.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650715_WhatsApp_Image_20231122_at_110132_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902033",
    "name":
"externallmg_1700631650719_WhatsApp_Image_20231122_at_110132_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650719_WhatsApp_Image_20231122_at_110132_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902034",
    "name":
"externallmg_1700631650721_WhatsApp_Image_20231122_at_110133_AM_1.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650721_WhatsApp_Image_20231122_at_110133_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902035",
    "name":
"externallmg_1700631650723_WhatsApp_Image_20231122_at_110133_AM_2.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650723_WhatsApp_Image_20231122_at_110133_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902036",
```

```
    "name":
"externallmg_1700631650726_WhatsApp_Image_20231122_at_110133_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650726_WhatsApp_Image_20231122_at_110133_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902037",
    "name":
"externallmg_1700631650730_WhatsApp_Image_20231122_at_110134_AM_1.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650730_WhatsApp_Image_20231122_at_110134_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902038",
    "name":
"externallmg_1700631650733_WhatsApp_Image_20231122_at_110134_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650733_WhatsApp_Image_20231122_at_110134_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655d94625586e00815902039",
    "name":
"externallmg_1700631650735_WhatsApp_Image_20231122_at_110135_AM.jpeg",
    "path": "cases/655886065586e008158ba338/
externallmg_1700631650735_WhatsApp_Image_20231122_at_110135_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"remarks": [],
"createdAt": "2023-11-18T09:38:14.978Z",
"updatedAt": "2023-11-23T04:50:51.190Z",
"__v": 0,
"invoiceId": "655886075586e008158ba33e",
"fullAddress": "Residential Flat No. 1906, 19th Floor, Building No Tower - E, Ganga
```



Altus, Mundhwa - Kharadi Road, Village - Kharadi, Pune, Taluka - Haveli, District - Pune, PIN Code - 411 014, State - Maharashtra, India",  
"updatedBy": "60092304a16fab0f2af9b0c2",  
"addressForMap": "",  
"caseReferredBy": "60b7177d2ffdf65bcd65882a",  
"contactPersonName": "Mr. Premsagar Sutar",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "Sales Person",  
"siteVisitContactNo": "9623538203",  
"buildingServicesRate": "2800",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": " Agreement",  
"finalBuiltUpPercentage": "10",  
"finalCarpetConvertToBuiltUpPer": "10",  
"finalMeasurementType": "Sq. Ft.",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 894.00",  
"flatRate": "12000",  
"landOtherRate": "9200",  
"landDetails": {  
 "holdType": {  
 "label": "Free Hold",  
 "value": "Free\_Hold"  
 },  
 "leaseDetails": {  
 "lessorName": "",  
 "lesseeName": "",  
 "leasePremium": "",  
 "leaseRent": "",  
 "leasePeriod": 0,  
 "leaseFrom": "",  
 "leaseTo": "",  
 "remainingLeasePeriod": 0,  
 "leaseDate": ""  
 }  
},  
"finalSaleablePercentage": "",  
"builtupPercentage": "10",  
"carpetTotal": "0",  
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 786.00\nEntrance Lobby Area in Sq. Ft. = 12.00\nDry Balcony Area in Sq. Ft. = 35.00\nBalcony Area in Sq. Ft. = 61.00\nTotal Carpet Area in Sq. Ft. = 894.00\n(Area as per Agreement for Sale)",  
"finalBuiltupArea": "0.00",

"finalCarpetArea": "0.00",  
"finalSalableArea": "0.00",  
"otherCarpetTotal": "0",  
"salablePercentage": "10",  
"siteMeasurementRemark": "",  
"toBeAdded": ""

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---