

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2742506",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 1371.253,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "627219d6afd7d55eddedd283",
  "role": "PICKUPPERSON",
  "firstName": "Mangesh ",
  "email": "mangeshpalande17@gmail.com",
  "lastName": "Palande",
  "mobileNo": "9833030550",
  "shortName": "MP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
  "designation": ""
```

```
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordinatiion",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.44975138199876",
  "longitude": "72.79086692762138"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.79086692762138,
    19.44975138199876
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-11-22T08:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-23",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Bolinj",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Bachraj Avenue Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Padmavati Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Agashi Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "13, Hissa No. 1, 2, Survey No. 22, Hissa No. 4, Survey No. 387-B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "504",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 303",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Vasai_Virar_City_Municipal_Corporation",
"label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building \"Omkar Plaza\" ",
"west": "Padmavati Nagar Road / Building \"Poonam Aura\"",
"south": "Internal Road",
"east": "Building \"Sambhav Gold\""
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
    },
    "extraDetailOfProperty": "",
    "dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
    "approvePlanVerified": "N.A.",
    "empanelledOfApprovePlan": "No"
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "15",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "buildingServicesDepreciatedRate": "375",
    "depreciatedCostOfConstruction": "7625.00",
    "depreciatedBuildingRate": "2125"
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "59600",
    "landRate": "14200",
    "igrImage": "cases/655d88d05586e008158ff420/igr_1700824089124_Image.png",
    "squareMeterGuideLineRate": "62580.00",
    "squareFeetGuideLineRate": "5814.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "5",
    "depreciationPercentage": "90",
    "rate": "5364.00",
    "squareFeetGuideLineRate": "5364.00",
    "squareMeterGuideLineRate": "57742.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Seller_Occupied",
      "label": "Seller Occupied"
    },
    "monthlyRent": "6,000",
    "assessmentNo": "BL03/305/42",
```

```
"taxPaidHolderName": "Yogesh V. Karangutkar",
"taxAmount": "Rs. 2591/- for Year 2023-24 dated 18.05.2023",
"electricityServiceConnectionNo": "001547085236",
"meterCardHolderName": "Yogesh Vijay Karangutkar",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2013",
    "date": "1",
```

```
"month": "1",
"year": "2013"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "10",
"totalLifeBuilding": "60",
"estimatedAge": "50",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "471.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
}
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/655d88d05586e008158ff420/
routeMap_1700817114175_Image.png",
    "routeLat": "19.449389",
    "routeLng": "72.791139",
    "stationName": "Virar",
    "routeDistance": "3.2 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "xhenl",
      "name": "xhenl",
      "image": "cases/655d88d05586e008158ff420/
routeMap_1700816983151_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2996625.00",
"finalValue": "2996625.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2529662.00",
"selectedBuildUpValue": "471.60",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65602b9fcabee4333992f27c",
"name":
"externallmg_1700801439019_WhatsApp_Image_20231124_at_84404_AM_2.jpeg",
"path": "cases/655d88d05586e008158ff420/
externallmg_1700801439019_WhatsApp_Image_20231124_at_84404_AM_2.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "65602bd5cabee4333992f36f",
"name":
"externallmg_1700801493792_WhatsApp_Image_20231124_at_84409_AM.jpeg",
"path": "cases/655d88d05586e008158ff420/
externallmg_1700801493792_WhatsApp_Image_20231124_at_84409_AM.jpeg",
"orientation": "landscape"
}
],
"externalPhotos": [
{
"status": false,
"_id": "65602b9fcabee4333992f281",
"name":
"externallmg_1700801439050_WhatsApp_Image_20231124_at_84406_AM_1.jpeg",
```

```
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439050_WhatsApp_Image_20231124_at_84406_AM_1.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65602b9fcabee4333992f28c",
    "name": "Living Room",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439087_WhatsApp_Image_20231124_at_84409_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65602bd5cabee4333992f374",
    "name": "Living Room",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493804_WhatsApp_Image_20231124_at_84417_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65602bd5cabee4333992f375",
    "name": "Living Room",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493807_WhatsApp_Image_20231124_at_84417_AM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6951",
    "max": "8634"
  },
  "builtUpRateRange": {
    "min": "5793",
    "max": "7196"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "393.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "655d88d05586e008158ff420",
"audioRemarks": [],
"ownerName": "Mr. Pravin P. Kulkarni",
"ownerPhoneNo": "9819214563",
"appAddress": "bachraj avanue bldg no 1 flat A/504 bachraj avanue bolinj virar w",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "06/11/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Yogesh V. Karangutkar & Mrs. Vaibhavi Y. Karangutkar",
      "to": {
        "value": "Purchaser",
```

```
    "label": "Purchaser"
  },
  "Purchaser": "Mr. Pravin P. Kulkarni & Mrs. Seema Pravin Kulkarni",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "16382/2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1700822423949_Sale_Deed__2023.pdf",
"path": "cases/655d88d05586e008158ff420/
document_1700822423949_Sale_Deed__2023.pdf",
"id": "289537",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Nov 24 2023 16:10:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "22/03/2013",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "VVCMC / TP / POC / VP-0536 / 551 / 2012-13"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1700822517462_Occupancy_Certificate.pdf",
"path": "cases/655d88d05586e008158ff420/
document_1700822517462_Occupancy_Certificate.pdf",
"id": "833579",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Nov 24 2023 16:11:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "15/09/2023",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "001547085236"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700823267622_Electricity_Bill.pdf",
  "path": "cases/655d88d05586e008158ff420/
document_1700823267622_Electricity_Bill.pdf",
  "id": "251592",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Nov 24 2023 16:24:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125faa6d152c1801b35b",
    "label": "Property Tax Receipt"
  },
  "inputs": {
    "documentDate": "18/05/2023",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "BL03/305/42"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700824300886_Property_Tax_Bill.pdf",
  "path": "cases/655d88d05586e008158ff420/
document_1700824300886_Property_Tax_Bill.pdf",
  "id": "701878",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Nov 24 2023 16:41:41 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae1268aa6d152c1801b383",
    "label": "Revised Development Permission"
  },
  "inputs": {
    "documentDate": "23/02/2010",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra ltd."
    },
    "remark": "Document No. CIDCO / VVSR / RDP / BP-1087 / W / 6048"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1700824880050_Revised_Development_Permission.pdf",
  "path": "cases/655d88d05586e008158ff420/
document_1700824880050_Revised_Development_Permission.pdf",
  "id": "665120",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Nov 24 2023 16:51:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/09/2023",
    "remark": "issued by Bachraj Avenue Co-op. Hsg. Soc. Ltd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1700825940616_287207.pdf",
  "path": "cases/655d88d05586e008158ff420/
document_1700825940616_287207.pdf",
  "id": "557935",
  "uploadedBy": "64cde526dc9f3034f3fefa49",
  "createdAt": "Fri Nov 24 2023 17:09:00 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005165",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "321996",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Wed Nov 22 2023 10:21:28 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Pravin P. Kulkarni",
"phone": "9819214563",
"ownershipShare": "",
"email": "",
"id": "858444"
},
{
"name": "Mrs. Seema Pravin Kulkarni",
"phone": "",
"email": "",
"ownershipShare": "",
"id": "636436"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "8",
"name": "Living Room",
"length": "9.00",
"length1": "9",
"length2": "0",
"width": "16.42",
"width1": "16",
"width2": "5",
"totalArea": "147.75",
"images": [],
"finalArea": "147.75",
"extraAreas": []
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
}
```

```
},
  "id": "8",
  "name": "Passage",
  "length": "",
  "length1": "8",
  "length2": "0",
  "width": "",
  "width1": "2",
  "width2": "11",
  "totalArea": "23.33",
  "images": [],
  "finalArea": "23.33",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "1",
  "width2": "0",
  "totalArea": "4.00",
  "images": [],
  "finalArea": "4.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bathroom",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "5",
  "width2": "5",
  "totalArea": "21.67",
```

```
"images": [],
"finalArea": "21.67",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Kitchen",
  "length": "8.33",
  "length1": "8",
  "length2": "4",
  "width": "7.33",
  "width1": "7",
  "width2": "4",
  "totalArea": "61.11",
  "images": [],
  "finalArea": "61.11",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "WC",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
```

```
"name": "Bedroom",
"length": "",
"length1": "12",
"length2": "0",
"width": "",
"width1": "9",
"width2": "2",
"totalArea": "110.00",
"images": [],
"finalArea": "110.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Cupboard",
  "length": "",
  "length1": "5",
  "length2": "0",
  "width": "",
  "width1": "2",
  "width2": "0",
  "totalArea": "10.00",
  "images": [],
  "finalArea": "10.00",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowered Area",
      "value": "Flowered_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  {
    "id": "0",
```



```
"length1": "9",
"length2": "00",
"length": "9.00",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "18.00",
"percentageBeforeTotal": "18.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "18"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "8",
  "length2": "10",
  "length": "8.83",
  "width1": "2",
  "width2": "3",
  "width": "2.25",
  "totalArea": "19.87",
  "percentageBeforeTotal": "19.87",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "19.87"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
```

```
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "7",
  "length2": "2",
  "length": "7.17",
  "width1": "2",
  "width2": "2",
  "width": "2.17",
  "totalArea": "15.53",
  "percentageBeforeTotal": "15.53",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15.53"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "677987",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "393",
    "squareMeterArea": "36.51",
    "docFinalBuiltUp": "471.6",
    "docFinalBuiltUpSquareMeter": "43.812",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
```

```
"indicatorArr": [  
  {  
    "printlnReport": true,  
    "_id": "6560843acabee433399413c1",  
    "property": "Residential Flat",  
    "area": "440",  
    "builtUpPercentage": "20",  
    "saleablePercentage": "0",  
    "rateType": "price_Indicator",  
    "areaType": "Carpet",  
    "source": "square_yards",  
    "expectedPrice": "3799000",  
    "expectedRate": "8634.09",  
    "builtUpExpectedRate": "7195.08",  
    "image": "cases/655d88d05586e008158ff420/  
indicator_1700823846915_Image.png",  
    "squareMeter": "40.88",  
    "id": "192381"  
  },  
  {  
    "printlnReport": true,  
    "_id": "6560843acabee433399413c2",  
    "property": "Residential Flat",  
    "area": "470",  
    "builtUpPercentage": "20",  
    "saleablePercentage": "0",  
    "rateType": "price_Indicator",  
    "areaType": "Carpet",  
    "source": "Nobroker.com",  
    "expectedPrice": "3600000",  
    "expectedRate": "7659.57",  
    "builtUpExpectedRate": "6382.98",  
    "image": "cases/655d88d05586e008158ff420/  
indicator_1700823882437_Image.png",  
    "squareMeter": "43.66",  
    "id": "903312"  
  },  
  {  
    "printlnReport": true,  
    "_id": "6560843acabee433399413c3",  
    "property": "Residential Flat",  
    "area": "308",  
    "builtUpPercentage": "0",  
    "saleablePercentage": "0",  
    "rateType": "sale_Instance",  
    "areaType": "Built_Up",
```

```
    "source": "Index_no.2",
    "expectedPrice": "1784000",
    "expectedRate": "5792.21",
    "builtUpExpectedRate": "0.00",
    "image": "cases/655d88d05586e008158ff420/
indicator_1700823926541_Image.png",
    "squareMeter": "28.61",
    "id": "841513"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27a",
    "name":
"externallmg_1700801439000_WhatsApp_Image_20231124_at_84403_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439000_WhatsApp_Image_20231124_at_84403_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27b",
    "name":
"externallmg_1700801439007_WhatsApp_Image_20231124_at_84404_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439007_WhatsApp_Image_20231124_at_84404_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27c",
    "name":
"externallmg_1700801439019_WhatsApp_Image_20231124_at_84404_AM_2.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439019_WhatsApp_Image_20231124_at_84404_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27d",
    "name":
"externallmg_1700801439028_WhatsApp_Image_20231124_at_84404_AM.jpeg",
```

```
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439028_WhatsApp_Image_20231124_at_84404_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27e",
    "name":
"externallmg_1700801439036_WhatsApp_Image_20231124_at_84405_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439036_WhatsApp_Image_20231124_at_84405_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f27f",
    "name":
"externallmg_1700801439041_WhatsApp_Image_20231124_at_84405_AM_2.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439041_WhatsApp_Image_20231124_at_84405_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f280",
    "name":
"externallmg_1700801439046_WhatsApp_Image_20231124_at_84405_AM.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439046_WhatsApp_Image_20231124_at_84405_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f281",
    "name":
"externallmg_1700801439050_WhatsApp_Image_20231124_at_84406_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439050_WhatsApp_Image_20231124_at_84406_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65602b9fcabee4333992f282",
  "name":
"externallmg_1700801439054_WhatsApp_Image_20231124_at_84406_AM_2.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439054_WhatsApp_Image_20231124_at_84406_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f283",
  "name":
"externallmg_1700801439058_WhatsApp_Image_20231124_at_84406_AM_3.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439058_WhatsApp_Image_20231124_at_84406_AM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f284",
  "name":
"externallmg_1700801439062_WhatsApp_Image_20231124_at_84406_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439062_WhatsApp_Image_20231124_at_84406_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f285",
  "name":
"externallmg_1700801439067_WhatsApp_Image_20231124_at_84407_AM_1.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439067_WhatsApp_Image_20231124_at_84407_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f286",
  "name":
"externallmg_1700801439071_WhatsApp_Image_20231124_at_84407_AM_2.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439071_WhatsApp_Image_20231124_at_84407_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f287",
    "name":
"externallmg_1700801439074_WhatsApp_Image_20231124_at_84407_AM_3.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439074_WhatsApp_Image_20231124_at_84407_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f288",
    "name":
"externallmg_1700801439077_WhatsApp_Image_20231124_at_84407_AM.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439077_WhatsApp_Image_20231124_at_84407_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f289",
    "name":
"externallmg_1700801439080_WhatsApp_Image_20231124_at_84408_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439080_WhatsApp_Image_20231124_at_84408_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f28a",
    "name":
"externallmg_1700801439082_WhatsApp_Image_20231124_at_84408_AM_2.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439082_WhatsApp_Image_20231124_at_84408_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602b9fcabee4333992f28b",
```

```
    "name":
"externallmg_1700801439086_WhatsApp_Image_20231124_at_84408_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439086_WhatsApp_Image_20231124_at_84408_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f28c",
  "name":
"externallmg_1700801439087_WhatsApp_Image_20231124_at_84409_AM_1.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439087_WhatsApp_Image_20231124_at_84409_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602b9fcabee4333992f28d",
  "name":
"externallmg_1700801439089_WhatsApp_Image_20231124_at_84409_AM_2.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801439089_WhatsApp_Image_20231124_at_84409_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f36e",
  "name":
"externallmg_1700801493783_WhatsApp_Image_20231124_at_84409_AM_3.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493783_WhatsApp_Image_20231124_at_84409_AM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f36f",
  "name":
"externallmg_1700801493792_WhatsApp_Image_20231124_at_84409_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493792_WhatsApp_Image_20231124_at_84409_AM.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f370",
  "name":
"externallmg_1700801493794_WhatsApp_Image_20231124_at_84410_AM_1.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493794_WhatsApp_Image_20231124_at_84410_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f371",
  "name":
"externallmg_1700801493797_WhatsApp_Image_20231124_at_84410_AM_2.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493797_WhatsApp_Image_20231124_at_84410_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f372",
  "name":
"externallmg_1700801493799_WhatsApp_Image_20231124_at_84410_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493799_WhatsApp_Image_20231124_at_84410_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f373",
  "name":
"externallmg_1700801493801_WhatsApp_Image_20231124_at_84416_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493801_WhatsApp_Image_20231124_at_84416_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f374",
  "name":
"externallmg_1700801493804_WhatsApp_Image_20231124_at_84417_AM_1.jpeg",
```

```
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493804_WhatsApp_Image_20231124_at_84417_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f375",
    "name":
"externallmg_1700801493807_WhatsApp_Image_20231124_at_84417_AM_2.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493807_WhatsApp_Image_20231124_at_84417_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f376",
    "name":
"externallmg_1700801493809_WhatsApp_Image_20231124_at_84417_AM_3.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493809_WhatsApp_Image_20231124_at_84417_AM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f377",
    "name":
"externallmg_1700801493812_WhatsApp_Image_20231124_at_84417_AM.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493812_WhatsApp_Image_20231124_at_84417_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f378",
    "name":
"externallmg_1700801493815_WhatsApp_Image_20231124_at_84418_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493815_WhatsApp_Image_20231124_at_84418_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65602bd5cabee4333992f379",
  "name":
"externallmg_1700801493819_WhatsApp_Image_20231124_at_84418_AM_2.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493819_WhatsApp_Image_20231124_at_84418_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f37a",
  "name":
"externallmg_1700801493822_WhatsApp_Image_20231124_at_84418_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493822_WhatsApp_Image_20231124_at_84418_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f37b",
  "name":
"externallmg_1700801493827_WhatsApp_Image_20231124_at_84455_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493827_WhatsApp_Image_20231124_at_84455_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f37c",
  "name":
"externallmg_1700801493830_WhatsApp_Image_20231124_at_84359_AM_1.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493830_WhatsApp_Image_20231124_at_84359_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65602bd5cabee4333992f37d",
  "name":
"externallmg_1700801493833_WhatsApp_Image_20231124_at_84359_AM.jpeg",
  "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493833_WhatsApp_Image_20231124_at_84359_AM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f37e",
    "name":
"externallmg_1700801493838_WhatsApp_Image_20231124_at_84402_AM_1.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493838_WhatsApp_Image_20231124_at_84402_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f37f",
    "name":
"externallmg_1700801493841_WhatsApp_Image_20231124_at_84402_AM.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493841_WhatsApp_Image_20231124_at_84402_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65602bd5cabee4333992f380",
    "name":
"externallmg_1700801493846_WhatsApp_Image_20231124_at_84403_AM.jpeg",
    "path": "cases/655d88d05586e008158ff420/
externallmg_1700801493846_WhatsApp_Image_20231124_at_84403_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1700824115432_Calculation_Sheet_NEW.xlsx",
    "path": "cases/655d88d05586e008158ff420/
processingDocuments/1700824115432_Calculation_Sheet_NEW.xlsx",
    "size": "6501066",
    "createdAt": "Fri Nov 24 2023 16:38:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
```

"remarks": [],  
"createdAt": "2023-11-22T04:51:28.201Z",  
"updatedAt": "2023-11-24T11:46:59.103Z",  
"\_\_v": 0,  
"invoiceId": "655d88d05586e008158ff429",  
"fullAddress": "Residential Flat No. 504, 5th Floor, Building No 1, Wing - A, Bachraj Avenue Co-op. Hsg. Soc. Ltd., Padmavati Nagar, Agashi Road, Village - Bolinj, Virar (West), Taluka - Vasai, District - Palghar, PIN - 401 303, State - Maharashtra, India",  
"updatedBy": "64cde526dc9f3034f3fefa49",  
"addressForMap": "",  
"caseReferredBy": "627219d6afd7d55eddedd283",  
"contactPersonName": "Mr. Yogesh V. Karangutkar",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "Seller",  
"siteVisitContactNo": "9819214563",  
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + Bathroom + WC + Cupboard",  
"carpetTotal": "389.86",  
"finalMeasurementType": "Sq. Ft.",  
"otherCarpetTotal": "53.40",  
"builtupPercentage": "20",  
"finalBuiltupArea": "531.91",  
"finalCarpetArea": "443.26",  
"finalSalableArea": "531.91",  
"salablePercentage": "0",  
"toBeAdded": "",  
"otherCompositionBuiltUpTotal": "0.00",  
"otherCompositionCarpetTotal": "53.40",  
"otherCompositionSaleableTotal": "0.00",  
"extendOfSiteRemark": "",  
"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 389.86\nFlowerbed Area in Sq. Ft. = 37.87\nDry Balcony Area in Sq. Ft. = 15.53\n\n",  
"finalAreaType": "Carpet Area",  
"finalAsPerArea": " Agreement",  
"finalBuiltUpPercentage": "20",  
"finalCarpetConvertToBuiltUpPer": "20",  
"finalSaleablePercentage": "0",  
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 393.00",  
"reportGeneratedDate": "Fri Nov 24 2023 14:35:49 GMT+0530 (India Standard Time)",  
"siteVisitDate": "2023-11-23",  
"buildingServicesRate": "2500",  
"flatRate": "8000",

```

"landOtherRate": "5500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<b>Composition :</b>			
Living Room	9'0"	16'5"	147.75
Passage	8'0"	2'11"	23.33
Passage	4'0"	1'0"	4.00
Bathroom	4'0"	5'5"	21.67
Kitchen	8'4"	7'4"	61.11
WC	4'0"	3'0"	12.00
Bedroom	12'0"	9'2"	110.00
Cupboard	5'0"	2'0"	10.00

Other  
Composition :

Flowered Area	9'00"	2'00"	18.00
Flowered Area	8'10"	2'3"	19.87
Dry Balcony Area	7'2"	2'2"	15.53