

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64bb68afa87c525d5c04ab8b",
    "firstName": "Sayali",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK + MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.406011881504043",
  "longitude": "73.26940150981955"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.26940150981955,
    19.406011881504043
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-27",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-27",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-27",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vasind",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasind (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Shahapur",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Morya Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Station Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Swami Vivekananda Nagar, Near Vasind Railway Station",
```



```
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "108/1/4/1, 108/1/2/B & 108/1/11/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "209",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 601",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
```

```
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Town_Planner,_Thane",
    "label": "Town Planner, Thane"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Hemachandra Nehate Housing complex",
    "west": "Internal Road",
    "south": "Yashwantrao Residence Housing society",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 3 & 1 of Layout",
    "west": "Property of adjacent survey",
    "south": "Plot No. 1, 2 & 3 of Layout",
    "east": "9 M wide road of Layout "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
```

```
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. BS / RK / BP /
Vasind / Shahapur / SSThane / 4037 Dated 25.03.2023 issued by Directorate of Town
Planning and Pricing- State Maharashtra, Thane",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "37500",
  "landRate": "2920",
  "igrImage": "cases/656323cecabee43339984f1d/igr_1701066682817_Image.png",
  "squareMeterGuideLineRate": "37500.00",
  "squareFeetGuideLineRate": "3484.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "37500.00",
  "squareMeterGuideLineRate": "37500.00",
  "squareFeetGuideLineRate": "3484.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "9000.00",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per Local norms",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2026",
  "fullDate": "1/1/2026"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Proposed,_Yes",
```

```
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "2",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "9"
},
```



```
"finalPlinthArea": {
  "area": "678.70",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/656323cecabee43339984f1d/
routeMap_1701257797879_Image.png",
    "routeLat": "19.406008",
    "routeLng": "73.269398",
    "stationName": "Vasind",
    "routeDistance": "500M"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "4hmoqn",
      "name": "4hmoqn",
      "image": "cases/656323cecabee43339984f1d/
routeMap_1701257700190_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4380700.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4380700.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Nov 29 2023 17:42:29 GMT+0530 (India Standard Time)",
  "number": "2303730",
  "dayCount": "16",
  "monthCount": "426",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "Complete",
  "percentage": "5",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "5",
  "percentage": "25",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "35.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2364591.00",
"selectedBuildUpValue": "678.70",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "6564263ecabee4333998f8dd",
"name": "externalImg_1701062197523_1701062260168_image_9.jpeg",
"path": "cases/656323cecabee43339984f1d/
externalImg_1701062197523_1701062260168_image_9.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "6564263ecabee4333998f8df",
"name": "externalImg_1701062198443_1701062260168_image_11.jpeg",
"path": "cases/656323cecabee43339984f1d/
externalImg_1701062198443_1701062260168_image_11.jpeg",
"orientation": "portrait"
}
```

```
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8de",
    "name": "externallmg_1701062198002_1701062260168_image_10.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062198002_1701062260168_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8d5",
    "name": "externallmg_1701062196229_1701062260168_image_1.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196229_1701062260168_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8db",
    "name": "externallmg_1701062197230_1701062260168_image_7.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062197230_1701062260168_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8d7",
    "name": "externallmg_1701062196448_1701062260168_image_3.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196448_1701062260168_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8dd",
    "name": "externallmg_1701062197523_1701062260168_image_9.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062197523_1701062260168_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6564263ecabee4333998f8e0",
    "name": "externallmg_1701062198793_1701062260168_image_12.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062198793_1701062260168_image_12.jpeg",
```

```
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6110",
    "max": "8974"
  },
  "builtUpRateRange": {
    "min": "5555",
    "max": "8159"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "617.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "656323cecabee43339984f1d",
"ownerName": "Mr. Nandkumar Nivrutti Karvande & Mrs. Sarita Nandkumar Karvande",
```

```
"ownerPhoneNo": "9011687124",
"fullAddress": "Residential Flat No. 209, 2nd Floor, Morya Heights, Swami
Vivekananda Nagar, Near Vasind Railway Station, Station Road, Village - Vasind,
Taluka - Shahapur, District - Thane, Vasind (East), PIN Code - 421 601, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/11/2023",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Morya Developers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Nandkumar Nivrutti Karvande & Mrs. Sarita Nandkumar
Karvande",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "5363/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "735165",
    "path": "cases/656323cecabee43339984f1d/
document_1700996005029_AGREEMENT_0001_3.pdf",
    "fileName": "document_1700996005029_AGREEMENT_0001_3.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "23/10/2023",
      "nameOfApprovingAuthority": {
```

```
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700053294"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1701253322868_rera_0001.pdf",
"path": "cases/656323cecabee43339984f1d/
document_1701253322868_rera_0001.pdf",
"id": "768934",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Wed Nov 29 2023 15:52:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "25/03/2023",
    "remark": "issued by Directorate of Town Planning and Pricing- State Maharashtra,
Thane (As Download from RERA Site).",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "BS / RK / BP / Vasind / Shahapur / SSThane / 4037"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "299906",
  "path": "cases/656323cecabee43339984f1d/
document_1701254425390_1701066723495_plan.pdf",
  "fileName": "document_1701254425390_1701066723495_plan.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
```

```
"documentDate": "06/07/2023",
"remark": "issued by District Collector Office, Thane (As Download from RERA
Site).",
"number": {
  "value": "No",
  "label": "No"
},
"No": "Revenue / K-1 / T-11 / BP / Vasind / Shahapur / SSR - 10 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "657669",
"path": "cases/656323cecabee43339984f1d/
document_1701256227208_1701066723176_CC.pdf",
"fileName": "document_1701256227208_1701066723176_CC.pdf"
}
],
"caseNumber": "005264",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "439788",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Nov 26 2023 16:24:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Nandkumar Nivrutti Karvande & Mrs. Sarita Nandkumar Karvande",
    "phone": "9011687124",
    "ownershipShare": "",
    "email": "",
    "id": "440199"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "203616",
    "name": "Living Room",
```

```
"length": "0.00",
"length1": "0",
"length2": "00",
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "",
  "length1": "0",
  "length2": "0",
  "width": "",
  "width1": "0",
  "width2": "0",
  "totalArea": "0.00",
  "images": [],
  "finalArea": "0.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
```

```
"length2": "00",
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "57.32",
  "totalAreaDocument": "617",
  "docBUILTUPPercentage": "10",
  "docFinalBUILTUP": "678.70",
  "docFinalBUILTUPSquareMeter": "63.05",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "877537"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "656437c8cabee433399950a1",
  "property": "Flat",
  "area": "650",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "2",
}
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "4500000",
"expectedRate": "6923.08",
"builtUpExpectedRate": "6293.71",
"image": "cases/656323cecabee43339984f1d/
indicator_1701065908195_Image.png",
"squareMeter": "60.39",
"id": "179796"
},
{
"printlnReport": true,
"_id": "656437c8cabee433399950a2",
"property": "Flat",
"area": "487",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "1",
"source": "Index_no.2",
"expectedPrice": "2975620",
"expectedRate": "6110.10",
"builtUpExpectedRate": "5554.64",
"image": "cases/656323cecabee43339984f1d/
indicator_1701065964287_Image.png",
"squareMeter": "45.24",
"id": "162938"
},
{
"printlnReport": true,
"_id": "6566e9085996860c2302a7f3",
"property": "Flat",
"area": "780",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Makaan.com",
"expectedPrice": "7000000",
"expectedRate": "8974.36",
"builtUpExpectedRate": "8158.51",
"image": "cases/656323cecabee43339984f1d/
indicator_1701243089741_Image.png",
"squareMeter": "72.46",
"id": "881742"
}
```



```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6564263ecabee4333998f8d4",
    "name": "externallmg_1701062194346_1701062260168_image_0.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062194346_1701062260168_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6564263ecabee4333998f8d5",
    "name": "externallmg_1701062196229_1701062260168_image_1.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196229_1701062260168_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6564263ecabee4333998f8d6",
    "name": "externallmg_1701062196323_1701062260168_image_2.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196323_1701062260168_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6564263ecabee4333998f8d7",
    "name": "externallmg_1701062196448_1701062260168_image_3.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196448_1701062260168_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6564263ecabee4333998f8d8",
    "name": "externallmg_1701062196613_1701062260168_image_4.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196613_1701062260168_image_4.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8d9",
  "name": "externallmg_1701062196929_1701062260168_image_5.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196929_1701062260168_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8da",
  "name": "externallmg_1701062196963_1701062260168_image_6.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062196963_1701062260168_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8db",
  "name": "externallmg_1701062197230_1701062260168_image_7.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062197230_1701062260168_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8dc",
  "name": "externallmg_1701062197472_1701062260168_image_8.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062197472_1701062260168_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8dd",
  "name": "externallmg_1701062197523_1701062260168_image_9.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062197523_1701062260168_image_9.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8de",
  "name": "externallmg_1701062198002_1701062260168_image_10.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062198002_1701062260168_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8df",
  "name": "externallmg_1701062198443_1701062260168_image_11.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062198443_1701062260168_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6564263ecabee4333998f8e0",
  "name": "externallmg_1701062198793_1701062260168_image_12.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062198793_1701062260168_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6564263ecabee4333998f8e1",
  "name": "externallmg_1701062170293_1701062237002_image_0.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062170293_1701062237002_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6564263ecabee4333998f8e2",
  "name": "externallmg_1701062170433_1701062237002_image_1.jpeg",
  "path": "cases/656323cecabee43339984f1d/
externallmg_1701062170433_1701062237002_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6564263ecabee4333998f8e3",
    "name": "externalImg_1701062170494_1701062237002_image_2.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externalImg_1701062170494_1701062237002_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6564263ecabee4333998f8e4",
    "name": "externalImg_1701062170549_1701062237002_image_3.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externalImg_1701062170549_1701062237002_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6564263ecabee4333998f8e5",
    "name": "externalImg_1701062170569_1701062237002_image_4.jpeg",
    "path": "cases/656323cecabee43339984f1d/
externalImg_1701062170569_1701062237002_image_4.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "CC.pdf",
    "filename": "1701066723176_CC.pdf",
    "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723176_CC.pdf",
    "size": "732210",
    "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1701066723261_igr1.pdf",
    "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723261_igr1.pdf",
    "size": "540640",
    "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
]
```

```
    },
    {
      "originalname": "igr2.pdf",
      "filename": "1701066723338_igr2.pdf",
      "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723338_igr2.pdf",
      "size": "517896",
      "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "MORYA HEIGHTS.pdf",
      "filename": "1701066723382_MORYA_HEIGHTS.pdf",
      "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723382_MORYA_HEIGHTS.pdf",
      "size": "1258176",
      "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "plan.pdf",
      "filename": "1701066723495_plan.pdf",
      "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723495_plan.pdf",
      "size": "1164990",
      "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Summary - nandkumar.xlsx",
      "filename": "1701066723592_Summary__nandkumar.xlsx",
      "path": "cases/656323cecabee43339984f1d/
processingDocuments/1701066723592_Summary__nandkumar.xlsx",
      "size": "3045037",
      "createdAt": "Mon Nov 27 2023 12:02:03 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2023-11-26T10:54:06.071Z",
  "updatedAt": "2023-11-29T12:24:04.771Z",
  "__v": 0,
  "invoiceId": "656323cecabee43339984f26",
  "updatedBy": "5fc78e26625ecd20ec1f88e9",
```

```

"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Haidar Shaikh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Supervisor",
"siteVisitContactNo": "9619700598",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 617.00",
"flatRate": "7100",
"landOtherRate": "4600",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"siteVisitDate": "2023-11-27",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "0.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"toBeAdded": "",
"finalSaleablePercentage": "0"

```

Name	Length	Width	Total
Composition :			
Living Room	0'00"	0'00"	0.00

Bedroom	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'0"	0'0"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Other Composition :			