

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.411556",
  "longitude": " 72.825556"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.825556,
    19.411556
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "27/11/2023 11:00 am"
    },
    {
      "dateTime": "27/11/2023 12:00 am"
    },
    {
      "dateTime": "27/11/2023 12:00 am"
    },
    {
      "dateTime": "27/11/2023 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-28",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-28",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-28",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Achole",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Palghar",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nallasopara (East), Palghar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chandresh Vaibhav Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```



```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Achole Cross Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Neminath Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C & D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "116",
```

```
"label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "3",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1213",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 209",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
},
```

```
"flooring": {
  "value": "Proposed_Vitrified_tiles_flooring",
  "label": "Proposed Vitrified tiles flooring"
},
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fixtures": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fixtures._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fixtures. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Alkapuri Station Road",
```

```
"west": "Shiv Krupa Society",
"south": "Ideal Park Society",
"east": "Neminath Nagar Society"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per approved plan, the composition of flat is 1 Bedroom
+ Living Room + Kitchen + 2 Toilets + Passage.",
"dateOfIssusApprovePlan": "Copy of Approved Plan No. VVCMC / TP / CC /
VP-6391 / 360 / 2021-2022 dated 11.11.2021 issued by Vasai Virar City Municipal
Corporation. (As downloaded from RERA site).",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "47100",
  "landRate": "13100",
```

```
"igrImage": "cases/65643595cabee43339994458/igr_1701509194757_Image.png",
"squareMeterGuideLineRate": "51810.00",
"squareFeetGuideLineRate": "4813.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "47100.00",
  "squareMeterGuideLineRate": "51810.00",
  "squareFeetGuideLineRate": "4813.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "8,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Open / Covered Car Parking ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
```

```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"buildingSpecification": {
"value": "Proposed_Standard",
"label": "Proposed Standard"
},
"structuralSafety": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceIssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
}
```



```
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "12",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "11"
},
"finalPlinthArea": {
  "area": "413.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65643595cabee43339994458/
routeMap_1701237041889_Image.png",
    "routeLat": "19.411556",
    "routeLng": "72.825583",
    "stationName": "Nallasopara",
    "routeDistance": "1.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```

```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "87eudd",
    "name": "87eudd",
    "image": "cases/65643595cabee43339994458/
routeMap_1701236995067_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3835200.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "3835200.00"
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "16",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "16",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "16",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "16",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "16",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "10",
  "percentage": "1.56",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "10",
  "percentage": "1.56",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "10",
  "percentage": "6.25",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "80.37",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1990657.00",
  "selectedBuildUpValue": "413.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,

```

```
    "_id": "6566af485996860c2301ee57",
    "name":
"externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6566af485996860c2301ee5a",
    "name":
"externallmg_1701228360023_WhatsApp_Image_20231128_at_44142_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360023_WhatsApp_Image_20231128_at_44142_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6566af485996860c2301ee5b",
    "name":
"externallmg_1701228360026_WhatsApp_Image_20231128_at_44143_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360026_WhatsApp_Image_20231128_at_44143_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6566af485996860c2301ee57",
    "name":
"externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6566af485996860c2301ee54",
    "name":
"externallmg_1701228359999_WhatsApp_Image_20231128_at_44139_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359999_WhatsApp_Image_20231128_at_44139_PM.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "6566af485996860c2301ee53",
      "name":
"externallmg_1701228359995_WhatsApp_Image_20231128_at_44139_PM_1.jpeg",
      "path": "cases/65643595cabee43339994458/
externallmg_1701228359995_WhatsApp_Image_20231128_at_44139_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6566af485996860c2301ee52",
      "name":
"externallmg_1701228359991_WhatsApp_Image_20231128_at_44138_PM.jpeg",
      "path": "cases/65643595cabee43339994458/
externallmg_1701228359991_WhatsApp_Image_20231128_at_44138_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10318",
    "max": "10896"
  },
  "builtUpRateRange": {
    "min": "8872",
    "max": "9906"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```



```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "376.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "65643595cabee43339994458",
"ownerName": "Mr. Indal Shravan Jadhav & Mrs. Sangita Indal Jadhav",
"ownerPhoneNo": "9960785475",
"appAddress": "Flat no. 1213, 12th Floor, C & D Wing, Chandresh Vaibhav CHS,
Achole Road, Nallasopara East",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/11/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Shree Ashoka Buildcon",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Indal Shravan Jadhav & Mrs. Sangita Indal Jadhav",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "18446/2023"
    },
    "isHardCopy": false,
```

```
"displayStatus": true,
"id": "660672",
"path": "cases/65643595cabee43339994458/
document_1701508889302_jadhavindal.pdf",
"fileName": "document_1701508889302_jadhavindal.pdf"
},
{
"documentType": {
"value": "60ae129faa6d152c1801b47d",
"label": "RERA Certificate"
},
"inputs": {
"documentDate": "08/03/2022",
"nameOfApprovingAuthority": {
"value": "Maharashtra_Real_Estate_Regulatory_Authority",
"label": "Maharashtra Real Estate Regulatory Authority"
},
"number": {
"value": "Registration_No",
"label": "Registration No"
},
"Registration_No": "P99000033830"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1701511263435_P99000033830.pdf",
"path": "cases/65643595cabee43339994458/
document_1701511263435_P99000033830.pdf",
"id": "944966",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Sat Dec 02 2023 15:31:03 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae1259aa6d152c1801b33d",
"label": "Revised Development Permission Certificate"
},
"inputs": {
"documentDate": "09/08/2022",
"nameOfApprovingAuthority": {
"value": "Vasai_Virar_City_Municipal_Corporation",
"label": "Vasai Virar City Municipal Corporation"
},
"number": {
"value": "Document_No",
"label": "Document No"
}
```

```
    },
    "Document_No": "VVCMC / TP / RDP / VP-6391 / 296 / 2022-2023 "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1701511351618_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "path": "cases/65643595cabee43339994458/document_1701511351618_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
  "id": "433794",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Dec 02 2023 15:32:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "11/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "VVCMC / TP / CC / VP-6391 / 360 / 2021-2022"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1701511459242_2_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "path": "cases/65643595cabee43339994458/document_1701511459242_2_Building_Plan_Approval___NA_Order_for_plotted_development.pdf",
  "id": "132721",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Dec 02 2023 15:34:19 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005270",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "818796",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Nov 27 2023 11:52:13 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Indal Shravan Jadhav & Mrs. Sangita Indal Jadhav",
"phone": "9960785475",
"ownershipShare": "",
"email": "",
"id": "312443"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "327949",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "376",
"squareMeterArea": "34.93",
"docFinalBuiltUp": "413.6",
"docFinalBuiltUpSquareMeter": "38.423",
"docBuiltpPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"printlnReport": true,
"_id": "656af850cebbe17144122488",
```

```
"property": "Residential Flat",
"area": "209",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Housing.Com",
"expectedPrice": "2225000",
"expectedRate": "10645.93",
"builtUpExpectedRate": "8871.61",
"image": "cases/65643595cabee43339994458/
indicator_1701509020020_Image.png",
"squareMeter": "19.42",
"id": "844703"
},
{
  "printlnReport": true,
  "_id": "656af850cebbe17144122489",
  "property": "Residential Flat",
  "area": "371",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "3480000",
  "expectedRate": "9380.05",
  "builtUpExpectedRate": "7816.71",
  "image": "cases/65643595cabee43339994458/
indicator_1701509074294_Image.png",
  "squareMeter": "34.47",
  "id": "285520"
},
{
  "printlnReport": true,
  "_id": "656af850cebbe1714412248a",
  "property": "Residential Flat",
  "area": "371",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "source": "Index_no.2",
  "expectedPrice": "3675000",
  "expectedRate": "9905.66",
  "builtUpExpectedRate": "0.00",
```

```
"image": "cases/65643595cabee43339994458/
indicator_1701509132735_Image.png",
"squareMeter": "34.47",
"id": "972499"
},
{
  "printlnReport": false,
  "_id": "656b170ecebbe17144128592",
  "property": "Residential Flat",
  "area": "825",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Housing.Com",
  "expectedPrice": "5210000",
  "expectedRate": "6315.15",
  "builtUpExpectedRate": "0.00",
  "image": "cases/65643595cabee43339994458/
indicator_1701517070034_Image.png",
  "squareMeter": "76.65",
  "id": "320267"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee4e",
    "name":
"externallmg_1701228359968_WhatsApp_Image_20231128_at_44136_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359968_WhatsApp_Image_20231128_at_44136_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee4f",
    "name":
"externallmg_1701228359974_WhatsApp_Image_20231128_at_44137_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359974_WhatsApp_Image_20231128_at_44137_PM_1.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee50",
    "name":
"externallmg_1701228359981_WhatsApp_Image_20231128_at_44137_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359981_WhatsApp_Image_20231128_at_44137_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee51",
    "name":
"externallmg_1701228359987_WhatsApp_Image_20231128_at_44138_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359987_WhatsApp_Image_20231128_at_44138_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee52",
    "name":
"externallmg_1701228359991_WhatsApp_Image_20231128_at_44138_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359991_WhatsApp_Image_20231128_at_44138_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee53",
    "name":
"externallmg_1701228359995_WhatsApp_Image_20231128_at_44139_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359995_WhatsApp_Image_20231128_at_44139_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee54",
    "name":
"externallmg_1701228359999_WhatsApp_Image_20231128_at_44139_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228359999_WhatsApp_Image_20231128_at_44139_PM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee55",
    "name":
"externallmg_1701228360004_WhatsApp_Image_20231128_at_44140_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360004_WhatsApp_Image_20231128_at_44140_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee56",
    "name":
"externallmg_1701228360008_WhatsApp_Image_20231128_at_44141_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360008_WhatsApp_Image_20231128_at_44141_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee57",
    "name":
"externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360012_WhatsApp_Image_20231128_at_44141_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee58",
    "name":
"externallmg_1701228360016_WhatsApp_Image_20231128_at_44142_PM_1.jpeg",
    "path": "cases/65643595cabee43339994458/
externallmg_1701228360016_WhatsApp_Image_20231128_at_44142_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566af485996860c2301ee59",
```

```
    "name":
"externallmg_1701228360020_WhatsApp_Image_20231128_at_44142_PM_2.jpeg",
  "path": "cases/65643595cabee43339994458/
externallmg_1701228360020_WhatsApp_Image_20231128_at_44142_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566af485996860c2301ee5a",
  "name":
"externallmg_1701228360023_WhatsApp_Image_20231128_at_44142_PM.jpeg",
  "path": "cases/65643595cabee43339994458/
externallmg_1701228360023_WhatsApp_Image_20231128_at_44142_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566af485996860c2301ee5b",
  "name":
"externallmg_1701228360026_WhatsApp_Image_20231128_at_44143_PM_1.jpeg",
  "path": "cases/65643595cabee43339994458/
externallmg_1701228360026_WhatsApp_Image_20231128_at_44143_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566af485996860c2301ee5c",
  "name":
"externallmg_1701228360028_WhatsApp_Image_20231128_at_44143_PM.jpeg",
  "path": "cases/65643595cabee43339994458/
externallmg_1701228360028_WhatsApp_Image_20231128_at_44143_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566af485996860c2301ee5d",
  "name":
"externallmg_1701228360031_WhatsApp_Image_20231128_at_44203_PM.jpeg",
  "path": "cases/65643595cabee43339994458/
externallmg_1701228360031_WhatsApp_Image_20231128_at_44203_PM.jpeg",
  "orientation": "portrait"
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1701509213216_Calculation_Sheet_NEW.xlsx",
    "path": "cases/65643595cabee43339994458/
processingDocuments/1701509213216_Calculation_Sheet_NEW.xlsx",
    "size": "928884",
    "createdAt": "Sat Dec 02 2023 14:56:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Index II.pdf",
    "filename": "1701511897701_Index_II.pdf",
    "path": "cases/65643595cabee43339994458/
processingDocuments/1701511897701_Index_II.pdf",
    "size": "33932",
    "createdAt": "Sat Dec 02 2023 15:41:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "Reference report same wing.doc",
    "filename": "1701511897703_Reference_report_same_wing.doc",
    "path": "cases/65643595cabee43339994458/
processingDocuments/1701511897703_Reference_report_same_wing.doc",
    "size": "5271040",
    "createdAt": "Sat Dec 02 2023 15:41:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "REference report.doc",
    "filename": "1701511897822_REference_report.doc",
    "path": "cases/65643595cabee43339994458/
processingDocuments/1701511897822_REference_report.doc",
    "size": "4945920",
    "createdAt": "Sat Dec 02 2023 15:41:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "Reference report.pdf",
    "filename": "1701511897898_Reference_report.pdf",
    "path": "cases/65643595cabee43339994458/
processingDocuments/1701511897898_Reference_report.pdf",
    "size": "1195088",
    "createdAt": "Sat Dec 02 2023 15:41:37 GMT+0530 (India Standard Time)",
```

```
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6569cdc3bd53ea1a14364a6c",
    "note": "Pending for Full set of agreement",
    "taskId": "656439c8cabee43339995b7a",
    "createdAt": "2023-12-01T12:12:51.416Z"
  }
],
"createdAt": "2023-11-27T06:22:14.003Z",
"updatedAt": "2023-12-02T11:51:16.836Z",
"__v": 0,
"invoiceId": "65643596cabee43339994461",
"fullAddress": "Residential Flat No. 1213, 12th Floor, Wing - 'C & D', Chandresh
Vaibhav Co-op. Hsg. Soc. Ltd., Neminath Nagar, Achole Cross Road, Village - Achole,
Taluka - Vasai, District - Palghar, Nallasopara (East), Palghar, PIN - 401 209, State -
Maharashtra, India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Pravin Mundhara",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Engineer",
"siteVisitContactNo": "9730884856",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
}
```

```
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 376.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Sat Dec 02 2023 10:29:25 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-11-28",
"buildingServicesRate": "2500",
"flatRate": "10200",
"landOtherRate": "7700",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
},
```

```
"roadFacing": false,  
"mall": false  
}  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			