

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8f2"
    },
    "type": "CREDITOFFICER",
    "_id": "6538a4a22a1baf5f34c1fd16",
    "firstName": "Anand Kumar",
    "lastName": "Trehan",
    "mobileNo": "",
    "workMobileNo": "7830030038",
    "email": "sme.mmcr@bankofbaroda.com"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "12500000",
    "discussWithPerson": "Anand Kumar",
    "expectedFees": 6250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8f2",
  "branchCode": "000009",
  "type": "BRANCH",
  "name": "MMCR FORT",
  "email": "sme.mmcr@bankofbaroda.com",
  "mobileNo": "22-22619603 ",
  "alternateMobileNo": "",
  "address": "3, Walchand Hirachand Marg,Ground Floor, Ballard Pier, Mumbai - 400
001, State - Maharashtra, Country - India.\n",
  "ledgerName": "",
  "fax": "22-22611259",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
```

```
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.203534853544436",
  "longitude": "73.09101248988878"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09101248988878,
    19.203534853544436
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-28",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Vile Parle (East), Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ravikiran Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tejpal Scheme Road No. 1",
```

```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
```



```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "526A",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "405",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 057",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  }
},
```

```
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
  "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows_with_M. S. Grills",
  "label": "Powder coated Aluminum sliding windows with M. S. Grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Under Construction Building",
    "west": "Open Plot",
    "south": "Sukhjoyt Apartment",
    "east": "Tejpal Scheme Road No. 1"
  },
  "asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "34640",
  "depreciatedBuildingRate": "2640"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "215850",
  "landRate": "108770",
  "igrImage": "cases/6564ca41cabee433399aadd6/igr_1701258273885_Image.png",
  "squareMeterGuideLineRate": "172680.00",
  "squareFeetGuideLineRate": "16043.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "92",
```

```
"rate": "15568.00",
"squareFeetGuideLineRate": "15568.00",
"squareMeterGuideLineRate": "167567.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "66,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Electricity Bill CA No. 152682737",
  "meterCardHolderName": "Subhash Premnath Prabhudesai",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "Mr. Sumit Jawalekar",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2015",
"fullDate": "1/1/2015"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
}
```

```
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
```

```
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "2",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1096.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6564ca41cabee433399aadd6/
routeMap_1701322416269_Image.png",
    "routeLat": "19.106833",
    "routeLng": "72.848806",
    "stationName": "Vile Parle",
    "routeDistance": "1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "gal2vk",
```



```
    "name": "gal2vk",
    "image": "cases/6564ca41cabee433399aadd6/
routeMap_1701322304267_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "31660960.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "31660960.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "17074982.00",
  "selectedBuildUpValue": "1096.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6566c0c45996860c2302042d",
      "name": "externalimg_r_1701232836361_IMG20231128155504.jpg",
      "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836361_IMG20231128155504.jpg",
      "orientation": "portrait"
    }
  ]
},
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6566c0e05996860c230204ba",
    "name": "externallmg_r_1701232864230_IMG20231128154844.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864230_IMG20231128154844.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6566c0e05996860c230204b2",
    "name": "externallmg_r_1701232864204_IMG20231128153440.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864204_IMG20231128153440.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0c45996860c2302042d",
    "name": "externallmg_r_1701232836361_IMG20231128155504.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836361_IMG20231128155504.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0e05996860c230204b9",
    "name": "externallmg_r_1701232864227_IMG20231128154836.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864227_IMG20231128154836.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0e95996860c23020552",
    "name": "externallmg_r_1701232873738_IMG20231128155521.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232873738_IMG20231128155521.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
```

```
{
  "status": false,
  "_id": "6566c0e05996860c230204bd",
  "name": "externallmg_r_1701232864240_IMG20231128155214.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864240_IMG20231128155214.jpg",
  "orientation": "portrait"
}
],
"compositionImages": [
  {
    "status": false,
    "_id": "6566c0c45996860c2302041c",
    "name": "Living Room",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836313_IMG20231128154048.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0c45996860c2302041d",
    "name": "Living Room",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836317_IMG20231128154059.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0c45996860c23020420",
    "name": "Living Room",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836323_IMG20231128154118.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0c45996860c23020422",
    "name": "Living Room",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836328_IMG20231128154149.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6566c0e05996860c230204b5",
    "name": "Living Room",
```

```
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864215_IMG20231128154203.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6566c0e05996860c230204b6",
    "name": "Living Room",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864212_IMG20231128154128.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "36765",
    "max": "39275"
  },
  "builtUpRateRange": {
    "min": "30638",
    "max": "32730"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "914.00",
"empanelmentNo": [
  "ZO:MZ:ADV:44:620"
```

```
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6564ca41cabee433399aadd6",
"ownerName": "Shri. Subhash Premnath Prabhudesai",
"ownerPhoneNo": "8322481332",
"appAddress": "404 4th floor\nRavikiran co operative society \nTejpal Road\nvileprale
Mumbai 57",
"remark": "Bob panji gova Branch\nAnil Kumar Shrivastava\n8322481332\n\nAll
Documents in Mumbai id ",
"documents": [
  {
    "documentType": {
      "value": "60ae1265aa6d152c1801b374",
      "label": "Agreement For Permanent Alternate Accomodation"
    },
    "inputs": {
      "documentDate": "03/03/2013",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Nivara Developers",
      "to": {
        "value": "Member",
        "label": "Member"
      },
      "Member": "Shri. Subhash Premnath Prabhudesai"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "428263",
    "path": "cases/6564ca41cabee433399aadd6/
document_1701104121429_120448.pdf",
    "fileName": "document_1701104121429_120448.pdf"
  },
  {
    "documentType": {
      "value": "6077c791395bc80714864a30",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "16/11/2023",
      "number": {
```

```
    "value": "CA_No",
    "label": "CA No"
  },
  "CA_No": "152682737"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1701322108960_62284.pdf",
"path": "cases/6564ca41cabee433399aadd6/
document_1701322108960_62284.pdf",
"id": "766504",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Thu Nov 30 2023 10:58:29 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005284",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "642867",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Nov 27 2023 22:26:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Subhash Premnath Prabhudesai",
    "phone": "8322481332",
    "ownershipShare": "",
    "email": "",
    "id": "384055"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "339860",
    "name": "Living Room",
    "length": "10.58",
    "length1": "10",
```

```
"length2": "7",
"width": "21.50",
"width1": "21",
"width2": "6",
"totalArea": "227.54",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "656818265996860c2303f70f",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "3.67",
    "length1": "3",
    "length2": "8",
    "width": "10.08",
    "width1": "10",
    "width2": "1",
    "totalArea": "36.97"
  }
],
"finalArea": "264.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "11.50",
  "length1": "11",
  "length2": "6",
  "width": "11.83",
  "width1": "11",
  "width2": "10",
  "totalArea": "136.08",
  "images": [],
  "finalArea": "136.08",
  "extraAreas": []
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "32.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "13.67",
  "width1": "13",
  "width2": "8",
  "totalArea": "135.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "135.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "15.08",
  "length1": "15",
  "length2": "1",
  "width": "8.08",
  "width1": "8",
```

```
"width2": "1",
"totalArea": "121.92",
"images": [],
"extraAreas": [],
"finalArea": "121.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "7.58",
  "width1": "7",
  "width2": "7",
  "totalArea": "34.76",
  "images": [],
  "finalArea": "34.76",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "140.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "140.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "8",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "34.61",
  "images": [],
  "finalArea": "34.61",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "6.00",
  "length1": "6",
  "length2": "0",
  "width": "2.00",
  "width1": "2",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1265aa6d152c1801b374",
      "label": "Agreement For Permanent Alternate Accomodation"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "id": "200916",
```

```
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "914",
"squareMeterArea": "84.91",
"docFinalBuiltUp": "1096.8",
"docFinalBuiltUpSquareMeter": "101.892",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "656724e75996860c230376e2",
  "property": "Tejpal Scheme Road, Vileparle East",
  "area": "662",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "26000000",
  "expectedRate": "39274.92",
  "builtUpExpectedRate": "32729.10",
  "image": "cases/6564ca41cabee433399aadd6/
indicator_1701258069026_Image.png",
  "squareMeter": "61.50",
  "id": "870996"
},
{
  "printlnReport": true,
  "_id": "656724e75996860c230376e3",
  "property": "Tejpal Scheme Road, Vileparle East",
  "area": "680",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "25000000",
  "expectedRate": "36764.71",
  "builtUpExpectedRate": "30637.25",
```



```
"image": "cases/6564ca41cabee433399aadd6/
indicator_1701258111881_Image.png",
"squareMeter": "63.17",
"id": "236797"
},
{
  "printlnReport": true,
  "_id": "656724e75996860c230376e4",
  "property": "Tejpal Scheme Road, Vileparle East",
  "area": "700",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "26800000",
  "expectedRate": "38285.71",
  "builtUpExpectedRate": "31904.76",
  "image": "cases/6564ca41cabee433399aadd6/
indicator_1701258154452_Image.png",
  "squareMeter": "65.03",
  "id": "232800"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302041b",
    "name": "externalImg_1701232836369_Screenshot_2023112815295263_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/6564ca41cabee433399aadd6/externalImg_1701232836369_Screens
hot_2023112815295263_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302041c",
    "name": "externalImg_r_1701232836313_IMG20231128154048.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externalImg_r_1701232836313_IMG20231128154048.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302041d",
    "name": "externallmg_r_1701232836317_IMG20231128154059.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836317_IMG20231128154059.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302041e",
    "name": "externallmg_r_1701232836304_IMG20231128153352.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836304_IMG20231128153352.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302041f",
    "name": "externallmg_r_1701232836308_IMG20231128154034.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836308_IMG20231128154034.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c23020420",
    "name": "externallmg_r_1701232836323_IMG20231128154118.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836323_IMG20231128154118.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c23020421",
    "name": "externallmg_r_1701232836326_IMG20231128154142.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836326_IMG20231128154142.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6566c0c45996860c23020422",
  "name": "externalimg_r_1701232836328_IMG20231128154149.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836328_IMG20231128154149.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0c45996860c23020423",
  "name": "externalimg_r_1701232836330_IMG20231128154209.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836330_IMG20231128154209.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0c45996860c23020424",
  "name": "externalimg_r_1701232836335_IMG20231128154734.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836335_IMG20231128154734.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0c45996860c23020425",
  "name": "externalimg_r_1701232836333_IMG20231128154728.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836333_IMG20231128154728.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0c45996860c23020426",
  "name": "externalimg_r_1701232836338_IMG20231128154826.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externalimg_r_1701232836338_IMG20231128154826.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6566c0c45996860c23020427",
    "name": "externallmg_r_1701232836341_IMG20231128155114.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836341_IMG20231128155114.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c23020428",
    "name": "externallmg_r_1701232836344_IMG20231128155220.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836344_IMG20231128155220.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c23020429",
    "name": "externallmg_r_1701232836348_IMG20231128155414.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836348_IMG20231128155414.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302042a",
    "name": "externallmg_r_1701232836346_IMG20231128155249.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836346_IMG20231128155249.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302042b",
    "name": "externallmg_r_1701232836351_IMG20231128155418.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836351_IMG20231128155418.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302042c",
```

```
    "name": "externallmg_r_1701232836356_IMG20231128155423.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836356_IMG20231128155423.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302042d",
    "name": "externallmg_r_1701232836361_IMG20231128155504.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836361_IMG20231128155504.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0c45996860c2302042e",
    "name": "externallmg_r_1701232836365_IMG20231128155534.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232836365_IMG20231128155534.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b0",
    "name": "externallmg_r_1701232864201_IMG20231128153438.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864201_IMG20231128153438.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b1",
    "name": "externallmg_r_1701232864196_IMG20231128153349.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864196_IMG20231128153349.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b2",
    "name": "externallmg_r_1701232864204_IMG20231128153440.jpg",
```

```
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864204_IMG20231128153440.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b3",
    "name": "externallmg_r_1701232864199_IMG20231128153354.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864199_IMG20231128153354.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b4",
    "name": "externallmg_r_1701232864208_IMG20231128154119.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864208_IMG20231128154119.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b5",
    "name": "externallmg_r_1701232864215_IMG20231128154203.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864215_IMG20231128154203.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b6",
    "name": "externallmg_r_1701232864212_IMG20231128154128.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864212_IMG20231128154128.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6566c0e05996860c230204b7",
    "name": "externallmg_r_1701232864219_IMG20231128154729.jpg",
    "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864219_IMG20231128154729.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204b8",
  "name": "externallmg_r_1701232864223_IMG20231128154833.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864223_IMG20231128154833.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204b9",
  "name": "externallmg_r_1701232864227_IMG20231128154836.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864227_IMG20231128154836.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204ba",
  "name": "externallmg_r_1701232864230_IMG20231128154844.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864230_IMG20231128154844.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204bb",
  "name": "externallmg_r_1701232864233_IMG20231128155152.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864233_IMG20231128155152.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204bc",
  "name": "externallmg_r_1701232864235_IMG20231128155159.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864235_IMG20231128155159.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204bd",
  "name": "externallmg_r_1701232864240_IMG20231128155214.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864240_IMG20231128155214.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204be",
  "name": "externallmg_r_1701232864237_IMG20231128155206.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864237_IMG20231128155206.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204bf",
  "name": "externallmg_r_1701232864242_IMG20231128155219.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864242_IMG20231128155219.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204c0",
  "name": "externallmg_r_1701232864244_IMG20231128155300.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864244_IMG20231128155300.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204c1",
  "name": "externallmg_r_1701232864247_IMG20231128155352.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864247_IMG20231128155352.jpg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204c2",
  "name": "externallmg_r_1701232864249_IMG20231128155415.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864249_IMG20231128155415.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e05996860c230204c3",
  "name": "externallmg_r_1701232864252_IMG20231128155508.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232864252_IMG20231128155508.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e95996860c23020550",
  "name": "externallmg_r_1701232873732_IMG20231128155508.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232873732_IMG20231128155508.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e95996860c23020551",
  "name": "externallmg_r_1701232873735_IMG20231128155519.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232873735_IMG20231128155519.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6566c0e95996860c23020552",
  "name": "externallmg_r_1701232873738_IMG20231128155521.jpg",
  "path": "cases/6564ca41cabee433399aadd6/
externallmg_r_1701232873738_IMG20231128155521.jpg",
  "orientation": "portrait"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "filename": "1701258483867_1695465043548_1694516251783_1694241590859_C
alculation_1_2.xlsx",
    "path": "cases/6564ca41cabee433399aadd6/processingDocuments/1701258483867
_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "4237299",
    "createdAt": "Wed Nov 29 2023 17:18:10 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "scan 1.pdf",
    "filename": "1701325034322_scan_1.pdf",
    "path": "cases/6564ca41cabee433399aadd6/
processingDocuments/1701325034322_scan_1.pdf",
    "size": "1425443",
    "createdAt": "Thu Nov 30 2023 11:47:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "scan 2.pdf",
    "filename": "1701325034487_scan_2.pdf",
    "path": "cases/6564ca41cabee433399aadd6/
processingDocuments/1701325034487_scan_2.pdf",
    "size": "1488393",
    "createdAt": "Thu Nov 30 2023 11:47:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  },
  {
    "originalname": "scan_3.pdf",
    "filename": "1701325034517_scan__3.pdf",
    "path": "cases/6564ca41cabee433399aadd6/
processingDocuments/1701325034517_scan__3.pdf",
    "size": "1150693",
    "createdAt": "Thu Nov 30 2023 11:47:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-11-27T16:56:33.592Z",
"updatedAt": "2023-11-30T10:25:00.704Z",
```

```
"__v": 0,
"invoiceId": "6564ca41cabee433399aaddc",
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 405, 4th Floor, Wing - B, Ravikiran Co-op. Hsg. Soc. Ltd., Tejpal Scheme Road No. 1, Village - Vile Parle, Taluka - Andheri, District - Mumbai Suburban, Vile Parle (East), Mumbai, PIN - 400 057, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Sumit Jawalekar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "8322481332",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Permanent Alternate Accomodation",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 914.00",
"flatRate": "35000",
"landOtherRate": "32000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "4 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "912.27",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1003.50",
"finalCarpetArea": "912.27",
"finalSalableArea": "1103.85",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": ""
```

```

"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Nov 30 2023 10:15:53 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-11-28"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	10'7"	21'6"	227.54
Bedroom	11'6"	11'10"	136.08
Toilet	4'5"	7'5"	32.76
Bedroom	9'11"	13'8"	135.53
Kitchen	15'1"	8'1"	121.92
Bedroom	4'7"	7'7"	34.76
Bedroom	12'10"	10'11"	140.10
Toilet	4'8"	7'5"	34.61
Passage	6'0"	2'0"	12.00

Other  
Composition :

---