

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645c9e717f94762ec7885ede"
    },
    "type": "CREDITOFFICER",
    "_id": "645c9e727f94762ec7885ee0",
    "firstName": "Sayali ",
    "lastName": "Purohit",
    "mobileNo": "",
    "workMobileNo": "9822908161",
    "email": "sayali@jantabank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "645c92ba7f94762ec7884195",
  "type": "BANK",
  "name": " Janta Sahkari Bank LTD",
  "displayName": " Janta Sahkari Bank LTD\t",
  "initial": "jsb"
},
"branch": {
  "_id": "645c9e717f94762ec7885ede",
  "name": "Mulund West",
  "branchCode": "",
  "mobileNo": "02225694988",
  "alternateMobileNo": "",
  "email": "mulund@jantabankpune.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Balaji Arcade, Plot No.544/A, CTS No.286, NS Rd, Mulund West,
Mumbai, Maharashtra 400080\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "645c93d47f94762ec788472a",
  "zoneName": "Mumbai Metro"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627222afafd7d55eddeddd82",
    "role": "FRONTDESK",
```

```
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
```

```
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
],
```

```
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.232188427240462",
  "longitude": " 73.1393598503026"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
```

```
"schedule": [],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-01",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-01",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-01",
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Katemanivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "12",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "5",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Erica",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Royal Garden, Shaktidham Complex, Near Durga Mata Mandir, Kolsewadi",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "63(P), 68(P), 73/1, 128(P)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```

    "name": "Gut No.",
    "key": "GUTNo",
    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN Code - 421 306",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/ _Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}

```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Suresh Apartment",
    "south": "Internal Road",
    "east": "Ambe Matta Mandir"
  },
  "asPerDocumentAgreement": {
    "north": "Central Railway Property",
    "west": "Survey No. 128 (P) and Survey No. 63 (P) Owned by Mr. K. R. Shukla",
    "south": "Survey No. 64 & 67/A Owned by Mr. K. R. Shukla",
    "east": "Central Railway Property"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Passage",
      "east": "Flat No. 1205",
      "south": "Road",
      "west": "Flat No. 1203"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9037.5",
  "depreciatedBuildingRate": "2237.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "46900",
  "landRate": "11600",
  "igrImage": "cases/6565baf83ee54b1d76a5c8a4/igr_1701950750148_Image.png",
  "squareMeterGuideLineRate": "51590.00",
  "squareFeetGuideLineRate": "4793.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "93",
  "rate": "4533.00",
  "squareFeetGuideLineRate": "4533.00",
  "squareMeterGuideLineRate": "48791.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "I_Class",
    "label": "I Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  }
},
```

```
"monthlyRent": "14000.00",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "1",
"month": "1",
"year": "2016",
"fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "15",
"flatFloorNo": "12",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"area": "757.20",
"measurementType": "Sq. Ft.",
```



```
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6565baf83ee54b1d76a5c8a4/
routeMap_1702009363013_Image.png",
    "routeLat": "19.232673",
    "routeLng": "73.138885",
    "stationName": "Kalyan",
    "routeDistance": "950M"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "pa1y4",
      "name": "pa1y4",
      "image": "cases/6565baf83ee54b1d76a5c8a4/
routeMap_1702009128229_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5702978.00",
"finalValue": "5702978.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3432388.00",
  "selectedBuildUpValue": "757.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6569cf3bbd53ea1a14365272",
      "name": "externallmg_1701432995132_1701433010062_image_13.jpeg",
      "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432995132_1701433010062_image_13.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6569cf3bbd53ea1a14365269",
      "name": "externallmg_1701432977593_1701433010061_image_3.jpeg",
      "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432977593_1701433010061_image_3.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6569cf3bbd53ea1a14365270",
      "name": "externallmg_1701432989747_1701433010062_image_10.jpeg",
```

```
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432989747_1701433010062_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a14365272",
    "name": "externallmg_1701432995132_1701433010062_image_13.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432995132_1701433010062_image_13.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526d",
    "name": "externallmg_1701432987327_1701433010062_image_7.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432987327_1701433010062_image_7.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526e",
    "name": "Living Room",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432987892_1701433010062_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526a",
    "name": "Living Room",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432978513_1701433010061_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a14365271",
    "name": "Dining",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432992268_1701433010062_image_11.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a14365267",
    "name": "Bedroom",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432968364_1701433010061_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a14365275",
    "name": "Bedroom",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701433113637_1701433187173_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a14365273",
    "name": "Kitchen",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432996674_1701433010062_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526c",
    "name": "Terrace",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432980730_1701433010062_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526b",
    "name": "Balcony",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432979712_1701433010061_image_5.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "8443",
"max": "9927"
},
"builtUpRateRange": {
  "min": "7036",
  "max": "8273"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "631.00",
"empanelmentNo": [
  "000000000"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6565baf83ee54b1d76a5c8a4",
"ownerName": "Mrs. Vaishali Sunil Joshi & Mr. Sunil Shivram Joshi",
"ownerPhoneNo": "9892777117",
"fullAddress": "Residential Flat No. 1204, 12th Floor, Building No 5, Erica, Royal Garden, Shaktidham Complex, Near Durga Mata Mandir, Kolsewadi, Village - Katemanivali, Taluka - Kalyan, District - Thane, Kalyan (East), PIN Code - 421 306, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "22/02/2014",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Royal Buildcon",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mrs. Vaishali Sunil Joshi & Mr. Sunil Shivram Joshi",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "954/2014"
},
"isHardCopy": false,
"displayStatus": true,
"fileName":
"document_1701165751569_janta_bank_mulund_svaishali_sunil_joshi.pdf",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
document_1701165751569_janta_bank_mulund_svaishali_sunil_joshi.pdf",
  "id": "286362",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Tue Nov 28 2023 15:33:36 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/06/2013",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "KDMC / NRV / BP / KV / 2013 - 2014 / 55"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1702010066604_214772.pdf",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
document_1702010066604_214772.pdf",
  "id": "388510",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Dec 08 2023 10:04:26 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005297",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "265083",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 28 2023 15:33:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vaishali Sunil Joshi & Mr. Sunil Shivram Joshi",
    "phone": "9892777117",
    "ownershipShare": "",
    "email": "",
    "id": "351446"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "337401",
    "name": "Living Room",
    "length": "14.00",
```

```
"length1": "14",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "140.00",
"images": [],
"extraAreas": [],
"finalArea": "140.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "32.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "",
  "length1": "11",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "0",
  "totalArea": "66.00",
  "images": [],
  "finalArea": "66.00",
  "extraAreas": []
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "8.00",
  "width1": "8",
  "width2": "0",
  "totalArea": "24.00",
  "images": [],
  "finalArea": "24.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "117.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "117.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
```

```
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "117.00",
  "images": [],
  "finalArea": "117.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "15.00",
  "images": [],
  "finalArea": "15.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "18.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Terrace",
      "value": "Terrace"
    }
  },
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "10",
  "length2": "00",
  "length": "10.00",
  "width1": "5",
  "width2": "00",
  "width": "5.00",
  "totalArea": "50.00",
  "percentageBeforeTotal": "50.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "50"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "4",
  "length2": "00",
  "length": "4.00",
  "width1": "9",
  "width2": "00",
  "width": "9.00",
  "totalArea": "36.00",
  "percentageBeforeTotal": "36.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "36"
}
],
"externalReport": [],
```

```
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "58.62",
    "totalAreaDocument": "631",
    "docBuiltpPercentage": "20",
    "docFinalBUILTUp": "757.20",
    "docFinalBUILTUpSquareMeter": "70.35",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "914987"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6571b52b4999312746cf4463",
    "property": "Flat",
    "area": "950",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "9000000",
    "source": "Nobroker.com",
    "expectedPrice": "9000000",
    "expectedRate": "9473.68",
    "builtUpExpectedRate": "7894.74",
    "image": "cases/6565baf83ee54b1d76a5c8a4/
indicator_1701950459768_Image.png",
    "squareMeter": "88.26",
    "id": "213794"
  },
  {
    "printlnReport": true,
    "_id": "6571b52b4999312746cf4464",
```

```
"property": "Flat",
"area": "989",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "7500000",
"expectedRate": "7583.42",
"builtUpExpectedRate": "0.00",
"image": "cases/6565baf83ee54b1d76a5c8a4/
indicator_1701950500427_Image.png",
"squareMeter": "91.88",
"id": "876616"
```

```
},
```

```
{
```

```
"printlnReport": true,
"_id": "6571b52b4999312746cf4465",
"property": "Flat",
"area": "685",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "9",
"source": "https://www.99acres.com/",
"expectedPrice": "6800000",
"expectedRate": "9927.01",
"builtUpExpectedRate": "8272.51",
"image": "cases/6565baf83ee54b1d76a5c8a4/
indicator_1701950530589_Image.png",
"squareMeter": "63.64",
"id": "597593"
```

```
},
```

```
{
```

```
"printlnReport": true,
"_id": "6571b52b4999312746cf4466",
"property": "Flat",
"area": "631",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "7",
"source": "Index_no.2",
"expectedPrice": "5327600",
```

```
    "expectedRate": "8443.11",
    "builtUpExpectedRate": "7035.92",
    "image": "cases/6565baf83ee54b1d76a5c8a4/
indicator_1701950601707_Image.png",
    "squareMeter": "58.62",
    "id": "828560"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365267",
    "name": "externallmg_1701432968364_1701433010061_image_0.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432968364_1701433010061_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365268",
    "name": "externallmg_1701432975018_1701433010061_image_1.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432975018_1701433010061_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365269",
    "name": "externallmg_1701432977593_1701433010061_image_3.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432977593_1701433010061_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526a",
    "name": "externallmg_1701432978513_1701433010061_image_4.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432978513_1701433010061_image_4.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526b",
    "name": "externallmg_1701432979712_1701433010061_image_5.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432979712_1701433010061_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526c",
    "name": "externallmg_1701432980730_1701433010062_image_6.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432980730_1701433010062_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526d",
    "name": "externallmg_1701432987327_1701433010062_image_7.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432987327_1701433010062_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526e",
    "name": "externallmg_1701432987892_1701433010062_image_8.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432987892_1701433010062_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6569cf3bbd53ea1a1436526f",
    "name": "externallmg_1701432987900_1701433010062_image_9.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432987900_1701433010062_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6569cf3bbd53ea1a14365270",
  "name": "externallmg_1701432989747_1701433010062_image_10.jpeg",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432989747_1701433010062_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6569cf3bbd53ea1a14365271",
  "name": "externallmg_1701432992268_1701433010062_image_11.jpeg",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432992268_1701433010062_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6569cf3bbd53ea1a14365272",
  "name": "externallmg_1701432995132_1701433010062_image_13.jpeg",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432995132_1701433010062_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6569cf3bbd53ea1a14365273",
  "name": "externallmg_1701432996674_1701433010062_image_14.jpeg",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701432996674_1701433010062_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6569cf3bbd53ea1a14365274",
  "name": "externallmg_1701433000302_1701433010062_image_15.jpeg",
  "path": "cases/6565baf83ee54b1d76a5c8a4/
externallmg_1701433000302_1701433010062_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6569cf3bbd53ea1a14365275",
    "name": "externalimg_1701433113637_1701433187173_image_0.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externalimg_1701433113637_1701433187173_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365276",
    "name": "externalimg_1701432877468_1701432942978_image_0.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externalimg_1701432877468_1701432942978_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365277",
    "name": "externalimg_1701432878804_1701432942978_image_1.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externalimg_1701432878804_1701432942978_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6569cf3bbd53ea1a14365278",
    "name": "externalimg_1701432886552_1701432942978_image_2.jpeg",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
externalimg_1701432886552_1701432942978_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- joshi.xlsx",
    "filename": "1701948062199_Calculation_2_joshi.xlsx",
    "path": "cases/6565baf83ee54b1d76a5c8a4/
processingDocuments/1701948062199_Calculation_2_joshi.xlsx",
    "size": "16066",
    "createdAt": "Thu Dec 07 2023 16:51:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
```

```
"originalname": "igr1.pdf",
"filename": "1701948062201_igr1.pdf",
"path": "cases/6565baf83ee54b1d76a5c8a4/
processingDocuments/1701948062201_igr1.pdf",
"size": "491987",
"createdAt": "Thu Dec 07 2023 16:51:04 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "Summary - joshi.xlsx",
"filename": "1701948062984_Summary__joshi.xlsx",
"path": "cases/6565baf83ee54b1d76a5c8a4/
processingDocuments/1701948062984_Summary__joshi.xlsx",
"size": "2994731",
"createdAt": "Thu Dec 07 2023 16:51:04 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-11-28T10:03:36.131Z",
"updatedAt": "2023-12-08T07:44:26.479Z",
"__v": 0,
"invoiceId": "6565baf83ee54b1d76a5c8af",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Rayan Joshi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Son",
"siteVisitContactNo": "7304023065",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 631.00",
"flatRate": "9300",
"landOtherRate": "6800",
"shopDetails": {
```



```

"typeOfShops": null,
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet +
Passage + 2 Balcony",
"carpetTotal": "592",
"otherCarpetTotal": "86.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "86.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "745.80",
"finalCarpetArea": "678.00",
"finalSalableArea": "820.38",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 559.00\nTerrace Area in Sq. Ft. =
50.00\nBalcony Aea in Sq. Ft. = 33.00\nDry Balcony Area in Sq. Ft. = 36.00\n\n",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"siteVisitDate": "2023-12-01"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'00"	10'00"	140.00

Dining	4'00"	8'00"	32.00
Kitchen	11'0"	6'0"	66.00
Toilet	3'0"	8'0"	24.00
Bedroom	13'00"	9'00"	117.00
Toilet	4'00"	7'00"	28.00
Bedroom	13'0"	9'0"	117.00
Passage	5'00"	7'00"	35.00
Balcony	3'0"	5'0"	15.00
Balcony	3'00"	6'00"	18.00
Other Composition :			
Terrace	10'00"	5'00"	50.00
Dry Balcony	4'00"	9'00"	36.00