

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7c3"
    },
    "type": "CREDITOFFICER",
    "_id": "64e727581452884516b694f4",
    "firstName": "Rajpal",
    "lastName": "Varma",
    "mobileNo": "",
    "workMobileNo": "7276503838",
    "email": "sbi.01821@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "Rajpal",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7c3",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Churchgate (Mumbai) Branch",
  "email": "sbi.01821@sbi.co.in",
  "mobileNo": "022-22030017",
  "alternateMobileNo": "",
  "address": "\\The International \\, 17 Maharshi Karve Road, Churchgate, Mumbai -
400 020, State - Maharashtra, Country - India. \\r\\n",
  "ledgerName": "STATE BANK OF INDIA - CHURCHGATE",
  "fax": "022-22002752",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "_id": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
  "firstName": "Shobha",
  "lastName": "Kuperkar",
  "shortName": "SH",
  "email": "shobha@vastukala.org",
  "designation": "",
  "mobileNo": "9004134140",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.010132285145087",
  "longitude": "72.83088706433773"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83088706433773,
    19.010132285145087
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-30",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mahim Division",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "29",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai City",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "1043 of TPS - IV",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "DB Crown",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gokhale Road (South)",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Prabhadevi",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1123",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "2904",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "G/S Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN Code - 400 025",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
```

```
"value": "HigherMiddleClass",
"label": "Higher Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Tower - B",
"west": "Saati Aasra CHSL",
"south": "Gokhale Road",
"east": "Motilal Oswal Tower"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per site information the composition of flat is Living
Room + Dinning + 4 Bedrooms + 4 Toilets.",
"dateOfIssusApprovePlan": "Copy of Part Occupancy Certificate Document No. EB /
```

5070 / GS / A / OCC / 1 / New dated 08.08.2023 issued by Municipal Corporation of Greater Mumbai. (part OCC for Wing 'A' comprising of Stilt + 4th to 6th Podium (pt.) for Parking + 7th to 9th Podium (pt.) + Service Area on Podium + 10th Podium (pt) + Fit.Centre + Swimming Pool + 12th Podium (pt) +13th Service Floor (pt.) + 14th to 62nd floors only.)",

"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."

},

"compositeRate": {

"remark": "At the time of visit, Builder has not allowed for Internal Site Inspection, Measurement & Photographs of the property. Details about the property has been provided by Sales Manager - Mr. Khudawan Kermani (Contact No. 9324743834)",

"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""

},

"igrRate": {

"propertyName": "Residential",
"rate": "215620",
"landRate": "95970",
"igrImage": "cases/6565c24f3ee54b1d76a5e9f1/igr_1701343152617_Image.png",
"squareMeterGuideLineRate": "215620.00",
"squareFeetGuideLineRate": "20032.00"

},

"igrFinalRate": {

"floorRatePercentage": "0",
"depreciationPercentage": "0",
"rate": "215620.00",
"squareMeterGuideLineRate": "215620.00",
"squareFeetGuideLineRate": "20032.00"

},

"outgoingDetail": {

"areaStatusList": {
"value": "I_Class",
"label": "I Class"

},

"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"

},

"propertyOccupiedByList": {
"value": "External_Site_Visit_Only",
"label": "External Site Visit Only"

},

```
"monthlyRent": "3,50,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "External site visit only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with 4 no. of Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "1",
"month": "1",
"year": "2023",
"fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Excellent",
  "label": "Excellent"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "Excellent",
"label": "Excellent"
},
"maintenanceOfTheBuilding": {
"value": "Excellent",
"label": "Excellent"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "3",
"noOfPodium": "10",
"noOfAmenityFloors": "2",
"noOfFloors": "55",
"flatFloorNo": "29",
"noOfLifts": "9",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "2199.60",
"measurementType": "Sq. Ft.",
```



```
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6565c24f3ee54b1d76a5e9f1/
routeMap_1701343720471_Image.png",
    "routeLat": "19.010089",
    "routeLng": "72.830971",
    "stationName": "Prabhadevi",
    "routeDistance": "750 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "zv5mz",
      "name": "zv5mz",
      "image": "cases/6565c24f3ee54b1d76a5e9f1/
routeMap_1701343653485_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "4",
"othersRate": "1000000",
"totalothersRate": "4000000",
"finaltotal": "123145000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "119145000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Nov 30 2023 18:18:20 GMT+0530 (India Standard Time)",
  "number": "2303767",
  "dayCount": "34",
  "monthCount": "463",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "44062387.00",
  "selectedBuildUpValue": "2199.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65685198bd53ea1a143392b3",
      "name": "externalImg_1701335421100_1701335491302_image_0.jpeg",
      "path": "cases/6565c24f3ee54b1d76a5e9f1/
externalImg_1701335421100_1701335491302_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65685198bd53ea1a143392b4",
      "name": "externalImg_1701335427272_1701335491302_image_1.jpeg",
      "path": "cases/6565c24f3ee54b1d76a5e9f1/
externalImg_1701335427272_1701335491302_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "65685198bd53ea1a143392b6",
    "name": "externallmg_1701335432585_1701335491302_image_3.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335432585_1701335491302_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65685198bd53ea1a143392b8",
    "name": "externallmg_1701335439889_1701335491302_image_5.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335439889_1701335491302_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65685198bd53ea1a143392b7",
    "name": "externallmg_1701335437149_1701335491302_image_4.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335437149_1701335491302_image_4.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "60715",
    "max": "71005"
  },
  "builtUpRateRange": {
    "min": "50597",
    "max": "59171"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "1833.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6565c24f3ee54b1d76a5e9f1",
"ownerName": "Mr. Anilkumar Poddar",
"ownerPhoneNo": "9167002128",
"appAddress": "Rustamjee crown\nTower A phase I Flat No 2904\nGokhale Road
\nMahim Prabhadevi\nMumbai 400 002",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "12/08/2020",
      "remark": "issued by Vinod P. Talathi"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "680666",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/document_1701167648050_170116771
5872_DocScanner_Nov_16_2023_729_PM.pdf",
    "fileName": "document_1701167648050_1701167715872_DocScanner_Nov_16_20
23_729_PM.pdf"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
```

```
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "10/06/2016",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Real Gem Buildtech Private Limited",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Anilkumar Poddar",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "5701/2016"
},
"isHardCopy": false,
"displayStatus": true,
"id": "118941",
"path": "cases/6565c24f3ee54b1d76a5e9f1/
document_1701342326656_ANIL_PODDAR_AGREEMENT.pdf",
"fileName": "document_1701342326656_ANIL_PODDAR_AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "08/08/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "remark": "(part OCC for Wing 'A' comprising of Stilt + 4th to 6th Podium (pt.) for
Parking + 7th to 9th Podium (pt.) + Service Area on Podium + 10th Podium (pt) +
Fit.Centre + Swimming Pool + 12th Podium (pt) +13th Service Floor (pt.) + 14th to 62nd
floors only.)",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
}
```

```
    "Document_No": "EB / 5070 / GS / A / OCC / 1 / New"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "651054",
  "path": "cases/6565c24f3ee54b1d76a5e9f1/
document_1701344865295_PART_OC__PPL_TOWER_A__C___08082023.pdf",
  "fileName":
"document_1701344865295_PART_OC__PPL_TOWER_A__C___08082023.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "23/02/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "EB / 5070 / GS / A / FCC / 5 / Amend"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1701344956302_cc.pdf",
  "path": "cases/6565c24f3ee54b1d76a5e9f1/document_1701344956302_cc.pdf",
  "id": "888561",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu Nov 30 2023 17:19:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005299",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "674528",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 28 2023 16:04:55 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mr. Anilkumar Poddar",
    "phone": "9167002128",
    "ownershipShare": "",
    "email": "",
    "id": "918282"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "170.29",
    "totalAreaDocument": "1833",
    "docBultupPercentage": "20",
    "docFinalBultUp": "2199.60",
    "docFinalBultUpSquareMeter": "204.35",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "451396"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65686fdcbd53ea1a1434447c",
    "property": "Rustomjee Crown, Prabhadevi",
    "area": "1483",
    "bultUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "41",
"source": "magic_bricks",
"expectedPrice": "105300000",
"expectedRate": "71004.72",
"builtUpExpectedRate": "59170.60",
"image": "cases/6565c24f3ee54b1d76a5e9f1/
indicator_1701342495026_Image.png",
"squareMeter": "137.78",
"id": "209309"
},
{
  "printlnReport": true,
  "_id": "65686fdcbd53ea1a1434447d",
  "property": "Rustomjee Crown, Prabhadevi",
  "area": "1988",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "40",
  "source": "https://www.99acres.com/",
  "expectedPrice": "140000000",
  "expectedRate": "70422.54",
  "builtUpExpectedRate": "58685.45",
  "image": "cases/6565c24f3ee54b1d76a5e9f1/
indicator_1701342578595_Image.png",
  "squareMeter": "184.69",
  "id": "267476"
},
{
  "printlnReport": true,
  "_id": "65686fdcbd53ea1a1434447e",
  "property": "Rustomjee Crown, Prabhadevi",
  "area": "2132",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "45",
  "source": "https://www.99acres.com/",
  "expectedPrice": "150000000",
  "expectedRate": "70356.47",
  "builtUpExpectedRate": "58630.39",
  "image": "cases/6565c24f3ee54b1d76a5e9f1/
indicator_1701342630399_Image.png",
```

```
"squareMeter": "198.07",
"id": "112091"
},
{
  "printlnReport": true,
  "_id": "65686fdcbd53ea1a1434447f",
  "property": "Rustomjee Crown, Prabhadevi",
  "area": "1964",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Higher",
  "source": "square_yards",
  "expectedPrice": "129000000",
  "expectedRate": "65682.28",
  "builtUpExpectedRate": "54735.23",
  "image": "cases/6565c24f3ee54b1d76a5e9f1/
indicator_1701342762124_Image.png",
  "squareMeter": "182.46",
  "id": "657981"
},
{
  "printlnReport": true,
  "_id": "65686fdcbd53ea1a14344480",
  "property": "Rustomjee Crown, Prabhadevi",
  "area": "1907",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "19",
  "source": "Index_no.2",
  "expectedPrice": "115784354",
  "expectedRate": "60715.45",
  "builtUpExpectedRate": "50596.20",
  "image": "cases/6565c24f3ee54b1d76a5e9f1/
indicator_1701342881194_Image.png",
  "squareMeter": "177.17",
  "id": "327690"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65685198bd53ea1a143392b3",
    "name": "externallmg_1701335421100_1701335491302_image_0.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335421100_1701335491302_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65685198bd53ea1a143392b4",
    "name": "externallmg_1701335427272_1701335491302_image_1.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335427272_1701335491302_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65685198bd53ea1a143392b5",
    "name": "externallmg_1701335430320_1701335491302_image_2.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335430320_1701335491302_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65685198bd53ea1a143392b6",
    "name": "externallmg_1701335432585_1701335491302_image_3.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335432585_1701335491302_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65685198bd53ea1a143392b7",
    "name": "externallmg_1701335437149_1701335491302_image_4.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335437149_1701335491302_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65685198bd53ea1a143392b8",
```

```
    "name": "externallmg_1701335439889_1701335491302_image_5.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335439889_1701335491302_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392b9",
    "name": "externallmg_1701335375937_1701335445285_image_0.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335375937_1701335445285_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392ba",
    "name": "externallmg_1701335377186_1701335445285_image_1.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335377186_1701335445285_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392bb",
    "name": "externallmg_1701335378510_1701335445285_image_2.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335378510_1701335445285_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392bc",
    "name": "externallmg_1701335380390_1701335445285_image_3.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335380390_1701335445285_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392bd",
    "name": "externallmg_1701335383128_1701335445285_image_4.jpeg",
```



```
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335383128_1701335445285_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392be",
    "name": "externallmg_1701335383875_1701335445285_image_5.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335383875_1701335445285_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65685198bd53ea1a143392bf",
    "name": "externallmg_1701335386015_1701335445285_image_6.jpeg",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
externallmg_1701335386015_1701335445285_image_6.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Potddar.xlsx",
    "filename": "1701343213797_Potddar.xlsx",
    "path": "cases/6565c24f3ee54b1d76a5e9f1/
processingDocuments/1701343213797_Potddar.xlsx",
    "size": "3001958",
    "createdAt": "Thu Nov 30 2023 16:50:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-11-28T10:34:55.959Z",
"updatedAt": "2023-11-30T12:52:12.205Z",
"__v": 0,
"invoiceId": "6565c2503ee54b1d76a5e9fa",
"uniqueNo": "",
"updatedBy": "60f915d3f3dd69653a592199",
"assignmentType": {
  "value": "Retail",
```

```
"label": "Retail"
},
"fullAddress": "Residential Flat No. 2904, 29th Floor, Wing - A, DB Crown, Plot No.
1043 of TPS - IV, Gokhale Road (South), Prabhadevi, Village - Mahim Division,
Municipality Ward No. G/S Ward, District - Mumbai City, Mumbai, PIN Code - 400 025,
State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Khudawan Kermani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Manager",
"siteVisitContactNo": "9324743834",
"siteVisitDate": "2023-11-30",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1833.00",
"flatRate": "65000",
"landOtherRate": "62000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
```

```
}  
,  
"finalSaleablePercentage": "0",  
"builtupPercentage": "10",  
"carpetTotal": "0",  
"extendOfSiteRemark": "",  
"finalBuiltupArea": "0.00",  
"finalCarpetArea": "0.00",  
"finalSalableArea": "0.00",  
"otherCarpetTotal": "0",  
"salablePercentage": "10",  
"siteMeasurementRemark": "",  
"toBeAdded": ""  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			