

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3628000",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 1814,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64535eb5ee347304f2a3005f",
  "role": "DELIVERYPERSON",
  "firstName": "Hemant",
  "email": "hkadam113@gmail.com",
  "lastName": "Kadam",
  "mobileNo": "9819455052",
  "shortName": "Hemant",
  "workWithDocumentMaker": "60b7189d2ffdf65bcd65882b",
  "profilePhoto": "users/64535eb5ee347304f2a3005f/
profilePhoto_1687240220512_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
```

```
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.448493950024297",
  "longitude": "72.81457355092232"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81457355092232,
    19.448493950024297
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "29/11/2023 02:00 pm"
    },
    {
      "dateTime": "29/11/2023 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-11-30",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Virar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "6",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Vasai",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sheetal Mayra",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mohak Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "242B/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1404",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 401 305",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Mohak House Nest Building",
    "west": "Mohak Road & Nalla",
    "south": "Internal Road",
    "east": "Aryan Sankul Building"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
```

```
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No.VVCMC /
TP / CC / VP - 0019 & 5062 / 516 / 2021 - 22 Dated 04.01.2022 issued by Vasai Virar
City Municipal Corporation",
"approvePlanVerified": "N.A, as the Building is Under Construction",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "52300",
  "landRate": "15900",
  "igrImage": "cases/6566eea65996860c2302c195/igr_1701254011951_Image.png",
  "squareMeterGuideLineRate": "57530.00",
  "squareFeetGuideLineRate": "5345.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "52300.00",
  "squareMeterGuideLineRate": "57530.00",
  "squareFeetGuideLineRate": "5345.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"monthlyRent": "14000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Basement + Stilt Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "3",
"noOfAmenityFloors": "",
"noOfFloors": "28",
"flatFloorNo": "14",
"noOfLifts": "8",
"noOfDwellingUnitsInBuilding": "20"
},
"finalPlinthArea": {
```



```
"area": "720.50",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6566eea65996860c2302c195/
routeMap_1701337050811_Image.png",
    "routeLat": "19.448261",
    "routeLng": "72.814540",
    "stationName": "Virar",
    "routeDistance": "450 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "as0i3e",
      "name": "as0i3e",
      "image": "cases/6566eea65996860c2302c195/
routeMap_1701336981592_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalKitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalSuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalInteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalElectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalExtraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalPotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalOthersRate": "0",
"finalTotal": "6550000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "6550000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3851073.00",
  "selectedBuildUpValue": "720.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "656841117e3df07ef44b0ba4",
      "name":
"externallmg_1701331217791_WhatsApp_Image_20231130_at_12449_PM.jpeg",
      "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217791_WhatsApp_Image_20231130_at_12449_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "656841117e3df07ef44b0ba0",
      "name":
"externallmg_1701331217767_WhatsApp_Image_20231130_at_12438_PM.jpeg",
      "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217767_WhatsApp_Image_20231130_at_12438_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
```

```
    "_id": "656841207e3df07ef44b0bea",
    "name":
"externallmg_1701331232188_WhatsApp_Image_20231130_at_12457_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232188_WhatsApp_Image_20231130_at_12457_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841207e3df07ef44b0be9",
    "name":
"externallmg_1701331232180_WhatsApp_Image_20231130_at_12456_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232180_WhatsApp_Image_20231130_at_12456_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841207e3df07ef44b0be8",
    "name":
"externallmg_1701331232175_WhatsApp_Image_20231130_at_12456_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232175_WhatsApp_Image_20231130_at_12456_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841207e3df07ef44b0be6",
    "name":
"externallmg_1701331232165_WhatsApp_Image_20231130_at_12455_PM_2.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232165_WhatsApp_Image_20231130_at_12455_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841207e3df07ef44b0be5",
    "name":
"externallmg_1701331232162_WhatsApp_Image_20231130_at_12455_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232162_WhatsApp_Image_20231130_at_12455_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841117e3df07ef44b0ba6",
```

```
    "name":
"externallmg_1701331217810_WhatsApp_Image_20231130_at_12452_PM_2.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217810_WhatsApp_Image_20231130_at_12452_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841207e3df07ef44b0be1",
    "name":
"externallmg_1701331232137_WhatsApp_Image_20231130_at_12453_PM_2.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232137_WhatsApp_Image_20231130_at_12453_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656841117e3df07ef44b0ba1",
    "name":
"externallmg_1701331217772_WhatsApp_Image_20231130_at_12439_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217772_WhatsApp_Image_20231130_at_12439_PM.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9777",
    "max": "10682"
  },
  "builtUpRateRange": {
    "min": "8889",
    "max": "9712"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "655.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6566eea65996860c2302c195",
"ownerName": "Mr. Satish V. Dure & Mrs. Dure Archana Satish",
"ownerPhoneNo": "9773793616",
"appAddress": "flat no. 1404 14 th floor bldg no. 6 Sheetal Mayra Virar ( e) 401305 ",
"remark": "site visit name - chandrakant, ram call 8828157587 \nvisit Today ( arejnt) ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "23/11/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. DGS Infra",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Satish V. Dure & Mrs. Dure Archana Satish",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  }
]
```

```
    },
    "Document_No": "22148/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "674962",
  "path": "cases/6566eea65996860c2302c195/
document_1701246668487_Satish_Dure.pdf",
  "fileName": "document_1701246668487_Satish_Dure.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "26/09/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "P99000046948"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1701336361940_P99000046948.pdf",
  "path": "cases/6566eea65996860c2302c195/
document_1701336361940_P99000046948.pdf",
  "id": "695428",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu Nov 30 2023 14:56:02 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/01/2022",
    "remark": "(C.C. received for Residential Building No. 6 - Stilt + Ground + 22 upper
floors only)",
    "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "VVCMC / TP / CC / VP - 0019 & 5062 / 516 / 2021 - 22 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1701336404555_CC.pdf",
"path": "cases/6566eea65996860c2302c195/document_1701336404555_CC.pdf",
"id": "423905",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Nov 30 2023 14:56:46 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "04/01/2022",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "remark": "(approved plan received for Residential Building No. 6 - Stilt + Ground +
22 upper floors only)",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC / TP / CC / VP - 0019 & 5062 / 516 / 2021 - 22"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "958341",
  "path": "cases/6566eea65996860c2302c195/
document_1701336463024_pLAN.pdf",
  "fileName": "document_1701336463024_pLAN.pdf"
},
{
  "documentType": {
    "value": "60ae1259aa6d152c1801b33d",
    "label": "Revised Development Permission Certificate"
  },
  "inputs": {
    "documentDate": "04/01/2022",
```

```
"nameOfApprovingAuthority": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"remark": "(RDP received for Residential with Shopline Building No. 06 - Stilt +
Ground + 22 upper floors only)",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "VVCMC / TP / RDP/ VP - 0019 & 5062 / 781/ 2021 - 22"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1701336498338_CC.pdf",
"path": "cases/6566eea65996860c2302c195/document_1701336498338_CC.pdf",
"id": "308904",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Nov 30 2023 14:58:18 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005316",
"createdBy": "64535eb5ee347304f2a3005f",
"caseHistory": [
{
  "id": "317749",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Wed Nov 29 2023 13:26:22 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Mr. Satish V. Dure & Mrs. Dure Archana Satish",
  "phone": "9773793616",
  "ownershipShare": "",
  "email": "",
  "id": "489344"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
```

```
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "60.85",
  "totalAreaDocument": "655.00",
  "docBUILTUPPercentage": "10",
  "docFinalBUILTUP": "720.50",
  "docFinalBUILTUPSquareMeter": "66.94",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "282733"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6567139d5996860c23032e57",
    "property": "DGS Sheetal Mayra Virar East",
    "area": "337",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "3295000.00",
    "expectedRate": "9777.45",
    "builtUpExpectedRate": "8888.59",
    "image": "cases/6566eea65996860c2302c195/
indicator_1701253614038_Image.png",
    "squareMeter": "31.31",
    "id": "911120"
  },
  {
    "printlnReport": true,
    "_id": "6567139d5996860c23032e58",
    "property": "DGS Sheetal Mayra 2 Bedroom 509 Sq.Ft. Apartment in Virar East ",
    "area": "509.00",
```

```
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "square_yards",
"expectedPrice": "5221000.00",
"expectedRate": "10257.37",
"builtUpExpectedRate": "9324.88",
"image": "cases/6566eea65996860c2302c195/
indicator_1701253669171_Image.png",
"squareMeter": "47.29",
"id": "582911"
},
{
  "printlnReport": true,
  "_id": "6567139d5996860c23032e59",
  "property": "DGS Sheetal Mayra, Vasai, Virar",
  "area": "337",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "3600000.00",
  "expectedRate": "10682.49",
  "builtUpExpectedRate": "9711.36",
  "image": "cases/6566eea65996860c2302c195/
indicator_1701253776629_Image.png",
  "squareMeter": "31.31",
  "id": "268082"
},
{
  "printlnReport": true,
  "_id": "6567139d5996860c23032e5a",
  "property": "DGS Sheetal Mayra By: DGS Group Virar East, Palghar - 401305",
  "area": "337",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "_",
  "expectedPrice": "3600000.00",
  "expectedRate": "10682.49",
  "builtUpExpectedRate": "9711.36",
  "image": "cases/6566eea65996860c2302c195/
indicator_1701253835994_Image.png",
```

```
    "squareMeter": "31.31",
    "id": "605019"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0b9e",
    "name":
"externallmg_1701331217756_WhatsApp_Image_20231130_at_12435_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217756_WhatsApp_Image_20231130_at_12435_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0b9f",
    "name":
"externallmg_1701331217762_WhatsApp_Image_20231130_at_12437_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217762_WhatsApp_Image_20231130_at_12437_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba0",
    "name":
"externallmg_1701331217767_WhatsApp_Image_20231130_at_12438_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217767_WhatsApp_Image_20231130_at_12438_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba1",
    "name":
"externallmg_1701331217772_WhatsApp_Image_20231130_at_12439_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217772_WhatsApp_Image_20231130_at_12439_PM.jpeg",
    "orientation": "landscape"
  },
  {

```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba2",
    "name":
"externallmg_1701331217779_WhatsApp_Image_20231130_at_12440_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217779_WhatsApp_Image_20231130_at_12440_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba3",
    "name":
"externallmg_1701331217785_WhatsApp_Image_20231130_at_12445_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217785_WhatsApp_Image_20231130_at_12445_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba4",
    "name":
"externallmg_1701331217791_WhatsApp_Image_20231130_at_12449_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217791_WhatsApp_Image_20231130_at_12449_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba5",
    "name":
"externallmg_1701331217798_WhatsApp_Image_20231130_at_12452_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217798_WhatsApp_Image_20231130_at_12452_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba6",
    "name":
"externallmg_1701331217810_WhatsApp_Image_20231130_at_12452_PM_2.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217810_WhatsApp_Image_20231130_at_12452_PM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841117e3df07ef44b0ba7",
    "name":
"externallmg_1701331217821_WhatsApp_Image_20231130_at_12452_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331217821_WhatsApp_Image_20231130_at_12452_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0be0",
    "name":
"externallmg_1701331232131_WhatsApp_Image_20231130_at_12453_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232131_WhatsApp_Image_20231130_at_12453_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0be1",
    "name":
"externallmg_1701331232137_WhatsApp_Image_20231130_at_12453_PM_2.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232137_WhatsApp_Image_20231130_at_12453_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0be2",
    "name":
"externallmg_1701331232147_WhatsApp_Image_20231130_at_12453_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232147_WhatsApp_Image_20231130_at_12453_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0be3",
```

```
"name":  
"externallmg_1701331232153_WhatsApp_Image_20231130_at_12454_PM_1.jpeg",  
  "path": "cases/6566eea65996860c2302c195/  
externallmg_1701331232153_WhatsApp_Image_20231130_at_12454_PM_1.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "656841207e3df07ef44b0be4",  
  "name":  
"externallmg_1701331232157_WhatsApp_Image_20231130_at_12454_PM.jpeg",  
  "path": "cases/6566eea65996860c2302c195/  
externallmg_1701331232157_WhatsApp_Image_20231130_at_12454_PM.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "656841207e3df07ef44b0be5",  
  "name":  
"externallmg_1701331232162_WhatsApp_Image_20231130_at_12455_PM_1.jpeg",  
  "path": "cases/6566eea65996860c2302c195/  
externallmg_1701331232162_WhatsApp_Image_20231130_at_12455_PM_1.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "656841207e3df07ef44b0be6",  
  "name":  
"externallmg_1701331232165_WhatsApp_Image_20231130_at_12455_PM_2.jpeg",  
  "path": "cases/6566eea65996860c2302c195/  
externallmg_1701331232165_WhatsApp_Image_20231130_at_12455_PM_2.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "656841207e3df07ef44b0be7",  
  "name":  
"externallmg_1701331232172_WhatsApp_Image_20231130_at_12455_PM.jpeg",  
  "path": "cases/6566eea65996860c2302c195/  
externallmg_1701331232172_WhatsApp_Image_20231130_at_12455_PM.jpeg",  
  "orientation": "landscape"  
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656841207e3df07ef44b0be8",
  "name":
"externallmg_1701331232175_WhatsApp_Image_20231130_at_12456_PM_1.jpeg",
  "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232175_WhatsApp_Image_20231130_at_12456_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656841207e3df07ef44b0be9",
  "name":
"externallmg_1701331232180_WhatsApp_Image_20231130_at_12456_PM.jpeg",
  "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232180_WhatsApp_Image_20231130_at_12456_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656841207e3df07ef44b0bea",
  "name":
"externallmg_1701331232188_WhatsApp_Image_20231130_at_12457_PM_1.jpeg",
  "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232188_WhatsApp_Image_20231130_at_12457_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656841207e3df07ef44b0beb",
  "name":
"externallmg_1701331232193_WhatsApp_Image_20231130_at_12457_PM_2.jpeg",
  "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232193_WhatsApp_Image_20231130_at_12457_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656841207e3df07ef44b0bec",
  "name":
"externallmg_1701331232197_WhatsApp_Image_20231130_at_12457_PM_3.jpeg",
```

```
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232197_WhatsApp_Image_20231130_at_12457_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0bed",
    "name":
"externallmg_1701331232200_WhatsApp_Image_20231130_at_12457_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232200_WhatsApp_Image_20231130_at_12457_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0bee",
    "name":
"externallmg_1701331232204_WhatsApp_Image_20231130_at_12458_PM_1.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232204_WhatsApp_Image_20231130_at_12458_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0bef",
    "name":
"externallmg_1701331232209_WhatsApp_Image_20231130_at_12458_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232209_WhatsApp_Image_20231130_at_12458_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656841207e3df07ef44b0bf0",
    "name":
"externallmg_1701331232212_WhatsApp_Image_20231130_at_12459_PM.jpeg",
    "path": "cases/6566eea65996860c2302c195/
externallmg_1701331232212_WhatsApp_Image_20231130_at_12459_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-11-29T07:56:22.289Z",
"updatedAt": "2023-11-30T10:04:00.213Z",
"__v": 0,
"invoiceId": "6566eea65996860c2302c19e",
"updatedBy": "60092304a16fab0f2af9b0c2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1404, 14th Floor, Building No 6, Sheetal Mayra,
Mohak Road, Village - Virar, Virar (East), Taluka - Vasai, District - Palghar, PIN Code -
401 305, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "64535eb5ee347304f2a3005f",
"contactPersonName": "Mr. Mehul Singh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"siteVisitContactNo": "9291006661",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 655.00",
"flatRate": "10000.00",
"landOtherRate": "7000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 412.00\nBalcony Area in Sq.
Ft. = 153.00\nEF Area in Sq. Ft. = 90.00\nTotal Carpet Area in Sq. Ft. = 655.00\n(Area
as per Agreement for Sale)",
"finalBuiltupArea": "0.00",
```

```

"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Nov 30 2023 14:51:57 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-11-30"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			