

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae8d68191f7b344b0055e3"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b29",
    "email": "nutesh.bhoir@cosmosbank.in",
    "firstName": "NUTESH BHOIR",
    "mobileNo": "9923159828",
    "workMobileNo": "9923159828",
    "lastName": "BHOIR"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae8d68191f7b344b0055e3",
  "name": "VASAI (WEST) BRANCH",
  "branchCode": "",
  "mobileNo": "020-67086708",
  "alternateMobileNo": "",
  "email": "nutesh.bhoir@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Morya Shopping Centre, S.No. 16, H.No. 10 & 11, NAVGHAR, \nAmbadi
Road, Vasai (West), Palghar - 401 202."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6401b61f0e28255fb44e636a",
"role": "SITEENGINEER",
"firstName": "Sanket",
"email": "ksanket7414@yahoo.com",
"lastName": "Karalkar",
"mobileNo": "8080582858",
"designation": "",
"shortName": "SAK",
"workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
}
],

```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.4204168761494",
  "longitude": "72.81545415393198"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  72.81545415393198,
  19.4204168761494
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2/12/2023 12:30 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Aachole",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nalasopara",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swati A ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gagan Vihar Complex",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```

```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "656817515996860c2303f2a8",
"ownerName": "Abhay D Naik",
"ownerPhoneNo": "9594495045",
"appAddress": "flat G/02 swati A wing gagan vihar complex achole x road nalasopara
east ",
"remark": "approx",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "path": "cases/656817515996860c2303f2a8/
document_1701320504083_1701320570857_vikas_rane_gagan_vihar.pdf",
    "fileName":
"document_1701320504083_1701320570857_vikas_rane_gagan_vihar.pdf",
    "displayStatus": false,
    "id": "223293",
```



```
"uploadedBy": "627219d6afd7d55eddedd283",
"createdAt": "Thu Nov 30 2023 10:32:09 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005339",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "212656",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 30 2023 10:32:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Abhay D Naik",
    "phone": "9594495045",
    "ownershipShare": "",
    "email": "",
    "id": "136070"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe17144135671",
    "name":
"externallmg_1701677467462_WhatsApp_Image_20231204_at_133146.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467462_WhatsApp_Image_20231204_at_133146.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe17144135672",
```

```
"name":
"externallmg_1701677467471_WhatsApp_Image_20231204_at_133148_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467471_WhatsApp_Image_20231204_at_133148_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135673",
  "name":
"externallmg_1701677467479_WhatsApp_Image_20231204_at_133148_2.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467479_WhatsApp_Image_20231204_at_133148_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135674",
  "name":
"externallmg_1701677467484_WhatsApp_Image_20231204_at_133148.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467484_WhatsApp_Image_20231204_at_133148.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135675",
  "name":
"externallmg_1701677467489_WhatsApp_Image_20231204_at_133149_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467489_WhatsApp_Image_20231204_at_133149_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135676",
  "name":
"externallmg_1701677467493_WhatsApp_Image_20231204_at_133149.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467493_WhatsApp_Image_20231204_at_133149.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135677",
  "name":
"externallmg_1701677467496_WhatsApp_Image_20231204_at_133152_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467496_WhatsApp_Image_20231204_at_133152_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135678",
  "name":
"externallmg_1701677467500_WhatsApp_Image_20231204_at_133152_2.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467500_WhatsApp_Image_20231204_at_133152_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe17144135679",
  "name":
"externallmg_1701677467503_WhatsApp_Image_20231204_at_133152_3.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467503_WhatsApp_Image_20231204_at_133152_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe1714413567a",
  "name":
"externallmg_1701677467507_WhatsApp_Image_20231204_at_133152.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467507_WhatsApp_Image_20231204_at_133152.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d899bcebbe1714413567b",
  "name":
"externallmg_1701677467511_WhatsApp_Image_20231204_at_133155_1.jpeg",
```

```
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467511_WhatsApp_Image_20231204_at_133155_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe1714413567c",
    "name":
"externallmg_1701677467514_WhatsApp_Image_20231204_at_133155_2.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467514_WhatsApp_Image_20231204_at_133155_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe1714413567d",
    "name":
"externallmg_1701677467518_WhatsApp_Image_20231204_at_133155.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467518_WhatsApp_Image_20231204_at_133155.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe1714413567e",
    "name":
"externallmg_1701677467521_WhatsApp_Image_20231204_at_133156_1.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467521_WhatsApp_Image_20231204_at_133156_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d899bcebbe1714413567f",
    "name":
"externallmg_1701677467523_WhatsApp_Image_20231204_at_133156_2.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677467523_WhatsApp_Image_20231204_at_133156_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "656d89abcebbe171441356b8",
  "name":
"externallmg_1701677483424_WhatsApp_Image_20231204_at_133156.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483424_WhatsApp_Image_20231204_at_133156.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356b9",
  "name":
"externallmg_1701677483426_WhatsApp_Image_20231204_at_133157_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483426_WhatsApp_Image_20231204_at_133157_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356ba",
  "name":
"externallmg_1701677483431_WhatsApp_Image_20231204_at_133157_2.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483431_WhatsApp_Image_20231204_at_133157_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356bb",
  "name":
"externallmg_1701677483433_WhatsApp_Image_20231204_at_133157_3.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483433_WhatsApp_Image_20231204_at_133157_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356bc",
  "name":
"externallmg_1701677483436_WhatsApp_Image_20231204_at_133157.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483436_WhatsApp_Image_20231204_at_133157.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d89abcebbe171441356bd",
    "name":
"externallmg_1701677483438_WhatsApp_Image_20231204_at_133158.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483438_WhatsApp_Image_20231204_at_133158.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d89abcebbe171441356be",
    "name":
"externallmg_1701677483440_WhatsApp_Image_20231204_at_133159_1.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483440_WhatsApp_Image_20231204_at_133159_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d89abcebbe171441356bf",
    "name":
"externallmg_1701677483442_WhatsApp_Image_20231204_at_133159_2.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483442_WhatsApp_Image_20231204_at_133159_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d89abcebbe171441356c0",
    "name":
"externallmg_1701677483444_WhatsApp_Image_20231204_at_133159_3.jpeg",
    "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483444_WhatsApp_Image_20231204_at_133159_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656d89abcebbe171441356c1",
```

```
"name":
"externallmg_1701677483446_WhatsApp_Image_20231204_at_133159.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483446_WhatsApp_Image_20231204_at_133159.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356c2",
  "name":
"externallmg_1701677483448_WhatsApp_Image_20231204_at_133200_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483448_WhatsApp_Image_20231204_at_133200_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356c3",
  "name":
"externallmg_1701677483451_WhatsApp_Image_20231204_at_133200.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483451_WhatsApp_Image_20231204_at_133200.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356c4",
  "name":
"externallmg_1701677483453_WhatsApp_Image_20231204_at_133201_1.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483453_WhatsApp_Image_20231204_at_133201_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356c5",
  "name":
"externallmg_1701677483456_WhatsApp_Image_20231204_at_133201_2.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483456_WhatsApp_Image_20231204_at_133201_2.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656d89abcebbe171441356c6",
  "name":
"externallmg_1701677483457_WhatsApp_Image_20231204_at_133201.jpeg",
  "path": "cases/656817515996860c2303f2a8/
externallmg_1701677483457_WhatsApp_Image_20231204_at_133201.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
{
  "originalname": "Doc2.docx",
  "filename": "1701493762752_Doc2.docx",
  "path": "cases/656817515996860c2303f2a8/
externalDocuments/1701493762752_Doc2.docx",
  "size": "3775373",
  "documentType": {
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Sat Dec 02 2023 10:39:25 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"processingDocuments": [
{
  "originalname": "Index.pdf",
  "filename": "1701493774004_Index.pdf",
  "path": "cases/656817515996860c2303f2a8/
processingDocuments/1701493774004_Index.pdf",
  "size": "119378",
  "createdAt": "Sat Dec 02 2023 10:39:34 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "kubal.xlsx",
  "filename": "1701493780000_kubal.xlsx",
  "path": "cases/656817515996860c2303f2a8/
processingDocuments/1701493780000_kubal.xlsx",
  "size": "11703",
  "createdAt": "Sat Dec 02 2023 10:39:40 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
```



```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdcf2",
      "role": "FRONTDESK",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "656d8978cebbe171441355a8",
    "note": "Photos Upload (Task Reopen)",
    "taskId": "656834025996860c23047b4c",
    "createdAt": "2023-12-04T08:10:32.187Z"
  }
],
"createdAt": "2023-11-30T05:02:09.220Z",
"updatedAt": "2023-12-04T08:11:23.538Z",
"__v": 0,
"invoiceId": "656817515996860c2303f2b2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": " Flat No. 2, Ground Floor, Swati A , Gagan Vihar Complex, Village -
Aachole, Nalasopara East, Nalasopara",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Abhay D Naik",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9594495045"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			