

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb41"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423130c",
    "firstName": "Sanjaykumar ",
    "email": "1thane.navimumbaii@bankofindia.co.in",
    "mobileNo": "-",
    "workMobileNo": "9969207619",
    "lastName": "SHrivastav"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb41",
  "branchCode": "000082",
  "type": "BRANCH",
  "name": "Thane Main Branch",
  "email": "thane.navimumbai@bankofindia.co.in",
  "mobileNo": "02225332942",
  "alternateMobileNo": "",
  "address": "1st Floor, Bank of India Building, Shivajipath, Opp. M H High School,
Thane (West), Thane - 400601, State - Maharashtra, Country - India.\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
```

```
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.19653675272756",
  "longitude": "72.98761048071773"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
```

```
0
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-05",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-05",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kalwa",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Nav Jagruti Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. Parsik Janata Sakari Bank, Kharegaon",
  "label": false
},
"wing": {
```



```
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "73/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 605",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
    "label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
    "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
```

```
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Grampanchayat_Kone",
    "label": "Grampanchayat Kone"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - A",
    "west": "Navsai Society",
    "south": "Vasudeo Park CHSL",
    "east": "Sandesh CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Passage",
      "east": "Staircase",
      "south": "Walls",
      "west": "Flat No. 403"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    }
  },
}
```

```
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
  "approvePlanVerified": "N.A",
  "empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "42",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9076",
  "depreciatedBuildingRate": "1276"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "61300",
  "landRate": "13900",
  "igrImage": "cases/6569bc31bd53ea1a143618bf/igr_1701941325031_Image.png",
  "squareMeterGuideLineRate": "49040.00",
  "squareFeetGuideLineRate": "4556.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "72",
  "rate": "4462.00",
  "squareFeetGuideLineRate": "4462.00",
  "squareMeterGuideLineRate": "48028.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "10,500",
```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Electricity city Bill Consumer No. 000020152681",
"meterCardHolderName": "Mr. Suresh C. Shinde",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per Local nomrs",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "1995",
"fullDate": "1/1/1995"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
},
"walls": {
  "value": "1",
  "label": "Yes"
},
},
"appearanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "28",
"totalLifeBuilding": "60",
"estimatedAge": "32",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "Basement",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "565.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6569bc31bd53ea1a143618bf/
routeMap_1701948800613_Image.png",
    "routeLat": "19.203111",
    "routeLng": "73.001024",
    "stationName": "Kalwa",
    "routeDistance": "1.8 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "o3ga59",
      "name": "o3ga59",
      "image": "cases/6569bc31bd53ea1a143618bf/
routeMap_1701948472745_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5127940.00",
"finalValue": "5127940.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2521030.00",
"selectedBuildUpValue": "565.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "656f1169c304607d2a3cad46",
"name": "externalimg_r_1701777728214_1701777796044_image_3.jpg",
"path": "cases/6569bc31bd53ea1a143618bf/
externalimg_r_1701777728214_1701777796044_image_3.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "656f1169c304607d2a3cad48",
"name": "externalimg_r_1701777726100_1701777796044_image_1.jpg",
"path": "cases/6569bc31bd53ea1a143618bf/
externalimg_r_1701777726100_1701777796044_image_1.jpg",
"orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [
{
"status": false,
"_id": "656f1169c304607d2a3cad54",
```

```
    "name": "externallmg_r_1701777749413_1701777796044_image_14.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777749413_1701777796044_image_14.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "656f1169c304607d2a3cad50",
    "name": "Bedroom",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777741587_1701777796044_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656f1169c304607d2a3cad52",
    "name": "Bedroom",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777746468_1701777796044_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656f1169c304607d2a3cad4b",
    "name": "Bedroom",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777730456_1701777796044_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656f1169c304607d2a3cad4e",
    "name": "Bedroom",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777735683_1701777796044_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656f1169c304607d2a3cad53",
    "name": "Bedroom",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777750906_1701777796044_image_15.jpg",
    "orientation": "portrait"
  }
]
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6682",
    "max": "13017"
  },
  "builtUpRateRange": {
    "min": "6075",
    "max": "10848"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "565.00",
"empanelmentNo": [
  "NMZ/CrMD/SK//2019-20-113"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6569bc31bd53ea1a143618bf",
"ownerName": "Mr. Suresh Chandrarao Shinde",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. B-402, 4th Floor, Nav Jagruti Co-Op. Hsg. Soc.
Ltd., Opp. Parsik Janata Sakari Bank, Kharegaon, Village - Kalwa, Taluka - Thane,
District - Thane, Thane (West), PIN Code - 400 605, State - Maharashtra, India",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "02/07/1995",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Mahalaxmi Construction",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Suresh Chandrarao Shinde",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "4532/1996"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "731860",
    "path": "cases/6569bc31bd53ea1a143618bf/
document_1701940698606_document_1701428261132_Boi_Main_br_Shinde.pdf",
    "fileName":
"document_1701940698606_document_1701428261132_Boi_Main_br_Shinde.pdf"
  },
  {
    "documentType": {
      "value": "60ae1264aa6d152c1801b371",
      "label": "Share Certificate "
    },
    "inputs": {
      "documentDate": "07/02/2013",
      "remark": "transfer in the name of Smt. Sushma Suresh Shinde ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "30"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1701946984767_199612.pdf",
    "path": "cases/6569bc31bd53ea1a143618bf/
document_1701946984767_199612.pdf",
    "id": "254637",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Thu Dec 07 2023 16:33:04 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "13/08/1981",
      "nameOfApprovingAuthority": {
        "value": "Grampanchayat_Kalwa",
        "label": "Grampanchayat Kalwa"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "357"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1701947402676_128322.pdf",
    "path": "cases/6569bc31bd53ea1a143618bf/
document_1701947402676_128322.pdf",
    "id": "186770",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Thu Dec 07 2023 16:40:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "21/11/2020",
      "remark": "issued by S. D. Deshpande Valuer",
      "number": {
        "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "1329 / SDD / BBC / BOI / Thane / 2020-2021 "
},
"isHardCopy": false,
"displayStatus": true,
"id": "853863",
"path": "cases/6569bc31bd53ea1a143618bf/
document_1701949191633_Agreement__Boi_Main_br_Shinde.pdf",
"fileName": "document_1701949191633_Agreement__Boi_Main_br_Shinde.pdf"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005370",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "448781",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Dec 01 2023 16:27:53 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Suresh Chandrarao Shinde",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "476260"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Bedroom",
    "length": "18.00",
```

```
"length1": "18",
"length2": "0",
"width": "10.00",
"width1": "10",
"width2": "0",
"totalArea": "180.00",
"images": [],
"finalArea": "180.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "17.00",
  "length1": "17",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "170.00",
  "images": [],
  "finalArea": "170.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "8.00",
  "length1": "8",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "72.00",
  "images": [],
  "finalArea": "72.00",
  "extraAreas": []
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "15.00",
  "images": [],
  "finalArea": "15.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
```

```
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "40.00",
"images": [],
"extraAreas": [],
"finalArea": "40.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "52.49",
  "totalAreaDocument": "565",
  "docBultupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "910827"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "657190594999312746cea5e4",
  "property": "Residential Flat",
  "area": "484",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "6300000",
```

```
    "expectedRate": "13016.53",
    "builtUpExpectedRate": "10847.11",
    "image": "cases/6569bc31bd53ea1a143618bf/
indicator_1701940801949_Image.png",
    "squareMeter": "44.97",
    "id": "696605"
  },
  {
    "printlnReport": true,
    "_id": "657190594999312746cea5e5",
    "property": "Residential Flat",
    "area": "656",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "7000000",
    "expectedRate": "10670.73",
    "builtUpExpectedRate": "0.00",
    "image": "cases/6569bc31bd53ea1a143618bf/
indicator_1701940852553_Image.png",
    "squareMeter": "60.94",
    "id": "207114"
  },
  {
    "printlnReport": true,
    "_id": "657190594999312746cea5e6",
    "property": "Residential Flat",
    "area": "400",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "source": "Index_no.2",
    "expectedPrice": "2430000",
    "expectedRate": "6075.00",
    "builtUpExpectedRate": "0.00",
    "image": "cases/6569bc31bd53ea1a143618bf/
indicator_1701940910770_Image.png",
    "squareMeter": "37.16",
    "id": "869618"
  }
],
"externallImages": [
  {
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad45",
    "name": "externallmg_r_1701777727104_1701777796044_image_2.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777727104_1701777796044_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad46",
    "name": "externallmg_r_1701777728214_1701777796044_image_3.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777728214_1701777796044_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad47",
    "name": "externallmg_r_1701777724725_1701777796044_image_0.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777724725_1701777796044_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad48",
    "name": "externallmg_r_1701777726100_1701777796044_image_1.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777726100_1701777796044_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad49",
    "name": "externallmg_r_1701777732266_1701777796044_image_6.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777732266_1701777796044_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "656f1169c304607d2a3cad4a",
  "name": "externallmg_r_1701777729245_1701777796044_image_4.jpg",
  "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777729245_1701777796044_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656f1169c304607d2a3cad4b",
  "name": "externallmg_r_1701777730456_1701777796044_image_5.jpg",
  "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777730456_1701777796044_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656f1169c304607d2a3cad4c",
  "name": "externallmg_r_1701777734340_1701777796044_image_7.jpg",
  "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777734340_1701777796044_image_7.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656f1169c304607d2a3cad4d",
  "name": "externallmg_r_1701777737759_1701777796044_image_9.jpg",
  "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777737759_1701777796044_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656f1169c304607d2a3cad4e",
  "name": "externallmg_r_1701777735683_1701777796044_image_8.jpg",
  "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777735683_1701777796044_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "656f1169c304607d2a3cad4f",
    "name": "externallmg_r_1701777739741_1701777796044_image_10.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777739741_1701777796044_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad50",
    "name": "externallmg_r_1701777741587_1701777796044_image_11.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777741587_1701777796044_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad51",
    "name": "externallmg_r_1701777743666_1701777796044_image_12.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777743666_1701777796044_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad52",
    "name": "externallmg_r_1701777746468_1701777796044_image_13.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777746468_1701777796044_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad53",
    "name": "externallmg_r_1701777750906_1701777796044_image_15.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externallmg_r_1701777750906_1701777796044_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656f1169c304607d2a3cad54",
```

```
    "name": "externalImg_r_1701777749413_1701777796044_image_14.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externalImg_r_1701777749413_1701777796044_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "656f1169c304607d2a3cad55",
    "name": "externalImg_r_1701777706555_1701777781243_image_2.png",
    "path": "cases/6569bc31bd53ea1a143618bf/
externalImg_r_1701777706555_1701777781243_image_2.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "656f1169c304607d2a3cad56",
    "name": "externalImg_r_1701777703900_1701777781243_image_0.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externalImg_r_1701777703900_1701777781243_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "656f1169c304607d2a3cad57",
    "name": "externalImg_r_1701777705089_1701777781243_image_1.jpg",
    "path": "cases/6569bc31bd53ea1a143618bf/
externalImg_r_1701777705089_1701777781243_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1701941348062_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6569bc31bd53ea1a143618bf/
processingDocuments/1701941348062_Calculation_Sheet_NEW.xlsx",
    "size": "3350652",
    "createdAt": "Thu Dec 07 2023 14:59:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-01T10:57:53.312Z",
"updatedAt": "2023-12-07T12:14:38.593Z",
"__v": 0,
"invoiceId": "6569bc31bd53ea1a143618c8",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Suresh Chandrarao Shinde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892592314",
"buildingServicesRate": "2200",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 565.00",
"flatRate": "10000",
"landOtherRate": "7800",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Kitchen + WC + Bathroom + Passage",
"carpetTotal": "489",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "537.90",
"finalCarpetArea": "489.00",
"finalSalableArea": "591.69",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
```

```

"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Dec 07 2023 15:39:52 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-05",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	18'0"	10'0"	180.00
Bedroom	17'0"	10'0"	170.00
Kitchen	8'0"	9'0"	72.00
WC	3'00"	4'00"	12.00
Bathroom	3'0"	5'0"	15.00
Passage	5'00"	8'00"	40.00
Other Composition :			