

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.2404548595497",
  "longitude": "72.86261133514516"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86261133514516,
    19.2404548595497
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2/12/2023 10:30 am"
    },
    {
      "dateTime": "2/12/2023 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-04",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
},
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mahajanwadi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "4",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East), Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krishna Kamal Green Ways Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Off. Western Express Highway",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "86(P), 87(P), 88(P)",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
```

```
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
"label": "Teak Wood Door frame with Solid door with safety door"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mira_Bhayander_Municipal_Corporation",
"label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building No. 7 & 8",
"west": "Open Plot",
"south": "Open Plot",
```

```
"east": "Garden"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "600",
  "depreciatedCostOfConstruction": "13400.00",
  "depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "97700",
  "landRate": "28700",
  "igrImage": "cases/6569c8c7bd53ea1a14363c2c/igr_1701771612978_Image.png",
  "squareMeterGuideLineRate": "78160.00",
  "squareFeetGuideLineRate": "7261.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "84",
  "rate": "6526.00",
  "squareFeetGuideLineRate": "6526.00",
  "squareMeterGuideLineRate": "70246.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "8,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "Sahpanna Swant",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
```

```
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2007",
"fullDate": "1/1/2007"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
```

```
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
```

```
"label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "4",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "357.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6569c8c7bd53ea1a14363c2c/
routeMap_1701757671877_Image.png",
    "routeLat": "19.264582",
    "routeLng": "72.878218",
    "stationName": "Mira Road",
    "routeDistance": "3.9 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  }
}
```



```
},
"locationMapImg": [
  {
    "id": "hqosu",
    "name": "hqosu",
    "image": "cases/6569c8c7bd53ea1a14363c2c/
routeMap_1701757579550_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3993200.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "3993200.00"
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2333698.00",
  "selectedBuildUpValue": "357.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "656e9e1fcebbe17144141ad2",
      "name":
"externalImg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
```

```
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "656e9e07cebbe17144141a3d",
    "name":
"externallmg_1701748230957_IMG_20231204_115133_copy_1200x1597.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748230957_IMG_20231204_115133_copy_1200x1597.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "656e9e07cebbe17144141a41",
    "name":
"externallmg_1701748231025_IMG_20231204_115334_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231025_IMG_20231204_115334_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656e9e07cebbe17144141a43",
    "name":
"externallmg_1701748231102_IMG_20231204_112909_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231102_IMG_20231204_112909_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656e9e07cebbe17144141a42",
    "name":
"externallmg_1701748231074_IMG_20231204_112907_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231074_IMG_20231204_112907_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "656e9e1fcebbe17144141acd",
    "name":
"externallmg_1701748255481_IMG_20231204_115137_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255481_IMG_20231204_115137_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656e9e1fcebbe17144141ad0",
    "name":
"externallmg_1701748255510_IMG_20231204_115214_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255510_IMG_20231204_115214_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656e9e1fcebbe17144141ad2",
    "name":
"externallmg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "656e9e07cebbe17144141a3c",
    "name":
"externallmg_1701748230943_IMG_20231204_113304_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748230943_IMG_20231204_113304_copy_1200x900.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "656e9e1fcebbe17144141ac9",
    "name": "Living Room",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255452_IMG_20231204_114813_copy_1200x900.jpg",
    "orientation": "landscape"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "656e9e07cebbe17144141a4a",
      "name": "Living Room",
      "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231175_IMG_20231204_114740_copy_1200x900.jpg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "656e9e07cebbe17144141a48",
      "name": "Living Room",
      "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231154_IMG_20231204_114732_copy_1200x900.jpg",
      "orientation": "landscape"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "12775",
    "max": "15101"
  },
  "builtUpRateRange": {
    "min": "10647",
    "max": "12584"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "298.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6569c8c7bd53ea1a14363c2c",
"ownerName": "Mr. Ramesh Duja Kunder & Mrs. Pramila Ramesh Kunder",
"ownerPhoneNo": "0986758668",
"appAddress": "flat no. 403. 4th floor Bldg 4 C3 mira Gauthan mahajanwadi Bldg
krishan kamal Green ways mira Road ",
"remark": "SSI surendra kamble \n8689869332",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "12/04/2004",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Creative Builder",
      "to": {
        "value": "Flatholder",
        "label": "Flatholder"
      },
      "Flatholder": "Mr. Ramesh Duja Kunder & Mrs. Pramila Ramesh Kunder",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "2966/2004"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "728538",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
document_1701431371522_SKMBT_C22023111009330.pdf",
    "fileName": "document_1701431371522_SKMBT_C22023111009330.pdf"
  },
  {
```

```
"documentType": {
  "value": "60ae124baa6d152c1801b2fd",
  "label": "Occupancy Certificate"
},
"inputs": {
  "documentDate": "02/05/2007",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MNP / NR / 1656 / 07-08"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1701771911694_150516.pdf",
"path": "cases/6569c8c7bd53ea1a14363c2c/
document_1701771911694_150516.pdf",
"id": "546576",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Dec 05 2023 15:55:11 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005375",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "849760",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Dec 01 2023 17:21:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ramesh Duja Kunder & Mrs. Pramila Ramesh Kunder",
    "phone": "0986758668",
    "ownershipShare": "",
    "email": "",
    "id": "517650"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "778483",
    "name": "Living Room",
    "length": "13.00",
    "length1": "13",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "117.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "117.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "8.08",
    "length1": "8",
    "length2": "1",
    "width": "7.50",
    "width1": "7",
    "width2": "6",
    "totalArea": "60.62",
    "images": [],
    "extraAreas": [],
    "finalArea": "60.62"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Bathroom",
    "length": "3.33",
```

```
"length1": "3",
"length2": "4",
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "14.44",
"images": [],
"extraAreas": [],
"finalArea": "14.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "88.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "88.56"
}
```

```
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "185115",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "298",
    "squareMeterArea": "27.68",
    "docFinalBuiltUp": "357.6",
    "docFinalBuiltUpSquareMeter": "33.216",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "656ef962cebbe171441502d6",
    "property": "Green Ways, Mira Road",
    "area": "454",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "5800000",
    "expectedRate": "12775.33",
    "builtUpExpectedRate": "10646.11",
    "image": "cases/6569c8c7bd53ea1a14363c2c/
indicator_1701770641130_Image.png",
    "squareMeter": "42.18",
    "id": "568708"
  },

```

```
{
  "printlnReport": true,
  "_id": "656ef962cebbe171441502d7",
  "property": "Green Ways, Mira Road",
  "area": "545",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "2",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8000000",
  "expectedRate": "14678.90",
  "builtUpExpectedRate": "12232.42",
  "image": "cases/6569c8c7bd53ea1a14363c2c/
indicator_1701770984600_Image.png",
  "squareMeter": "50.63",
  "id": "839920"
},
{
  "printlnReport": true,
  "_id": "656ef962cebbe171441502d8",
  "property": "Green Ways, Mira Road",
  "area": "298",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "4500000",
  "expectedRate": "15100.67",
  "builtUpExpectedRate": "12583.89",
  "image": "cases/6569c8c7bd53ea1a14363c2c/
indicator_1701771048901_Image.png",
  "squareMeter": "27.69",
  "id": "765317"
},
{
  "printlnReport": true,
  "_id": "656ef962cebbe171441502d9",
  "property": "Green Ways, Mira Road",
  "area": "433",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "6500000",
"expectedRate": "15011.55",
"builtUpExpectedRate": "12509.62",
"image": "cases/6569c8c7bd53ea1a14363c2c/
indicator_1701771098442_Image.png",
"squareMeter": "40.23",
"id": "188169"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "656e9e07cebbe17144141a3c",
"name":
"externalImg_1701748230943_IMG_20231204_113304_copy_1200x900.jpg",
"path": "cases/6569c8c7bd53ea1a14363c2c/
externalImg_1701748230943_IMG_20231204_113304_copy_1200x900.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "656e9e07cebbe17144141a3d",
"name":
"externalImg_1701748230957_IMG_20231204_115133_copy_1200x1597.jpg",
"path": "cases/6569c8c7bd53ea1a14363c2c/
externalImg_1701748230957_IMG_20231204_115133_copy_1200x1597.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "656e9e07cebbe17144141a3e",
"name":
"externalImg_1701748230979_IMG_20231204_115148_copy_1200x1600.jpg",
"path": "cases/6569c8c7bd53ea1a14363c2c/
externalImg_1701748230979_IMG_20231204_115148_copy_1200x1600.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```



```
    "_id": "656e9e07cebbe17144141a3f",
    "name":
"externallmg_1701748230993_IMG_20231204_115253_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748230993_IMG_20231204_115253_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a40",
    "name":
"externallmg_1701748231010_IMG_20231204_115333_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231010_IMG_20231204_115333_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a41",
    "name":
"externallmg_1701748231025_IMG_20231204_115334_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231025_IMG_20231204_115334_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a42",
    "name":
"externallmg_1701748231074_IMG_20231204_112907_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231074_IMG_20231204_112907_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a43",
    "name":
"externallmg_1701748231102_IMG_20231204_112909_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231102_IMG_20231204_112909_copy_1200x1600.jpg",
    "orientation": "portrait"
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e07cebbe17144141a44",
  "name":
"externallmg_1701748231109_IMG_20231204_114719_copy_1200x900.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231109_IMG_20231204_114719_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e07cebbe17144141a45",
  "name":
"externallmg_1701748231118_IMG_20231204_114721_copy_1200x900.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231118_IMG_20231204_114721_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e07cebbe17144141a46",
  "name":
"externallmg_1701748231129_IMG_20231204_114726_copy_1200x900.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231129_IMG_20231204_114726_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e07cebbe17144141a47",
  "name":
"externallmg_1701748231144_IMG_20231204_114730_copy_1200x900.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231144_IMG_20231204_114730_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e07cebbe17144141a48",
  "name":
"externallmg_1701748231154_IMG_20231204_114732_copy_1200x900.jpg",
```

```
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231154_IMG_20231204_114732_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a49",
    "name":
"externallmg_1701748231163_IMG_20231204_114738_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231163_IMG_20231204_114738_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e07cebbe17144141a4a",
    "name":
"externallmg_1701748231175_IMG_20231204_114740_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748231175_IMG_20231204_114740_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac2",
    "name":
"externallmg_1701748255393_IMG_20231204_114744_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255393_IMG_20231204_114744_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac3",
    "name":
"externallmg_1701748255406_IMG_20231204_114747_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255406_IMG_20231204_114747_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "656e9e1fcebbe17144141ac4",
    "name":
"externallmg_1701748255413_IMG_20231204_114748_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255413_IMG_20231204_114748_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac5",
    "name":
"externallmg_1701748255418_IMG_20231204_114759_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255418_IMG_20231204_114759_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac6",
    "name":
"externallmg_1701748255427_IMG_20231204_114804_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255427_IMG_20231204_114804_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac7",
    "name":
"externallmg_1701748255436_IMG_20231204_114806_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255436_IMG_20231204_114806_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac8",
    "name":
"externallmg_1701748255444_IMG_20231204_114811_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255444_IMG_20231204_114811_copy_1200x900.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141ac9",
    "name":
"externallmg_1701748255452_IMG_20231204_114813_copy_1200x900.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255452_IMG_20231204_114813_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141aca",
    "name":
"externallmg_1701748255461_IMG_20231204_115025_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255461_IMG_20231204_115025_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141acb",
    "name":
"externallmg_1701748255466_IMG_20231204_115027_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255466_IMG_20231204_115027_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141acc",
    "name":
"externallmg_1701748255472_IMG_20231204_115136_copy_1200x1600.jpg",
    "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255472_IMG_20231204_115136_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656e9e1fcebbe17144141acd",
```

```
    "name":
"externallmg_1701748255481_IMG_20231204_115137_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255481_IMG_20231204_115137_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ace",
  "name":
"externallmg_1701748255490_IMG_20231204_115146_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255490_IMG_20231204_115146_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141acf",
  "name":
"externallmg_1701748255498_IMG_20231204_115149_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255498_IMG_20231204_115149_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ad0",
  "name":
"externallmg_1701748255510_IMG_20231204_115214_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255510_IMG_20231204_115214_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ad1",
  "name":
"externallmg_1701748255521_IMG_20231204_115215_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255521_IMG_20231204_115215_copy_1200x1600.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ad2",
  "name":
"externallmg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255542_IMG_20231204_115301_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ad3",
  "name":
"externallmg_1701748255550_IMG_20231204_190951_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255550_IMG_20231204_190951_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656e9e1fcebbe17144141ad4",
  "name":
"externallmg_1701748255559_IMG_20231204_191503_copy_1200x1600.jpg",
  "path": "cases/6569c8c7bd53ea1a14363c2c/
externallmg_1701748255559_IMG_20231204_191503_copy_1200x1600.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1701517262858_1700114326532_1699252194037_Calculation_1.xlsx",
    "filename": "1701771709117_1701517262858_1700114326532_1699252194037_C
alculation_1.xlsx",
    "path": "cases/6569c8c7bd53ea1a14363c2c/processingDocuments/1701771709117
_1701517262858_1700114326532_1699252194037_Calculation_1.xlsx",
    "size": "2242712",
    "createdAt": "Tue Dec 05 2023 15:51:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "656b233ecebbe1714412a81c",
    "note": "Rate verification done, visit not done and Pending for OC ",
    "taskId": "6569c8c7bd53ea1a14363c3f",
    "createdAt": "2023-12-02T12:29:50.476Z"
  }
],
"createdAt": "2023-12-01T11:51:35.443Z",
"updatedAt": "2023-12-05T10:26:11.496Z",
"__v": 0,
"invoiceId": "6569c8c7bd53ea1a14363c37",
"updatedBy": "60eebe33f3dd69653a5837ae",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 403, 4th Floor, Building No 4, Krishna Kamal
Green Ways Co-op. Hsg. Soc. Ltd., Off. Western Express Highway, Village -
Mahajanwadi, Taluka - Thane, District - Thane, Mira Road (East), Thane, PIN - 401
107, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Akshay Waghela",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Broker",
"siteVisitContactNo": "9099298745",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + WC",
"carpetTotal": "292.62",
"finalMeasurementType": "Sq. Ft.",
```



```

"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "321.88",
"finalCarpetArea": "292.62",
"finalSalableArea": "354.07",
"salablePercentage": "10",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 298.00",
"reportGeneratedDate": "Tue Dec 05 2023 10:36:26 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-04",
"buildingServicesRate": "2500.00",
"flatRate": "14000",
"landOtherRate": "11500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'00"	9'00"	117.00
Kitchen	8'1"	7'6"	60.62
Bathroom	3'4"	4'4"	14.44
WC	4'00"	3'00"	12.00
Bedroom	9'9"	9'1"	88.56
Other Composition :			