

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba95"
    },
    "type": "CREDITOFFICER",
    "_id": "656d5647cebbe1714412cd85",
    "firstName": "Rohan",
    "lastName": "Doley",
    "mobileNo": "",
    "workMobileNo": "9365326861",
    "email": "ubin0531600@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Abhilash Kumar",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba95",
  "branchCode": "000025",
  "type": "BRANCH",
  "name": "Bhuleshwar Branch",
  "email": "bhuleshwar@unionbankofindia.com",
  "mobileNo": "022-23826281",
  "alternateMobileNo": "",
  "address": "37/41, Barfiwala Building, Ground Floor, V.P. Road, Mumbai - 400 004,
State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
  "deliveryPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9969039853",
    "shortName": "SHP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "ADMIN",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
```

```
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
```

```
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
```

```
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.1161268145516",
  "longitude": "72.85599736657201"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85599736657201,
    19.1161268145516
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-04",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "Unit",
```

```
"label": "Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gundavali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Mumbai",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri (East), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Arvind Chambers Premises Co-op. Society Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```



```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Andheri Kurla Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "85/2(P)",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "348, 348/1, 349, 349/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 069",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
```

```
},
"flooring": {
  "value": "MosaicTileFlooring",
  "label": "Mosaic Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Aluminium_Sliding_Windows_with_window_grills",
  "label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "company_ownership",
    "label": "company ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Solitaire Corporate Park",
```

```
"west": "STC Society",
"south": "STC Society",
"east": "Service Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Staircase",
    "east": "Building Marginal Space",
    "south": "Building Marginal Space",
    "west": "Lift"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "The composition of Office is single unit.",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "Building External repair work in is progress.",
  "depreciationPercentage": "60",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "20",
  "depreciatedCostOfConstruction": "23820",
  "depreciatedBuildingRate": "1120"
},
"igrRate": {
  "propertyName": "Commercial office ",
  "rate": "160660",
  "landRate": "69650",
  "igrImage": "cases/656caf98cebbe1714412b653/igr_1701770380738_Image.png",
  "squareMeterGuideLineRate": "160660.00",
```

```
"squareFeetGuideLineRate": "14926.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "55",
  "rate": "11121.00",
  "squareMeterGuideLineRate": "119706.00",
  "squareFeetGuideLineRate": "11121.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "1,91,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1978",
  "fullDate": "1/1/1978"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
```



```
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_agreement",
    "label": "As per agreement"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "15",
  "ageOfBuilding": "45",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "3",
  "flatFloorNo": "1",
  "noOfLifts": "1",
  "noOfDwellingUnitsInBuilding": "1"
},
"finalPlinthArea": {
  "area": "3375.60",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/656caf98cebbe1714412b653/
routeMap_1701776040426_Image.png",
    "routeLat": "19.115000",
    "routeLng": "72.854389",
    "stationName": "Western Express Highway",
    "routeDistance": "300"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,

```

```
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "izp66b",
      "name": "izp66b",
      "image": "cases/656caf98cebbe1714412b653/
routeMap_1701775998397_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "67005660.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "67005660.00"
},
"outward": {
```

```
"status": true,
"remark": "SYSTEMGENERATED",
"date": "Fri Dec 08 2023 17:20:07 GMT+0530 (India Standard Time)",
"number": "2303893",
"dayCount": "20",
"monthCount": "122",
"generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "37540048.00",
  "selectedBuildUpValue": "3375.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb70",
    "name": "externallmg_1701690825139_1701690738810_image_2.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690825139_1701690738810_image_2.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb78",
    "name": "externallmg_1701691180707_1701690738810_image_10.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691180707_1701690738810_image_10.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb73",
    "name": "externallmg_1701691052118_1701690738810_image_5.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691052118_1701690738810_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb75",
    "name": "externallmg_1701691165840_1701690738810_image_7.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691165840_1701690738810_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb71",
    "name": "externallmg_1701690903321_1701690738810_image_3.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690903321_1701690738810_image_3.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "656dbf7ecebbe1714413eb77",
    "name": "externallmg_1701691177155_1701690738810_image_9.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691177155_1701690738810_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb7a",
    "name": "externallmg_1701691182879_1701690738810_image_12.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691182879_1701690738810_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb7d",
    "name": "externallmg_1701691198349_1701690738810_image_15.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691198349_1701690738810_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656dbf7ecebbe1714413eb7c",
    "name": "externallmg_1701691194634_1701690738810_image_14.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691194634_1701690738810_image_14.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "21818",
    "max": "25161"
  },
  "builtUpRateRange": {
    "min": "18182",
    "max": "20968"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "2813.00",
"empanelmentNo": [
  "RO(S):ADV:VAL:012: 2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"paymentId": [],
"_id": "656caf98cebbe1714412b653",
"ownerName": "Anantco Solutions Private Limited ",
"ownerPhoneNo": "9365326861",
"appAddress": "Office first Floor\nGundavli\nAndheri East\nMumbai\n",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "27/03/2016",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "M/s. Seth Enterprises Private Limited ",
      "to": {
```

```
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "M/s. Prakash Securities Private Limited",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "4298/2016"
},
"isHardCopy": false,
"displayStatus": true,
"id": "435476",
"path": "cases/656caf98cebbe1714412b653/
document_1701621492482_1701621528028_Arvind_chamber.pdf",
"fileName": "document_1701621492482_1701621528028_Arvind_chamber.pdf"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "09/11/2023",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Prakash Securities Private Limited",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Anantco Solutions Private Limited ",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "18454"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702287127109_Registered_Sale_Deed_2.pdf",
  "path": "cases/656caf98cebbe1714412b653/
document_1702287127109_Registered_Sale_Deed_2.pdf",
  "id": "720641",
```

```
"uploadedBy": "64dc7184ccaf1e7b7f637f47",
"createdAt": "Mon Dec 11 2023 15:02:07 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005391",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "825449",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Dec 03 2023 22:10:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Anantco Solutions Private Limited ",
    "phone": "9365326861",
    "ownershipShare": "",
    "email": "",
    "id": "579062"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Mezzanine",
      "value": "Mezzanine"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "80",
    "length2": "10",
    "length": "80.83",
    "width1": "26",
    "width2": "8",
```

```
"width": "26.67",
"totalArea": "2155.55",
"percentageBeforeTotal": "2475.92",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "6571b18c4999312746cf308f",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "7.25",
    "length1": "7",
    "length2": "3",
    "width": "30.25",
    "width1": "30",
    "width2": "3",
    "totalArea": "219.31"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "6571b1b54999312746cf30f9",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "15.75",
    "length1": "15",
    "length2": "9",
    "width": "6.42",
    "width1": "6",
    "width2": "5",
    "totalArea": "101.06"
  }
],
"percentage": "100",
"finalArea": "2475.92"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60ae1245aa6d152c1801b2e3",
    "label": "Sale Deed"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "914158",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "2813",
  "squareMeterArea": "261.34",
  "docFinalBuiltUp": "3375.6",
  "docFinalBuiltUpSquareMeter": "313.60799999999995",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "656ef4c5cebbe1714414f6fc",
    "property": "Commercial Office",
    "area": "3100",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "65000000",
    "expectedRate": "20967.74",
    "builtUpExpectedRate": "0.00",
    "image": "cases/656caf98cebbe1714412b653/
indicator_1701770238879_Image.png",
    "squareMeter": "288.00",
    "id": "271994"
  },
  {
    "printlnReport": true,
    "_id": "656ef4c5cebbe1714414f6fd",
    "property": "Commercial office",
    "area": "1650",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "30000000",
"expectedRate": "18181.82",
"builtUpExpectedRate": "0.00",
"image": "cases/656caf98cebbe1714412b653/
indicator_1701770293565_Image.png",
"squareMeter": "153.29",
"id": "436964"
},
{
  "printlnReport": false,
  "_id": "657acffb3fcadc6777699ec8",
  "property": "Commercial",
  "area": "3250",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "100000000",
  "expectedRate": "30769.23",
  "builtUpExpectedRate": "27972.03",
  "image": "cases/656caf98cebbe1714412b653/
indicator_1702547451621_Image.png",
  "squareMeter": "301.94",
  "id": "874327"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb6e",
    "name": "externallmg_1701690670920_1701690738809_image_0.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690670920_1701690738809_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb6f",
    "name": "externallmg_1701690751820_1701690738810_image_1.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690751820_1701690738810_image_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb70",
  "name": "externallmg_1701690825139_1701690738810_image_2.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690825139_1701690738810_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb71",
  "name": "externallmg_1701690903321_1701690738810_image_3.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690903321_1701690738810_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb72",
  "name": "externallmg_1701690952498_1701690738810_image_4.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690952498_1701690738810_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb73",
  "name": "externallmg_1701691052118_1701690738810_image_5.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691052118_1701690738810_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb74",
  "name": "externallmg_1701691133178_1701690738810_image_6.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691133178_1701690738810_image_6.jpeg",
  "orientation": "portrait"
}
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "656dbf7ecebbe1714413eb75",
      "name": "externallmg_1701691165840_1701690738810_image_7.jpeg",
      "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691165840_1701690738810_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "656dbf7ecebbe1714413eb76",
      "name": "externallmg_1701691170965_1701690738810_image_8.jpeg",
      "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691170965_1701690738810_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "656dbf7ecebbe1714413eb77",
      "name": "externallmg_1701691177155_1701690738810_image_9.jpeg",
      "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691177155_1701690738810_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "656dbf7ecebbe1714413eb78",
      "name": "externallmg_1701691180707_1701690738810_image_10.jpeg",
      "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691180707_1701690738810_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "656dbf7ecebbe1714413eb79",
      "name": "externallmg_1701691181105_1701690738810_image_11.jpeg",
      "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691181105_1701690738810_image_11.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb7a",
  "name": "externallmg_1701691182879_1701690738810_image_12.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691182879_1701690738810_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb7b",
  "name": "externallmg_1701691188964_1701690738810_image_13.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691188964_1701690738810_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb7c",
  "name": "externallmg_1701691194634_1701690738810_image_14.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691194634_1701690738810_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb7d",
  "name": "externallmg_1701691198349_1701690738810_image_15.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691198349_1701690738810_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656dbf7ecebbe1714413eb7e",
  "name": "externallmg_1701691209020_1701690738810_image_16.jpeg",
  "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691209020_1701690738810_image_16.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb7f",
    "name": "externallmg_1701691218484_1701690738810_image_17.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691218484_1701690738810_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb80",
    "name": "externallmg_1701691240074_1701690738810_image_18.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691240074_1701690738810_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb81",
    "name": "externallmg_1701691251449_1701690738810_image_19.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701691251449_1701690738810_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb82",
    "name": "externallmg_1701690610185_1701690684169_image_0.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690610185_1701690684169_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "656dbf7ecebbe1714413eb83",
    "name": "externallmg_1701690617100_1701690684169_image_1.jpeg",
    "path": "cases/656caf98cebbe1714412b653/
externallmg_1701690617100_1701690684169_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
```

```
{
  "originalname": "Valuation_Report_Anantco Solutions Private Limited.pdf",
  "filename":
"1702297216136_Valuation_Report_Anantco_Solutions_Private_Limited.pdf",
  "path": "cases/656caf98cebbe1714412b653/externalDocuments/1702297216136_Valuation_Report_Anantco_Solutions_Private_Limited.pdf",
  "size": "1034950",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Mon Dec 11 2023 17:50:16 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "Invoice anatco.pdf",
  "filename": "1702297216153_Invoice_anatco.pdf",
  "path": "cases/656caf98cebbe1714412b653/externalDocuments/1702297216153_Invoice_anatco.pdf",
  "size": "45386",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Mon Dec 11 2023 17:50:16 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "1702378900576_5391.pdf",
  "filename": "1702378818774_1702378900576_5391.pdf",
  "path": "cases/656caf98cebbe1714412b653/externalDocuments/1702378818774_1702378900576_5391.pdf",
  "size": "352959",
  "documentType": {
    "value": "60ae124daa6d152c1801b307",
    "label": "Office Copy"
  },
  "createdAt": "Tue Dec 12 2023 16:30:21 GMT+0530 (India Standard Time)",
  "uploadedBy": "62727444afd7d55eddee092c"
}
],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
```

```
"createdBy": {
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "lastName": "Moozhickal",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "CHECKER",
"display": true,
"status": true,
"_id": "6576d6039e3cbd4940a7ca29",
"note": "Owners name change as per new agreement (Task Reopen)",
"taskId": "6571b3f44999312746cf4011",
"createdAt": "2023-12-11T09:27:31.375Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "PREPARE_INVOICE",
  "display": true,
  "status": true,
  "_id": "6576e0749e3cbd4940a7eb70",
  "note": "owners name change (Task Reopen)",
  "taskId": "657303d7d4a67a1d0042ab5d",
  "createdAt": "2023-12-11T10:12:04.885Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "PRINT",
  "display": true,
  "status": true,
  "_id": "6576e0899e3cbd4940a7ecc5",
```

```
"note": "owners name change (Task Reopen)",
"taskId": "657305bed4a67a1d0042af8d",
"createdAt": "2023-12-11T10:12:25.968Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6576e09e9e3cbd4940a7ee57",
  "note": "owners name change (Task Reopen)",
  "taskId": "6571b3f44999312746cf4011",
  "createdAt": "2023-12-11T10:12:46.599Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "657acfaa3fcadc6777699b98",
  "note": "value change (Task Reopen)",
  "taskId": "6571b3f44999312746cf4011",
  "createdAt": "2023-12-14T09:49:30.242Z"
}
],
"createdAt": "2023-12-03T16:40:56.070Z",
"updatedAt": "2023-12-14T09:53:03.351Z",
"__v": 0,
"invoiceId": "656caf98cebbe1714412b65c",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
}
```

```
},
"fullAddress": "Commercial Office No. 1st Floor, Arvind Chambers Premises Co-op.
Society Ltd., New/Current Survey No. 85/2(P), CTS No. 348, 348/1, 349, 349/1, Andheri
Kurla Road, Village - Gundavali, District - Mumbai, Andheri (East), Mumbai, PIN - 400
069, State - Maharashtra, India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Kamlesh Rawal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Staff",
"siteVisitContactNo": "7083387021",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Sale Deed",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 2813.00",
"flatRate": "25500",
"landOtherRate": "22700",
"siteVisitDate": "2023-12-04",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "2723.51",
"finalCarpetArea": "2475.92",
"finalSalableArea": "2995.86",
"otherCarpetTotal": "2476",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Fri Dec 08 2023 16:02:21 GMT+0530 (India Standard Time)",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",

```

```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"briefDescOfProperty": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "2475.92",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			
Mezzanine	80'10"	26'8"	2155.55