

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "23800000",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 11900,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordinatiion",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
```

```
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.245791714091812",
  "longitude": "72.86994217975729"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86994217975729,
    19.245791714091812
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "5/12/2023 11:30 am"
  },
  {
    "dateTime": "5/12/2023 12:00 am"
  },
  {
    "dateTime": "5/12/2023 12:00 am"
  },
  {
    "dateTime": "5/12/2023 12:00 am"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-05",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dahisar ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dahisar (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Harshgiri Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shiv Vallabh Cross Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Rawalpada ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "155, Hissa No. 1/A(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "2561-A/2 & 2543-A/1",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 068",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shree Chitrakut CHSL",
    "west": "Shiv Vallabh Cross Road ",
    "south": "Internal Road ",
    "east": "Om Suryodaya CHSL "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
```

```
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "30",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "750",
  "depreciatedCostOfConstruction": "19250.00",
  "depreciatedBuildingRate": "1750"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "136750",
  "landRate": "57110",
  "igrImage": "cases/656ead31cebbe171441430df/igr_1701842330225_Image.png",
  "squareMeterGuideLineRate": "136750.00",
  "squareFeetGuideLineRate": "12705.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "80",
  "rate": "11225.00",
  "squareFeetGuideLineRate": "11225.00",
  "squareMeterGuideLineRate": "120822.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
```

```
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "16,500",
"assessmentNo": "Bill No. RN1102473460000",
"taxPaidHolderName": "RN1102473460000",
"taxAmount": "01.04.2022 To 30.09.2022 = Rs. 1,57,507.00<br />\n01.10.2022 To
31.03.2023 = Rs. 1,57,507.00<br />\nTotal = Rs. 3,15,014.00",
"electricityServiceConnectionNo": "Consumer No. 9000 0122 8092",
"meterCardHolderName": "Mrs. Vidhya Sunil Nagvekar ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
}
```

```
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
```

```
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "20",
"totalLifeBuilding": "60",
"estimatedAge": "40",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "1",
```



```
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "490.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    },
    "routeMapImg": "cases/656ead31cebbe171441430df/
routeMap_1702707996632_Image.png",
    "routeLat": "19.245239",
    "routeLng": "72.870415",
    "stationName": "Ovaripada ",
    "routeDistance": "900 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "cd5e5",
      "name": "cd5e5",
      "image": "cases/656ead31cebbe171441430df/
routeMap_1702707705239_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7873250.00",
"finalValue": "7873250.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Dec 16 2023 17:30:05 GMT+0530 (India Standard Time)",
  "number": "2304015",
  "dayCount": "19",
  "monthCount": "244",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5509230.00",
  "selectedBuildUpValue": "490.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "656fec94c304607d2a3cee34",
      "name":
"externallmg_1701833876425_IMG_20231205_140737_copy_1200x900.jpg",
      "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876425_IMG_20231205_140737_copy_1200x900.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "656fec84c304607d2a3cede5",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860721_IMG_20231205_135908_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec84c304607d2a3cede6",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860735_IMG_20231205_135919_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec84c304607d2a3cede3",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860665_IMG_20231205_140616_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656fec84c304607d2a3cede7",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860751_IMG_20231205_135921_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec84c304607d2a3cedea",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860777_IMG_20231205_135929_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee26",
    "name": "Living Room",
```

```
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876252_IMG_20231205_135940_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee27",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876270_IMG_20231205_135946_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee2b",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876316_IMG_20231205_140446_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee2d",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876333_IMG_20231205_140510_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee34",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876425_IMG_20231205_140737_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "656fec94c304607d2a3cee33",
    "name": "Living Room",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876410_IMG_20231205_140732_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "19682",
    "max": "20485"
  },
  "builtUpRateRange": {
    "min": "16402",
    "max": "17071"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "409.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "656ead31cebbe171441430df",
"ownerName": "Mrs. Vidhya Sunil Nagvekar",
"ownerPhoneNo": "8879073432",
"appAddress": "Flat no A- 101 1 St floor Harshgiri Co-operative HSG Soc Ltd
Ashokvan Shiva Vallabh Road Dahisar East - 400068",
"remark": "7045081439 Ankita Vishal Nagweka (SSL Furkan - 7304140226 )",
"documents": [
  {
    "documentType": {
```

```
"value": "60ae1266aa6d152c1801b37b",
"label": "Deed Of Release"
},
"inputs": {
  "documentDate": "08/12/2022",
  "from": {
    "value": "The_Releasers",
    "label": "The Releasers"
  },
  "The_Releasers": "Mr. Vishal Sunil Nagwekar & Ms. Ankita Sunil Nagwekar ",
  "to": {
    "value": "The_Releasee",
    "label": "The Releasee"
  },
  "The_Releasee": "Mrs. Vidhya Sunil Nagvekar "
},
"isHardCopy": false,
"displayStatus": true,
"id": "822190",
"path": "cases/656ead31cebbe171441430df/document_1701751897141_1701751972987_SBI_Racpc_Borivali_West_Furkan_SSL_Valuation__Structural.pdf",
"fileName": "document_1701751897141_1701751972987_SBI_Racpc_Borivali_West_Furkan_SSL_Valuation__Structural.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "14/11/2003",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / A - 0790 / BP (WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "342155",
  "path": "cases/656ead31cebbe171441430df/document_1702704804347_295926.pdf",
```

```
"fileName": "document_1702704804347_295926.pdf"
},
{
  "documentType": {
    "value": "60ae126aaa6d152c1801b38b",
    "label": "Property Tax Bill"
  },
  "inputs": {
    "remark": " for the year 2022 - 2023",
    "to": {
      "value": "Tax_Holder",
      "label": "Tax Holder"
    },
    "Tax_Holder": "Harshgiri Co-Op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "RN1102473460000"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702705197756_240563.pdf",
  "path": "cases/656ead31cebbe171441430df/
document_1702705197756_240563.pdf",
  "id": "270345",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Dec 16 2023 11:09:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/11/2023",
    "remark": " in the name of Mrs. Vidhya Sunil Nagvekar issued by Harshgiri Co-Op.
Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "30726"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"fileName": "document_1702705340537_164005.pdf",
"path": "cases/656ead31cebbe171441430df/
document_1702705340537_164005.pdf",
"id": "637282",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Dec 16 2023 11:12:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "10/11/2023",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "9000 0122 8092"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702705402429_375597.pdf",
  "path": "cases/656ead31cebbe171441430df/
document_1702705402429_375597.pdf",
  "id": "840655",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Dec 16 2023 11:13:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "remark": " transferred dated 07.01.2023 issued by Harshgiri Cp.Op. Hsg. Soc.
Ltd.",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mrs. Vidhya Sunil Nagvekar",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "02"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702705531351_document_1701751897141_17017519729
87_SBI_Racpc_Borivali_West_Furkan_SSL_Valuation__Structural.pdf",
  "path": "cases/656ead31cebbe171441430df/document_1702705531351_document
_1701751897141_1701751972987_SBI_Racpc_Borivali_West_Furkan_SSL_Valuation
__Structural.pdf",
  "id": "620815",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Dec 16 2023 11:15:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1252aa6d152c1801b31d",
    "label": "Society Letter"
  },
  "inputs": {
    "documentDate": "12/12/2023",
    "remark": " for confirmation of Building Number issued by Harshgiri Co-Op. Hsg.
Soc. Ltd."
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1702705673180_Oc_Confirmation_1.pdf",
  "path": "cases/656ead31cebbe171441430df/
document_1702705673180_Oc_Confirmation_1.pdf",
  "id": "245021",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Dec 16 2023 11:17:53 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005411",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "391191",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 05 2023 10:25:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vidhya Sunil Nagvekar",
```

```
"phone": "8879073432",
"ownershipShare": "",
"email": "",
"id": "782905"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "449719",
"name": "Living Room",
"length": "15.67",
"length1": "15",
"length2": "8",
"width": "9.58",
"width1": "9",
"width2": "7",
"totalArea": "150.14",
"images": [],
"extraAreas": [],
"finalArea": "150.14"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Passage",
"length": "7.25",
"length1": "7",
"length2": "3",
"width": "2.92",
"width1": "2",
"width2": "11",
"totalArea": "21.15",
"images": [],
"extraAreas": [],
"finalArea": "21.15"
}
]
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "2",
"name": "Kitchen",
"length": "8.00",
"length1": "8",
"length2": "00",
"width": "7.50",
"width1": "7",
"width2": "6",
"totalArea": "60.00",
"images": [],
"extraAreas": [],
"finalArea": "60.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "27.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.75",
  "length1": "11",
  "length2": "9",
  "width": "9.58",
```



```
"width1": "9",
"width2": "7",
"totalArea": "112.60",
"images": [],
"extraAreas": [],
"finalArea": "112.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "22.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.85"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Release Deed",
      "value": "60ae1293aa6d152c1801b446"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "38.00",
    "totalAreaDocument": "409",
    "docBultupPercentage": "20",
    "docFinalBultUp": "490.80",
    "docFinalBultUpSquareMeter": "45.60",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
```

```
    "docFinalSaleableSquareMeter": "0.00",
    "id": "231560"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65700ddec304607d2a3d5b95",
    "property": "Residential Flat",
    "area": "371",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "7600000",
    "expectedRate": "20485.18",
    "builtUpExpectedRate": "17070.98",
    "image": "cases/656ead31cebbe171441430df/
indicator_1701842195010_Image.png",
    "squareMeter": "34.47",
    "id": "449656"
  },
  {
    "printlnReport": true,
    "_id": "65700ddec304607d2a3d5b96",
    "property": "Residential Flat",
    "area": "409",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "8050000",
    "expectedRate": "19682.15",
    "builtUpExpectedRate": "16401.79",
    "image": "cases/656ead31cebbe171441430df/
indicator_1701842270296_Image.png",
    "squareMeter": "38.00",
    "id": "240468"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "656fec84c304607d2a3cede3",
    "name":
"externallmg_1701833860665_IMG_20231205_140616_copy_1200x1597.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860665_IMG_20231205_140616_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede4",
    "name":
"externallmg_1701833860701_IMG_20231205_135905_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860701_IMG_20231205_135905_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede5",
    "name":
"externallmg_1701833860721_IMG_20231205_135908_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860721_IMG_20231205_135908_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede6",
    "name":
"externallmg_1701833860735_IMG_20231205_135919_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860735_IMG_20231205_135919_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede7",
    "name":
"externallmg_1701833860751_IMG_20231205_135921_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860751_IMG_20231205_135921_copy_1200x900.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede8",
    "name":
"externallmg_1701833860763_IMG_20231205_135923_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860763_IMG_20231205_135923_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cede9",
    "name":
"externallmg_1701833860770_IMG_20231205_135924_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860770_IMG_20231205_135924_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cedea",
    "name":
"externallmg_1701833860777_IMG_20231205_135929_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860777_IMG_20231205_135929_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cedeb",
    "name":
"externallmg_1701833860783_IMG_20231205_135935_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860783_IMG_20231205_135935_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec84c304607d2a3cedec",
```

```
    "name":
"externallmg_1701833860801_IMG_20231205_135938_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833860801_IMG_20231205_135938_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee26",
  "name":
"externallmg_1701833876252_IMG_20231205_135940_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876252_IMG_20231205_135940_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee27",
  "name":
"externallmg_1701833876270_IMG_20231205_135946_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876270_IMG_20231205_135946_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee28",
  "name":
"externallmg_1701833876288_IMG_20231205_135947_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876288_IMG_20231205_135947_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee29",
  "name":
"externallmg_1701833876301_IMG_20231205_135951_copy_1200x1600.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876301_IMG_20231205_135951_copy_1200x1600.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee2a",
  "name":
"externallmg_1701833876307_IMG_20231205_140444_copy_1200x1600.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876307_IMG_20231205_140444_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee2b",
  "name":
"externallmg_1701833876316_IMG_20231205_140446_copy_1200x1600.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876316_IMG_20231205_140446_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee2c",
  "name":
"externallmg_1701833876322_IMG_20231205_140508_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876322_IMG_20231205_140508_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee2d",
  "name":
"externallmg_1701833876333_IMG_20231205_140510_copy_1200x900.jpg",
  "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876333_IMG_20231205_140510_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "656fec94c304607d2a3cee2e",
  "name":
"externallmg_1701833876348_IMG_20231205_140513_copy_1200x900.jpg",
```

```
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876348_IMG_20231205_140513_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee2f",
    "name":
"externallmg_1701833876362_IMG_20231205_140641_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876362_IMG_20231205_140641_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee30",
    "name":
"externallmg_1701833876372_IMG_20231205_140642_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876372_IMG_20231205_140642_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee31",
    "name":
"externallmg_1701833876384_IMG_20231205_140644_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876384_IMG_20231205_140644_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee32",
    "name":
"externallmg_1701833876398_IMG_20231205_140645_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876398_IMG_20231205_140645_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "656fec94c304607d2a3cee33",
    "name":
"externallmg_1701833876410_IMG_20231205_140732_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876410_IMG_20231205_140732_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee34",
    "name":
"externallmg_1701833876425_IMG_20231205_140737_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876425_IMG_20231205_140737_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee35",
    "name":
"externallmg_1701833876442_IMG_20231205_191208_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876442_IMG_20231205_191208_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee36",
    "name":
"externallmg_1701833876450_IMG_20231205_191220_copy_1200x900.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876450_IMG_20231205_191220_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "656fec94c304607d2a3cee37",
    "name":
"externallmg_1701833876463_IMG_20231205_191223_copy_1200x1600.jpg",
    "path": "cases/656ead31cebbe171441430df/
externallmg_1701833876463_IMG_20231205_191223_copy_1200x1600.jpg",
```



```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "SBI - Smt. Shradha Sharad Jadav & Shri. Sharad Dattaram Jadhav - Final Report.pdf",
    "filename": "1701842395586_SBI__Smt_Shradha_Sharad_Jadav__Shri_Sharad_Dattaram_Jadhav__Final_Report.pdf",
    "path": "cases/656ead31cebbe171441430df/processingDocuments/1701842395586_SBI__Smt_Shradha_Sharad_Jadav__Shri_Sharad_Dattaram_Jadhav__Final_Report.pdf",
    "size": "13066893",
    "createdAt": "Wed Dec 06 2023 11:29:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1701842396107_Summary_Sheet.xlsx",
    "path": "cases/656ead31cebbe171441430df/processingDocuments/1701842396107_Summary_Sheet.xlsx",
    "size": "1546315",
    "createdAt": "Wed Dec 06 2023 11:29:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1702449337212_Calculation_Sheet.xlsx",
    "path": "cases/656ead31cebbe171441430df/processingDocuments/1702449337212_Calculation_Sheet.xlsx",
    "size": "16265",
    "createdAt": "Wed Dec 13 2023 12:05:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Oc Confirmation_1.pdf",
    "filename": "1702708487530_Oc_Confirmation_1.pdf",
    "path": "cases/656ead31cebbe171441430df/processingDocuments/1702708487530_Oc_Confirmation_1.pdf",
    "size": "272205",
    "createdAt": "Sat Dec 16 2023 12:04:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "657175944999312746ce6557",
    "note": "Pending for Building number confirmation",
    "taskId": "656ec747cebbe17144148787",
    "createdAt": "2023-12-07T07:34:44.461Z"
  }
],
"createdAt": "2023-12-05T04:55:13.136Z",
"updatedAt": "2023-12-16T12:04:07.943Z",
"__v": 0,
"invoiceId": "656ead31cebbe171441430e8",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 101, 1st Floor, Building No 2, Wing - A, Harshgiri
Co-Op. Hsg. Soc. Ltd., Shiv Vallabh Cross Road, Rawalpada , Village - Dahisar , Taluka
- Borivali , District - Mumbai Suburban , Dahisar (East), PIN - 400 068, State -
Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mrs. Vidhya Sunil Nagvekar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "8879073432",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Release Deed",
```

```
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 409.00",
"flatRate": "20000",
"landOtherRate": "17500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "333.93",
"extendOfSiteRemark": "All the above areas are within 4% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.",
"finalBuiltupArea": "433.32",
"finalCarpetArea": "393.93",
"finalSalableArea": "476.66",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
}
```

"reportGeneratedDate": "Sat Dec 16 2023 11:01:03 GMT+0530 (India Standard Time)",

"siteVisitDate": "2023-12-05",

"otherCompositionBuiltUpTotal": "0.00",

"otherCompositionCarpetTotal": "0.00",

"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	15'8"	9'7"	150.14
Passage	7'3"	2'11"	21.15
Kitchen	8'00"	7'6"	60.00
Toilet	7'3"	3'9"	27.19
Bedroom	11'9"	9'7"	112.60
Toilet	5'10"	3'11"	22.85
Other Composition :			