

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECCC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "63fda584ce84bf289baadaf6",
  "role": "PICKUPPERSON",
  "firstName": "Mahendra",
  "email": "mahindra.bijlaney@gmail.com",
  "lastName": "Bijlaney",
  "mobileNo": "9833016592",
  "shortName": "MB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fda584ce84bf289baadaf6/
profilePhoto_1677567364613_WhatsApp_Image_20230228_at_121901_PM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
```

```
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      {
        "title": {
          "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.415563993104332",
  "longitude": "72.86359232393205"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86359232393205,
    19.415563993104332
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "7/12/2023 01:00 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-07",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Waliv",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "4",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Narmada House",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "1, Hissa No. 3(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "104",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```

    "key": "postalCode",
    "value": "PIN - 401 208",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",

```

```
"label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Open Plot ",
  "west": "Open Plot ",
  "south": "Hanuman Mandir Road",
  "east": "Building No. 2"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A",
```

```
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "15",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6625",
  "depreciatedBuildingRate": "2125"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "43100",
  "landRate": "8640",
  "igrImage": "cases/657173fb4999312746ce58cc/igr_1702034766887_Image.png",
  "squareMeterGuideLineRate": "40945.00",
  "squareFeetGuideLineRate": "3804.00"
},
"igrFinalRate": {
  "floorRatePercentage": "95",
  "depreciationPercentage": "132.5",
  "rate": "4779.00",
  "squareMeterGuideLineRate": "51444.00",
  "squareFeetGuideLineRate": "4779.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "13,000",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per VVCMC / CIDCO norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2013",
    "fullDate": "1/1/2013"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
```

```
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "50",
"ageOfBuilding": "10",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "466.80",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
```



```
    "routeMapImg": "cases/657173fb4999312746ce58cc/
routeMap_1702018008326_Image.png",
    "routeLat": "19.415271",
    "routeLng": "72.863679",
    "stationName": "Nalla Sopara",
    "routeDistance": "7.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "v3axb",
      "name": "v3axb",
      "image": "cases/657173fb4999312746ce58cc/
routeMap_1702017787604_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
    "superfineFinishRate": "0",
    "totalsuperfineFinishRate": "0",
    "interiorDecorationsQty": "0",
    "interiorDecorationsRate": "0",
    "totalinteriorDecorationsRate": "0",
    "electricityDepositsQty": "0",
    "electricityDepositsRate": "0",
    "totalelectricityDepositsRate": "0",
```

```
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2577125.00",
"finalValue": "2577125.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "1635667.00",
  "selectedBuildUpValue": "466.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6571cd79d4a67a1d00410cf4",
      "name":
"externallmg_1701956985585_WhatsApp_Image_20231207_at_174156.jpeg",
      "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985585_WhatsApp_Image_20231207_at_174156.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6571cd79d4a67a1d00410cf0",
      "name": "Living Room",
      "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985496_WhatsApp_Image_20231207_at_174155_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "6571cd79d4a67a1d00410cfe",
      "name": "Living Room",
      "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985689_WhatsApp_Image_20231207_at_174200_2.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    "status": false,
    "_id": "6571cd79d4a67a1d00410cfb",
    "name": "Living Room",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985669_WhatsApp_Image_20231207_at_174159_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d3a",
    "name": "Living Room",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002912_WhatsApp_Image_20231207_at_174201_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d44",
    "name": "Living Room",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003033_WhatsApp_Image_20231207_at_174205_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"wardrobes": {
  "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "389.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "657173fb4999312746ce58cc",
"ownerName": "Mrs. Minarva Tapas Sahoo & Mr. Tapas D. Sahoo ",
"ownerPhoneNo": "9767014211",
"appAddress": "Flat No.104, Building 1, Narmada House, Wali . Vasai",
"remark": "\nFOR ANY QUERY CONTACT SIDDHESH LINGAYAT - 9821913038",
"documents": [
  {
    "documentType": {
      "value": "60ae1294aa6d152c1801b44b",
      "label": "Agreement For Re-Sale"
    },
    "inputs": {
      "documentDate": "09/11/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Bhanwarlal R. Lohar ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Minarva Tapas Sahoo & Mr. Tapas D. Sahoo "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1702015734634_agreement.pdf",
    "path": "cases/657173fb4999312746ce58cc/
document_1702015734634_agreement.pdf",
    "id": "575178",
```

```
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Dec 08 2023 11:38:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "13/01/2013",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "VVCMC / TP / OC / VP - 0069 / 487 / 2012 -13"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1702015848494_526468.pdf",
"path": "cases/657173fb4999312746ce58cc/
document_1702015848494_526468.pdf",
"id": "101338",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Dec 08 2023 11:40:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "31/05/2010",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CIDCO / VVSR / CC / BP - 4629 / E / 475"
},
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1702015968530_229099.pdf",
"path": "cases/657173fb4999312746ce58cc/
document_1702015968530_229099.pdf",
"id": "797186",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri Dec 08 2023 11:42:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005480",
"createdBy": "63fda584ce84bf289baadaf6",
"caseHistory": [
{
  "id": "766198",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Dec 07 2023 12:57:55 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Mrs. Minarva Tapas Sahoo & Mr. Tapas D. Sahoo ",
  "phone": "9767014211",
  "ownershipShare": "",
  "email": "",
  "id": "605214"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "551880",
  "name": "Living Room",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "16.00",
  "width1": "16",
  "width2": "00",
  "totalArea": "144.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "144.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "21.33",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6572b68cd4a67a1d0041a472",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "3.58",
      "length1": "3",
      "length2": "7",
      "width": "3.00",
      "width1": "3",
      "width2": "00",
      "totalArea": "10.75"
    }
  ],
  "finalArea": "32.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
```

```
"length": "9.25",
"length1": "9",
"length2": "3",
"width": "11.67",
"width1": "11",
"width2": "8",
"totalArea": "107.92",
"images": [],
"extraAreas": [],
"finalArea": "107.92"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "23.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.75",
  "length1": "4",
  "length2": "9",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "14.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.25"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "60.71",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.71"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flowerbed",
      "value": "Flowerbed"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "9",
    "length2": "2",
    "length": "9.17",
    "width1": "2",
    "width2": "4",
    "width": "2.33",
    "totalArea": "21.39",
    "percentageBeforeTotal": "42.97",
    "images": [],
    "extraAreas": [
      {
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"_id": "6572b6ead4a67a1d0041a57b",
"name": "Extra",
"extraAreaType": "Add",
"length": "9.25",
"length1": "9",
"length2": "3",
"width": "2.33",
"width1": "2",
"width2": "4",
"totalArea": "21.58"
}
],
"percentage": "100",
"finalArea": "42.97"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1294aa6d152c1801b44b",
    "label": "Agreement For Re-Sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "150132",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "389",
  "squareMeterArea": "36.14",
  "docFinalBuiltUp": "466.8",
  "docFinalBuiltUpSquareMeter": "43.368",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
```

```
"printlnReport": false,
  "_id": "6572fd13d4a67a1d00429156",
  "property": "Flat",
  "area": "380",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "3200000",
  "expectedRate": "8421.05",
  "builtUpExpectedRate": "7017.54",
  "image": "cases/657173fb4999312746ce58cc/
indicator_1702033408588_Image.png",
  "squareMeter": "35.30",
  "id": "275350"
},
{
  "printlnReport": false,
  "_id": "65731026d4a67a1d0042c856",
  "property": "AV Complex, Vasai East",
  "area": "387",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "2850000",
  "expectedRate": "7364.34",
  "builtUpExpectedRate": "6136.95",
  "image": "cases/657173fb4999312746ce58cc/
indicator_1702039541152_Image.png",
  "squareMeter": "35.95",
  "id": "380995"
},
{
  "printlnReport": false,
  "_id": "65731026d4a67a1d0042c857",
  "property": "Shraddha Apartment, Vasai East",
  "area": "365",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
```



```
    "source": "Index_no.2",
    "expectedPrice": "2475000",
    "expectedRate": "6780.82",
    "builtUpExpectedRate": "5650.68",
    "image": "cases/657173fb4999312746ce58cc/
indicator_1702039589934_Image.png",
    "squareMeter": "33.91",
    "id": "802331"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410ceb",
    "name":
"externallmg_1701956985370_WhatsApp_Image_20231207_at_174236.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985370_WhatsApp_Image_20231207_at_174236.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cec",
    "name":
"externallmg_1701956985374_WhatsApp_Image_20231207_at_174118.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985374_WhatsApp_Image_20231207_at_174118.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410ced",
    "name":
"externallmg_1701956985400_WhatsApp_Image_20231207_at_174142_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985400_WhatsApp_Image_20231207_at_174142_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cee",
    "name":
"externallmg_1701956985432_WhatsApp_Image_20231207_at_174142.jpeg",
```

```
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985432_WhatsApp_Image_20231207_at_174142.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cef",
    "name":
"externallmg_1701956985458_WhatsApp_Image_20231207_at_174154.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985458_WhatsApp_Image_20231207_at_174154.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cf0",
    "name":
"externallmg_1701956985496_WhatsApp_Image_20231207_at_174155_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985496_WhatsApp_Image_20231207_at_174155_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cf1",
    "name":
"externallmg_1701956985507_WhatsApp_Image_20231207_at_174155.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985507_WhatsApp_Image_20231207_at_174155.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cf2",
    "name":
"externallmg_1701956985517_WhatsApp_Image_20231207_at_174156_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985517_WhatsApp_Image_20231207_at_174156_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6571cd79d4a67a1d00410cf3",
  "name":
"externallmg_1701956985552_WhatsApp_Image_20231207_at_174156_2.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985552_WhatsApp_Image_20231207_at_174156_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd79d4a67a1d00410cf4",
  "name":
"externallmg_1701956985585_WhatsApp_Image_20231207_at_174156.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985585_WhatsApp_Image_20231207_at_174156.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd79d4a67a1d00410cf5",
  "name":
"externallmg_1701956985598_WhatsApp_Image_20231207_at_174157_1.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985598_WhatsApp_Image_20231207_at_174157_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd79d4a67a1d00410cf6",
  "name":
"externallmg_1701956985610_WhatsApp_Image_20231207_at_174157.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985610_WhatsApp_Image_20231207_at_174157.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd79d4a67a1d00410cf7",
  "name":
"externallmg_1701956985623_WhatsApp_Image_20231207_at_174158_1.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985623_WhatsApp_Image_20231207_at_174158_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cf8",
    "name":
"externallmg_1701956985629_WhatsApp_Image_20231207_at_174158_2.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985629_WhatsApp_Image_20231207_at_174158_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cf9",
    "name":
"externallmg_1701956985644_WhatsApp_Image_20231207_at_174158.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985644_WhatsApp_Image_20231207_at_174158.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cfa",
    "name":
"externallmg_1701956985662_WhatsApp_Image_20231207_at_174159_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985662_WhatsApp_Image_20231207_at_174159_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cfb",
    "name":
"externallmg_1701956985669_WhatsApp_Image_20231207_at_174159_2.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701956985669_WhatsApp_Image_20231207_at_174159_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd79d4a67a1d00410cfc",
```

```
    "name":  
    "externallmg_1701956985675_WhatsApp_Image_20231207_at_174159.jpeg",  
    "path": "cases/657173fb4999312746ce58cc/  
externallmg_1701956985675_WhatsApp_Image_20231207_at_174159.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6571cd79d4a67a1d00410cfd",  
    "name":  
    "externallmg_1701956985685_WhatsApp_Image_20231207_at_174200_1.jpeg",  
    "path": "cases/657173fb4999312746ce58cc/  
externallmg_1701956985685_WhatsApp_Image_20231207_at_174200_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6571cd79d4a67a1d00410cfe",  
    "name":  
    "externallmg_1701956985689_WhatsApp_Image_20231207_at_174200_2.jpeg",  
    "path": "cases/657173fb4999312746ce58cc/  
externallmg_1701956985689_WhatsApp_Image_20231207_at_174200_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6571cd8bd4a67a1d00410d3a",  
    "name":  
    "externallmg_1701957002912_WhatsApp_Image_20231207_at_174201_1.jpeg",  
    "path": "cases/657173fb4999312746ce58cc/  
externallmg_1701957002912_WhatsApp_Image_20231207_at_174201_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6571cd8bd4a67a1d00410d3b",  
    "name":  
    "externallmg_1701957002920_WhatsApp_Image_20231207_at_174201.jpeg",  
    "path": "cases/657173fb4999312746ce58cc/  
externallmg_1701957002920_WhatsApp_Image_20231207_at_174201.jpeg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d3c",
  "name":
"externallmg_1701957002940_WhatsApp_Image_20231207_at_174202_1.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002940_WhatsApp_Image_20231207_at_174202_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d3d",
  "name":
"externallmg_1701957002944_WhatsApp_Image_20231207_at_174202_2.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002944_WhatsApp_Image_20231207_at_174202_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d3e",
  "name":
"externallmg_1701957002962_WhatsApp_Image_20231207_at_174202.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002962_WhatsApp_Image_20231207_at_174202.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d3f",
  "name":
"externallmg_1701957002967_WhatsApp_Image_20231207_at_174203_1.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002967_WhatsApp_Image_20231207_at_174203_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d40",
  "name":
"externallmg_1701957002977_WhatsApp_Image_20231207_at_174203_2.jpeg",
```

```
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957002977_WhatsApp_Image_20231207_at_174203_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d41",
    "name":
"externallmg_1701957003000_WhatsApp_Image_20231207_at_174203.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003000_WhatsApp_Image_20231207_at_174203.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d42",
    "name":
"externallmg_1701957003006_WhatsApp_Image_20231207_at_174204_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003006_WhatsApp_Image_20231207_at_174204_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d43",
    "name":
"externallmg_1701957003011_WhatsApp_Image_20231207_at_174204.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003011_WhatsApp_Image_20231207_at_174204.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6571cd8bd4a67a1d00410d44",
    "name":
"externallmg_1701957003033_WhatsApp_Image_20231207_at_174205_1.jpeg",
    "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003033_WhatsApp_Image_20231207_at_174205_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6571cd8bd4a67a1d00410d45",
  "name":
"externallmg_1701957003038_WhatsApp_Image_20231207_at_174205_2.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003038_WhatsApp_Image_20231207_at_174205_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d46",
  "name":
"externallmg_1701957003044_WhatsApp_Image_20231207_at_174205.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003044_WhatsApp_Image_20231207_at_174205.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6571cd8bd4a67a1d00410d47",
  "name":
"externallmg_1701957003048_WhatsApp_Image_20231207_at_174206.jpeg",
  "path": "cases/657173fb4999312746ce58cc/
externallmg_1701957003048_WhatsApp_Image_20231207_at_174206.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"document_1701933003915_1701933080878_TAPAS_SAHOO_04.pdf",
    "filename": "1702015622848_document_1701933003915_1701933080878_TAPAS_
SAHOO_04.pdf",
    "path": "cases/657173fb4999312746ce58cc/processingDocuments/1702015622848
_document_1701933003915_1701933080878_TAPAS_SAHOO_04.pdf",
    "size": "6583794",
    "createdAt": "Fri Dec 08 2023 11:37:03 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname":
"document_1701933748974_1701933812510_TAPAS_SAHOO_OC.pdf",
    "filename": "1702015622987_document_1701933748974_1701933812510_TAPAS_
```



```
SAHOO_OC.pdf",
  "path": "cases/657173fb4999312746ce58cc/processingDocuments/1702015622987
_document_1701933748974_1701933812510_TAPAS_SAHOO_OC.pdf",
  "size": "2463581",
  "createdAt": "Fri Dec 08 2023 11:37:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname":
"document_1701933874963_1701933953531_TAPAS_SAHOO_AGREEMENT.pdf",
  "filename": "1702015623038_document_1701933874963_1701933953531_TAPAS_
SAHOO_AGREEMENT.pdf",
  "path": "cases/657173fb4999312746ce58cc/processingDocuments/1702015623038
_document_1701933874963_1701933953531_TAPAS_SAHOO_AGREEMENT.pdf",
  "size": "2349175",
  "createdAt": "Fri Dec 08 2023 11:37:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname":
"document_1701934028742_1701934107576_TAPAS_SAHOO_AGREEMENT_03.pdf",
  "filename": "1702015623082_document_1701934028742_1701934107576_TAPAS_
SAHOO_AGREEMENT_03.pdf",
  "path": "cases/657173fb4999312746ce58cc/processingDocuments/1702015623082
_document_1701934028742_1701934107576_TAPAS_SAHOO_AGREEMENT_03.pdf"
,
  "size": "1718677",
  "createdAt": "Fri Dec 08 2023 11:37:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname":
"document_1701934062266_1701934140532_TAPAS_SAHOO_AGREEMENT_02.pdf",
  "filename": "1702015623133_document_1701934062266_1701934140532_TAPAS_
SAHOO_AGREEMENT_02.pdf",
  "path": "cases/657173fb4999312746ce58cc/processingDocuments/1702015623133
_document_1701934062266_1701934140532_TAPAS_SAHOO_AGREEMENT_02.pdf"
,
  "size": "1262018",
  "createdAt": "Fri Dec 08 2023 11:37:03 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname":
"1701947649021_1698233439717_1697718211173_1696854326515_Calculation_1
(4).xlsx",
```

```
"filename": "1702031573913_1701947649021_1698233439717_1697718211173_1
696854326515_Calculation_1_4.xlsx",
"path": "cases/657173fb4999312746ce58cc/processingDocuments/1702031573913
_1701947649021_1698233439717_1697718211173_1696854326515_Calculation_1_4
.xlsx",
"size": "1890335",
"createdAt": "Fri Dec 08 2023 16:02:53 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-07T07:27:55.810Z",
"updatedAt": "2023-12-08T12:46:53.963Z",
"__v": 0,
"invoiceId": "657173fb4999312746ce58dc",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 104, 1st Floor, Building No 1, Narmada House, Plot
No. 4, Village - Waliv, Taluka - Vasai , District - Palghar, Vasai (East), PIN - 401 208,
State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "63fda584ce84bf289baadaf6",
"contactPersonName": "Mr. Kamlesh Bhatt ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contact Person",
"siteVisitContactNo": "9767014211",
"builtupPercentage": "10",
"carpetTotal": "368.04",
"extendOfSiteRemark": "",
"finalBuiltupArea": "467.79",
"finalCarpetArea": "425.26",
"finalSalableArea": "514.56",
"otherCarpetTotal": "43",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 382.00\nFlower Bed Area in Sq.
Ft. = 43.00\n\n",
"toBeAdded": "",
```

```

"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"finalMeasurementType": "Sq. Ft.",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "42.97",
"otherCompositionSaleableTotal": "0.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Re-Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 389.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri Dec 08 2023 11:20:06 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-12-07",
"buildingServicesRate": "2500",
"flatRate": "7000",
"landOtherRate": "4500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'00"	16'00"	144.00

Passage	5'4"	4'00"	21.33
Bedroom	9'3"	11'8"	107.92
Bathroom	5'10"	4'00"	23.33
WC	4'9"	3'00"	14.25
Kitchen	7'9"	7'10"	60.71
Other Composition :			
Flowerbed	9'2"	2'4"	21.39