

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb7e0add0a6d4cc439286c",
    "firstName": "Pushpa",
    "lastName": "Potinde",
    "mobileNo": "",
    "workMobileNo": "9403511861",
    "email": "cs.ho@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
```

```
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
```

```
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.021139623181714",
  "longitude": "73.8269477745409"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
}
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "35 & 36",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sagar Sparsh Apartment E & F Wing ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dr. Nanasaheb Dharmadhikari Marg, Amrutdham",
  "label": false
},
}
```

```
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": " Audumbar Nagar",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Manjuprabha Hospital",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "246/ 10",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "F-503",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```



```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "657817a29e3cbd4940a9639f",
"ownerName": "Tushar Khairnar ",
"ownerPhoneNo": "9604283582",
"fullAddress": " Flat No. F-503, 5th Floor, Sagar Sparsh Apartment E & F Wing , Near
Manjuprabha Hospital, Plot No. 35 & 36, Dr. Nanasaheb Dharmadhikari Marg,
Amrutdham, Audumbar Nagar, Village - Nashik, Taluka - Nashik, District - Nashik,
Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1702369174082_ATS.pdf",
    "path": "cases/657817a29e3cbd4940a9639f/document_1702369174082_ATS.pdf",
    "id": "222355",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Dec 12 2023 13:49:46 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "005558",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "854080",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 12 2023 13:49:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Tushar Khairnar ",
    "phone": "9604283582",
    "ownershipShare": ""
  }
]
```



```
    "email": "",
    "id": "977361"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96622",
    "name":
"externalImg_1702369273293_WhatsApp_Image_20231209_at_63310_PM_1.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externalImg_1702369273293_WhatsApp_Image_20231209_at_63310_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96623",
    "name":
"externalImg_1702369273437_WhatsApp_Image_20231209_at_63310_PM_2.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externalImg_1702369273437_WhatsApp_Image_20231209_at_63310_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96624",
    "name":
"externalImg_1702369273547_WhatsApp_Image_20231209_at_63310_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externalImg_1702369273547_WhatsApp_Image_20231209_at_63310_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "657817fb9e3cbd4940a96625",
    "name":
"externallmg_1702369273681_WhatsApp_Image_20231209_at_63311_PM_1.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273681_WhatsApp_Image_20231209_at_63311_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96626",
    "name":
"externallmg_1702369273737_WhatsApp_Image_20231209_at_63311_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273737_WhatsApp_Image_20231209_at_63311_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96627",
    "name":
"externallmg_1702369273814_WhatsApp_Image_20231209_at_63312_PM_1.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273814_WhatsApp_Image_20231209_at_63312_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96628",
    "name":
"externallmg_1702369273869_WhatsApp_Image_20231209_at_63312_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273869_WhatsApp_Image_20231209_at_63312_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96629",
    "name":
"externallmg_1702369273926_WhatsApp_Image_20231209_at_63313_PM_1.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273926_WhatsApp_Image_20231209_at_63313_PM_1.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a9662a",
  "name":
"externallmg_1702369273965_WhatsApp_Image_20231209_at_63313_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369273965_WhatsApp_Image_20231209_at_63313_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a9662b",
  "name":
"externallmg_1702369274001_WhatsApp_Image_20231209_at_63314_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274001_WhatsApp_Image_20231209_at_63314_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a9662c",
  "name":
"externallmg_1702369274058_WhatsApp_Image_20231209_at_63315_PM_1.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274058_WhatsApp_Image_20231209_at_63315_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a9662d",
  "name":
"externallmg_1702369274079_WhatsApp_Image_20231209_at_63315_PM_2.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274079_WhatsApp_Image_20231209_at_63315_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a9662e",
  "name":
"externallmg_1702369274133_WhatsApp_Image_20231209_at_63315_PM.jpeg",
```

```
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274133_WhatsApp_Image_20231209_at_63315_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a9662f",
    "name":
"externallmg_1702369274171_WhatsApp_Image_20231209_at_63316_PM_1.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274171_WhatsApp_Image_20231209_at_63316_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96630",
    "name":
"externallmg_1702369274260_WhatsApp_Image_20231209_at_63316_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274260_WhatsApp_Image_20231209_at_63316_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96631",
    "name":
"externallmg_1702369274297_WhatsApp_Image_20231209_at_63317_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274297_WhatsApp_Image_20231209_at_63317_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657817fb9e3cbd4940a96632",
    "name":
"externallmg_1702369274447_WhatsApp_Image_20231212_at_13822_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274447_WhatsApp_Image_20231212_at_13822_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "657817fb9e3cbd4940a96633",
  "name":
"externallmg_1702369274550_WhatsApp_Image_20231212_at_13824_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274550_WhatsApp_Image_20231212_at_13824_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a96634",
  "name":
"externallmg_1702369274923_WhatsApp_Image_20231212_at_13832_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274923_WhatsApp_Image_20231212_at_13832_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657817fb9e3cbd4940a96635",
  "name":
"externallmg_1702369274927_WhatsApp_Image_20231212_at_13836_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369274927_WhatsApp_Image_20231212_at_13836_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657818029e3cbd4940a96682",
  "name":
"externallmg_1702369281398_WhatsApp_Image_20231212_at_13839_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281398_WhatsApp_Image_20231212_at_13839_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657818029e3cbd4940a96683",
  "name":
"externallmg_1702369281418_WhatsApp_Image_20231212_at_13841_PM.jpeg",
  "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281418_WhatsApp_Image_20231212_at_13841_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657818029e3cbd4940a96684",
    "name":
"externallmg_1702369281465_WhatsApp_Image_20231212_at_13855_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281465_WhatsApp_Image_20231212_at_13855_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657818029e3cbd4940a96685",
    "name":
"externallmg_1702369281516_WhatsApp_Image_20231212_at_13901_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281516_WhatsApp_Image_20231212_at_13901_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657818029e3cbd4940a96686",
    "name":
"externallmg_1702369281801_WhatsApp_Image_20231212_at_13906_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281801_WhatsApp_Image_20231212_at_13906_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657818029e3cbd4940a96687",
    "name":
"externallmg_1702369281869_WhatsApp_Image_20231212_at_13908_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externallmg_1702369281869_WhatsApp_Image_20231212_at_13908_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657818029e3cbd4940a96688",
```

```

    "name":
    "externalImg_1702369281928_WhatsApp_Image_20231212_at_13910_PM.jpeg",
    "path": "cases/657817a29e3cbd4940a9639f/
externalImg_1702369281928_WhatsApp_Image_20231212_at_13910_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-12T08:19:46.565Z",
"updatedAt": "2023-12-12T08:21:22.186Z",
"__v": 0,
"invoiceId": "657817a29e3cbd4940a963a5",
"updatedAtBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Tushar Khairnar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9604283582"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			