

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b934"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230e06",
    "firstName": "Akash Gaykar",
    "email": "0_default_jssblaw@mtnl.net.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9819171133"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1424187",
    "discussWithPerson": "Akash Gaykar",
    "expectedFees": 712.0935000000001,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
  }
}
```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b934",
  "branchCode": "000001",
  "type": "BRANCH",
  "name": "Andheri (West) Branch",
  "email": "jssblaw@mtnl.net.in",
  "mobileNo": "02226206985",
  "alternateMobileNo": "",
  "address": "Shop No. 11 & 12, Rukmini Purushottam CHSL, J.P. Road, Near
Navarnag Cinema Bus Stop, Andheri (West), Mumbai - 400 058, State - Maharashtra,
Country - India. ",
  "ledgerName": "JANSEVA SAHAKARI BANK Andheri (West) Branch",
  "fax": " ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c8cdd2a5c3051014f62c65",
  "role": "SITEENGINEER",
  "firstName": "Bhavesh",
  "email": "freelancevaluer@gmail.com",
  "lastName": "Shelar",
  "mobileNo": "9272696074",
  "designation": "",
  "shortName": "BSS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/64c8cdd2a5c3051014f62c65/profilePhoto_1690881490040_3
25961526_225125063269350_5532229620043102208_n.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.77061693205292",
  "longitude": "72.7724360411165"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.7724360411165,
    19.77061693205292
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/12/2023 06:00 pm"
    },
    {
      "dateTime": "12/12/2023 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-17",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kambalgaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "D3 (As per Scheme Building No. 13)",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Boisar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Palghar",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Happinest",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Phase 4, Boisar Housing Complex",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "50",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "7",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 501",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Boisar",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```

}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Town_Planner,_Branch_Oû ce,_Palghar",
    "label": "Town Planner, Branch Oû ce, Palghar"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. D2",
    "west": "Internal Road",
    "south": "Open Plot",
    "east": "Building No. D4"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",

```

```
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.\n",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "5500.00",
  "depreciatedBuildingRate": "2500"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "35100",
  "landRate": "5070",
  "igrImage": "cases/657840ae9e3cbd4940a9e52b/igr_1703245795641_Image.png",
  "squareMeterGuideLineRate": "35100.00",
  "squareFeetGuideLineRate": "3261.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "95",
  "rate": "3121.00",
  "squareFeetGuideLineRate": "3121.00",
  "squareMeterGuideLineRate": "33599.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
```

```
"label": "Vacant"
},
"monthlyRent": "4,500",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per Local norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2019",
  "fullDate": "1/1/2019"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "4",
"totalLifeBuilding": "60",
"estimatedAge": "56",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
```



```
"area": "415.80",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/657840ae9e3cbd4940a9e52b/
routeMap_1703313234606_Image.png",
    "routeLat": "19.770500",
    "routeLng": "72.772639",
    "stationName": "Boisar",
    "routeDistance": "4.9 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ppnrud",
      "name": "ppnrud",
      "image": "cases/657840ae9e3cbd4940a9e52b/
routeMap_1703313501800_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
```

```
"totalKitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalSuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalInteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalElectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalExtraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalPotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalOthersRate": "0",
"finalTotal": "2079000.00",
"finalValue": "2079000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Dec 23 2023 13:08:36 GMT+0530 (India Standard Time)",
  "number": "2304149",
  "dayCount": "9",
  "monthCount": "378",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1297712.00",
  "selectedBuildUpValue": "415.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "657fca9965d49d78457a5ec8",
      "name":
"externalImg_1702873753155_WhatsApp_Image_20231218_at_094031_1.jpeg",
      "path": "cases/657840ae9e3cbd4940a9e52b/
externalImg_1702873753155_WhatsApp_Image_20231218_at_094031_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
```

```
    "_id": "657fca9965d49d78457a5ec3",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753136_WhatsApp_Image_20231218_at_094029.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "657fcaa665d49d78457a5f1e",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766090_WhatsApp_Image_20231218_at_094032.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "657fcaa665d49d78457a5f24",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766112_WhatsApp_Image_20231218_at_094034_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "657fcaa665d49d78457a5f1d",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766089_WhatsApp_Image_20231218_at_094032_2.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "657fca9965d49d78457a5eca",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753164_WhatsApp_Image_20231218_at_094031.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "657fca9965d49d78457a5ec8",
    "name": "Living Room",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753155_WhatsApp_Image_20231218_at_094031_1.jpeg",
    "orientation": "landscape"
  }
}
```

```
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "5093",
    "max": "7296"
  },
  "builtUpRateRange": {
    "min": "4244",
    "max": "6081"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "378.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "657840ae9e3cbd4940a9e52b",
"ownerName": "Mr. Harishchandra Gayadeen Prajapati Kumbhar & Mrs. Sabya H. Prajapati Kumbhar",
"ownerPhoneNo": "7977047895",
"appAddress": "Flat no 07 Ground floor Tower No D3 Happiness Boisar Phase IV Eklavya School Betegaon Kambalgaon Boisar East Plaghar 401501",
"remark": "Engg ko bolo visit key pahile call kare customers ko Phir jaane ko bola visit ko",
```

```
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "06/12/2022",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Mahindra Lifespace Developers Ltd. ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Harishchandra Gayadeen Prajapati Kumbhar & Mrs. Sabya H. Prajapati Kumbhar",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "8328 / 2022"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "496484",
    "path": "cases/657840ae9e3cbd4940a9e52b/document_1702379465796_1702379550111_Harish_kumbhar_flat_no_7.pdf",
    "fileName": "document_1702379465796_1702379550111_Harish_kumbhar_flat_no_7.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "11/03/2023",
      "remark": " Zilla Parishad, Palghar.",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "PMC / GP / PV / VS / 629"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703312196815_document_1702379465796_17023795501
11_Harish_kumbhar_flat_no_7.pdf",
    "path": "cases/657840ae9e3cbd4940a9e52b/document_1703312196815_document
_1702379465796_1702379550111_Harish_kumbhar_flat_no_7.pdf",
    "id": "317297",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Dec 23 2023 11:46:37 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "20/10/2017",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "P99000014293"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703312243654_document_1702379465796_17023795501
11_Harish_kumbhar_flat_no_7.pdf",
    "path": "cases/657840ae9e3cbd4940a9e52b/document_1703312243654_document
_1702379465796_1702379550111_Harish_kumbhar_flat_no_7.pdf",
    "id": "948851",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Dec 23 2023 11:47:24 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005570",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "173483",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 12 2023 16:44:54 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Harishchandra Gayadeen Prajapati Kumbhar & Mrs. Sabya H.
Prajapati Kumbhar",
  "phone": "7977047895",
  "ownershipShare": "",
  "email": "",
  "id": "964427"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "237385",
    "name": "Living Room",
    "length": "9.67",
    "length1": "9",
    "length2": "8",
    "width": "12.67",
    "width1": "12",
    "width2": "8",
    "totalArea": "122.44",
    "images": [],
    "extraAreas": [],
    "finalArea": "122.44"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "11.75",
    "length1": "11",
    "length2": "9",
    "width": "6.67",
    "width1": "6",
    "width2": "8",
    "totalArea": "78.33",
    "images": [],
    "extraAreas": [],
```

```
"finalArea": "78.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.67",
  "length1": "10",
  "length2": "8",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "74.67",
  "images": [],
  "finalArea": "74.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "16.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "",
```

```
"length1": "6",
"length2": "0",
"width": "",
"width1": "1",
"width2": "5",
"totalArea": "8.50",
"images": [],
"finalArea": "8.50",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "62.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "62.50"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "35.12",
    "totalAreaDocument": "378",
    "docBultupPercentage": "10",
    "docFinalBultUp": "415.80",
```

```
    "docFinalBuiltUpSquareMeter": "38.63",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "285536"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "658577f33ac9822dbc9578c1",
    "property": "Residential Flat",
    "area": "380",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "2200000",
    "expectedRate": "5789.47",
    "builtUpExpectedRate": "4824.56",
    "image": "cases/657840ae9e3cbd4940a9e52b/
indicator_1703245200191_Image.png",
    "squareMeter": "35.30",
    "id": "637400"
  },
  {
    "printlnReport": true,
    "_id": "658577f33ac9822dbc9578c2",
    "property": "Residential Flat",
    "area": "270",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "1970000",
    "expectedRate": "7296.30",
    "builtUpExpectedRate": "6080.25",
    "image": "cases/657840ae9e3cbd4940a9e52b/
indicator_1703245228936_Image.png",
    "squareMeter": "25.08",
    "id": "696686"
  },
  {
```

```
"printlnReport": true,
  "_id": "658577f33ac9822dbc9578c3",
  "property": "Residential Flat",
  "area": "432",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "2200000",
  "expectedRate": "5092.59",
  "builtUpExpectedRate": "4243.83",
  "image": "cases/657840ae9e3cbd4940a9e52b/
indicator_1703245265874_Image.png",
  "squareMeter": "40.13",
  "id": "504141"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec2",
    "name":
"externallmg_1702873753131_WhatsApp_Image_20231218_at_094029_1.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753131_WhatsApp_Image_20231218_at_094029_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec3",
    "name":
"externallmg_1702873753136_WhatsApp_Image_20231218_at_094029.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753136_WhatsApp_Image_20231218_at_094029.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec4",
    "name":
"externallmg_1702873753138_WhatsApp_Image_20231218_at_094030_1.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753138_WhatsApp_Image_20231218_at_094030_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec5",
    "name":
"externallmg_1702873753144_WhatsApp_Image_20231218_at_094030_2.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753144_WhatsApp_Image_20231218_at_094030_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec6",
    "name":
"externallmg_1702873753148_WhatsApp_Image_20231218_at_094030_3.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753148_WhatsApp_Image_20231218_at_094030_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec7",
    "name":
"externallmg_1702873753149_WhatsApp_Image_20231218_at_094030.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753149_WhatsApp_Image_20231218_at_094030.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec8",
    "name":
"externallmg_1702873753155_WhatsApp_Image_20231218_at_094031_1.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753155_WhatsApp_Image_20231218_at_094031_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fca9965d49d78457a5ec9",
```

```
    "name":
"externallmg_1702873753160_WhatsApp_Image_20231218_at_094031_2.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753160_WhatsApp_Image_20231218_at_094031_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fca9965d49d78457a5eca",
  "name":
"externallmg_1702873753164_WhatsApp_Image_20231218_at_094031.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753164_WhatsApp_Image_20231218_at_094031.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fca9965d49d78457a5ecb",
  "name":
"externallmg_1702873753165_WhatsApp_Image_20231218_at_094032_1.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873753165_WhatsApp_Image_20231218_at_094032_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f1d",
  "name":
"externallmg_1702873766089_WhatsApp_Image_20231218_at_094032_2.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766089_WhatsApp_Image_20231218_at_094032_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f1e",
  "name":
"externallmg_1702873766090_WhatsApp_Image_20231218_at_094032.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766090_WhatsApp_Image_20231218_at_094032.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f1f",
  "name":
"externallmg_1702873766092_WhatsApp_Image_20231218_at_094033_1.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766092_WhatsApp_Image_20231218_at_094033_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f20",
  "name":
"externallmg_1702873766098_WhatsApp_Image_20231218_at_094033_2.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766098_WhatsApp_Image_20231218_at_094033_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f21",
  "name":
"externallmg_1702873766101_WhatsApp_Image_20231218_at_094033_3.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766101_WhatsApp_Image_20231218_at_094033_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f22",
  "name":
"externallmg_1702873766105_WhatsApp_Image_20231218_at_094033.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766105_WhatsApp_Image_20231218_at_094033.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f23",
  "name":
"externallmg_1702873766111_WhatsApp_Image_20231218_at_094034_1.jpeg",
```

```
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766111_WhatsApp_Image_20231218_at_094034_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fcaa665d49d78457a5f24",
    "name":
"externallmg_1702873766112_WhatsApp_Image_20231218_at_094034_2.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766112_WhatsApp_Image_20231218_at_094034_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fcaa665d49d78457a5f25",
    "name":
"externallmg_1702873766113_WhatsApp_Image_20231218_at_094034.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766113_WhatsApp_Image_20231218_at_094034.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fcaa665d49d78457a5f26",
    "name":
"externallmg_1702873766116_WhatsApp_Image_20231218_at_094035_1.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766116_WhatsApp_Image_20231218_at_094035_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fcaa665d49d78457a5f27",
    "name":
"externallmg_1702873766119_WhatsApp_Image_20231218_at_094035_2.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766119_WhatsApp_Image_20231218_at_094035_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "657fcaa665d49d78457a5f28",
  "name":
"externallmg_1702873766123_WhatsApp_Image_20231218_at_094035_3.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766123_WhatsApp_Image_20231218_at_094035_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f29",
  "name":
"externallmg_1702873766124_WhatsApp_Image_20231218_at_094035.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766124_WhatsApp_Image_20231218_at_094035.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f2a",
  "name":
"externallmg_1702873766129_WhatsApp_Image_20231218_at_094036_1.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766129_WhatsApp_Image_20231218_at_094036_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f2b",
  "name":
"externallmg_1702873766130_WhatsApp_Image_20231218_at_094036_2.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766130_WhatsApp_Image_20231218_at_094036_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "657fcaa665d49d78457a5f2c",
  "name":
"externallmg_1702873766133_WhatsApp_Image_20231218_at_094036.jpeg",
  "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766133_WhatsApp_Image_20231218_at_094036.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "657fcaa665d49d78457a5f2d",
    "name":
"externallmg_1702873766138_WhatsApp_Image_20231218_at_094037.jpeg",
    "path": "cases/657840ae9e3cbd4940a9e52b/
externallmg_1702873766138_WhatsApp_Image_20231218_at_094037.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65813e8665d49d78457ccc80",
    "note": "Pending For Value Confirmation From Bank Side",
    "taskId": "6578549a9e3cbd4940aa2bd5",
    "createdAt": "2023-12-19T06:56:06.380Z"
  }
],
"createdAt": "2023-12-12T11:14:54.174Z",
"updatedAt": "2023-12-23T07:38:39.266Z",
"__v": 0,
"invoiceId": "657840ae9e3cbd4940a9e538",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 7, Ground Floor, Building No D3 (As per Scheme
Building No. 13), Happinest, Plot No. 1, Phase 4, Boisar Housing Complex, Village -
```

Kambalgaon, Boisar, Taluka - Palghar, District - Palghar , Boisar, PIN - 401 501, State - Maharashtra, Country - India",

"updatedBy": "64cde526dc9f3034f3fefa49",

"addressForMap": "",

"caseReferredBy": "60af6ae22ffdf65bcd65861d",

"contactPersonName": "Mr. Harishchandra Gayadeen Prajapati Kumbhar ",

"email": "",

"isExternal": "false",

"isUrgent": "false",

"ownershipShare": "",

"purchaseValueAsPerDocument": "",

"relationWithOwner": "Owner",

"siteVisitContactNo": "7977047895",

"buildingServicesRate": "2500",

"finalAreaType": "Carpet Area",

"finalAsPerArea": "Agreement For Sale",

"finalBuiltUpPercentage": "10",

"finalCarpetConvertToBuiltUpPer": "10",

"finalMeasurementType": "Sq. Ft.",

"finalValuationAreaString": "Carpet Area in Sq. Ft. = 378.00",

"flatRate": "5500",

"landOtherRate": "3000",

"shopDetails": {

  "typeOfShops": {

    "label": "Independent Building",

    "value": "Independent\_Building"

  },

  "roadFacing": false,

  "mall": false

},

"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom + Passage",

"carpetTotal": "362.8",

"otherCarpetTotal": "0.00",

"builtupPercentage": "10",

"finalBuiltupArea": "399.08",

"finalCarpetArea": "362.80",

"finalSalableArea": "438.99",

"salablePercentage": "10",

"toBeAdded": "",

"extendOfSiteRemark": "",

"siteMeasurementRemark": "\n",

"finalSaleablePercentage": "0",

"landDetails": {

  "holdType": {

    "label": "Free Hold",

```

"value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Sat Dec 23 2023 11:40:43 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-17",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'8"	12'8"	122.44
Kitchen	11'9"	6'8"	78.33
Bedroom	10'8"	7'00"	74.67
WC	5'2"	3'2"	16.36
Bathroom	6'0"	1'5"	8.50
Passage	10'5"	6'00"	62.50
Other Composition :			