

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312bd",
    "firstName": "Swarup",
    "email": "1racpcghatkopar.sanctions@sbi.co.in",
    "mobileNo": "-",
    "workMobileNo": "8668951779",
    "lastName": " Shivane"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8000000",
    "discussWithPerson": "Swarup",
    "expectedFees": 4000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },
]
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.112614100113937",
  "longitude": "72.93435830622911"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.93435830622911,
```

```
19.112614100113937
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-22",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-22",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Hariyali ",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vikhroli (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swastik Tulip",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kannamwar Nagar\t",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "113(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "356(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1108",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 083",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MHADA",
"label": "MHADA"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Vikhroli Flyover",
"west": "Proposed Building No. 8",
"south": "Atmaram Surve Marg ",
"east": "Proposed Building No. 11"
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available ",
"east": "Details not available ",
"south": "Details not available ",
"west": "Details not available "
},
"asPerDocument": {
"north": "Details not available ",
"east": "Details not available ",
"south": "Details not available ",
"west": "Details not available "
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
    },
    "extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 1 Bedroom + Living Room + Kitchen + 2 Toilets + chajja Area.",
    "dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MHADA / 9 / 1182 / 2022 dated 14.10.2021 issued by MHADA.",
    "approvePlanVerified": "No",
    "empannelledOfApprovePlan": "Building is under construction "
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "0",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "buildingServicesDepreciatedRate": "0",
    "depreciatedCostOfConstruction": "21300.00",
    "depreciatedBuildingRate": "3000"
  },
  "igrRate": {
    "propertyName": "Residential",
    "rate": "139830",
    "landRate": "58970",
    "igrImage": "cases/6583f93c65d49d784580d2a8/igr_1703243491522_Image.png",
    "squareMeterGuideLineRate": "153813.00",
    "squareFeetGuideLineRate": "14290.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "10",
    "depreciationPercentage": "0",
    "rate": "139830.00",
    "squareMeterGuideLineRate": "153813.00",
    "squareFeetGuideLineRate": "14290.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Building_Under_Construction",
      "label": "Building Under Construction"
    }
  },
  "monthlyRent": "21,000",
```

```
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MHADA norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Stilt Car Parking Space ",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
```

```
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
```

```
"label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "11",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "441.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
}
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6583f93c65d49d784580d2a8/
routeMap_1703316312745_Image.png",
    "routeLat": "19.112635",
    "routeLng": "72.934364",
    "stationName": "Vikhroli",
    "routeDistance": "1.00 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "s2iosb",
      "name": "s2iosb",
      "image": "cases/6583f93c65d49d784580d2a8/
routeMap_1703316179310_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8541300.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8541300.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "1",
"percentage": "1.7391304347826086",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "11.74",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "6303319.00",
"selectedBuildUpValue": "441.10",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "658549f278f7547c095cf6a6",
"name": "externalImg_1703234002745_1703234090014_image_1.jpeg",
"path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703234002745_1703234090014_image_1.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "658549f278f7547c095cf6a6",
"name": "externalImg_1703234002745_1703234090014_image_1.jpeg",
"path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703234002745_1703234090014_image_1.jpeg",
"orientation": "landscape"
}
},
{
"status": false,
"_id": "658549f278f7547c095cf6a8",
"name": "externalImg_1703234014424_1703234090014_image_3.jpeg",
"path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703234014424_1703234090014_image_3.jpeg",
"orientation": "portrait"
}
},
}
```

```
{
  "status": false,
  "_id": "658549f278f7547c095cf6a9",
  "name": "externallmg_1703234016284_1703234090014_image_4.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703234016284_1703234090014_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "658549f278f7547c095cf6a7",
  "name": "externallmg_1703234006691_1703234090014_image_2.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703234006691_1703234090014_image_2.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "21099",
    "max": "22414"
  },
  "builtUpRateRange": {
    "min": "19182",
    "max": "20377"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```



```
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "401.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "6583f93c65d49d784580d2a8",
"ownerName": "Mr. Michael Coutinho & Mrs. Delia Michael Coutinho ",
"ownerPhoneNo": "9920769007",
"appAddress": "Flat no. 1108, 11th Floor, Swastik Tulip, Village - Hariyali, Kannamwar
Nagar Vikroli East",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "22/05/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Swastik Homes",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Michael Coutinho & Mrs. Delia Michael Coutinho ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "9806 / 2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "500264",
    "path": "cases/6583f93c65d49d784580d2a8/
document_1703147813293_1703147906581_CamScanner_12212023_131819.pdf",
```

```
"fileName":
"document_1703147813293_1703147906581_CamScanner_12212023_131819.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/01/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MH / EE / (BP) / GM / MHADA-9 / 1182 / 2023 / CC / 1 / New"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1703314748452_document_1703147813293_17031479065
81_CamScanner_12212023_131819.pdf",
"path": "cases/6583f93c65d49d784580d2a8/document_1703314748452_document
_1703147813293_1703147906581_CamScanner_12212023_131819.pdf",
"id": "193763",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Dec 23 2023 12:29:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/10/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    }
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  }
},
}
```

```
    "No": "MHADA / 9 / 1182 / 2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "734005",
  "path": "cases/6583f93c65d49d784580d2a8/document_1703314814593_plan.pdf",
  "fileName": "document_1703314814593_plan.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "24/01/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51800049000"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703314847870_document_1703147813293_17031479065
81_CamScanner_12212023_131819.pdf",
  "path": "cases/6583f93c65d49d784580d2a8/document_1703314847870_document
_1703147813293_1703147906581_CamScanner_12212023_131819.pdf",
  "id": "606859",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Sat Dec 23 2023 12:30:48 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005802",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "393923",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 21 2023 14:07:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Michael Coutinho & Mrs. Delia Michael Coutinho ",
    "phone": "9920769007",
```

```
"ownershipShare": "",
"email": "",
"id": "942745"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "37.25",
  "totalAreaDocument": "401",
  "docBuiltpUpPercentage": "10",
  "docFinalBuiltpUp": "441.10",
  "docFinalBuiltpUpSquareMeter": "40.98",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "757955"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65856eed3ac9822dbc954dc4",
  "property": "Swastik Tulip, Vikhroli",
  "area": "401",
  "builtpUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Dwello.com",
  "expectedPrice": "8988000",
```

```
    "expectedRate": "22413.97",
    "builtUpExpectedRate": "20376.33",
    "image": "cases/6583f93c65d49d784580d2a8/
indicator_1703243038888_Image.png",
    "squareMeter": "37.25",
    "id": "467145"
  },
  {
    "printlnReport": true,
    "_id": "65856eed3ac9822dbc954dc5",
    "property": "Swastik Tulip, Vikhroli",
    "area": "640",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "1",
    "source": "magic_bricks",
    "expectedPrice": "14200000",
    "expectedRate": "22187.50",
    "builtUpExpectedRate": "20170.45",
    "image": "cases/6583f93c65d49d784580d2a8/
indicator_1703243104001_Image.png",
    "squareMeter": "59.46",
    "id": "658055"
  },
  {
    "printlnReport": true,
    "_id": "65856eed3ac9822dbc954dc6",
    "property": "Swastik Tulip, Vikhroli",
    "area": "564",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Commonfloor.com",
    "expectedPrice": "11900000",
    "expectedRate": "21099.29",
    "builtUpExpectedRate": "19181.17",
    "image": "cases/6583f93c65d49d784580d2a8/
indicator_1703243401720_Image.png",
    "squareMeter": "52.40",
    "id": "765439"
  }
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658549f278f7547c095cf6a5",
    "name": "externalimg_1703233999594_1703234090014_image_0.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalimg_1703233999594_1703234090014_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658549f278f7547c095cf6a6",
    "name": "externalimg_1703234002745_1703234090014_image_1.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalimg_1703234002745_1703234090014_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658549f278f7547c095cf6a7",
    "name": "externalimg_1703234006691_1703234090014_image_2.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalimg_1703234006691_1703234090014_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658549f278f7547c095cf6a8",
    "name": "externalimg_1703234014424_1703234090014_image_3.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalimg_1703234014424_1703234090014_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658549f278f7547c095cf6a9",
    "name": "externalimg_1703234016284_1703234090014_image_4.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalimg_1703234016284_1703234090014_image_4.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658549f278f7547c095cf6aa",
  "name": "externallmg_1703233915195_1703234006794_image_0.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703233915195_1703234006794_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658549f278f7547c095cf6ab",
  "name": "externallmg_1703233917554_1703234006794_image_1.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703233917554_1703234006794_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658549f278f7547c095cf6ac",
  "name": "externallmg_1703233920591_1703234006794_image_2.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703233920591_1703234006794_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658549f278f7547c095cf6ad",
  "name": "externallmg_1703233924460_1703234006794_image_4.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703233924460_1703234006794_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "658549f278f7547c095cf6ae",
  "name": "externallmg_1703233926845_1703234006794_image_5.jpeg",
  "path": "cases/6583f93c65d49d784580d2a8/
externallmg_1703233926845_1703234006794_image_5.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "658549f278f7547c095cf6af",
    "name": "externalImg_1703233932005_1703234006794_image_6.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703233932005_1703234006794_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "658549f278f7547c095cf6b0",
    "name": "externalImg_1703233937780_1703234006794_image_7.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703233937780_1703234006794_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "658549f278f7547c095cf6b1",
    "name": "externalImg_1703233975830_1703234068449_image_0.jpeg",
    "path": "cases/6583f93c65d49d784580d2a8/
externalImg_1703233975830_1703234068449_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1703145651214_Calculation.xlsx",
    "filename": "1703243525512_1703145651214_Calculation.xlsx",
    "path": "cases/6583f93c65d49d784580d2a8/
processingDocuments/1703243525512_1703145651214_Calculation.xlsx",
    "size": "1628438",
    "createdAt": "Fri Dec 22 2023 16:42:05 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-21T08:37:16.968Z",
"updatedAt": "2023-12-23T10:55:16.854Z",
"__v": 0,
"invoiceId": "6583f93d65d49d784580d2ae",
```



```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1108, 11th Floor, Swastik Tulip, Kannamwar Nagar
\, Village - Hariyali , Taluka - Kurla, District - Mumbai Suburban , Vikhroli (East), PIN -
400 083, State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Miss. Priyanka Kamble",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8976181655",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 401.00",
"flatRate": "21300",
"landOtherRate": "18300",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
```

```

    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Dec 23 2023 12:17:44 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-22"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			