

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500000",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 1250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "64535eb5ee347304f2a3005f",
  "role": "DELIVERYPERSON",
  "firstName": "Hemant",
  "email": "hkadam113@gmail.com",
  "lastName": "Kadam",
  "mobileNo": "9819455052",
  "shortName": "Hemant",
  "workWithDocumentMaker": "60b7189d2ffdf65bcd65882b",
  "profilePhoto": "users/64535eb5ee347304f2a3005f/
profilePhoto_1687240220512_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
```

```
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.08035397337514",
  "longitude": "72.88527153432369"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88527153432369,
    19.08035397337514
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/12/2023 04:30 pm"
    },
    {
      "dateTime": "23/12/2023 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kohinoor City A CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kirol ROad",
  "label": false
},
}
```

```
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off L B S Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "875",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```



```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6586bc895b664a64c316e3d9",
"ownerName": "Suraj Vijay Kulkarni ",
"ownerPhoneNo": "8169697648",
"appAddress": "Flat no. 876 Kohinoor City A - CHS LTD Kurla ( w) 400070 ",
"remark": "Amalgamated flats hai 875 , 876 ",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1703488460664_Agreement_875.pdf",
    "path": "cases/6586bc895b664a64c316e3d9/
document_1703488460664_Agreement_875.pdf",
    "id": "985172",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Mon Dec 25 2023 12:44:20 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005865",
"createdBy": "64535eb5ee347304f2a3005f",
"caseHistory": [
  {
    "id": "145330",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 23 2023 16:25:05 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Suraj Vijay Kulkarni ",
    "phone": "8169697648",
    "ownershipShare": "",
    "email": "",
    "id": "654640"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```



```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9eefd",
    "name": "externalImg_1703488476520_externalImg_1703267252414_17032673424
45_image_0.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalImg_1703488476520_external
mg_1703267252414_1703267342445_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9eefe",
    "name": "externalImg_1703488476543_externalImg_1703267252617_17032673424
45_image_1.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalImg_1703488476543_external
mg_1703267252617_1703267342445_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9eeff",
    "name": "externalImg_1703488476579_externalImg_1703267252736_17032673424
45_image_2.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalImg_1703488476579_external
mg_1703267252736_1703267342445_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef00",
    "name": "externalImg_1703488476617_externalImg_1703267296107_17032673810
97_image_0.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalImg_1703488476617_external
mg_1703267296107_1703267381097_image_0.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef01",
    "name": "externallmg_1703488476656_externallmg_1703267296261_1703267381097_image_1.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476656_externallmg_1703267296261_1703267381097_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef02",
    "name": "externallmg_1703488476708_externallmg_1703267296596_1703267381097_image_2.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476708_externallmg_1703267296596_1703267381097_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef03",
    "name": "externallmg_1703488476744_externallmg_1703267296744_1703267381097_image_3.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476744_externallmg_1703267296744_1703267381097_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef04",
    "name": "externallmg_1703488476776_externallmg_1703267296998_1703267381097_image_4.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476776_externallmg_1703267296998_1703267381097_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bddb7b4df714da9ef05",
    "name": "externallmg_1703488476808_externallmg_1703267297313_1703267381097_image_5.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476808_externallmg_1703267297313_1703267381097_image_5.jpeg",
    "orientation": "portrait"
  }
]
```

```
97_image_5.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476808_externallmg_1703267297313_1703267381097_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892bddb7b4df714da9ef06",
  "name": "externallmg_1703488476818_externallmg_1703267297522_1703267381097_image_6.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476818_externallmg_1703267297522_1703267381097_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892bddb7b4df714da9ef07",
  "name": "externallmg_1703488476861_externallmg_1703267297900_1703267381097_image_7.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476861_externallmg_1703267297900_1703267381097_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892bddb7b4df714da9ef08",
  "name": "externallmg_1703488476890_externallmg_1703267298076_1703267381097_image_8.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488476890_externallmg_1703267298076_1703267381097_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892be4b7b4df714da9ef58",
  "name": "externallmg_1703488483703_externallmg_1703267298373_1703267381097_image_9.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483703_externallmg_1703267298373_1703267381097_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef59",
    "name": "externallmg_1703488483736_externallmg_1703267298646_17032673810
97_image_10.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483736_externall
mg_1703267298646_1703267381097_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef5a",
    "name": "externallmg_1703488483758_externallmg_1703267298921_17032673810
97_image_11.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483758_externall
mg_1703267298921_1703267381097_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef5b",
    "name": "externallmg_1703488483803_externallmg_1703267338606_17032674201
91_image_0.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483803_externall
mg_1703267338606_1703267420191_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef5c",
    "name": "externallmg_1703488483809_externallmg_1703267338681_17032674201
91_image_1.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483809_externall
mg_1703267338681_1703267420191_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef5d",
    "name": "externallmg_1703488483832_externallmg_1703267339067_17032674201
91_image_2.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483832_externall
```

```
mg_1703267339067_1703267420191_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892be4b7b4df714da9ef5e",
  "name": "externallmg_1703488483876_externallmg_1703267339499_17032674201
91_image_3.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483876_externall
mg_1703267339499_1703267420191_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892be4b7b4df714da9ef5f",
  "name": "externallmg_1703488483910_externallmg_1703267339999_17032674201
91_image_4.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483910_externall
mg_1703267339999_1703267420191_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892be4b7b4df714da9ef60",
  "name": "externallmg_1703488483942_externallmg_1703267340297_17032674201
91_image_5.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483942_externall
mg_1703267340297_1703267420191_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892be4b7b4df714da9ef61",
  "name": "externallmg_1703488483991_externallmg_1703267340737_17032674201
91_image_6.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488483991_externall
mg_1703267340737_1703267420191_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65892be4b7b4df714da9ef62",
    "name": "externalimg_1703488484039_externalimg_1703267341019_17032674201
91_image_7.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488484039_external
mg_1703267341019_1703267420191_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892be4b7b4df714da9ef63",
    "name": "externalimg_1703488484076_externalimg_1703267341312_17032674201
91_image_8.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488484076_external
mg_1703267341312_1703267420191_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efcf",
    "name": "externalimg_1703488496870_externalimg_1703267341504_17032674201
91_image_9.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488496870_external
mg_1703267341504_1703267420191_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd0",
    "name": "externalimg_1703488496894_externalimg_1703267341768_17032674201
91_image_10.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488496894_external
mg_1703267341768_1703267420191_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd1",
    "name": "externalimg_1703488496919_externalimg_1703267341964_17032674201
91_image_11.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488496919_external
mg_1703267341964_1703267420191_image_11.jpeg",
    "orientation": "portrait"
  }
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd2",
    "name": "externallmg_1703488496944_externallmg_1703267342143_1703267420191_image_12.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488496944_externallmg_1703267342143_1703267420191_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd3",
    "name": "externallmg_1703488496987_externallmg_1703267342409_1703267420191_image_13.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488496987_externallmg_1703267342409_1703267420191_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd4",
    "name": "externallmg_1703488497016_externallmg_1703267342591_1703267420191_image_14.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488497016_externallmg_1703267342591_1703267420191_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd5",
    "name": "externallmg_1703488497057_externallmg_1703267342999_1703267420191_image_15.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488497057_externallmg_1703267342999_1703267420191_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892bf1b7b4df714da9efd6",
    "name": "externallmg_1703488497081_externallmg_1703267343274_1703267420191_image_16.jpeg",
    "path": "cases/6586bc895b664a64c316e3d9/externallmg_1703488497081_externallmg_1703267343274_1703267420191_image_16.jpeg",
    "orientation": "landscape"
  }
]
```

```
91_image_16.jpeg",
  "path": "cases/6586bc895b664a64c316e3d9/externalimg_1703488497081_externall
mg_1703267343274_1703267420191_image_16.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "Calculation.xlsx",
    "filename": "1703330120044_Calculation.xlsx",
    "path": "cases/6586bc895b664a64c316e3d9/
processingDocuments/1703330120044_Calculation.xlsx",
    "size": "2329859",
    "createdAt": "Sat Dec 23 2023 16:45:20 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-23T10:55:05.663Z",
"updatedAt": "2023-12-25T07:14:57.220Z",
"__v": 0,
"invoiceId": "6586bc895b664a64c316e3df",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 875, 8th Floor, Kohinoor City A CHSL, Kirol ROad,
Off L B S Road, Village - Kurla, Kurla West, Mumbai, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "64535eb5ee347304f2a3005f",
"contactPersonName": "Suraj Vijay Kulkarni ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8169697648"
}
```


Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			