

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4607000",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 2303.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64d09914dc9f3034f3008833",
"role": "SITEENGINEER+MAKAR",
"firstName": "Meetal",
"email": "meetalirasal@gmail.com",
"lastName": "Rasal",
"mobileNo": "7397882283",
"designation": "Junior Architect",
"shortName": "MR",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.343109610872414",
  "longitude": "72.82350216441749"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82350216441749,
    19.343109610872414
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-25",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-25",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
]
```

```
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Juchandra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "8",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "1",
    "label": true
  },
}
```

```
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Naigaon (East), Palghar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Krishna Bhoomi",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
```

```
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
```



```
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "358B",
"label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "5",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "803",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
```

```
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 208",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
```

```
"roof": {
  "value": "Proposed_R.C.C._Slab",
  "label": "Proposed R.C.C. Slab"
},
"flooring": {
  "value": "Proposed_Vitrified_tiles_flooring",
  "label": "Proposed Vitrified tiles flooring"
},
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
```

```
"label": "No"
},
"asPerActualAgreement": {
  "north": "Open Plot",
  "west": "Jay Vijay Nagar Building",
  "south": "B. G. Kini Road",
  "east": "Internal Road & Parasnath Building"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per agreement sale plan, the composition of flat will be 2
Bedrooms + Living Room + Kitchen + 2 Toilets + Passage.",
"dateOfIssusApprovePlan": "Copy of Approved Plan No. VCMC / TP / CC / VP /
6450 / 464 / 2021-2022 Dated 31.12.2021 issued by Vasai Virar City Municipal
Corporation.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
```

```
"igrRate": {
  "propertyName": "Residential",
  "rate": "52000",
  "landRate": "6860",
  "igrImage": "cases/6586c58d5b664a64c31708e4/igr_1703579813325_Image.png",
  "squareMeterGuideLineRate": "54600.00",
  "squareFeetGuideLineRate": "5073.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "52000.00",
  "squareMeterGuideLineRate": "54600.00",
  "squareFeetGuideLineRate": "5073.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "12,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "carParking": "Proposed Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Proposed_Plain_Looking",
    "label": "Proposed Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
    "fullDate": "1/1/2025"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "Proposed_R.C.C._Framed_Structure",
    "label": "Proposed R.C.C Framed Structure"
  },
  "typeOfFoundation": {
    "value": "Proposed_R.C.C._Foundation",
    "label": "Proposed R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"materialUsedList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"buildingSpecification": {
"value": "Proposed_Standard",
"label": "Proposed Standard"
},
"structuralSafety": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceIssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
}
```

```
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "8",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "596.20",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6586c58d5b664a64c31708e4/
routeMap_1703590256360_Image.png",
    "routeLat": "19.362528",
    "routeLng": "72.862111",
    "stationName": "Naigaon",
    "routeDistance": "3.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
```



```
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "1aye2d",
    "name": "1aye2d",
    "image": "cases/6586c58d5b664a64c31708e4/
routeMap_1703590179406_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4878000.00",
```

```
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4878000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3024523.00",
  "selectedBuildUpValue": "596.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65892e04b7b4df714da9f80e",
      "name": "externallmg_1703489006085_1703489075283_image_8.jpeg",
      "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489006085_1703489075283_image_8.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65892e04b7b4df714da9f811",
      "name": "externallmg_1703489008842_1703489075283_image_11.jpeg",
      "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489008842_1703489075283_image_11.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65892e04b7b4df714da9f808",
      "name": "externallmg_1703488990385_1703489075283_image_2.jpeg",
      "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488990385_1703489075283_image_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65892e04b7b4df714da9f809",
      "name": "externallmg_1703488994030_1703489075283_image_3.jpeg",
      "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488994030_1703489075283_image_3.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "65892e04b7b4df714da9f80a",
      "name": "externallmg_1703488999265_1703489075283_image_4.jpeg",
      "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488999265_1703489075283_image_4.jpeg",
      "orientation": "landscape"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "65892e04b7b4df714da9f80d",
  "name": "externallmg_1703489005272_1703489075283_image_7.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489005272_1703489075283_image_7.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65892e04b7b4df714da9f80f",
  "name": "externallmg_1703489007282_1703489075283_image_9.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489007282_1703489075283_image_9.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65892e04b7b4df714da9f80e",
  "name": "externallmg_1703489006085_1703489075283_image_8.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489006085_1703489075283_image_8.jpeg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65892e04b7b4df714da9f814",
  "name": "externallmg_1703489009389_1703489075283_image_14.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489009389_1703489075283_image_14.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9402",
    "max": "11594"
  },
  "builtUpRateRange": {
    "min": "8548",
    "max": "10541"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```



```
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "542.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6586c58d5b664a64c31708e4",
"ownerName": "Mrs. Reeta Ramesh Yadav",
"ownerPhoneNo": "9892360047",
"appAddress": "Flat no 803 8 th floor B-wing Shree Krishna Bhoomi Village Juchandra
Naigaon East 401208",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
  },
  "inputs": {
    "documentDate": "31/03/2023",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    }
  },
},
```

```
"Promoter": "M/s. Shree Krishna Buildcon",
"to": {
  "value": "Purchaser",
  "label": "Purchaser"
},
"Purchaser": "Mrs. Reeta Ramesh Yadav",
"number": {
  "value": "Registration_No",
  "label": "Registration No"
},
"Registration_No": "5701/2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1703589357181_1703586576960_document_16813837341
83_ReetaRameshYadav_SBI_Racpc_Borivali_West_1.pdf",
"path": "cases/6586c58d5b664a64c31708e4/document_1703589357181_17035865
76960_document_1681383734183_ReetaRameshYadav_SBI_Racpc_Borivali_West_1.
pdf",
"id": "828462",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Dec 26 2023 16:45:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "28/04/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P99000034992"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1703589404445_P99000034992.pdf",
  "path": "cases/6586c58d5b664a64c31708e4/
document_1703589404445_P99000034992.pdf",
  "id": "377899",
```

```
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Dec 26 2023 16:46:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "31/12/2021",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "VVCMC / TP / CC / VP / 6450 / 464 / 2021-2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1703589480519_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/6586c58d5b664a64c31708e4/document_1703589480519_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "642771",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Tue Dec 26 2023 16:48:00 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005867",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "869329",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 23 2023 17:03:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Reeta Ramesh Yadav",
    "phone": "9892360047",
    "ownershipShare": ""
  }
]
```

```
"email": "",
  "id": "925875"
},
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "516834",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "542",
    "squareMeterArea": "50.35",
    "docFinalBuiltUp": "596.2",
    "docFinalBuiltUpSquareMeter": "55.385000000000005",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "658a90e3b7b4df714dabeeb9",
    "property": "Shree Krishna Bhoomi, Naigaon East",
    "area": "345",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "3800000",
    "expectedRate": "11014.49",
```

```
    "builtUpExpectedRate": "10013.18",
    "image": "cases/6586c58d5b664a64c31708e4/
indicator_1703579613913_Image.png",
    "squareMeter": "32.05",
    "id": "284038"
  },
  {
    "printlnReport": true,
    "_id": "658a90e3b7b4df714dabeeba",
    "property": "Shree Krishna Bhoomi, Naigaon East",
    "area": "585",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "5500000",
    "expectedRate": "9401.71",
    "builtUpExpectedRate": "8547.01",
    "image": "cases/6586c58d5b664a64c31708e4/
indicator_1703579648287_Image.png",
    "squareMeter": "54.35",
    "id": "909949"
  },
  {
    "printlnReport": true,
    "_id": "658a90e3b7b4df714dabeebb",
    "property": "Shree Krishna Bhoomi, Naigaon East",
    "area": "345",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "4000000",
    "expectedRate": "11594.20",
    "builtUpExpectedRate": "10540.18",
    "image": "cases/6586c58d5b664a64c31708e4/
indicator_1703579759955_Image.png",
    "squareMeter": "32.05",
    "id": "856692"
  }
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892e04b7b4df714da9f806",
  "name": "externallmg_1703488986419_1703489075282_image_0.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488986419_1703489075282_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892e04b7b4df714da9f807",
  "name": "externallmg_1703488988884_1703489075283_image_1.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488988884_1703489075283_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892e04b7b4df714da9f808",
  "name": "externallmg_1703488990385_1703489075283_image_2.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488990385_1703489075283_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892e04b7b4df714da9f809",
  "name": "externallmg_1703488994030_1703489075283_image_3.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488994030_1703489075283_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65892e04b7b4df714da9f80a",
  "name": "externallmg_1703488999265_1703489075283_image_4.jpeg",
  "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703488999265_1703489075283_image_4.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f80b",
    "name": "externallmg_1703489001903_1703489075283_image_5.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489001903_1703489075283_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f80c",
    "name": "externallmg_1703489004281_1703489075283_image_6.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489004281_1703489075283_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f80d",
    "name": "externallmg_1703489005272_1703489075283_image_7.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489005272_1703489075283_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f80e",
    "name": "externallmg_1703489006085_1703489075283_image_8.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489006085_1703489075283_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f80f",
    "name": "externallmg_1703489007282_1703489075283_image_9.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externallmg_1703489007282_1703489075283_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65892e04b7b4df714da9f810",
    "name": "externalimg_1703489008182_1703489075283_image_10.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489008182_1703489075283_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f811",
    "name": "externalimg_1703489008842_1703489075283_image_11.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489008842_1703489075283_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f812",
    "name": "externalimg_1703489009211_1703489075283_image_12.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489009211_1703489075283_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f813",
    "name": "externalimg_1703489009283_1703489075283_image_13.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489009283_1703489075283_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f814",
    "name": "externalimg_1703489009389_1703489075283_image_14.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489009389_1703489075283_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "65892e04b7b4df714da9f815",
    "name": "externalimg_1703489010331_1703489075283_image_15.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489010331_1703489075283_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65892e04b7b4df714da9f816",
    "name": "externalimg_1703489011395_1703489075283_image_16.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703489011395_1703489075283_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65892e04b7b4df714da9f817",
    "name": "externalimg_1703488937941_1703489031856_image_0.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703488937941_1703489031856_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65892e04b7b4df714da9f818",
    "name": "externalimg_1703488939034_1703489031856_image_1.jpeg",
    "path": "cases/6586c58d5b664a64c31708e4/
externalimg_1703488939034_1703489031856_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1698233439717_1697718211173_1696854326515_Calculation
(1).xlsx",
    "filename": "1703580000439_1698233439717_1697718211173_1696854326515_C
alculation_1.xlsx",
    "path": "cases/6586c58d5b664a64c31708e4/processingDocuments/1703580000439
_1698233439717_1697718211173_1696854326515_Calculation_1.xlsx",
    "size": "2148212",
    "createdAt": "Tue Dec 26 2023 14:10:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
```

```
    },
    {
      "originalName":
"document_1681383734183_ReetaRameshYadav_SBI_Racpc_Borivali_West (1).pdf",
      "filename": "1703586576960_document_1681383734183_ReetaRameshYadav_SBI
_Racpc_Borivali_West_1.pdf",
      "path": "cases/6586c58d5b664a64c31708e4/processingDocuments/1703586576960
_document_1681383734183_ReetaRameshYadav_SBI_Racpc_Borivali_West_1.pdf",
      "size": "17937356",
      "createdAt": "Tue Dec 26 2023 15:59:46 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalName": "Valuation_Report Reeta Yadav.pdf",
      "filename": "1703586586358_Valuation_Report_Reeta_Yadav.pdf",
      "path": "cases/6586c58d5b664a64c31708e4/
processingDocuments/1703586586358_Valuation_Report_Reeta_Yadav.pdf",
      "size": "1101789",
      "createdAt": "Tue Dec 26 2023 15:59:46 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60f915d3f3dd69653a592199",
        "role": "MAKER + RATE VERIFIER + CHEAKER",
        "firstName": "Shobha",
        "lastName": "Kuperkar",
        "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "658a918db7b4df714dabf119",
      "note": "Rate verification done pending for bank confirmation",
      "taskId": "6586d0175b664a64c3172daf",
      "createdAt": "2023-12-26T08:40:45.557Z"
    }
  ],
  "createdAt": "2023-12-23T11:33:33.571Z",
  "updatedAt": "2023-12-26T11:34:44.733Z",
  "__v": 0,
```

```
"invoiceId": "6586c58d5b664a64c31708ed",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 803, 8th Floor, Building No 1, Wing - B, Shree
Krishna Bhoomi, Village - Juchandra, Taluka - Vasai, District - Palghar, Naigaon (East),
Palghar, PIN - 401 208, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Nikita Dhuri ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Receptionist",
"siteVisitContactNo": "8080135539",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 542.00",
"flatRate": "9000",
"landOtherRate": "6300",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
```

```

"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Tue Dec 26 2023 16:03:44 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-25"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			