

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231254",
    "firstName": "Shreyash",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9503732605"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Bijendra ",
    "expectedFees": 1500,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
```

```
"role": "PICKUPPERSON",
"firstName": "Ravindra",
"email": "ravindrakasare186@gmail.com",
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.122819046212015",
  "longitude": "72.99356298417156"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.99356298417156,
    19.122819046212015
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "25/12/2023 08:00 am"
  },
  {
    "dateTime": "25/12/2023 12:00 am"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-25",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-12-25",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ghansoli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "230",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vaibhavshali Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "1",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 701",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
```

```
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Everest Nagar CHSL",
    "west": "SN Road",
    "south": "Sector No. 1 Road",
    "east": "Row House"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
```

```
"west": "",
"south": "",
"east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "The loading between measured Carpet area to Built up area mentioned in
the agreement is 45% For the purpose of valuation we have considered loading factor.",
  "depreciationPercentage": "33",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "825",
  "depreciatedCostOfConstruction": "9475.00",
  "depreciatedBuildingRate": "1675"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "96100",
  "landRate": "35500",
  "igrImage": "cases/6587d5e5b7b4df714da8f241/igr_1703497026601_Image.png",
  "squareMeterGuideLineRate": "86490.00",
  "squareFeetGuideLineRate": "8035.00"
},
"igrFinalRate": {
  "floorRatePercentage": "90",
  "depreciationPercentage": "78",
  "rate": "6993.00",
  "squareFeetGuideLineRate": "6993.00",
  "squareMeterGuideLineRate": "75272.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Seller_Occupied",
  "label": "Seller Occupied"
},
"monthlyRent": "7,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Consumer No. 000158543095",
"meterCardHolderName": "Shri Ramesh Gudda Kotian",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per NMMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2001",
  "fullDate": "1/1/2001"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "22",
"totalLifeBuilding": "60",
"estimatedAge": "38",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "2",
"noOfLifts": "",
```



```
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "339.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6587d5e5b7b4df714da8f241/
routeMap_1703490276721_Image.png",
    "routeLat": "19.112083",
    "routeLng": "73.004417",
    "stationName": "Ghansoli",
    "routeDistance": "3.1 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "96djin",
      "name": "96djin",
      "image": "cases/6587d5e5b7b4df714da8f241/
routeMap_1703490021621_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
```

```
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3212025.00",
"finalValue": "3212025.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
"rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2370627.00",
  "selectedBuildUpValue": "339.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65891c2bb7b4df714da99da3",
      "name":
"externalImg_1703484459348_WhatsApp_Image_20231225_at_110916_1.jpeg",
      "path": "cases/6587d5e5b7b4df714da8f241/
externalImg_1703484459348_WhatsApp_Image_20231225_at_110916_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65891c15b7b4df714da99c3f",
      "name":
"externalImg_1703484436994_WhatsApp_Image_20231225_at_110801_1.jpeg",
      "path": "cases/6587d5e5b7b4df714da8f241/
externalImg_1703484436994_WhatsApp_Image_20231225_at_110801_1.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65891c2bb7b4df714da99da7",
    "name":
"externallmg_1703484459357_WhatsApp_Image_20231225_at_110917_2.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459357_WhatsApp_Image_20231225_at_110917_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65891c2bb7b4df714da99da4",
    "name":
"externallmg_1703484459351_WhatsApp_Image_20231225_at_110916_2.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459351_WhatsApp_Image_20231225_at_110916_2.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65891c15b7b4df714da99c43",
    "name": "Living Room",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437000_WhatsApp_Image_20231225_at_110839.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65891c15b7b4df714da99c4a",
    "name": "Living Room",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437010_WhatsApp_Image_20231225_at_110842.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65891c2bb7b4df714da99d9c",
    "name": "Living Room",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459320_WhatsApp_Image_20231225_at_110858_1.jpeg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10384",
    "max": "13889"
  },
  "builtUpRateRange": {
    "min": "9440",
    "max": "11575"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "339.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6587d5e5b7b4df714da8f241",
"ownerName": "Ms. Esakki Ammal Subramanian Yadav",
"ownerPhoneNo": "7039488464",
"appAddress": "flat no 202 2 nd floor A wing vaibhavshali Bldg chs Ltd ploa no. 230
sector 1 Ghansoli mum. 701",
```

```
"remark": "saler number 9867782026\nbankar . 7766o52375",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "04/11/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Ramesh Gudda Kotian",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Ms. Esakki Ammal Subramanian Yadav & Mrs. Petchjammal
Subramani an Yadav",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "18150-2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "182131",
    "path": "cases/6587d5e5b7b4df714da8f241/
document_1703400912314_1703401006375_Agreement_for_sale.pdf",
    "fileName": "document_1703400912314_1703401006375_Agreement_for_sale.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "18/01/2001",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      },
      "number": {
        "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "EE (BP) / ATPO / 2936 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1703497411838_Occupancy_Certificate.pdf",
"path": "cases/6587d5e5b7b4df714da8f241/
document_1703497411838_Occupancy_Certificate.pdf",
"id": "614992",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Dec 25 2023 15:13:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "27/11/2023",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "000158543095"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "103191",
  "path": "cases/6587d5e5b7b4df714da8f241/
document_1703497557670_122837.pdf",
  "fileName": "document_1703497557670_122837.pdf"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "22/07/2014",
    "remark": "bearing Nos. 156 to 160 having 5 Shares of Rs. 50/- each transferred in
the name of Ramesh Gudda Koatian issued by Vaibhavshali Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
}
```

```
    "Document_No": "32"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1703498084027_Share_Certificate.pdf",
  "path": "cases/6587d5e5b7b4df714da8f241/
document_1703498084027_Share_Certificate.pdf",
  "id": "894232",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Mon Dec 25 2023 15:24:44 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005873",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "506716",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sun Dec 24 2023 12:25:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Esakki Ammal Subramanian Yadav",
    "phone": "7039488464",
    "ownershipShare": "",
    "email": "",
    "id": "722318"
  },
  {
    "name": "Mrs. Petchjammal Subramanian Yadav",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "204562"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "549061",
"name": "Living Room",
"length": "8.50",
"length1": "8",
"length2": "6",
"width": "8.83",
"width1": "8",
"width2": "10",
"totalArea": "75.08",
"images": [],
"extraAreas": [],
"finalArea": "75.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "19.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "5.50",
  "length1": "5",
  "length2": "6",
  "width": "5.83",
  "width1": "5",
  "width2": "10",
  "totalArea": "32.08",
  "images": [],
```

```
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "65894899b7b4df714daa4259",
    "name": "Kitchen",
    "extraAreaType": "Add",
    "length": "1.67",
    "length1": "1",
    "length2": "8",
    "width": "3.00",
    "width1": "3",
    "width2": "00",
    "totalArea": "5.00"
  }
],
"finalArea": "37.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "7.92",
```

```
"length1": "7",
"length2": "11",
"width": "6.58",
"width1": "6",
"width2": "7",
"totalArea": "52.12",
"images": [],
"finalArea": "52.12",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Cupboard",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "10.33",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6589493cb7b4df714daa45c7",
      "name": "Cupboard",
      "extraAreaType": "Add",
      "length": "2.67",
      "length1": "2",
      "length2": "8",
      "width": "4.92",
      "width1": "4",
      "width2": "11",
      "totalArea": "13.11"
    }
  ],
  "finalArea": "23.439999999999998"
},
],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "976982",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "339",
    "squareMeterArea": "31.49",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65894d60b7b4df714daa53b3",
    "property": "Flat",
    "area": "338",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3300000",
    "expectedRate": "9763.31",
    "builtUpExpectedRate": "0.00",
    "image": "cases/6587d5e5b7b4df714da8f241/
indicator_1703496880667_Image.png",
    "squareMeter": "31.40",
    "id": "581484"
  },
  {
```



```
"printlnReport": true,
  "_id": "65894d60b7b4df714daa53b4",
  "property": "Flat",
  "area": "339",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "square_yards",
  "expectedPrice": "3200000",
  "expectedRate": "9439.53",
  "builtUpExpectedRate": "0.00",
  "image": "cases/6587d5e5b7b4df714da8f241/
indicator_1703496908242_Image.png",
  "squareMeter": "31.49",
  "id": "751075"
},
{
  "printlnReport": true,
  "_id": "65894d60b7b4df714daa53b5",
  "property": "Flat",
  "area": "360",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "5000000",
  "expectedRate": "13888.89",
  "builtUpExpectedRate": "11574.07",
  "image": "cases/6587d5e5b7b4df714da8f241/
indicator_1703496941182_Image.png",
  "squareMeter": "33.45",
  "id": "472609"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c39",
    "name":
"externallmg_1703484436582_WhatsApp_Image_20231225_at_110759_1.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436582_WhatsApp_Image_20231225_at_110759_1.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c3a",
  "name":
"externallmg_1703484436978_WhatsApp_Image_20231225_at_110759_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436978_WhatsApp_Image_20231225_at_110759_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c3b",
  "name":
"externallmg_1703484436983_WhatsApp_Image_20231225_at_110759.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436983_WhatsApp_Image_20231225_at_110759.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c3c",
  "name":
"externallmg_1703484436987_WhatsApp_Image_20231225_at_110800_1.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436987_WhatsApp_Image_20231225_at_110800_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c3d",
  "name":
"externallmg_1703484436990_WhatsApp_Image_20231225_at_110800_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436990_WhatsApp_Image_20231225_at_110800_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c3e",
  "name":
"externallmg_1703484436992_WhatsApp_Image_20231225_at_110800.jpeg",
```

```
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436992_WhatsApp_Image_20231225_at_110800.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c3f",
    "name":
"externallmg_1703484436994_WhatsApp_Image_20231225_at_110801_1.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436994_WhatsApp_Image_20231225_at_110801_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c40",
    "name":
"externallmg_1703484436996_WhatsApp_Image_20231225_at_110801.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436996_WhatsApp_Image_20231225_at_110801.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c41",
    "name":
"externallmg_1703484436997_WhatsApp_Image_20231225_at_110822.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436997_WhatsApp_Image_20231225_at_110822.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c42",
    "name":
"externallmg_1703484436999_WhatsApp_Image_20231225_at_110838.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484436999_WhatsApp_Image_20231225_at_110838.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65891c15b7b4df714da99c43",
  "name":
"externallmg_1703484437000_WhatsApp_Image_20231225_at_110839.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437000_WhatsApp_Image_20231225_at_110839.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c44",
  "name":
"externallmg_1703484437003_WhatsApp_Image_20231225_at_110840.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437003_WhatsApp_Image_20231225_at_110840.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c45",
  "name":
"externallmg_1703484437005_WhatsApp_Image_20231225_at_110841_1.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437005_WhatsApp_Image_20231225_at_110841_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c46",
  "name":
"externallmg_1703484437005_WhatsApp_Image_20231225_at_110841_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437005_WhatsApp_Image_20231225_at_110841_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c15b7b4df714da99c47",
  "name":
"externallmg_1703484437007_WhatsApp_Image_20231225_at_110841_3.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437007_WhatsApp_Image_20231225_at_110841_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c48",
    "name":
"externallmg_1703484437008_WhatsApp_Image_20231225_at_110841.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437008_WhatsApp_Image_20231225_at_110841.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c49",
    "name":
"externallmg_1703484437009_WhatsApp_Image_20231225_at_110842_1.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437009_WhatsApp_Image_20231225_at_110842_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c15b7b4df714da99c4a",
    "name":
"externallmg_1703484437010_WhatsApp_Image_20231225_at_110842.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484437010_WhatsApp_Image_20231225_at_110842.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99d9b",
    "name":
"externallmg_1703484459317_WhatsApp_Image_20231225_at_110857.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459317_WhatsApp_Image_20231225_at_110857.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99d9c",
```

```
    "name":
"externallmg_1703484459320_WhatsApp_Image_20231225_at_110858_1.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459320_WhatsApp_Image_20231225_at_110858_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99d9d",
  "name":
"externallmg_1703484459321_WhatsApp_Image_20231225_at_110858_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459321_WhatsApp_Image_20231225_at_110858_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99d9e",
  "name":
"externallmg_1703484459325_WhatsApp_Image_20231225_at_110858.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459325_WhatsApp_Image_20231225_at_110858.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99d9f",
  "name":
"externallmg_1703484459326_WhatsApp_Image_20231225_at_110859_1.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459326_WhatsApp_Image_20231225_at_110859_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da0",
  "name":
"externallmg_1703484459329_WhatsApp_Image_20231225_at_110859_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459329_WhatsApp_Image_20231225_at_110859_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da1",
  "name":
"externallmg_1703484459342_WhatsApp_Image_20231225_at_110859.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459342_WhatsApp_Image_20231225_at_110859.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da2",
  "name":
"externallmg_1703484459345_WhatsApp_Image_20231225_at_110915.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459345_WhatsApp_Image_20231225_at_110915.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da3",
  "name":
"externallmg_1703484459348_WhatsApp_Image_20231225_at_110916_1.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459348_WhatsApp_Image_20231225_at_110916_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da4",
  "name":
"externallmg_1703484459351_WhatsApp_Image_20231225_at_110916_2.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459351_WhatsApp_Image_20231225_at_110916_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65891c2bb7b4df714da99da5",
  "name":
"externallmg_1703484459354_WhatsApp_Image_20231225_at_110916.jpeg",
```

```
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459354_WhatsApp_Image_20231225_at_110916.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99da6",
    "name":
"externallmg_1703484459356_WhatsApp_Image_20231225_at_110917_1.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459356_WhatsApp_Image_20231225_at_110917_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99da7",
    "name":
"externallmg_1703484459357_WhatsApp_Image_20231225_at_110917_2.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459357_WhatsApp_Image_20231225_at_110917_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99da8",
    "name":
"externallmg_1703484459358_WhatsApp_Image_20231225_at_110917_3.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459358_WhatsApp_Image_20231225_at_110917_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65891c2bb7b4df714da99da9",
    "name":
"externallmg_1703484459360_WhatsApp_Image_20231225_at_110917.jpeg",
    "path": "cases/6587d5e5b7b4df714da8f241/
externallmg_1703484459360_WhatsApp_Image_20231225_at_110917.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "65891c2bb7b4df714da99daa",
  "name":
"externalImg_1703484459362_WhatsApp_Image_20231225_at_110918.jpeg",
  "path": "cases/6587d5e5b7b4df714da8f241/
externalImg_1703484459362_WhatsApp_Image_20231225_at_110918.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Calculation (2)- yadav.xlsx",
  "filename": "1703497070210_Calculation_2_yadav.xlsx",
  "path": "cases/6587d5e5b7b4df714da8f241/
processingDocuments/1703497070210_Calculation_2_yadav.xlsx",
  "size": "16073",
  "createdAt": "Mon Dec 25 2023 15:07:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - yadav.xlsx",
  "filename": "1703497070213_Summary__yadav.xlsx",
  "path": "cases/6587d5e5b7b4df714da8f241/
processingDocuments/1703497070213_Summary__yadav.xlsx",
  "size": "667263",
  "createdAt": "Mon Dec 25 2023 15:07:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-24T06:55:33.080Z",
"updatedAt": "2023-12-25T10:11:41.083Z",
"__v": 0,
"invoiceId": "6587d5e5b7b4df714da8f24a",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - A, Vaibhavshali Co-op. Hsg.
Soc. Ltd., Plot No. 230, Sector 1, Village - Ghansoli, Navi Mumbai, Taluka - Thane,
District - Thane, PIN - 400 701, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": ""
```

```
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Ramesh Kotian",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller",
"siteVisitContactNo": "7039488464",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Toilet +
Cupboard",
"carpetTotal": "235.41",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "282.49",
"finalCarpetArea": "235.41",
"finalSalableArea": "310.74",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 339.00",
"buildingServicesRate": "2500",
"flatRate": "10300",
"landOtherRate": "7800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Mon Dec 25 2023 15:06:35 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2023-12-25",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
```

```

"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	8'6"	8'10"	75.08
Passage	6'9"	2'11"	19.69
Kitchen	5'6"	5'10"	32.08
Toilet	7'00"	4'00"	28.00
Bedroom	7'11"	6'7"	52.12
Cupboard	5'2"	2'00"	10.33
Other Composition :			