

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312bd",
    "firstName": "Swarup",
    "email": "1racpcghatkopar.sanctions@sbi.co.in",
    "mobileNo": "-",
    "workMobileNo": "8668951779",
    "lastName": " Shivane"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.002947882800992",
  "longitude": "73.11970293927186"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11970293927186,
    19.002947882800992
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "26/12/2023 04:30 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-27",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "New Panvel",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "150-151",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pearl Apartments Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "New Panvel (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Sai Sankalp",
    "west": "Internal Road",
    "south": "Plot No. 152",
    "east": "Residential Building"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 5B",
    "west": "Plot No. 27",
    "south": "Road 6 Mtrs.",
    "east": "Plot No. 5A"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
```

```
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available, we assumed that
the construction is as per approved plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9512.5",
  "depreciatedBuildingRate": "1712.5"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "95900",
  "landRate": "43900",
  "igrImage": "cases/658a9420b7b4df714dabf769/igr_1703677772974_Image.png",
  "squareMeterGuideLineRate": "81515.00",
  "squareFeetGuideLineRate": "7573.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "79",
  "rate": "6839.00",
  "squareMeterGuideLineRate": "73616.00",
  "squareFeetGuideLineRate": "6839.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
},
```

```
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "9500",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Electricity Bill Consumer No. 028510539348",
"meterCardHolderName": "Mrs. Amruta Anant Ogale",
"undividedAreaOfLandAsPerSaleDeed": "N.A.",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Kumud",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
```

```
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2002",
  "fullDate": "1/1/2002"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
```

```
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
```

```
},
"finalPlinthArea": {
  "area": "479.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/658a9420b7b4df714dabf769/
routeMap_1703677891328_Image.png",
    "routeLat": "19.002730",
    "routeLng": "73.119508",
    "stationName": "Panvel",
    "routeDistance": "1.6 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "8jdc2c",
      "name": "8jdc2c",
      "image": "cases/658a9420b7b4df714dabf769/
routeMap_1703677832525_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```



```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4556727.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4556727.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2653122.00",
  "selectedBuildUpValue": "387.94",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "658c04e8c71d833b91796d36",
      "name": "externalimg_1703675111376_IMG_20231227_1201.jpg",
      "path": "cases/658a9420b7b4df714dabf769/
externalimg_1703675111376_IMG_20231227_1201.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "658c04e8c71d833b91796d3b",
      "name": "externalimg_1703675111391_IMG_20231227_53621.jpg",
      "path": "cases/658a9420b7b4df714dabf769/
externalimg_1703675111391_IMG_20231227_53621.jpg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "658c04e8c71d833b91796d38",
      "name": "externalimg_1703675111382_IMG_20231227_1874.jpg",
```

```
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111382_IMG_20231227_1874.jpg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "658c04fac71d833b91796dbc",
    "name": "externallmg_r_1703675129907_IMG20231227101118.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_r_1703675129907_IMG20231227101118.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "658c04fac71d833b91796db8",
    "name": "externallmg_1703675129899_IMG_20231227_59276.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129899_IMG_20231227_59276.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "658c04fac71d833b91796db7",
    "name": "externallmg_1703675129853_IMG_20231227_58957.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129853_IMG_20231227_58957.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658c04e8c71d833b91796d33",
    "name": "externallmg_1703675111358_IMG_20231227_0267.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111358_IMG_20231227_0267.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "658c04fac71d833b91796dbb",
    "name": "externallmg_r_1703675129982_IMG20231227101211.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_r_1703675129982_IMG20231227101211.jpg",
```

```
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "658c04f2c71d833b91796d84",
    "name": "Living Room",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121476_IMG_20231227_57497.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "658c04f2c71d833b91796d80",
    "name": "Living Room",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121472_IMG_20231227_56179.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658c04e8c71d833b91796d3a",
    "name": "Living Room",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111390_IMG_20231227_5882.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "658c04e8c71d833b91796d39",
    "name": "Living Room",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111387_IMG_20231227_5410.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "479.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "658a9420b7b4df714dabf769",
"ownerName": "Mr. Amol Maruti Pawar",
"ownerPhoneNo": "9372145698",
"appAddress": "Flat no. 304, 3rd Floor, Pearl Apartment, Plot no. 150, Sector - 4,
Panvel E",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/10/2023",
      "from": {
        "value": "Seller",
        "label": "Seller"
      }
    }
  }
]
```

```
    },
    "Seller": "Ms. Amruta Anant Ogale alias Mrs. Amruta Siddhartha Joshi",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Amol Maruti Pawar",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "16211/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "585751",
  "path": "cases/658a9420b7b4df714dabf769/
document_1703590325439_Racpc_GHatkopar_Amol_Pawar.pdf",
  "fileName": "document_1703590325439_Racpc_GHatkopar_Amol_Pawar.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "05/12/2002",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / EE(BP) / ATPO / 704"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1703675704791_OC.pdf",
  "path": "cases/658a9420b7b4df714dabf769/document_1703675704791_OC.pdf",
  "id": "599252",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Dec 27 2023 16:45:05 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "6077c791395bc80714864a30",
  "label": "Electricity Bill"
},
"inputs": {
  "documentDate": "10/12/2023",
  "number": {
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": "028510539348"
},
"isHardCopy": false,
"displayStatus": false,
"id": "617468",
"path": "cases/658a9420b7b4df714dabf769/
document_1703677283377_1414489.pdf",
"fileName": "document_1703677283377_1414489.pdf"
}
],
"caseNumber": "005895",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "908815",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Dec 26 2023 14:21:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Amol Maruti Pawar",
    "phone": "9372145698",
    "ownershipShare": "",
    "email": "",
    "id": "187815"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "466995",
  "name": "Living Room",
  "length": "15.33",
  "length1": "15",
  "length2": "4",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "150.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "85.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "10.86",
```

```
"images": [],
"extraAreas": [],
"finalArea": "10.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "10.86",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "",
  "length1": "4",
  "length2": "6",
  "width": "",
  "width1": "3",
  "width2": "9",
  "totalArea": "16.87",
  "images": [],
  "finalArea": "16.87",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
```

```
"name": "Bedroom",
"length": "10.33",
"length1": "10",
"length2": "4",
"width": "8.83",
"width1": "8",
"width2": "10",
"totalArea": "91.28",
"images": [],
"extraAreas": [],
"finalArea": "91.28"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "2.42",
  "width1": "2",
  "width2": "5",
  "totalArea": "21.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.35"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "404401",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "479",
```

```
"squareMeterArea": "44.5",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": false,
  "_id": "658c0e52c71d833b917997dd",
  "property": "Residential Flat",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "5300000",
  "expectedRate": "13250.00",
  "builtUpExpectedRate": "11041.67",
  "image": "cases/658a9420b7b4df714dabf769/
indicator_1703677457401_Image.png",
  "squareMeter": "37.16",
  "id": "160430"
},
{
  "printlnReport": false,
  "_id": "658c0e52c71d833b917997de",
  "property": "Residential Flat",
  "area": "600",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6500000",
  "expectedRate": "10833.33",
  "builtUpExpectedRate": "0.00",
  "image": "cases/658a9420b7b4df714dabf769/
indicator_1703677475055_Image.png",
  "squareMeter": "55.74",
  "id": "702172"
```

```
    },
    {
      "printlnReport": false,
      "_id": "658c0e52c71d833b917997df",
      "property": "Residential Flat",
      "area": "530",
      "builtUpPercentage": "20",
      "saleablePercentage": "0",
      "rateType": "price_Indicator",
      "areaType": "Carpet",
      "source": "https://www.99acres.com/",
      "expectedPrice": "5800000",
      "expectedRate": "10943.40",
      "builtUpExpectedRate": "9119.50",
      "image": "cases/658a9420b7b4df714dabf769/
indicator_1703677495956_Image.png",
      "squareMeter": "49.24",
      "id": "405341"
    },
    {
      "printlnReport": false,
      "_id": "658c0e52c71d833b917997e0",
      "property": "Residential Flat",
      "area": "540",
      "builtUpPercentage": "0",
      "saleablePercentage": "0",
      "rateType": "price_Indicator",
      "areaType": "Built_Up",
      "source": "Nobroker.com",
      "expectedPrice": "6000000",
      "expectedRate": "11111.11",
      "builtUpExpectedRate": "0.00",
      "image": "cases/658a9420b7b4df714dabf769/
indicator_1703677522338_Image.png",
      "squareMeter": "50.17",
      "id": "661762"
    }
  ],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "658c04e8c71d833b91796d33",
      "name": "externalImg_1703675111358_IMG_20231227_0267.jpg",
      "path": "cases/658a9420b7b4df714dabf769/
externalImg_1703675111358_IMG_20231227_0267.jpg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d34",
  "name": "externallmg_1703675111363_IMG_20231227_0559.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111363_IMG_20231227_0559.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d35",
  "name": "externallmg_1703675111372_IMG_20231227_0852.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111372_IMG_20231227_0852.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d36",
  "name": "externallmg_1703675111376_IMG_20231227_1201.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111376_IMG_20231227_1201.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d37",
  "name": "externallmg_1703675111379_IMG_20231227_1491.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111379_IMG_20231227_1491.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d38",
  "name": "externallmg_1703675111382_IMG_20231227_1874.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111382_IMG_20231227_1874.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d39",
  "name": "externallmg_1703675111387_IMG_20231227_5410.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111387_IMG_20231227_5410.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d3a",
  "name": "externallmg_1703675111390_IMG_20231227_5882.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111390_IMG_20231227_5882.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04e8c71d833b91796d3b",
  "name": "externallmg_1703675111391_IMG_20231227_53621.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675111391_IMG_20231227_53621.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d7f",
  "name": "externallmg_1703675121471_IMG_20231227_55222.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121471_IMG_20231227_55222.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d80",
  "name": "externallmg_1703675121472_IMG_20231227_56179.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121472_IMG_20231227_56179.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d81",
  "name": "externallmg_1703675121473_IMG_20231227_56664.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121473_IMG_20231227_56664.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d82",
  "name": "externallmg_1703675121474_IMG_20231227_56922.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121474_IMG_20231227_56922.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d83",
  "name": "externallmg_1703675121475_IMG_20231227_57199.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121475_IMG_20231227_57199.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d84",
  "name": "externallmg_1703675121476_IMG_20231227_57497.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121476_IMG_20231227_57497.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04f2c71d833b91796d85",
  "name": "externallmg_1703675121479_IMG_20231227_57817.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675121479_IMG_20231227_57817.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c04fac71d833b91796db5",
    "name": "externallmg_1703675129843_IMG_20231227_58313.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129843_IMG_20231227_58313.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c04fac71d833b91796db6",
    "name": "externallmg_1703675129847_IMG_20231227_58619.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129847_IMG_20231227_58619.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c04fac71d833b91796db7",
    "name": "externallmg_1703675129853_IMG_20231227_58957.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129853_IMG_20231227_58957.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c04fac71d833b91796db8",
    "name": "externallmg_1703675129899_IMG_20231227_59276.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129899_IMG_20231227_59276.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c04fac71d833b91796db9",
    "name": "externallmg_1703675129902_IMG_20231227_59620.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675129902_IMG_20231227_59620.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "658c04fac71d833b91796dba",
  "name": "externalimg_1703675129905_IMG_20231227_59863.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externalimg_1703675129905_IMG_20231227_59863.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04fac71d833b91796dbb",
  "name": "externalimg_r_1703675129982_IMG20231227101211.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externalimg_r_1703675129982_IMG20231227101211.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04fac71d833b91796dbc",
  "name": "externalimg_r_1703675129907_IMG20231227101118.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externalimg_r_1703675129907_IMG20231227101118.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c04fac71d833b91796dbd",
  "name": "externalimg_r_1703675129953_IMG20231227101206.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externalimg_r_1703675129953_IMG20231227101206.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658c0505c71d833b91796df0",
  "name": "externalimg_1703675140191_IMG_20231227_152647.jpg",
  "path": "cases/658a9420b7b4df714dabf769/
externalimg_1703675140191_IMG_20231227_152647.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "658c0505c71d833b91796df1",
    "name": "externallmg_1703675140263_IMG_20231227_152653.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_1703675140263_IMG_20231227_152653.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c0505c71d833b91796df2",
    "name": "externallmg_1703675140336_Screenshot_2023122710074523_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/658a9420b7b4df714dabf769/externallmg_1703675140336_Screensh
ot_2023122710074523_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658c0505c71d833b91796df3",
    "name": "externallmg_r_1703675140316_IMG20231227102846.jpg",
    "path": "cases/658a9420b7b4df714dabf769/
externallmg_r_1703675140316_IMG20231227102846.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Racpc GHatkopar.. Amol Pawar.pdf",
    "filename": "1703588569326_Racpc_GHatkopar_Amol_Pawar.pdf",
    "path": "cases/658a9420b7b4df714dabf769/
processingDocuments/1703588569326_Racpc_GHatkopar_Amol_Pawar.pdf",
    "size": "19326722",
    "createdAt": "Tue Dec 26 2023 16:32:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=Amol.xlsx",
    "filename": "1703588573037_Summary_NewAmol.xlsx",
    "path": "cases/658a9420b7b4df714dabf769/
processingDocuments/1703588573037_Summary_NewAmol.xlsx",
    "size": "2929928",
    "createdAt": "Tue Dec 26 2023 16:32:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-26T08:51:44.957Z",
"updatedAt": "2023-12-27T11:55:38.947Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 304, 3rd Floor, Pearl Apartments Co-op. Hsg. Soc.
Ltd., Plot No. 150-151, Sector 4, Village - New Panvel, New Panvel (East), Taluka -
Panvel, District - Raigad, Navi Mumbai, 410206, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Jagdish ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Friend of Seller",
"siteVisitContactNo": "9372145698",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet + Passage +
Bathroom + Balcony",
"carpetTotal": "366.59",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "465.53",
"finalCarpetArea": "387.94",
"finalSalableArea": "512.08",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 479.00",
"buildingServicesRate": "2500",
"flatRate": "10300",
```

```

"landOtherRate": "7800",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Dec 27 2023 17:11:56 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-12-27"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'4"	9'10"	150.78
Kitchen	10'5"	8'3"	85.94
Toilet	3'10"	2'10"	10.86
Passage	3'10"	2'10"	10.86
Bathroom	4'6"	3'9"	16.87
Bedroom	10'4"	8'10"	91.28
Balcony	8'10"	2'5"	21.35
Other Composition :			