

```
{
  "typeOfReport": {
    "value": "Structural_Report",
    "label": "Structural Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b949"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f50",
    "firstName": "Vishwas Mane",
    "email": "0_default_vishwas.mane@janasevabank.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8779298387"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2395000",
    "discussWithPerson": "Vishwas Mane",
    "expectedFees": 1197.5,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b949",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "Borivli (West) Branch",
  "email": "jssbl@mtnl.net.in",
  "mobileNo": "28332893",
  "alternateMobileNo": "",
  "address": "Aravali Business Centre(Phhol Mahal) Ramdas Surtale Marg Off
SOdawala Lane Boriwali (West) Mumbai 4000092",
  "ledgerName": "Janseva Sahakari Bank Borivali (W)",
  "fax": "28998842",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
"label": "BANK",
"value": "BANK"
},
"location": {
"latitude": "19.21594895767435",
```

```
"longitude": "72.98305730767335"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.98305730767335,
    19.21594895767435
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "28/12/2023 04:30 pm"
    },
    {
      "dateTime": "28/12/2023 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
```

```
"name": "Village",
"key": "village",
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C/38",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
}
```

```
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Akash Gang Shanti Nagar CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "8",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shanti Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```

```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```



```
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "658d53f2c71d833b917b48d2",
"ownerName": "Mrs P Krushnaveni ",
"ownerPhoneNo": "9833488825",
"appAddress": "Flat no 402 4 th floor Bldg no C/38 Bldg Akash Ganga Shantinagar
CHS Ltd Shanti Nagar Mira road East 401107",
"remark": "Structural report chahiye urgent kal ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/658d53f2c71d833b917b48d2/document_1703760704851_1703760801256_Mrs_P_Krushnaveni_Structural_JSB_Borivali_West.pdf",
    "fileName": "document_1703760704851_1703760801256_Mrs_P_Krushnaveni_Structural_JSB_Borivali_West.pdf",
    "id": "719176",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Thu Dec 28 2023 16:24:41 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005984",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "280337",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Dec 28 2023 16:24:42 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs P Krushnaveni ",
    "phone": "9833488825",
    "ownershipShare": "",
    "email": "",
    "id": "133480"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e0",
    "name":
"externallmg_1703855519632_IMG_20231229_144844_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519632_IMG_20231229_144844_copy_1200x900.jpg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e1",
    "name":
"externallmg_1703855519642_IMG_20231229_144847_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519642_IMG_20231229_144847_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e2",
    "name":
"externallmg_1703855519654_IMG_20231229_144853_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519654_IMG_20231229_144853_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e3",
    "name":
"externallmg_1703855519664_IMG_20231229_144859_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519664_IMG_20231229_144859_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e4",
    "name":
"externallmg_1703855519673_IMG_20231229_144901_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519673_IMG_20231229_144901_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e5",
```

```
    "name":
"externallmg_1703855519682_IMG_20231229_144905_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519682_IMG_20231229_144905_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e6",
    "name":
"externallmg_1703855519691_IMG_20231229_144907_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519691_IMG_20231229_144907_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e7",
    "name":
"externallmg_1703855519701_IMG_20231229_144914_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519701_IMG_20231229_144914_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e8",
    "name":
"externallmg_1703855519710_IMG_20231229_144916_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519710_IMG_20231229_144916_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec59fc71d833b917da4e9",
    "name":
"externallmg_1703855519721_IMG_20231229_144920_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519721_IMG_20231229_144920_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec59fc71d833b917da4ea",
  "name":
"externallmg_1703855519730_IMG_20231229_144924_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519730_IMG_20231229_144924_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec59fc71d833b917da4eb",
  "name":
"externallmg_1703855519738_IMG_20231229_144929_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855519738_IMG_20231229_144929_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da52d",
  "name":
"externallmg_1703855532816_IMG_20231229_144931_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532816_IMG_20231229_144931_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da52e",
  "name":
"externallmg_1703855532825_IMG_20231229_144933_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532825_IMG_20231229_144933_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da52f",
  "name":
"externallmg_1703855532834_IMG_20231229_144940_copy_1200x900.jpg",
```

```
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532834_IMG_20231229_144940_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da530",
    "name":
"externallmg_1703855532853_IMG_20231229_144941_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532853_IMG_20231229_144941_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da531",
    "name":
"externallmg_1703855532871_IMG_20231229_145015_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532871_IMG_20231229_145015_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da532",
    "name":
"externallmg_1703855532878_IMG_20231229_145020_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532878_IMG_20231229_145020_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da533",
    "name":
"externallmg_1703855532883_IMG_20231229_145033_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532883_IMG_20231229_145033_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "658ec5adc71d833b917da534",
  "name":
"externallmg_1703855532888_IMG_20231229_145120_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532888_IMG_20231229_145120_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da535",
  "name":
"externallmg_1703855532902_IMG_20231229_145124_copy_1200x900.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532902_IMG_20231229_145124_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da536",
  "name":
"externallmg_1703855532916_IMG_20231229_145131_copy_1200x1600.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532916_IMG_20231229_145131_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da537",
  "name":
"externallmg_1703855532924_IMG_20231229_145150_copy_1200x1597.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532924_IMG_20231229_145150_copy_1200x1597.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da538",
  "name":
"externallmg_1703855532947_IMG_20231229_145153_copy_1200x1600.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532947_IMG_20231229_145153_copy_1200x1600.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da539",
    "name":
"externallmg_1703855532958_IMG_20231229_145155_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532958_IMG_20231229_145155_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da53a",
    "name":
"externallmg_1703855532968_IMG_20231229_145159_copy_1200x900.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532968_IMG_20231229_145159_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da53b",
    "name":
"externallmg_1703855532981_IMG_20231229_145218_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532981_IMG_20231229_145218_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da53c",
    "name":
"externallmg_1703855532989_IMG_20231229_145220_copy_1200x1600.jpg",
    "path": "cases/658d53f2c71d833b917b48d2/
externallmg_1703855532989_IMG_20231229_145220_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658ec5adc71d833b917da53d",
```

```
"name":
"externalImg_1703855532999_IMG_20231229_145221_copy_1200x1600.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externalImg_1703855532999_IMG_20231229_145221_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da53e",
  "name":
"externalImg_1703855533009_IMG_20231229_175748_copy_1200x1600.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externalImg_1703855533009_IMG_20231229_175748_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658ec5adc71d833b917da53f",
  "name":
"externalImg_1703855533014_IMG_20231229_175756_copy_1200x1600.jpg",
  "path": "cases/658d53f2c71d833b917b48d2/
externalImg_1703855533014_IMG_20231229_175756_copy_1200x1600.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-28T10:54:42.074Z",
"updatedAt": "2023-12-29T13:12:13.172Z",
"__v": 0,
"invoiceId": "658d53f2c71d833b917b48db",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 402, 4th Floor, Building No C/38, Akash Gang
Shanti Nagar CHSL, Sector 8, Shanti Nagar, Mira Road East, Thane, State -
Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
```

"contactPersonName": "Mrs P Krushnaveni ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833488825"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			