

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8da"
    },
    "type": "CREDITOFFICER",
    "_id": "64e31653ae896715ef7f8b9b",
    "firstName": "Sonali",
    "lastName": "Keni",
    "mobileNo": "",
    "workMobileNo": "9870198131",
    "email": "sonalikenic@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8da",
  "branchCode": "000003",
  "type": "BRANCH",
  "name": "Kandivali (West) Branch",
  "email": "kandivali@cosmosbank.in",
  "mobileNo": "022-28073762 ",
  "alternateMobileNo": "28051426",
  "address": "Shop No. 6 - 7, Sangita Apartment, Opp. Balbharti School, S. V. Road,
Kandivali (West), Mumbai - 400 067, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "COSMOS BANK- KANDIVALI(WEST)",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.28203061305817",
  "longitude": " 72.88721896810682"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "5/01/2024 12:00 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ghodbunder",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "18",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "J P North Estela",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Vinay Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Next To R N A Kashmirira Road",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1806",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "6592afa0440d8733f0aab023",
"ownerName": "Sudeep Day",
"ownerPhoneNo": "9307982334",
"fullAddress": " Flat No. 1806, 18th Floor, Wing - C, J P North Estela, Vinay Nagar,
```


Next To R N A Kashmirira Road, Village - Ghodbunder, Mira Road East, Thane",

"remark": "",

"documents": [

{
 "documentType": {
 "value": "60ae124eaa6d152c1801b30b",
 "label": "Other"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1704112029127_362868.pdf",

"path": "cases/6592afa0440d8733f0aab023/

document_1704112029127_362868.pdf",

"id": "294049",

"uploadedBy": "62691c48afd7d55eddecfda3",

"createdAt": "Mon Jan 01 2024 17:57:12 GMT+0530 (India Standard Time)"

}

],

"assignmentType": {

"value": "Commercial",

"label": "Commercial"

},

"caseNumber": "006043",

"createdBy": "62691c48afd7d55eddecfda3",

"caseHistory": [

{

"id": "571342",

"title": "Create Lead",

"description": "Create Lead",

"datetime": "Mon Jan 01 2024 17:57:12 GMT+0530 (India Standard Time)"

}

],

"owners": [

{

"name": "Sudeep Day",

"phone": "9307982334",

"ownershipShare": "",

"email": "",

"id": "848538"

}

],

"proposePurchasers": [],

"siteInspection": [],

"composition": [],

"otherComposition": [],

"externalReport": [],

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e01b8f39506e8344e3e4",
    "name":
"externalImg_1704517659630_IMG_20240105_153248_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externalImg_1704517659630_IMG_20240105_153248_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e01b8f39506e8344e3e5",
    "name":
"externalImg_1704517659647_IMG_20240105_153251_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externalImg_1704517659647_IMG_20240105_153251_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e01b8f39506e8344e3e6",
    "name":
"externalImg_1704517659662_IMG_20240105_153336_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externalImg_1704517659662_IMG_20240105_153336_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e01b8f39506e8344e3e7",
    "name":
"externalImg_1704517659677_IMG_20240105_153338_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externalImg_1704517659677_IMG_20240105_153338_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6598e01b8f39506e8344e3e8",
  "name":
"externallmg_1704517659689_IMG_20240105_153459_copy_1200x1600.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659689_IMG_20240105_153459_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e01b8f39506e8344e3e9",
  "name":
"externallmg_1704517659694_IMG_20240105_153501_copy_1200x1600.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659694_IMG_20240105_153501_copy_1200x1600.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e01b8f39506e8344e3ea",
  "name":
"externallmg_1704517659699_IMG_20240105_154449_copy_1200x900.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659699_IMG_20240105_154449_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e01b8f39506e8344e3eb",
  "name":
"externallmg_1704517659714_IMG_20240105_154453_copy_1200x900.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659714_IMG_20240105_154453_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e01b8f39506e8344e3ec",
  "name":
"externallmg_1704517659728_IMG_20240105_154459_copy_1200x900.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659728_IMG_20240105_154459_copy_1200x900.jpg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e01b8f39506e8344e3ed",
    "name":
"externallmg_1704517659735_IMG_20240105_154502_copy_1200x900.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517659735_IMG_20240105_154502_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e06c8f39506e8344e43c",
    "name":
"externallmg_1704517739885_IMG_20240105_154508_copy_1200x900__Copy.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517739885_IMG_20240105_154508_copy_1200x900__Copy.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e06c8f39506e8344e43d",
    "name":
"externallmg_1704517739901_IMG_20240105_154508_copy_1200x900.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517739901_IMG_20240105_154508_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e06c8f39506e8344e43e",
    "name":
"externallmg_1704517739913_IMG_20240105_154510_copy_1200x900__Copy.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517739913_IMG_20240105_154510_copy_1200x900__Copy.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e06c8f39506e8344e43f",
```

```
    "name":  
    "externallmg_1704517739923_IMG_20240105_154510_copy_1200x900.jpg",  
    "path": "cases/6592afa0440d8733f0aab023/  
externallmg_1704517739923_IMG_20240105_154510_copy_1200x900.jpg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6598e06c8f39506e8344e440",  
    "name":  
    "externallmg_1704517739933_IMG_20240105_154513_copy_1200x1600__Copy.jpg",  
    "path": "cases/6592afa0440d8733f0aab023/  
externallmg_1704517739933_IMG_20240105_154513_copy_1200x1600__Copy.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6598e06c8f39506e8344e441",  
    "name":  
    "externallmg_1704517739957_IMG_20240105_154513_copy_1200x1600.jpg",  
    "path": "cases/6592afa0440d8733f0aab023/  
externallmg_1704517739957_IMG_20240105_154513_copy_1200x1600.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6598e06c8f39506e8344e442",  
    "name":  
    "externallmg_1704517739978_IMG_20240105_154517_copy_1200x1600__Copy.jpg",  
    "path": "cases/6592afa0440d8733f0aab023/  
externallmg_1704517739978_IMG_20240105_154517_copy_1200x1600__Copy.jpg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6598e06c8f39506e8344e443",  
    "name":  
    "externallmg_1704517739987_IMG_20240105_154517_copy_1200x1600.jpg",  
    "path": "cases/6592afa0440d8733f0aab023/  
externallmg_1704517739987_IMG_20240105_154517_copy_1200x1600.jpg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e06c8f39506e8344e444",
  "name":
"externallmg_1704517739996_IMG_20240105_154535_copy_1200x900__Copy.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517739996_IMG_20240105_154535_copy_1200x900__Copy.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e06c8f39506e8344e445",
  "name":
"externallmg_1704517740008_IMG_20240105_154535_copy_1200x900.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517740008_IMG_20240105_154535_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e07d8f39506e8344e493",
  "name":
"externallmg_1704517757752_IMG_20240105_154538_copy_1200x900__Copy.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757752_IMG_20240105_154538_copy_1200x900__Copy.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e07d8f39506e8344e494",
  "name":
"externallmg_1704517757766_IMG_20240105_154538_copy_1200x900.jpg",
  "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757766_IMG_20240105_154538_copy_1200x900.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6598e07d8f39506e8344e495",
  "name":
"externallmg_1704517757775_IMG_20240105_154547_copy_1200x900__Copy.jpg",
```

```
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757775_IMG_20240105_154547_copy_1200x900__Copy.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e496",
    "name":
"externallmg_1704517757785_IMG_20240105_154547_copy_1200x900.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757785_IMG_20240105_154547_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e497",
    "name":
"externallmg_1704517757798_IMG_20240105_154550_copy_1200x900__Copy.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757798_IMG_20240105_154550_copy_1200x900__Copy.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e498",
    "name":
"externallmg_1704517757808_IMG_20240105_154550_copy_1200x900.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757808_IMG_20240105_154550_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e499",
    "name":
"externallmg_1704517757818_IMG_20240105_154553_copy_1200x900__Copy.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757818_IMG_20240105_154553_copy_1200x900__Copy.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6598e07d8f39506e8344e49a",
    "name":
"externallmg_1704517757831_IMG_20240105_154553_copy_1200x900.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757831_IMG_20240105_154553_copy_1200x900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e49b",
    "name":
"externallmg_1704517757845_IMG_20240105_160632_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757845_IMG_20240105_160632_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e07d8f39506e8344e49c",
    "name":
"externallmg_1704517757851_IMG_20240105_160636_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517757851_IMG_20240105_160636_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4da",
    "name":
"externallmg_1704517770127_IMG_20240105_161305_copy_1200x1597.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770127_IMG_20240105_161305_copy_1200x1597.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4db",
    "name":
"externallmg_1704517770151_IMG_20240105_161329_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770151_IMG_20240105_161329_copy_1200x1600.jpg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4dc",
    "name":
"externallmg_1704517770160_IMG_20240105_161333_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770160_IMG_20240105_161333_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4dd",
    "name":
"externallmg_1704517770169_IMG_20240105_161334_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770169_IMG_20240105_161334_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4de",
    "name":
"externallmg_1704517770178_IMG_20240105_161641_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770178_IMG_20240105_161641_copy_1200x1600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6598e08a8f39506e8344e4df",
    "name":
"externallmg_1704517770185_IMG_20240105_161944_copy_1200x1600.jpg",
    "path": "cases/6592afa0440d8733f0aab023/
externallmg_1704517770185_IMG_20240105_161944_copy_1200x1600.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6594f0bf2fcdd54ce8d938c9",
    "note": "Pending for Car parking letter from bank side",
    "taskId": "6592afa0440d8733f0aab03d",
    "createdAt": "2024-01-03T05:29:35.784Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "6598dfd88f39506e8344e2c6",
    "note": "revised (Task Reopen)",
    "taskId": "6597a6f92fcdd54ce8dcbce4",
    "createdAt": "2024-01-06T05:06:32.030Z"
  }
],
"createdAt": "2024-01-01T12:27:12.413Z",
"updatedAt": "2024-01-06T05:09:30.281Z",
"__v": 0,
"invoiceId": "6592afa0440d8733f0aab02d",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60af6ae2ffdf65bcd65861d",
"contactPersonName": "Sudeep Day",
"email": "",
```

"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9307982334"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			