

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "firstName": "Rohan ",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Rohan ",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordinatiion",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.17860100631538",
  "longitude": "73.0845602313349"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0845602313349,
```

```
19.17860100631538
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "3/01/2024 11:00 am"
    },
    {
      "dateTime": "3/01/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-03",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
  }
}
```

```
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gharivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "32",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
```

```
"name": "Taluka",
"key": "taluka",
"value": "Kalyan ",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Runwal Garden Phase 4 Building No. 31 & 32",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan Shilphata Road, Bhadra Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Desale Pada",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
}
```



```
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "4/1 to 4/6, 4/9 to 4/11 & others ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
```

```
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1505",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
```

```
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 204",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
    "label": "Proposed Powder Coated Aluminum Sliding Windows"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
```

```
"value": "Proposed_Cement_Plastering",
"label": "Proposed Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Mumbai_Metropolitan_Region_Development_Authority",
"label": "Mumbai Metropolitan Region Development Authority"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Proposed Building No. 31",
"west": "Internal Road ",
"south": "Runwal My City Road ",
"east": "Proposed Building No. 33"
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available ",
"east": "Details not available ",
"south": "Details not available ",
"west": "Details not available "
},
"asPerDocument": {
"north": "Details not available ",
```

```
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per approved plan, the composition of residential flat will be 2 Bedrooms + Living Room + Kitchen + 2 Toilets + Passage ",
"dateOfIssusApprovePlan": "Copy of Approved Plan No. SROT / KGC / 2401 / BP / ITP – Usarghar – Gharivali – Sagaon – 01 / Site-A / Vol-XXVI / 383 / 2021 dated 12.04.2021 issued by Mumbai Metropolitan Region Development Authority. ",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "Building is under construction "
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "63900",
  "landRate": "9600",
  "igrImage": "cases/6593efac440d8733f0abd699/igr_1704339712769_Image.png",
  "squareMeterGuideLineRate": "70290.00",
  "squareFeetGuideLineRate": "6530.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "63900.00",
  "squareMeterGuideLineRate": "70290.00",
  "squareFeetGuideLineRate": "6530.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"monthlyRent": "20,000",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MMRDA norms ",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Along with One Basement Car Parking Space ",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
}
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
```

```
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "32",
"flatFloorNo": "15",
"noOfLifts": "5",
```



```
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
  "area": "609.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6593efac440d8733f0abd699/
routeMap_1704353655629_Image.png",
    "routeLat": "19.181917",
    "routeLng": "73.085917",
    "stationName": "Dombivli",
    "routeDistance": "8.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "bi2td6",
      "name": "bi2td6",
      "image": "cases/6593efac440d8733f0abd699/
routeMap_1704353579179_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6758800.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "6758800.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jan 04 2024 15:14:44 GMT+0530 (India Standard Time)",
  "number": "2304340",
  "dayCount": "10",
  "monthCount": "42",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "Complete",
  "percentage": "5",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "10",
  "percentage": "11.428571428571427",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "10",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "10",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "10",
  "percentage": "1.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "10",
  "percentage": "1.00",
  "isHideFloor": false,
  "status": true
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "27.43",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3979382.00",
  "selectedBuildUpValue": "609.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659548ca2fcdd54ce8da578e",
      "name":
"externalImg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
      "path": "cases/6593efac440d8733f0abd699/
externalImg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "659548ca2fcdd54ce8da578e",
```

```
    "name":
"externallmg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659548ca2fcdd54ce8da578d",
    "name":
"externallmg_1704282313901_WhatsApp_Image_20240103_at_165648_1.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313901_WhatsApp_Image_20240103_at_165648_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659548ca2fcdd54ce8da5791",
    "name":
"externallmg_1704282313940_WhatsApp_Image_20240103_at_165649.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313940_WhatsApp_Image_20240103_at_165649.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659548ca2fcdd54ce8da578f",
    "name":
"externallmg_1704282313929_WhatsApp_Image_20240103_at_165648_3.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313929_WhatsApp_Image_20240103_at_165648_3.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11848",
    "max": "12897"
  },
  "builtUpRateRange": {
    "min": "10772",
    "max": "11725"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "554.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "6593efac440d8733f0abd699",
"ownerName": "Ankita Singh & Anant Kumar ",
"ownerPhoneNo": "8591983562",
"appAddress": "Flat no. 1505, 15th Floor, Building no. 32, Runwal Garden Phase 4,
Gharivali, Kalyan Dombivali ",
"remark": "Value confirm With Shobha madam ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "23/12/2023",
      "from": {
        "value": "Promoter",
```

```
    "label": "Promoter"
  },
  "Promoter": "M/s. Runwal Residency Pvt. Ltd.",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Ankita Singh & Anant Kumar",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "17899 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "921539",
"path": "cases/6593efac440d8733f0abd699/
document_1704203327719_1704203431346_Ankita_Singh_.pdf",
"fileName": "document_1704203327719_1704203431346_Ankita_Singh_.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "29/04/2021",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51700029155 "
},
"isHardCopy": false,
"displayStatus": false,
"id": "752814",
"path": "cases/6593efac440d8733f0abd699/
document_1704352233103_1693993853057_P51700029155.pdf",
"fileName": "document_1704352233103_1693993853057_P51700029155.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "12/04/2021",
  "nameOfApprovingAuthority": {
    "value": "Mumbai_Metropolitan_Region_Development_Authority",
    "label": "Mumbai Metropolitan Region Development Authority"
  },
  "remark": " (As downloaded form RERA site) ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "SROT / Growth Centre / 2401 / BP / ITP – Usarghar – Gharivali – Sagaon –
01 / Site-A / Vol-XXVI / 383 / 2021 "
},
"isHardCopy": false,
"displayStatus": false,
"id": "423455",
"path": "cases/6593efac440d8733f0abd699/document_1704352473279_169399385
3022_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"fileName": "document_1704352473279_1693993853022_1_Commencement_Certi
ficates___NA_Order_for_plotted_development.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "12/04/2021",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "remark": " (As downloaded form RERA site) ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SROT / KGC / 2401 / BP / ITP – Usarghar – Gharivali – Sagaon – 01 / Site-
A / Vol-XXVI / 383 / 2021 "
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1704352566690_1693993853043_20_Building_Plan_Appro
val___NA_Order_for_plotted_development.pdf",
  "path": "cases/6593efac440d8733f0abd699/document_1704352566690_169399385
```

```
3043_20_Building_Plan_Approval____NA_Order_for_plotted_development.pdf",
  "id": "295459",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jan 04 2024 12:46:06 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006063",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "883318",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 02 2024 16:42:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ankita Singh & Anant Kumar ",
    "phone": "8591983562",
    "ownershipShare": "",
    "email": "",
    "id": "229658"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "51.47",
    "totalAreaDocument": "554",
    "docBuiltupPercentage": "10",
    "docFinalBuiltUp": "609.40",
    "docFinalBuiltUpSquareMeter": "56.62",
```

```
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "703419"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6596290b2fcdd54ce8da9f7d",
  "property": "Runwal Garden, Dombivli East",
  "area": "504",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "13",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6500000",
  "expectedRate": "12896.83",
  "builtUpExpectedRate": "11724.39",
  "image": "cases/6593efac440d8733f0abd699/
indicator_1704339564631_Image.png",
  "squareMeter": "46.82",
  "id": "925062"
},
{
  "printlnReport": true,
  "_id": "6596290b2fcdd54ce8da9f7e",
  "property": "Runwal Garden, Dombivli East",
  "area": "353",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "16",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4500000",
  "expectedRate": "12747.88",
  "builtUpExpectedRate": "11588.98",
  "image": "cases/6593efac440d8733f0abd699/
indicator_1704339594930_Image.png",
  "squareMeter": "32.79",
  "id": "423546"
},
}
```

```
{
  "printlnReport": true,
  "_id": "6596290b2fcdd54ce8da9f7f",
  "property": "Runwal Garden, Dombivli East",
  "area": "633",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "22",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7500000",
  "expectedRate": "11848.34",
  "builtUpExpectedRate": "10771.22",
  "image": "cases/6593efac440d8733f0abd699/
indicator_1704339640855_Image.png",
  "squareMeter": "58.81",
  "id": "170096"
},
{
  "printlnReport": true,
  "_id": "6596290b2fcdd54ce8da9f80",
  "property": "Runwal Garden, Dombivli East",
  "area": "612",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "21",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7300000",
  "expectedRate": "11928.10",
  "builtUpExpectedRate": "10843.73",
  "image": "cases/6593efac440d8733f0abd699/
indicator_1704339673251_Image.png",
  "squareMeter": "56.86",
  "id": "517177"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659548ca2fcdd54ce8da578d",
    "name":
"externallmg_1704282313901_WhatsApp_Image_20240103_at_165648_1.jpeg",
```

```
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313901_WhatsApp_Image_20240103_at_165648_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659548ca2fcdd54ce8da578e",
    "name":
"externallmg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313920_WhatsApp_Image_20240103_at_165648_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659548ca2fcdd54ce8da578f",
    "name":
"externallmg_1704282313929_WhatsApp_Image_20240103_at_165648_3.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313929_WhatsApp_Image_20240103_at_165648_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659548ca2fcdd54ce8da5790",
    "name":
"externallmg_1704282313936_WhatsApp_Image_20240103_at_165648.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313936_WhatsApp_Image_20240103_at_165648.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659548ca2fcdd54ce8da5791",
    "name":
"externallmg_1704282313940_WhatsApp_Image_20240103_at_165649.jpeg",
    "path": "cases/6593efac440d8733f0abd699/
externallmg_1704282313940_WhatsApp_Image_20240103_at_165649.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "659548ca2fcdd54ce8da5792",
  "name":
"externalImg_1704282313945_WhatsApp_Image_20240103_at_165650.jpeg",
  "path": "cases/6593efac440d8733f0abd699/
externalImg_1704282313945_WhatsApp_Image_20240103_at_165650.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalName":
"1703225495575_1694516251783_1694241590859_Calculation_1_2.xlsx",
  "filename": "1704339739549_1703225495575_1694516251783_1694241590859_C
alculation_1_2.xlsx",
  "path": "cases/6593efac440d8733f0abd699/processingDocuments/1704339739549
_1703225495575_1694516251783_1694241590859_Calculation_1_2.xlsx",
  "size": "2799850",
  "createdAt": "Thu Jan 04 2024 09:12:20 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-02T11:12:44.228Z",
"updatedAt": "2024-01-04T09:57:02.433Z",
"__v": 0,
"invoiceId": "6593efac440d8733f0abd6a2",
"uniqueNo": "",
"updatedBy": "64cde526dc9f3034f3fefa49",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1505, 15th Floor, Building No 32, Runwal Garden
Phase 4 Building No. 31 & 32, Kalyan Shilphata Road, Bhadra Nagar, Desale Pada,
Village - Gharivali, Taluka - Kalyan , District - Thane , Dombivali (East), PIN - 421 204,
State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Miss. Anuja ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```



```
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "8097793668",
"buildingServicesRate": "2800.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 554.00",
"flatRate": "12200",
"landOtherRate": "9400",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 531.00\nDeck Area in Sq. Ft. =
23.00",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
```

```
},  
"reportGeneratedDate": "Thu Jan 04 2024 12:36:18 GMT+0530 (India Standard  
Time)",  
"siteVisitDate": "2024-01-03"  
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			