

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231052",
    "firstName": "amol Kamble",
    "email": "0_default_amol.kamble@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9967776684"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "AMOL KAMBLE",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
```

```
"role": "PICKUPPERSON",
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.993600794773148",
  "longitude": " 72.84293925660246"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84293925660246,
    18.993600794773148
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/01/2024 11:30 am"
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",

```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Charni Road, Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Panchratna Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Mama Parmanand Marg",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opera House",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1/1487, 3/1487",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "436",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 044",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
```

```
"value": "WoodenFlooring",
"label": "Wooden Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Wooden_frame_openable_window",
"label": "Wooden frame openable window"
},
"fixtures": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering_with_POP_false_Ceiling",
"label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
"ownership": {
"value": "company_ownership",
"label": "company ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Bansilal Building & Road",
"west": "Gardi Mansion & Lamington Road",
"south": "New Queens Road",
```

```
"east": "Sopariwala Building & Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_Purpose",
    "label": "Commercial Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  }
},
```

```
"monthlyRent": "5,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Mr. Pravik Shah",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "1",
"month": "1",
"year": "1975",
"fullDate": "1/1/1975"
},
"planningArea": {
  "value": "Commercial",
  "label": "Commercial"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenancelssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_agreement",
"label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "11",
"ageOfBuilding": "49",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "25",
"flatFloorNo": "4",
"noOfLifts": "12",
"noOfDwellingUnitsInBuilding": "50"
},
"finalPlinthArea": {
"area": "300.00",
"areaType": "Built Up",
```

```
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65962f302fcdd54ce8daa7a5/
routeMap_1704362353179_Image.png",
    "routeLat": "18.955316",
    "routeLng": "72.816555",
    "stationName": "Charni Road",
    "routeDistance": "450 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "wo7lfp",
      "name": "wo7lfp",
      "image": "cases/65962f302fcdd54ce8daa7a5/
routeMap_1704362304778_Image.png"
    }
  ],
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "300.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659654cf2fcdd54ce8db3038",
      "name":
"externallmg_1704350926867_WhatsApp_Image_20240104_at_120840.jpeg",
      "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926867_WhatsApp_Image_20240104_at_120840.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "659654c22fcdd54ce8db2fc8",
    "name":
"externallmg_1704350914748_WhatsApp_Image_20240104_at_120839.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350914748_WhatsApp_Image_20240104_at_120839.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3039",
    "name":
"externallmg_1704350926876_WhatsApp_Image_20240104_at_120844.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926876_WhatsApp_Image_20240104_at_120844.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db303b",
    "name":
"externallmg_1704350926890_WhatsApp_Image_20240104_at_120923_1.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926890_WhatsApp_Image_20240104_at_120923_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db303e",
    "name":
"externallmg_1704350926902_WhatsApp_Image_20240104_at_120924_2.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926902_WhatsApp_Image_20240104_at_120924_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db303c",
    "name":
"externallmg_1704350926893_WhatsApp_Image_20240104_at_120923.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926893_WhatsApp_Image_20240104_at_120923.jpeg",
    "orientation": "landscape"
  }
]
```

```
}
],
"compositionImages": [
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3044",
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926921_WhatsApp_Image_20240104_at_120927_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3043",
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926918_WhatsApp_Image_20240104_at_120926.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3042",
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926915_WhatsApp_Image_20240104_at_120925.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3041",
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926911_WhatsApp_Image_20240104_at_120925_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3048",
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926934_WhatsApp_Image_20240104_at_120928.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659654cf2fcdd54ce8db3045",
```

```
    "name": "Office",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926926_WhatsApp_Image_20240104_at_120927_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "250.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65962f302fcdd54ce8daa7a5",
"ownerName": "Royal Diam",
"ownerPhoneNo": "9824087079",
```



```
"appAddress": "ofc no - 436, pancharatna chs, Opera House, charni road, ",
"remark": "contact - Paras\nvastukala + Vankar ",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "13/01/2017",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "M/s. Choice Diamond",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "M/s. Royal Diam",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "280/2017"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1704361051377_436.pdf",
    "path": "cases/65962f302fcdd54ce8daa7a5/document_1704361051377_436.pdf",
    "id": "338335",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Thu Jan 04 2024 15:07:31 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "30/06/2017",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "M/s. Royal Diam",
    }
  }
]
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "328"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1704361203054_Share_Cert.pdf",
"path": "cases/65962f302fcdd54ce8daa7a5/
document_1704361203054_Share_Cert.pdf",
"id": "793604",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Thu Jan 04 2024 15:10:03 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/12/2023",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "21957"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1704361247199_436_Maint.pdf",
  "path": "cases/65962f302fcdd54ce8daa7a5/
document_1704361247199_436_Maint.pdf",
  "id": "619847",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Jan 04 2024 15:10:47 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006091",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "681922",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 04 2024 09:38:16 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Royal Diam",
    "phone": "9824087079",
    "ownershipShare": "",
    "email": "",
    "id": "507446"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "864202",
    "name": "Office",
    "length": "9.42",
    "length1": "9",
    "length2": "5",
    "width": "25.33",
    "width1": "25",
    "width2": "4",
    "totalArea": "238.56",
    "images": [],
    "extraAreas": [],
    "finalArea": "238.56"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "216040",
```

```
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "250",
"squareMeterArea": "23.23",
"docFinalBuiltUp": "300",
"docFinalBuiltUpSquareMeter": "27.876",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659654c22fcdd54ce8db2fc6",
"name":
"externalImg_1704350914727_WhatsApp_Image_20240104_at_120837.jpeg",
"path": "cases/65962f302fcdd54ce8daa7a5/
externalImg_1704350914727_WhatsApp_Image_20240104_at_120837.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659654c22fcdd54ce8db2fc7",
"name":
"externalImg_1704350914744_WhatsApp_Image_20240104_at_120838.jpeg",
"path": "cases/65962f302fcdd54ce8daa7a5/
externalImg_1704350914744_WhatsApp_Image_20240104_at_120838.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659654c22fcdd54ce8db2fc8",
"name":
"externalImg_1704350914748_WhatsApp_Image_20240104_at_120839.jpeg",
"path": "cases/65962f302fcdd54ce8daa7a5/
externalImg_1704350914748_WhatsApp_Image_20240104_at_120839.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659654cf2fcdd54ce8db3038",
    "name":
"externallmg_1704350926867_WhatsApp_Image_20240104_at_120840.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926867_WhatsApp_Image_20240104_at_120840.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db3039",
    "name":
"externallmg_1704350926876_WhatsApp_Image_20240104_at_120844.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926876_WhatsApp_Image_20240104_at_120844.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303a",
    "name":
"externallmg_1704350926884_WhatsApp_Image_20240104_at_120845.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926884_WhatsApp_Image_20240104_at_120845.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303b",
    "name":
"externallmg_1704350926890_WhatsApp_Image_20240104_at_120923_1.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926890_WhatsApp_Image_20240104_at_120923_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303c",
    "name":
"externallmg_1704350926893_WhatsApp_Image_20240104_at_120923.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926893_WhatsApp_Image_20240104_at_120923.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303d",
    "name":
"externallmg_1704350926898_WhatsApp_Image_20240104_at_120924_1.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926898_WhatsApp_Image_20240104_at_120924_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303e",
    "name":
"externallmg_1704350926902_WhatsApp_Image_20240104_at_120924_2.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926902_WhatsApp_Image_20240104_at_120924_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db303f",
    "name":
"externallmg_1704350926905_WhatsApp_Image_20240104_at_120924.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926905_WhatsApp_Image_20240104_at_120924.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db3040",
    "name":
"externallmg_1704350926908_WhatsApp_Image_20240104_at_120925_1.jpeg",
    "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926908_WhatsApp_Image_20240104_at_120925_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659654cf2fcdd54ce8db3041",
```

```
"name":
"externallmg_1704350926911_WhatsApp_Image_20240104_at_120925_2.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926911_WhatsApp_Image_20240104_at_120925_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3042",
  "name":
"externallmg_1704350926915_WhatsApp_Image_20240104_at_120925.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926915_WhatsApp_Image_20240104_at_120925.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3043",
  "name":
"externallmg_1704350926918_WhatsApp_Image_20240104_at_120926.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926918_WhatsApp_Image_20240104_at_120926.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3044",
  "name":
"externallmg_1704350926921_WhatsApp_Image_20240104_at_120927_1.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926921_WhatsApp_Image_20240104_at_120927_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3045",
  "name":
"externallmg_1704350926926_WhatsApp_Image_20240104_at_120927_2.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926926_WhatsApp_Image_20240104_at_120927_2.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3046",
  "name":
"externallmg_1704350926928_WhatsApp_Image_20240104_at_120927.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926928_WhatsApp_Image_20240104_at_120927.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3047",
  "name":
"externallmg_1704350926931_WhatsApp_Image_20240104_at_120928_1.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926931_WhatsApp_Image_20240104_at_120928_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3048",
  "name":
"externallmg_1704350926934_WhatsApp_Image_20240104_at_120928.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926934_WhatsApp_Image_20240104_at_120928.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659654cf2fcdd54ce8db3049",
  "name":
"externallmg_1704350926937_WhatsApp_Image_20240104_at_120929.jpeg",
  "path": "cases/65962f302fcdd54ce8daa7a5/
externallmg_1704350926937_WhatsApp_Image_20240104_at_120929.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```



```
"createdAt": "2024-01-04T04:08:16.874Z",
"updatedAt": "2024-01-04T10:00:57.232Z",
"__v": 0,
"invoiceId": "65962f312fcdd54ce8daa7ae",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Office No. 436, 4th Floor, Panchratna Co-op. Hsg. Soc.
Ltd., CTS No. 1/1487, 3/1487, Mama Parmanand Marg, Opera House, Girgaon
Division, Charni Road, Mumbai, PIN - 400 044, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr. Pravik Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "9920094472",
"briefDescOfProperty": "Office",
"carpetTotal": "238.56",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "262.42",
"finalCarpetArea": "238.56",
"finalSalableArea": "288.66",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Sale Deed",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 250.00",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  }
},
"leaseDetails": {
```

```

    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

Name	Length	Width	Total
Composition :			
Office	9'5"	25'4"	238.56
Other Composition :			