

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "firstName": "Rajeev kumar ",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "725000",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 362.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "657157794999312746cdc402",
"role": "MAKER + RATE VERFIER",
"firstName": "Komal",
"email": "pawarkomal580@gmail.com",
"lastName": "pawar",
"mobileNo": "7447457799",
"designation": "Rate Verifier +Maker",
"shortName": "KP",
```

```
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
```

```
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.166451880185484",
  "longitude": "72.83848826626213"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83848826626213,
    19.166451880185484
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
```

```
{
  "dateTime": "4/01/2024 06:00 pm"
}
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-01-06",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "P H Pahadi Goregaon",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Raj Residency Co. Op. Hsg. Soc. (Prop)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Subhash Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "New Hanuman Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
```



```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "50 A (Part) ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 400 104 ",
"label": false
},
"suburb": {
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "Goregaon (West), Mumbai",
"label": false
}
},
"flatSpecifications": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_wood_door_frame_with_solid_flush_door",
"label": "Teak wood door frame with solid flush door"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"asPerDocumentAgreement": {
"north": "By CTS No. 50 (pt), Subhash Nagar Society ",
"west": "By Existing Hanuman Nagar Public Road ",
"south": "By Public Road ",
"east": "By CTS No. 50 (pt), New Subhash Nagar Society "
},
"unitBoundaries": {
"asPerActual": {
"north": "Open to Sky ",
"east": "Open to Sky ",
"south": "Passage / Flat No. 601 ",
"west": "Flat No. 603"
},
"asPerDocument": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved plan not provided, not verified. ",
"approvePlanVerified": "N.A.",
```

```
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "15",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "26050",
  "depreciatedBuildingRate": "2550"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "160470.00",
  "landRate": "76820",
  "igrImage": "cases/65969f6f2fcdd54ce8dc07a0/igr_1704433191249_Image.png",
  "squareMeterGuideLineRate": "168494.00",
  "squareFeetGuideLineRate": "15654.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "90",
  "rate": "14802.00",
  "squareFeetGuideLineRate": "14802.00",
  "squareMeterGuideLineRate": "159327.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "25000.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM Norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2014",
    "fullDate": "1/1/2014"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```

```
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
"value": "Approx.",
"label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "10",
"totalLifeBuilding": "60",
"estimatedAge": "50",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "564.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
}
```



```
    },
    "routeMapImg": "cases/65969f6f2fcdd54ce8dc07a0/
routeMap_1704809046632_Image.png",
    "routeLat": "19.166442",
    "routeLng": "72.838526",
    "stationName": "Goregaon ",
    "routeDistance": "2.1 Km "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "aqh377",
      "name": "aqh377",
      "image": "cases/65969f6f2fcdd54ce8dc07a0/
routeMap_1704808962024_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
```

```
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12243500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "12243500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jan 15 2024 18:05:49 GMT+0530 (India Standard Time)",
  "number": "2304525",
  "dayCount": "13",
  "monthCount": "227",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8348328.00",
  "selectedBuildUpValue": "564.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659b7a068f39506e83465ec3",
      "name": "externallmg_1704688134783_IMG20240106WA0194.jpg",
      "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134783_IMG20240106WA0194.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "659b7a068f39506e83465ec7",
      "name": "externallmg_1704688134791_IMG20240106WA0198.jpg",
      "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134791_IMG20240106WA0198.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "659b79f68f39506e83465e2b",
      "name": "externallmg_1704688118204_IMG20240106WA0200.jpg",
      "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118204_IMG20240106WA0200.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
```

```
{
  "status": false,
  "_id": "659b79f68f39506e83465e32",
  "name": "externallmg_1704688118235_IMG20240106WA0208.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118235_IMG20240106WA0208.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [
  {
    "status": false,
    "_id": "659b79f68f39506e83465e2a",
    "name": "externallmg_1704688118199_IMG20240106WA0199.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118199_IMG20240106WA0199.jpg",
    "orientation": "portrait"
  }
],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "659b7a068f39506e83465ebd",
    "name": "externallmg_1704688134767_IMG20240106WA0187.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134767_IMG20240106WA0187.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659b7a068f39506e83465ec2",
    "name": "externallmg_1704688134781_IMG20240106WA0192.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134781_IMG20240106WA0192.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "659b79f68f39506e83465e2c",
    "name": "Living Room",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118210_IMG20240106WA0201.jpg",
    "orientation": "portrait"
  }
],
```

```
{
  "status": false,
  "_id": "659b79f68f39506e83465e2d",
  "name": "Living Room",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118214_IMG20240106WA0203.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "659b79f68f39506e83465e2e",
  "name": "Living Room",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118217_IMG20240106WA0204.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24272",
    "max": "25532"
  },
  "builtUpRateRange": {
    "min": "20227",
    "max": "21277"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "470.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65969f6f2fcdd54ce8dc07a0",
"ownerName": "Mr. Jaison Baby Thomas & Mrs. Anu George",
"ownerPhoneNo": "9969324924",
"appAddress": "B 604 RAJ RESIDENCY GOREGAON NAVJAGRUTI CHS LTD NEW
HANUMAN ROAD SUBHASH NAGAR \nGOREGAON WEST MUMBAI 400401",
"remark": "9967342754 vaishali jadhav\n",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "08/08/2016",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Raj Builders & Developers ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Jaison Baby Thomas & Mrs. Anu George",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "8202 / 2016"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "377624",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
document_1704369724634_1704369829219_AGREEMENT_0001_4.pdf",
    "fileName":
"document_1704369724634_1704369829219_AGREEMENT_0001_4.pdf"
```

```
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "17/01/2009",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CHE / 9670 / BP (WS) / AP / AR"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1704807745951_96862.pdf",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/document_1704807745951_96862.pdf",
  "id": "276268",
  "uploadedBy": "657157794999312746cdc402",
  "createdAt": "Tue Jan 09 2024 19:12:26 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006112",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "251230",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 04 2024 17:37:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Jaison Baby Thomas & Mrs. Anu George",
    "phone": "9969324924",
    "ownershipShare": "",
    "email": "",
    "id": "685033"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "623629",
    "name": "Living Room",
    "length": "15.58",
    "length1": "15",
    "length2": "7",
    "width": "9.67",
    "width1": "9",
    "width2": "8",
    "totalArea": "150.64",
    "images": [],
    "extraAreas": [],
    "finalArea": "150.64"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "7.00",
    "length1": "7",
    "length2": "0",
    "width": "5.00",
    "width1": "5",
    "width2": "0",
    "totalArea": "35.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "35.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Kitchen",
```

```
"length": "8.33",
"length1": "8",
"length2": "4",
"width": "8.25",
"width1": "8",
"width2": "3",
"totalArea": "68.75",
"images": [],
"extraAreas": [],
"finalArea": "68.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "15.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.50",
  "length1": "11",
  "length2": "6",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "112.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "112.12"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.42",
  "length1": "3",
  "length2": "5",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "23.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "26.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.56"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "43.66",
"totalAreaDocument": "470.00",
"docBuiltpUpPercentage": "20",
"docFinalBUILTUp": "564.00",
"docFinalBUILTUpSquareMeter": "52.40",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "177878"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6597963f2fcdd54ce8dc6ef7",
  "property": "Raj Residency I Goregaon West, Mumbai",
  "area": "331.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "8451000.00",
  "expectedRate": "25531.72",
  "builtUpExpectedRate": "21276.44",
  "image": "cases/65969f6f2fcdd54ce8dc07a0/indicator_1704432728030_Image.png",
  "squareMeter": "30.75",
  "id": "687464"
},
{
  "printlnReport": true,
  "_id": "6597963f2fcdd54ce8dc6ef8",
  "property": "1 BHK Flat For Sale in Raj Residency, Motilal Nagar 3, Mumbai",
  "area": "475.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "12000000.00",
```

```
"expectedRate": "25263.16",
"builtUpExpectedRate": "21052.63",
"image": "cases/65969f6f2fcdd54ce8dc07a0/indicator_1704432773747_Image.png",
"squareMeter": "44.13",
"id": "469592"
},
{
  "printlnReport": true,
  "_id": "6597963f2fcdd54ce8dc6ef9",
  "property": "1 BHK Flat In Samarth Srushti For Sale In Goregaon West",
  "area": "464.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "11500000.00",
  "expectedRate": "24784.48",
  "builtUpExpectedRate": "20653.74",
  "image": "cases/65969f6f2fcdd54ce8dc07a0/indicator_1704432934048_Image.png",
  "squareMeter": "43.11",
  "id": "914373"
},
{
  "printlnReport": true,
  "_id": "6597963f2fcdd54ce8dc6efa",
  "property": "2 BHK Flat In Sethia Link View For Sale In Goregaon West",
  "area": "721.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "17500000.00",
  "expectedRate": "24271.84",
  "builtUpExpectedRate": "20226.54",
  "image": "cases/65969f6f2fcdd54ce8dc07a0/indicator_1704433074338_Image.png",
  "squareMeter": "66.98",
  "id": "819643"
},
{
  "printlnReport": false,
  "_id": "65a5240802c44c777bb5d9da",
  "property": "2 BHK Flat In Mavji Meeras Empire , Goregaon West For Sale In
Goregaon West",
  "area": "639.00",
```



```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Nobroker.com",
"expectedPrice": "17500000.00",
"expectedRate": "27386.54",
"builtUpExpectedRate": "22822.12",
"image": "cases/65969f6f2fcdd54ce8dc07a0/indicator_1705321480164_Image.png",
"squareMeter": "59.37",
"id": "196625"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659b79f68f39506e83465e2a",
"name": "externalImg_1704688118199_IMG20240106WA0199.jpg",
"path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688118199_IMG20240106WA0199.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659b79f68f39506e83465e2b",
"name": "externalImg_1704688118204_IMG20240106WA0200.jpg",
"path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688118204_IMG20240106WA0200.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659b79f68f39506e83465e2c",
"name": "externalImg_1704688118210_IMG20240106WA0201.jpg",
"path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688118210_IMG20240106WA0201.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "659b79f68f39506e83465e2d",
"name": "externalImg_1704688118214_IMG20240106WA0203.jpg",
```

```
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118214_IMG20240106WA0203.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b79f68f39506e83465e2e",
    "name": "externallmg_1704688118217_IMG20240106WA0204.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118217_IMG20240106WA0204.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b79f68f39506e83465e2f",
    "name": "externallmg_1704688118222_IMG20240106WA0205.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118222_IMG20240106WA0205.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b79f68f39506e83465e30",
    "name": "externallmg_1704688118227_IMG20240106WA0206.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118227_IMG20240106WA0206.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b79f68f39506e83465e31",
    "name": "externallmg_1704688118231_IMG20240106WA0207.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118231_IMG20240106WA0207.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b79f68f39506e83465e32",
    "name": "externallmg_1704688118235_IMG20240106WA0208.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118235_IMG20240106WA0208.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b79f68f39506e83465e33",
  "name": "externallmg_1704688118238_IMG20240106WA0209.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118238_IMG20240106WA0209.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b79f68f39506e83465e34",
  "name": "externallmg_1704688118241_IMG20240106WA0210.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118241_IMG20240106WA0210.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b79f68f39506e83465e35",
  "name": "externallmg_1704688118244_IMG20240106WA0211.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688118244_IMG20240106WA0211.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465eb4",
  "name": "externallmg_1704688134742_IMG20240106WA0210.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134742_IMG20240106WA0210.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465eb5",
  "name": "externallmg_1704688134743_IMG20240106WA0211.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134743_IMG20240106WA0211.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465eb6",
    "name": "externallmg_1704688134747_IMG20240106WA0212.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134747_IMG20240106WA0212.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465eb7",
    "name": "externallmg_1704688134749_IMG20240106WA0213.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134749_IMG20240106WA0213.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465eb8",
    "name": "externallmg_1704688134751_IMG20240106WA0214.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134751_IMG20240106WA0214.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465eb9",
    "name": "externallmg_1704688134757_IMG20240106WA0183.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134757_IMG20240106WA0183.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465eba",
    "name": "externallmg_1704688134763_IMG20240106WA0184.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134763_IMG20240106WA0184.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ebb",
  "name": "externallmg_1704688134764_IMG20240106WA0185.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134764_IMG20240106WA0185.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ebc",
  "name": "externallmg_1704688134766_IMG20240106WA0186.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134766_IMG20240106WA0186.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ebd",
  "name": "externallmg_1704688134767_IMG20240106WA0187.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134767_IMG20240106WA0187.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ebe",
  "name": "externallmg_1704688134769_IMG20240106WA0188.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134769_IMG20240106WA0188.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ebf",
  "name": "externallmg_1704688134772_IMG20240106WA0189.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externallmg_1704688134772_IMG20240106WA0189.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465ec0",
    "name": "externalimg_1704688134776_IMG20240106WA0190.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalimg_1704688134776_IMG20240106WA0190.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465ec1",
    "name": "externalimg_1704688134778_IMG20240106WA0191.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalimg_1704688134778_IMG20240106WA0191.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465ec2",
    "name": "externalimg_1704688134781_IMG20240106WA0192.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalimg_1704688134781_IMG20240106WA0192.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465ec3",
    "name": "externalimg_1704688134783_IMG20240106WA0194.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalimg_1704688134783_IMG20240106WA0194.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659b7a068f39506e83465ec4",
    "name": "externalimg_1704688134786_IMG20240106WA0195.jpg",
    "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalimg_1704688134786_IMG20240106WA0195.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "659b7a068f39506e83465ec5",
  "name": "externalImg_1704688134788_IMG20240106WA0196.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688134788_IMG20240106WA0196.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ec6",
  "name": "externalImg_1704688134790_IMG20240106WA0197.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688134790_IMG20240106WA0197.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659b7a068f39506e83465ec7",
  "name": "externalImg_1704688134791_IMG20240106WA0198.jpg",
  "path": "cases/65969f6f2fcdd54ce8dc07a0/
externalImg_1704688134791_IMG20240106WA0198.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60092304a16fab0f2af9b0c2",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Nitesh",
      "lastName": "Khedekar",
      "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6597e7ea8f39506e83447be3",
    "note": "1.17 - 1.25",
    "taskId": "6596a5b72fcdd54ce8dc19c9",
```

```
"createdAt": "2024-01-05T11:28:42.638Z"
},
{
  "createdBy": {
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Nitesh",
    "lastName": "Khedekar",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "6597e8098f39506e83447c53",
  "note": "1.17 = 1.25 REQ.",
  "taskId": "6596a5b72fcdd54ce8dc19c9",
  "createdAt": "2024-01-05T11:29:13.128Z"
}
],
"createdAt": "2024-01-04T12:07:11.081Z",
"updatedAt": "2024-01-15T12:37:53.499Z",
"__v": 0,
"invoiceId": "65969f6f2fcdd54ce8dc07ab",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 604, 6th Floor, Wing - B, Raj Residency Co. Op.
Hsg. Soc. (Prop), Subhash Nagar, New Hanuman Road, Village - P H Pahadi
Goregaon, Goregaon (West), Mumbai, Taluka - Borivali, District - Mumbai Suburban ,
PIN - 400 104 , State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Jaison B Thomas ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9969324924",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
```



```
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 470.00",
"flatRate": "26500.00",
"landOtherRate": "23500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + Passage + 2
Toilet",
"carpetTotal": "431.13",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "517.36",
"finalCarpetArea": "431.13",
"finalSalableArea": "569.09",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Mon Jan 15 2024 17:46:55 GMT+0530 (India Standard
Time)",
```

"siteVisitDate": "2024-01-06"

}

Name	Length	Width	Total
Composition :			
Living Room	15'7"	9'8"	150.64
Dining	7'0"	5'0"	35.00
Kitchen	8'4"	8'3"	68.75
Passage	5'0"	3'0"	15.00
Bedroom	11'6"	9'9"	112.12
Toilet	3'5"	6'9"	23.06
Toilet	3'9"	7'1"	26.56
Other Composition :			