

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb59"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231331",
    "firstName": "Namrata Ghone",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9769152981"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",

```

```
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb59",
  "branchCode": "000352",
  "type": "BRANCH",
  "name": "RACPC Nashik ",
  "email": "sbi.10518@sbi.co.in",
  "mobileNo": "02532501640",
  "alternateMobileNo": "",
  "address": "1st Floor,Patel Plaza ,N.D.Patel Road,Opp BSNL,Landmark Seawoods
Navratna Hotel Nashik-422001",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
```

```
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.992281565560802",
  "longitude": "73.70930807793638"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Pimpalgaon Bahula",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "38",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "Behind State Bank of India , Jaswant Nagar, Shramik Nagar, Gangapur
Satpur Link Road, ",
"label": false
},
"wing": {
"status": false,
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "213/1",
"label": true
},
"hissaNo": {
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```



```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "659d27578f39506e834a028a",
"ownerName": "Sunil Dhakane",
"ownerPhoneNo": "9011704947",
"fullAddress": " Row House No. Basement Floor, Behind State Bank of India ,
```

Jaswant Nagar, Shramik Nagar, Gangapur Satpur Link Road, , Plot No. 38, New/
Current Survey No. 213/1, Village - Pimpalgaon Bahula, Taluka - Nashik, District -
Nashik, Nashik, 422007",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1704798026471_Dhakne_Building_plan_.pdf",

"path": "cases/659d27578f39506e834a028a/

document_1704798026471_Dhakne_Building_plan_.pdf",

"id": "379248",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Jan 09 2024 16:30:39 GMT+0530 (India Standard Time)"

},

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1704798033691_Sunil_Dhakane_agreement_.pdf",

"path": "cases/659d27578f39506e834a028a/

document_1704798033691_Sunil_Dhakane_agreement_.pdf",

"id": "228528",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Jan 09 2024 16:30:39 GMT+0530 (India Standard Time)"

}

],

"assignmentType": {

"value": "Retail",

"label": "Retail"

},

"caseNumber": "006234",

"createdBy": "63f9ed37ce84bf289ba991ac",

"caseHistory": [

{

"id": "288210",

"title": "Create Lead",

"description": "Create Lead",

"datetime": "Tue Jan 09 2024 16:30:39 GMT+0530 (India Standard Time)"


```
}
],
"owners": [
  {
    "name": "Sunil Dhakane",
    "phone": "9011704947",
    "ownershipShare": "",
    "email": "",
    "id": "333183"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0783",
    "name":
"externalImg_1704799259140_WhatsApp_Image_20240108_at_22648_PM_1.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externalImg_1704799259140_WhatsApp_Image_20240108_at_22648_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0784",
    "name":
"externalImg_1704799259222_WhatsApp_Image_20240108_at_22648_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externalImg_1704799259222_WhatsApp_Image_20240108_at_22648_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0785",
    "name":
"externalImg_1704799259321_WhatsApp_Image_20240108_at_22650_PM_1.jpeg",
```

```
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259321_WhatsApp_Image_20240108_at_22650_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0786",
    "name":
"externallmg_1704799259423_WhatsApp_Image_20240108_at_22650_PM_2.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259423_WhatsApp_Image_20240108_at_22650_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0787",
    "name":
"externallmg_1704799259463_WhatsApp_Image_20240108_at_22650_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259463_WhatsApp_Image_20240108_at_22650_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0788",
    "name":
"externallmg_1704799259560_WhatsApp_Image_20240108_at_22652_PM_1.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259560_WhatsApp_Image_20240108_at_22652_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0789",
    "name":
"externallmg_1704799259615_WhatsApp_Image_20240108_at_22652_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259615_WhatsApp_Image_20240108_at_22652_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659d2c1c02c44c777bad078a",
    "name":
"externallmg_1704799259657_WhatsApp_Image_20240108_at_22653_PM_1.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259657_WhatsApp_Image_20240108_at_22653_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad078b",
    "name":
"externallmg_1704799259695_WhatsApp_Image_20240108_at_22653_PM_2.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259695_WhatsApp_Image_20240108_at_22653_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad078c",
    "name":
"externallmg_1704799259722_WhatsApp_Image_20240108_at_22653_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259722_WhatsApp_Image_20240108_at_22653_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad078d",
    "name":
"externallmg_1704799259747_WhatsApp_Image_20240108_at_22656_PM_1.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259747_WhatsApp_Image_20240108_at_22656_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad078e",
    "name":
"externallmg_1704799259761_WhatsApp_Image_20240108_at_22656_PM_2.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259761_WhatsApp_Image_20240108_at_22656_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad078f",
    "name":
"externallmg_1704799259787_WhatsApp_Image_20240108_at_22656_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259787_WhatsApp_Image_20240108_at_22656_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0790",
    "name":
"externallmg_1704799259847_WhatsApp_Image_20240108_at_22657_PM_1.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259847_WhatsApp_Image_20240108_at_22657_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0791",
    "name":
"externallmg_1704799259940_WhatsApp_Image_20240108_at_22657_PM_2.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259940_WhatsApp_Image_20240108_at_22657_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0792",
    "name":
"externallmg_1704799259967_WhatsApp_Image_20240108_at_22657_PM.jpeg",
    "path": "cases/659d27578f39506e834a028a/
externallmg_1704799259967_WhatsApp_Image_20240108_at_22657_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659d2c1c02c44c777bad0793",
```

```
    "name":
"externallmg_1704799260048_WhatsApp_Image_20240108_at_22658_PM_1.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799260048_WhatsApp_Image_20240108_at_22658_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c1c02c44c777bad0794",
  "name":
"externallmg_1704799260101_WhatsApp_Image_20240108_at_22658_PM_2.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799260101_WhatsApp_Image_20240108_at_22658_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c1c02c44c777bad0795",
  "name":
"externallmg_1704799260158_WhatsApp_Image_20240108_at_22658_PM.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799260158_WhatsApp_Image_20240108_at_22658_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c1c02c44c777bad0796",
  "name":
"externallmg_1704799260174_WhatsApp_Image_20240108_at_22659_PM_1.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799260174_WhatsApp_Image_20240108_at_22659_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c2502c44c777bad0831",
  "name":
"externallmg_1704799268755_WhatsApp_Image_20240108_at_22654_PM.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799268755_WhatsApp_Image_20240108_at_22654_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c2502c44c777bad0832",
  "name":
"externallmg_1704799268780_WhatsApp_Image_20240108_at_22659_PM_2.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799268780_WhatsApp_Image_20240108_at_22659_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c2502c44c777bad0833",
  "name":
"externallmg_1704799268820_WhatsApp_Image_20240108_at_22659_PM.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799268820_WhatsApp_Image_20240108_at_22659_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c2502c44c777bad0834",
  "name":
"externallmg_1704799268860_WhatsApp_Image_20240108_at_22700_PM_1.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799268860_WhatsApp_Image_20240108_at_22700_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659d2c2502c44c777bad0835",
  "name":
"externallmg_1704799268913_WhatsApp_Image_20240108_at_22700_PM.jpeg",
  "path": "cases/659d27578f39506e834a028a/
externallmg_1704799268913_WhatsApp_Image_20240108_at_22700_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

```
"createdAt": "2024-01-09T11:00:39.743Z",
"updatedAt": "2024-01-09T11:21:09.035Z",
"__v": 0,
"invoiceId": "659d27578f39506e834a0293",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Sunil Dhakane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9011704947"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			