

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d8"
    },
    "type": "CREDITOFFICER",
    "_id": "659cdb3c8f39506e8348d695",
    "firstName": "Sumedh",
    "lastName": "Chavan",
    "mobileNo": "",
    "workMobileNo": "9769639911",
    "email": "1so1amt2.04732@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d8",
  "branchCode": "000031",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Andheri (East)",
  "email": "varsha.bhat@sbi.co.in",
  "mobileNo": "022-26819792",
  "alternateMobileNo": "022-26822158",
  "address": "102, Natraj Building, 194, Sir M. V. Road, W. E. Highway-Metro Junction,
Andheri (East), Mumbai - 400 069, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - IFB ANDHERI(E)",
  "fax": "022-26831648",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
```

```
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "_id": "5fc78e26625ecd20ec1f88e9",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "firstName": "Vaishali",
  "lastName": "Sarmalkar",
  "shortName": "VS",
  "email": "v.sarmalkar@vastukala.org",
  "designation": "",
  "mobileNo": "9004437379",
  "role": "MAKER+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "1"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.125903278904698",
  "longitude": "72.82909389325242"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-10",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-10",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-09",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Andheri",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "C-3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Skyvistas Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "D. N. Nagar Municipal School Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "MHADA Layout, Bhai Bhagat Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "106-A (Pt)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "195 (pt)",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1702",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 053",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (West)\t",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "WoodenFlooring",
    "label": "Wooden Flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "HigherMiddleClass",
    "label": "Higher Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "B' Wing of Sky Vistas",
    "west": "D N Nagar Municipal School Road",
    "south": "Internal Road / Shri Harshad C Valia International School",
    "east": "Barfiwala School Road"
  },
  "asPerDocumentAgreement": {
    "north": "40 Feet Wide Road",
    "west": "60 Feet Wide Road",
    "south": "40 Feet Wide Road",
    "east": "60 Feet Wide Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
```

```
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No. CE /
8913 / BSII / WS / AK Dated 06.09.2016 issued by MCGM.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "As per document flat is on 14th Habitable floor, as per site it is on 17th
floor.",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "42140",
  "depreciatedBuildingRate": "2640"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "141530",
  "landRate": "69790",
  "igrImage": "cases/659d3c8f02c44c777bad55e7/igr_1705127711007_Image.png",
  "squareMeterGuideLineRate": "155683.00",
  "squareFeetGuideLineRate": "14463.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "92",
  "rate": "13825.00",
  "squareMeterGuideLineRate": "148812.00",
  "squareFeetGuideLineRate": "13825.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "I_Class",
    "label": "I Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "92,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Pavali Gulati (PEEWEE Production LLP)",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "2 Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  }
},
```

```
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
```

```
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "3",
"noOfPodium": "3",
"noOfAmenityFloors": "",
"noOfFloors": "16",
"flatFloorNo": "14",
"noOfLifts": "4",
```



```
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1080.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/659d3c8f02c44c777bad55e7/
routeMap_1705138935250_Image.png",
    "routeLat": "19.125675",
    "routeLng": "72.829084",
    "stationName": "Andheri",
    "routeDistance": "450m"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "kprpws",
      "name": "kprpws",
      "image": "cases/659d3c8f02c44c777bad55e7/
routeMap_1705138735167_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "2",
"othersRate": "1500000",
"totalothersRate": "3000000",
"finaltotal": "40926000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "37926000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "14931000.00",
  "selectedBuildUpValue": "1080.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659df70f02c44c777bad7b8b",
      "name": "externallmg_1704851103628_1704851199063_image_5.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851103628_1704851199063_image_5.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "659df70f02c44c777bad7b65",
      "name": "externallmg_1704850860521_1704850963144_image_7.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860521_1704850963144_image_7.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
```

```
{
  "status": false,
  "_id": "659df70f02c44c777bad7b8d",
  "name": "externallmg_1704851109967_1704851199063_image_7.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851109967_1704851199063_image_7.jpeg",
  "orientation": "landscape"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b69",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860941_1704850963144_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b6d",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861574_1704850963144_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b72",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850940598_1704851050193_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b73",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850949227_1704851050193_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "659df70f02c44c777bad7b77",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850991996_1704851050193_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b7f",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851025891_1704851050193_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "659df70f02c44c777bad7b80",
    "name": "Living Room",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851031887_1704851050193_image_14.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "35606",
    "max": "47101"
  },
  "builtUpRateRange": {
    "min": "29672",
    "max": "39252"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```



```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
```

```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "900.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "659d3c8f02c44c777bad55e7",
"ownerName": "Mr. Dhaval Atul Barot",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "7021081581",
"contactPersonName": "Mr. Chandrakant Humbe",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Dhaval Atul Barot",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "521607"
  },
  {
    "name": "Mrs. Chaitali Dhaval Barot",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "682236"
  }
],
"caseReferredBy": "62727444afd7d55eddee092c",
"relationWithOwner": "Representative of Owner",
"fullAddress": "Residential Flat No. 1702, 14th Floor, Building No C-3, Wing - A,
Skyvistas Co-op. Hsg. Soc. Ltd., D. N. Nagar Municipal School Road, MHADA Layout,
Bhai Bhagat Marg, Village - Andheri, Andheri (West)\t, Taluka - Andheri, District -
Mumbai Suburban, PIN - 400 053, State - Maharashtra, India",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "inputs": {
      "documentDate": "27/07/2016",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Bharat Infrastructure & Engineering Pvt. Ltd.",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Dhaval Atul Barot & Mrs. Chaitali Dhaval Barot",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "6768/2016"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "668108",
    "path": "cases/659d3c8f02c44c777bad55e7/document_1704803525767_1702__SK
YVISTAS_AGREEMENT_FOR_SALE___DHAVAL_BAROT__CHAITALI_BAROT_27_J
ULY_2016.pdf",
    "fileName": "document_1704803525767_1702__SKYVISTAS_AGREEMENT_FOR_
SALE___DHAVAL_BAROT__CHAITALI_BAROT_27_JULY_2016.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "07/09/2016",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_Of_Greater_Mumbai",
        "label": "Municipal Corporation Of Greater Mumbai"
      },
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "CE / 8913 / WS / AK"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1705142600007_Part_OC__2016.pdf",
"path": "cases/659d3c8f02c44c777bad55e7/
document_1705142600007_Part_OC__2016.pdf",
"id": "307015",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Sat Jan 13 2024 16:13:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/10/2023",
    "remark": "in the name of Mr. Dhaval Atul Barot & Mrs. Chaitali Dhaval Barot
issued by Skyvisgtas Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "7498"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "662699",
  "path": "cases/659d3c8f02c44c777bad55e7/
document_1705142758324_Maintenance_Bill.pdf",
  "fileName": "document_1705142758324_Maintenance_Bill.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "02/01/2012",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    }
  }
}
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 8913 / BSII / WS / AH / AK"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName":
"document_1705142827307_document_1704859400697_Sky_Vistas__CC.pdf",
  "path": "cases/659d3c8f02c44c777bad55e7/
document_1705142827307_document_1704859400697_Sky_Vistas__CC.pdf",
  "id": "796185",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Sat Jan 13 2024 16:17:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "18/09/2019",
    "remark": "bearing Nos. 0781 to 0790 having 10 Shares of Rs. 50/- each in the
name of Mr. Dhaval Atul Barot & Mrs. Chaitali Dhaval Barot issued by Sjyvistas Co-op.
Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "78"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1705143000294_document_1704859376870_Share_Certifi
cate_1702Dhaval_Barot__Chaitali_Barot.pdf",
  "path": "cases/659d3c8f02c44c777bad55e7/document_1705143000294_document_
1704859376870_Share_Certificate_1702Dhaval_Barot__Chaitali_Barot.pdf",
  "id": "881748",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Sat Jan 13 2024 16:20:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
```

```
"label": "Approved Building Plan"
},
"inputs": {
  "documentDate": "09/03/2020",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MHADA - 105 / 024 / 2020"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1705146525733_Plan.pdf",
"path": "cases/659d3c8f02c44c777bad55e7/document_1705146525733_Plan.pdf",
"id": "875923",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Sat Jan 13 2024 17:18:53 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "06/09/2016",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CE / 8913 / BSII / WS / AK"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1705299289482_plan2016.pdf",
  "path": "cases/659d3c8f02c44c777bad55e7/
document_1705299289482_plan2016.pdf",
  "id": "326993",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9",
```

```
    "createdAt": "Mon Jan 15 2024 11:44:58 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "006242",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "136382",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Jan 09 2024 18:01:11 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "999754",
    "name": "Living Room",
    "length": "25.17",
    "length1": "25",
    "length2": "2",
    "width": "5.25",
    "width1": "5",
    "width2": "3",
    "totalArea": "132.12",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "65a261f002c44c777bb426b7",
        "name": "Living with Kitchen",
```

```
    "extraAreaType": "Add",
    "length": "10.50",
    "length1": "10",
    "length2": "6",
    "width": "20.67",
    "width1": "20",
    "width2": "8",
    "totalArea": "217.00"
  }
],
"finalArea": "349.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "19.00",
  "width1": "19",
  "width2": "00",
  "totalArea": "96.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "23.61",
  "images": [],
  "extraAreas": [],
```



```
"finalArea": "23.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.33",
  "length1": "10",
  "length2": "4",
  "width": "14.58",
  "width1": "14",
  "width2": "7",
  "totalArea": "150.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Cupboard",
  "length": "2.25",
  "length1": "2",
  "length2": "3",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "15.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "9.75",
```

```
"length1": "9",
"length2": "9",
"width": "2.67",
"width1": "2",
"width2": "8",
"totalArea": "26.00",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "65a262d102c44c777bb429b2",
    "name": "Toilet",
    "extraAreaType": "Add",
    "length": "5.42",
    "length1": "5",
    "length2": "5",
    "width": "6.92",
    "width1": "6",
    "width2": "11",
    "totalArea": "37.46"
  }
],
"finalArea": "63.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Balcony",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "100.79",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "_id": "65a2632702c44c777bb42a48",
  "name": "Balcony",
  "extraAreaType": "Add",
  "length": "21.75",
  "length1": "21",
  "length2": "9",
  "width": "5.08",
  "width1": "5",
  "width2": "1",
  "totalArea": "110.56"
}
],
"finalArea": "211.35000000000002"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "83.61",
    "totalAreaDocument": "900",
    "docBuiltpupPercentage": "20",
    "docFinalBUILTUp": "1080.00",
    "docFinalBUILTUpSquareMeter": "100.34",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "138361"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65a22f5c02c44c777bb3805b",
```

```
"property": "Flat",
"area": "1380",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "13",
"source": "https://www.99acres.com/",
"expectedPrice": "65000000",
"expectedRate": "47101.45",
"builtUpExpectedRate": "39251.21",
"image": "cases/659d3c8f02c44c777bad55e7/
indicator_1705127406463_Image.png",
"squareMeter": "128.21",
"id": "611059"
},
{
  "printlnReport": true,
  "_id": "65a22f5c02c44c777bb3805c",
  "property": "Flat",
  "area": "1380",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "64000000",
  "expectedRate": "46376.81",
  "builtUpExpectedRate": "38647.34",
  "image": "cases/659d3c8f02c44c777bad55e7/
indicator_1705127450647_Image.png",
  "squareMeter": "128.21",
  "id": "498562"
},
{
  "printlnReport": true,
  "_id": "65a22f5c02c44c777bb3805d",
  "property": "Flat",
  "area": "1380",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "10",
  "source": "magic_bricks",
  "expectedPrice": "62500000",
```

```
    "expectedRate": "45289.86",
    "builtUpExpectedRate": "37741.55",
    "image": "cases/659d3c8f02c44c777bad55e7/
indicator_1705127485093_Image.png",
    "squareMeter": "128.21",
    "id": "855848"
  },
  {
    "printlnReport": true,
    "_id": "65a22f5c02c44c777bb3805e",
    "property": "Flat",
    "area": "1420",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "13",
    "source": "magic_bricks",
    "expectedPrice": "62400000",
    "expectedRate": "43943.66",
    "builtUpExpectedRate": "36619.72",
    "image": "cases/659d3c8f02c44c777bad55e7/
indicator_1705127511511_Image.png",
    "squareMeter": "131.92",
    "id": "866269"
  },
  {
    "printlnReport": true,
    "_id": "65a22f5c02c44c777bb3805f",
    "property": "Flat",
    "area": "1379",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "5",
    "source": "Index_no.2",
    "expectedPrice": "49100000.00",
    "expectedRate": "35605.51",
    "builtUpExpectedRate": "29671.26",
    "image": "cases/659d3c8f02c44c777bad55e7/
indicator_1705127607935_Image.png",
    "squareMeter": "128.11",
    "id": "993657"
  }
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b5e",
    "name": "externalimg_1704850858835_1704850963144_image_0.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externalimg_1704850858835_1704850963144_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b5f",
    "name": "externalimg_1704850859308_1704850963144_image_1.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externalimg_1704850859308_1704850963144_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b60",
    "name": "externalimg_1704850859359_1704850963144_image_2.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externalimg_1704850859359_1704850963144_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b61",
    "name": "externalimg_1704850859643_1704850963144_image_3.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externalimg_1704850859643_1704850963144_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b62",
    "name": "externalimg_1704850860080_1704850963144_image_4.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externalimg_1704850860080_1704850963144_image_4.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b63",
  "name": "externallmg_1704850860151_1704850963144_image_5.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860151_1704850963144_image_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b64",
  "name": "externallmg_1704850860238_1704850963144_image_6.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860238_1704850963144_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b65",
  "name": "externallmg_1704850860521_1704850963144_image_7.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860521_1704850963144_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b66",
  "name": "externallmg_1704850860596_1704850963144_image_8.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860596_1704850963144_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b67",
  "name": "externallmg_1704850860720_1704850963144_image_9.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860720_1704850963144_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b68",
    "name": "externallmg_1704850860894_1704850963144_image_10.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860894_1704850963144_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b69",
    "name": "externallmg_1704850860941_1704850963144_image_11.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850860941_1704850963144_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b6a",
    "name": "externallmg_1704850861157_1704850963144_image_12.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861157_1704850963144_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b6b",
    "name": "externallmg_1704850861280_1704850963144_image_13.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861280_1704850963144_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b6c",
    "name": "externallmg_1704850861505_1704850963144_image_14.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861505_1704850963144_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "659df70f02c44c777bad7b6d",
  "name": "externallmg_1704850861574_1704850963144_image_15.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861574_1704850963144_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b6e",
  "name": "externallmg_1704850861901_1704850963145_image_16.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850861901_1704850963145_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b6f",
  "name": "externallmg_1704850862212_1704850963145_image_17.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850862212_1704850963145_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b70",
  "name": "externallmg_1704850862357_1704850963145_image_18.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850862357_1704850963145_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b71",
  "name": "externallmg_1704850862660_1704850963145_image_19.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850862660_1704850963145_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "659df70f02c44c777bad7b72",
    "name": "externallmg_1704850940598_1704851050193_image_0.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850940598_1704851050193_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b73",
    "name": "externallmg_1704850949227_1704851050193_image_1.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850949227_1704851050193_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b74",
    "name": "externallmg_1704850959686_1704851050193_image_2.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850959686_1704851050193_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b75",
    "name": "externallmg_1704850971004_1704851050193_image_3.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850971004_1704851050193_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b76",
    "name": "externallmg_1704850976199_1704851050193_image_4.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850976199_1704851050193_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b77",
```

```
    "name": "externallmg_1704850991996_1704851050193_image_5.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850991996_1704851050193_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b78",
    "name": "externallmg_1704850999844_1704851050193_image_6.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704850999844_1704851050193_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b79",
    "name": "externallmg_1704851003105_1704851050193_image_7.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851003105_1704851050193_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7a",
    "name": "externallmg_1704851005211_1704851050193_image_8.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851005211_1704851050193_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7b",
    "name": "externallmg_1704851012655_1704851050193_image_9.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851012655_1704851050193_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7c",
    "name": "externallmg_1704851016128_1704851050193_image_10.jpeg",
```

```
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851016128_1704851050193_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7d",
    "name": "externallmg_1704851021169_1704851050193_image_11.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851021169_1704851050193_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7e",
    "name": "externallmg_1704851021970_1704851050193_image_12.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851021970_1704851050193_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b7f",
    "name": "externallmg_1704851025891_1704851050193_image_13.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851025891_1704851050193_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b80",
    "name": "externallmg_1704851031887_1704851050193_image_14.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851031887_1704851050193_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659df70f02c44c777bad7b81",
    "name": "externallmg_1704851034148_1704851050193_image_15.jpeg",
    "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851034148_1704851050193_image_15.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b82",
  "name": "externallmg_1704851036053_1704851050193_image_16.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851036053_1704851050193_image_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b83",
  "name": "externallmg_1704851039581_1704851050193_image_17.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851039581_1704851050193_image_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b84",
  "name": "externallmg_1704851044041_1704851050193_image_18.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851044041_1704851050193_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b85",
  "name": "externallmg_1704851048882_1704851050193_image_19.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851048882_1704851050193_image_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b86",
  "name": "externallmg_1704851090896_1704851199063_image_0.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851090896_1704851199063_image_0.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659df70f02c44c777bad7b87",
      "name": "externallmg_1704851095123_1704851199063_image_1.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851095123_1704851199063_image_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659df70f02c44c777bad7b88",
      "name": "externallmg_1704851098143_1704851199063_image_2.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851098143_1704851199063_image_2.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659df70f02c44c777bad7b89",
      "name": "externallmg_1704851100078_1704851199063_image_3.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851100078_1704851199063_image_3.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659df70f02c44c777bad7b8a",
      "name": "externallmg_1704851102390_1704851199063_image_4.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851102390_1704851199063_image_4.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "659df70f02c44c777bad7b8b",
      "name": "externallmg_1704851103628_1704851199063_image_5.jpeg",
      "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851103628_1704851199063_image_5.jpeg",
      "orientation": "landscape"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b8c",
  "name": "externallmg_1704851105197_1704851199063_image_6.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851105197_1704851199063_image_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "659df70f02c44c777bad7b8d",
  "name": "externallmg_1704851109967_1704851199063_image_7.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851109967_1704851199063_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659df70f02c44c777bad7b8e",
  "name": "externallmg_1704851207160_1704851289707_image_0.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851207160_1704851289707_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659df70f02c44c777bad7b8f",
  "name": "externallmg_1704851208393_1704851300910_image_0.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851208393_1704851300910_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659df70f02c44c777bad7b90",
  "name": "externallmg_1704851208749_1704851318667_image_0.jpeg",
  "path": "cases/659d3c8f02c44c777bad55e7/
externallmg_1704851208749_1704851318667_image_0.jpeg",
  "orientation": "portrait"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- dhaval.xlsx",
    "filename": "1705127802765_Calculation_2_dhaval.xlsx",
    "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127802765_Calculation_2_dhaval.xlsx",
    "size": "16079",
    "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1705127802767_igr1.pdf",
    "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127802767_igr1.pdf",
    "size": "509241",
    "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1705127802806_igr2.pdf",
    "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127802806_igr2.pdf",
    "size": "464939",
    "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Maintanance Bill 1702.pdf",
    "filename": "1705127802934_Maintanance_Bill_1702.pdf",
    "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127802934_Maintanance_Bill_1702.pdf",
    "size": "116443",
    "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "OC for Skyvista A Tower.pdf",
    "filename": "1705127803474_OC_for_Skyvista_A_Tower.pdf",
    "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127803474_OC_for_Skyvista_A_Tower.pdf",
    "size": "88102",
    "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
]
```



```
    },
    {
      "originalname": "Share Certificate 1702-Dhaval Barot & Chaitali Barot.pdf",
      "filename":
"1705127804171_Share_Certificate_1702Dhaval_Barot__Chaitali_Barot.pdf",
      "path": "cases/659d3c8f02c44c777bad55e7/processingDocuments/1705127804171
_Share_Certificate_1702Dhaval_Barot__Chaitali_Barot.pdf",
      "size": "432507",
      "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Sky Vistas - CC.pdf",
      "filename": "1705127804179_Sky_Vistas__CC.pdf",
      "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127804179_Sky_Vistas__CC.pdf",
      "size": "1716465",
      "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Summary - dhaval.xlsx",
      "filename": "1705127804517_Summary__dhaval.xlsx",
      "path": "cases/659d3c8f02c44c777bad55e7/
processingDocuments/1705127804517_Summary__dhaval.xlsx",
      "size": "3252976",
      "createdAt": "Sat Jan 13 2024 12:06:44 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "64dc7184ccaf1e7b7f637f47",
        "role": "FRONTDESK",
        "firstName": "Binumon",
        "lastName": "Moozhickal",
        "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
      },
      "workType": "MAKER",
      "display": true,
      "status": true,
      "_id": "65a2743c02c44c777bb4601d",
    }
  ]
}
```

```

    "note": "Revise (Task Reopen)",
    "taskId": "65a22f8402c44c777bb38122",
    "createdAt": "2024-01-13T11:30:04.156Z"
  }
],
"createdAt": "2024-01-09T12:31:11.809Z",
"updatedAt": "2024-01-15T06:16:25.337Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"siteVisitDate": "2024-01-09",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 900.00",
"flatRate": "42500",
"landOtherRate": "39500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Cupboard +
Balcony",
"carpetTotal": "910.37",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1001.41",
"finalCarpetArea": "910.37",
"finalSalableArea": "1001.41",
"salablePercentage": "0",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Sat Jan 13 2024 15:08:58 GMT+0530 (India Standard Time)"
}

```

Name	Length	Width	Total
Composition :			
Living Room	25'2"	5'3"	132.12

Kitchen	5'1"	19'00"	96.58
Toilet	5'8"	4'2"	23.61
Bedroom	10'4"	14'7"	150.69
Cupboard	2'3"	6'11"	15.56
Toilet	9'9"	2'8"	26.00
Balcony	9'10"	10'3"	100.79
Other Composition :			