

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64f2efcceb1f822256e0cc7b"
    },
    "type": "CREDITOFFICER",
    "_id": "64f2efcceb1f822256e0cc7d",
    "firstName": "Chandan",
    "lastName": "Kishore",
    "mobileNo": "",
    "workMobileNo": "7030544490",
    "email": "brmgr353@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64f2efcceb1f822256e0cc7b",
  "name": "Vashi Turbhe Branch",
  "branchCode": "",
  "mobileNo": "9699789032",
  "alternateMobileNo": "",
  "email": "brmgr353@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "P-17, Sector 1, Cldco Old Admin Building, Vashi, Navi Mumbai, 400703"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.78561807075657",
  "longitude": "73.34960579999999"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-11",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "6_BHK",
  "label": "6 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khopoli",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Khalapur",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Madhav Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shankar Lake",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "3, Hissa No. 1-B & 2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "4451, 4452, 4453/2, 4450 & 4454/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "29",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN Code - 410 203",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
}
```

```

},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Khopoli_Nagarparishad",
  "label": "Khopoli Nagarparishad"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Internal Road",
  "south": "Wing - B",
  "east": "Open Garden / Shankar Lake"
},
"asPerDocumentAgreement": {
  "north": "Road",
  "west": "Road",
  "south": "KMC Gim",
  "east": "KMC Garden"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Walls",
    "east": "Walls",
    "south": "Staircase",
    "west": "Flat No. 27"
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "Flat Nos. 28, 29 & 30 are amalgamated with separate entrance . The said valuation is for Flat No. 29.",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
"approvePlanVerified": "N.A.",

```

```
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "Flat Nos. 28, 29 & 30 are amalgamated with separate entrance. The said
valuation is for Flat No. 29. For the purpose of valuation we have considered the area
as per agreement.",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "4400",
  "depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "27900",
  "landRate": "6950",
  "igrImage": "cases/659e813602c44c777baef7ff/igr_1706676264679_Image.png",
  "squareMeterGuideLineRate": "27900.00",
  "squareFeetGuideLineRate": "2592.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "84",
  "rate": "2281.00",
  "squareFeetGuideLineRate": "2281.00",
  "squareMeterGuideLineRate": "24548.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "27500.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
```

```
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2008",
    "fullDate": "1/1/2008"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
}
```

```
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1050.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
```



```
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/659e813602c44c777baef7ff/
routeMap_1706687658023_Image.png",
  "routeLat": "18.785733",
  "routeLng": "73.349803",
  "stationName": "Khopoli",
  "routeDistance": "650M"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "6xyh8p",
    "name": "6xyh8p",
    "image": "cases/659e813602c44c777baef7ff/
routeMap_1706687622948_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4620000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4620000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "2395050.00",
  "selectedBuildUpValue": "1050.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659ff1e002c44c777bb16cb6",
      "name": "externallmg_r_1704980953710_1704981067782_image_0.jpg",
      "path": "cases/659e813602c44c777baef7ff/externallmg_r_1704980953710_1704981067782_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65b9fd536635d840ef56686f",
      "name": "externallmg_r_1706687825531_externallmg_r_1704980801583_1704980903300_image_6.jpg",
      "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687825531_externallmg_r_1704980801583_1704980903300_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b9fd536635d840ef566870",
      "name": "externallmg_r_1706687826156_externallmg_r_1704980865350_1704980974623_image_2.jpg",
      "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687826156_externallmg_r_1704980865350_1704980974623_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "65b9fd776635d840ef56688f",
    "name": "externallmg_r_1706687858774_externallmg_r_1704980826290_1704980903300_image_18.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687858774_externallmg_r_1704980826290_1704980903300_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566890",
    "name": "externallmg_r_1706687859421_externallmg_r_1704980828272_1704980903300_image_19.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687859421_externallmg_r_1704980828272_1704980903300_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566891",
    "name": "externallmg_r_1706687857445_externallmg_r_1704980815377_1704980903300_image_13.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687857445_externallmg_r_1704980815377_1704980903300_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566892",
    "name": "externallmg_r_1706687858010_externallmg_r_1704980817373_1704980903300_image_14.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687858010_externallmg_r_1704980817373_1704980903300_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566893",
    "name": "externallmg_r_1706687860587_externallmg_r_1704980870959_1704980974623_image_6.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687860587_externallmg_r_1704980870959_1704980974623_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566894",
```

```
    "name": "externallmg_r_1706687860023_externallmg_r_1704980867213_1704980974623_image_4.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687860023_externallmg_r_1704980867213_1704980974623_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd776635d840ef566895",
    "name": "externallmg_r_1706687861192_externallmg_r_1704980872724_1704980974623_image_7.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687861192_externallmg_r_1704980872724_1704980974623_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd966635d840ef5668bc",
    "name": "externallmg_r_1706687892616_externallmg_r_1704980876422_1704980974623_image_9.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687892616_externallmg_r_1704980876422_1704980974623_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd966635d840ef5668bd",
    "name": "externallmg_r_1706687891296_externallmg_r_1704980810324_1704980903300_image_10.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687891296_externallmg_r_1704980810324_1704980903300_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fd966635d840ef5668be",
    "name": "externallmg_r_1706687891926_externallmg_r_1704980824207_1704980903300_image_17.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687891926_externallmg_r_1704980824207_1704980903300_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b9fdaa6635d840ef566909",
    "name": "externallmg_r_1706687912247_externallmg_r_1704980864223_1704980903300_image_17.jpg",
    "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687912247_externallmg_r_1704980864223_1704980903300_image_17.jpg",
    "orientation": "portrait"
  }
}
```

```
0974623_image_1.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687912247_extern
allmg_r_1704980864223_1704980974623_image_1.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "65b9fdd56635d840ef566945",
  "name": "externallmg_r_1706687956354_externallmg_r_1704980884505_170498
0974623_image_13.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687956354_extern
allmg_r_1704980884505_1704980974623_image_13.jpg",
  "orientation": "landscape"
},
{
  "status": false,
  "_id": "65b9fdd56635d840ef566946",
  "name": "externallmg_r_1706687955270_externallmg_r_1704980878219_170498
0974623_image_10.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687955270_extern
allmg_r_1704980878219_1704980974623_image_10.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "659ff1e002c44c777bb16cb6",
  "name": "externallmg_r_1704980953710_1704981067782_image_0.jpg",
  "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980953710_1704981067782_image_0.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "3895",
    "max": "6380"
  },
  "builtUpRateRange": {
    "min": "3541",
    "max": "5801"
  }
}
},
```



```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1050.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "659e813602c44c777baef7ff",
"ownerName": "Mrs. Vanita Himatlal Goradia",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Flat No. 29, 1st Floor, Wing - A, Madhav Residency, Near
Shankar Lake, Village - Khopoli, Taluka - Khalapur, District - Raigad, PIN Code - 410
203, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/10/2009",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      }
    }
  }
]
```

```
    },
    "Promoter": "M/s. Dolphin Developers",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mrs. Vanita Himatlal Goradia",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "2540/2009"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "138908",
  "path": "cases/659e813602c44c777baef7ff/
document_1704886569235_Flat_No_29.pdf",
  "fileName": "document_1704886569235_Flat_No_29.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "12/12/2006",
    "nameOfApprovingAuthority": {
      "value": "Khopoli_Municipal_Council",
      "label": "Khopoli Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "Khonapa / B.V./ Bandh / 1473 / 3901"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706684697892_81761.pdf",
  "path": "cases/659e813602c44c777baef7ff/document_1706684697892_81761.pdf",
  "id": "748697",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Jan 31 2024 12:34:57 GMT+0530 (India Standard Time)"
}
],
```

```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006268",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "467703",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 10 2024 17:06:22 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vanita Himatlal Goradia",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "935563"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
    "name": "Living Room",
    "length": "",
    "length1": "17",
    "length2": "0",
    "width": "",
    "width1": "11",
    "width2": "0",
    "totalArea": "187.00",
    "images": [],
    "finalArea": "187.00",
    "extraAreas": []
  },
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Living Room",
  "length": "",
  "length1": "11",
  "length2": "0",
  "width": "",
  "width1": "33",
  "width2": "0",
  "totalArea": "363.00",
  "images": [],
  "finalArea": "363.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "96.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
```

```
"width2": "00",
"totalArea": "88.00",
"images": [],
"extraAreas": [],
"finalArea": "88.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "140.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "140.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "150.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "6",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "150.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "16.00",
  "length1": "16",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "144.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "144.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "16.00",
  "length1": "16",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "144.00",
```



```
"images": [],
"extraAreas": [],
"finalArea": "144.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "",
  "length1": "19",
  "length2": "0",
  "width": "",
  "width1": "9",
  "width2": "0",
  "totalArea": "171.00",
  "images": [],
  "finalArea": "171.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "15.00",
  "length1": "15",
  "length2": "00",
  "width": "14.00",
  "width1": "14",
  "width2": "00",
  "totalArea": "210.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "210.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
```

```
"name": "Toilet",
"length": "5.00",
"length1": "5",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "50.00",
"images": [],
"extraAreas": [],
"finalArea": "50.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "30.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "25",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "6.00",
  "width1": "6",
  "width2": "0",
  "totalArea": "30.00",
  "images": [],
  "finalArea": "30.00",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "16",
  "name": "Toilet",
  "length": "",
  "length1": "4",
  "length2": "0",
  "width": "",
  "width1": "8",
  "width2": "0",
  "totalArea": "32.00",
  "images": [],
  "finalArea": "32.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "16",
  "name": "Toilet",
  "length": "6.00",
```

```
"length1": "6",
"length2": "00",
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "42.00",
"images": [],
"extraAreas": [],
"finalArea": "42.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "18",
  "name": "Passage",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "8.00",
  "width1": "8",
  "width2": "0",
  "totalArea": "56.00",
  "images": [],
  "finalArea": "56.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "18",
  "name": "Passage",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "54.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.00"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "25",
  "name": "Passage",
  "length": "",
  "length1": "5",
  "length2": "0",
  "width": "",
  "width1": "6",
  "width2": "0",
  "totalArea": "30.00",
  "images": [],
  "finalArea": "30.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "20",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "15.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "21",
  "name": "Cupboard",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
```

```
"width": "6.00",
"width1": "6",
"width2": "00",
"totalArea": "30.00",
"images": [],
"extraAreas": [],
"finalArea": "30.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "24",
  "name": "Balcony",
  "length": "18.00",
  "length1": "18",
  "length2": "0",
  "width": "18.00",
  "width1": "18",
  "width2": "0",
  "totalArea": "324.00",
  "images": [],
  "finalArea": "324.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "23",
  "name": "Balcony",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "98.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "98.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "24",
  "name": "Balcony",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "64.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "64.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "97.55",
    "totalAreaDocument": "1050",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "418705"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65b9d0416635d840ef55a83c",
```

```
"property": "Flat",
"area": "925",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Housing.Com",
"expectedPrice": "3275000",
"expectedRate": "3540.54",
"builtUpExpectedRate": "3275000",
"image": "cases/659e813602c44c777baef7ff/indicator_1706676158958_Image.png",
"squareMeter": "85.94",
"id": "371249"
},
{
  "printlnReport": true,
  "_id": "65b9d0416635d840ef55a83d",
  "property": "Flat",
  "area": "945",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Housing.Com",
  "expectedPrice": "4200000",
  "expectedRate": "4444.44",
  "builtUpExpectedRate": "4200000",
  "image": "cases/659e813602c44c777baef7ff/indicator_1706676182783_Image.png",
  "squareMeter": "87.79",
  "id": "733759"
},
{
  "printlnReport": true,
  "_id": "65b9d0416635d840ef55a83e",
  "property": "Flat",
  "area": "862",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "5000000",
  "expectedRate": "5800.46",
  "builtUpExpectedRate": "5000000",
  "image": "cases/659e813602c44c777baef7ff/indicator_1706676208519_Image.png",
  "squareMeter": "80.08",
```



```
"id": "581378"
},
{
  "printlnReport": true,
  "_id": "65b9d0416635d840ef55a83f",
  "property": "Flat",
  "area": "1036",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "5500000",
  "expectedRate": "5308.88",
  "builtUpExpectedRate": "5500000",
  "image": "cases/659e813602c44c777baef7ff/indicator_1706676233863_Image.png",
  "squareMeter": "96.25",
  "id": "814633"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659ff1e002c44c777bb16cb5",
    "name": "externallmg_r_1704980954731_1704981067782_image_1.jpg",
    "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980954731_1704981067782_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659ff1e002c44c777bb16cb6",
    "name": "externallmg_r_1704980953710_1704981067782_image_0.jpg",
    "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980953710_1704981067782_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659ff1e002c44c777bb16cb7",
    "name": "externallmg_r_1704980955801_1704981067782_image_2.jpg",
    "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980955801_1704981067782_image_2.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659ff1e002c44c777bb16cb8",
  "name": "externallmg_r_1704980943934_1704981056406_image_3.png",
  "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980943934_1704981056406_image_3.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659ff1e002c44c777bb16cb9",
  "name": "externallmg_r_1704980943439_1704981056406_image_2.jpg",
  "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980943439_1704981056406_image_2.jpg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659ff1e002c44c777bb16cba",
  "name": "externallmg_r_1704980942013_1704981056406_image_0.jpg",
  "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980942013_1704981056406_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "659ff1e002c44c777bb16cbb",
  "name": "externallmg_r_1704980942722_1704981056406_image_1.jpg",
  "path": "cases/659e813602c44c777baef7ff/
externallmg_r_1704980942722_1704981056406_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd536635d840ef56686f",
  "name": "externallmg_r_1706687825531_externallmg_r_1704980801583_1704980
903300_image_6.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687825531_external
lmg_r_1704980801583_1704980903300_image_6.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd536635d840ef566870",
  "name": "externallmg_r_1706687826156_externallmg_r_1704980865350_1704980974623_image_2.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687826156_external_lmg_r_1704980865350_1704980974623_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd776635d840ef56688f",
  "name": "externallmg_r_1706687858774_externallmg_r_1704980826290_1704980903300_image_18.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687858774_external_lmg_r_1704980826290_1704980903300_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd776635d840ef566890",
  "name": "externallmg_r_1706687859421_externallmg_r_1704980828272_1704980903300_image_19.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687859421_external_lmg_r_1704980828272_1704980903300_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd776635d840ef566891",
  "name": "externallmg_r_1706687857445_externallmg_r_1704980815377_1704980903300_image_13.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687857445_external_lmg_r_1704980815377_1704980903300_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd776635d840ef566892",
```

```
    "name": "externalimg_r_1706687858010_externalimg_r_1704980817373_1704980903300_image_14.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalimg_r_1706687858010_externalimg_r_1704980817373_1704980903300_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fd776635d840ef566893",
    "name": "externalimg_r_1706687860587_externalimg_r_1704980870959_1704980974623_image_6.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalimg_r_1706687860587_externalimg_r_1704980870959_1704980974623_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fd776635d840ef566894",
    "name": "externalimg_r_1706687860023_externalimg_r_1704980867213_1704980974623_image_4.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalimg_r_1706687860023_externalimg_r_1704980867213_1704980974623_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fd776635d840ef566895",
    "name": "externalimg_r_1706687861192_externalimg_r_1704980872724_1704980974623_image_7.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalimg_r_1706687861192_externalimg_r_1704980872724_1704980974623_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fd966635d840ef5668bc",
    "name": "externalimg_r_1706687892616_externalimg_r_1704980876422_1704980974623_image_9.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalimg_r_1706687892616_externalimg_r_1704980876422_1704980974623_image_9.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd966635d840ef5668bd",
  "name": "externallmg_r_1706687891296_externallmg_r_1704980810324_1704980
903300_image_10.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687891296_external
lmg_r_1704980810324_1704980903300_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fd966635d840ef5668be",
  "name": "externallmg_r_1706687891926_externallmg_r_1704980824207_1704980
903300_image_17.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687891926_external
lmg_r_1704980824207_1704980903300_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fdaa6635d840ef566908",
  "name": "externallmg_r_1706687912967_externallmg_r_1704980866229_1704980
974623_image_3.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687912967_external
lmg_r_1704980866229_1704980974623_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fdaa6635d840ef566909",
  "name": "externallmg_r_1706687912247_externallmg_r_1704980864223_1704980
974623_image_1.jpg",
  "path": "cases/659e813602c44c777baef7ff/externallmg_r_1706687912247_external
lmg_r_1704980864223_1704980974623_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b9fdaa6635d840ef56690a",
  "name": "externallmg_r_1706687911114_externallmg_r_1704980803970_1704980
903300_image_7.jpg",
```

```
    "path": "cases/659e813602c44c777baef7ff/externalImg_r_1706687911114_external
    Img_r_1704980803970_1704980903300_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fdaa6635d840ef56690b",
    "name": "externalImg_r_1706687911630_externalImg_r_1704980819715_1704980
    903300_image_15.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalImg_r_1706687911630_external
    Img_r_1704980819715_1704980903300_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fdd56635d840ef566945",
    "name": "externalImg_r_1706687956354_externalImg_r_1704980884505_1704980
    974623_image_13.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalImg_r_1706687956354_external
    Img_r_1704980884505_1704980974623_image_13.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b9fdd56635d840ef566946",
    "name": "externalImg_r_1706687955270_externalImg_r_1704980878219_1704980
    974623_image_10.jpg",
    "path": "cases/659e813602c44c777baef7ff/externalImg_r_1706687955270_external
    Img_r_1704980878219_1704980974623_image_10.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Summary New=VANITA.xlsx",
    "filename": "1706676300088_Summary_NewVANITA.xlsx",
    "path": "cases/659e813602c44c777baef7ff/
    processingDocuments/1706676300088_Summary_NewVANITA.xlsx",
    "size": "2884921",
    "createdAt": "Wed Jan 31 2024 10:15:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65a8c9391db9ea33c2d12b1a",
    "note": "7-8 properties of same customer. required documents list of all the
properties already shared with banker. ",
    "taskId": "659e816e02c44c777baefae8",
    "createdAt": "2024-01-18T06:46:17.074Z"
  }
],
"createdAt": "2024-01-10T11:36:22.182Z",
"updatedAt": "2024-01-31T09:38:02.666Z",
"__v": 0,
"invoiceId": "659e813602c44c777baef808",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Raj Kapoor Yadav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Contractor",
"siteVisitContactNo": "8600084922",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1050.00",
"flatRate": "5000",
```

```

"landOtherRate": "2500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "6 Bedroom + 2 Living Room + 3 Kitchen + 6 Toilet + 4
Passage + Cupboard + 3 Balcony",
"carpetTotal": "2725",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "2997.50",
"finalCarpetArea": "2725.00",
"finalSalableArea": "3297.25",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 2209.00\nCupboard Area in Sq.
Ft. = 30.00\nBalcony area in Sq. Ft. = 486.00\n(Measurement of Flat Nos. 28, 29 & 30)
\n\n",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'0"	11'0"	187.00
Living Room	11'0"	33'0"	363.00

Kitchen	12'00"	8'00"	96.00
Kitchen	11'00"	8'00"	88.00
Kitchen	14'00"	10'00"	140.00
Bedroom	15'00"	10'00"	150.00
Bedroom	15'00"	10'00"	150.00
Bedroom	16'00"	9'00"	144.00
Bedroom	16'00"	9'00"	144.00
Bedroom	19'0"	9'0"	171.00
Bedroom	15'00"	14'00"	210.00
Toilet	5'00"	10'00"	50.00
Toilet	5'00"	6'00"	30.00
Toilet	5'0"	6'0"	30.00
Toilet	3'00"	9'00"	27.00
Toilet	4'0"	8'0"	32.00
Toilet	6'00"	7'00"	42.00
Passage	7'0"	8'0"	56.00
Passage	9'00"	6'00"	54.00
Passage	5'0"	6'0"	30.00
Passage	3'00"	5'00"	15.00
Cupboard	5'00"	6'00"	30.00
Balcony	18'0"	18'0"	324.00
Balcony	14'00"	7'00"	98.00
Balcony	8'00"	8'00"	64.00
Other Composition :			