

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65a2084302c44c777bb3079c"
    },
    "type": "CREDITOFFICER",
    "_id": "65a2084302c44c777bb3079e",
    "firstName": "Manish",
    "lastName": "Prasad",
    "mobileNo": "",
    "workMobileNo": "9473474007",
    "email": "manish.prasad@isarc.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "65a0ef2102c44c777bb2191e",
  "type": "BANK",
  "name": "India SME Asset reconstruction Company Limited",
  "displayName": "India SME Asset reconstruction Company Limited",
  "initial": "ISARC"
},
"branch": {
  "_id": "65a2084302c44c777bb3079c",
  "name": "MIDC Andheri ",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "manish.prasad@isarc.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "India SME Asset Reconstruction Company Limited,\n\nArena House, 2nd
Floor, Gate no.3, Plot No.103,\n\nRoad No.12, MIDC, Andheri (East), Mumbai – 400
093."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "65a0f2e802c44c777bb2203e",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "5ff3ead28cda966090eacbbe",
  "role": "VALUER",
  "firstName": "Umang ",
  "email": "umang@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9819670183",
  "shortName": "umang",
  "workWithDocumentMaker": "5fc75d341095af19d8b34239",
  "profilePhoto": "users/5ff3ead28cda966090eacbbe/
profilePhoto_1678667749982_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "[N]C.C.I.T/I -14/52/2008-09",
  "label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.989590983807503",
  "longitude": "72.81307552009821"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81307552009821,
    18.989590983807503
  ]
}
]
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Worli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "C",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Poonam Apartent",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shiv Sagar Estate",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Dr Annie Besant Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "506",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```



```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "Mumbai",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Worli",
```

```
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65a20ada02c44c777bb30b08",
"ownerName": "Bhagwan Devji Rathod 506",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8779750791",
"contactPersonName": "Ashok Keer",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Bhagwan Devji Rathod 506",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "777712"
  }
],
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"relationWithOwner": "Bank Staff",
"fullAddress": "Residential Flat No. 506, 5th Floor, Building No C, Poonam Apartent,
Shiv Sagar Estate, Dr Annie Besant Road, Village - Worli, Worli, Mumbai, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
```



```
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1705118424756_506poonam_apt.pdf",
  "path": "cases/65a20ada02c44c777bb30b08/
document_1705118424756_506poonam_apt.pdf",
  "id": "125117",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Jan 13 2024 09:30:26 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "006320",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "742181",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Sat Jan 13 2024 09:30:26 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a766d09413402ebab73420",
    "name": "externalImg_1705469647657_1705469766501_image_0.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externalImg_1705469647657_1705469766501_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a766d09413402ebab73421",
  "name": "externallmg_1705469647992_1705469766501_image_1.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469647992_1705469766501_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a766d09413402ebab73422",
  "name": "externallmg_1705469648320_1705469766501_image_2.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469648320_1705469766501_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a766f69413402ebab735a5",
  "name": "externallmg_1705469682086_1705469801380_image_0.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469682086_1705469801380_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a766f69413402ebab735a6",
  "name": "externallmg_1705469682611_1705469801380_image_1.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469682611_1705469801380_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a766f69413402ebab735a7",
  "name": "externallmg_1705469683139_1705469801380_image_2.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469683139_1705469801380_image_2.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a766f69413402ebab735a8",
      "name": "externallmg_1705469683732_1705469801380_image_3.jpeg",
      "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469683732_1705469801380_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a766f69413402ebab735a9",
      "name": "externallmg_1705469684203_1705469801380_image_4.jpeg",
      "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469684203_1705469801380_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a766f69413402ebab735aa",
      "name": "externallmg_1705469684487_1705469801380_image_5.jpeg",
      "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469684487_1705469801380_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a766f69413402ebab735ab",
      "name": "externallmg_1705469684813_1705469801380_image_6.jpeg",
      "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469684813_1705469801380_image_6.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65a766f69413402ebab735ac",
      "name": "externallmg_1705469685192_1705469801380_image_7.jpeg",
      "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469685192_1705469801380_image_7.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a766f69413402ebab735ad",
  "name": "externallmg_1705469685584_1705469801380_image_8.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469685584_1705469801380_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab7366f",
  "name": "externallmg_1705469736754_1705469854580_image_0.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469736754_1705469854580_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab73670",
  "name": "externallmg_1705469736993_1705469854580_image_1.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469736993_1705469854580_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab73671",
  "name": "externallmg_1705469737397_1705469854580_image_2.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469737397_1705469854580_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab73672",
  "name": "externallmg_1705469737838_1705469854580_image_3.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469737838_1705469854580_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a7672c9413402ebab73673",
    "name": "externallmg_1705469738149_1705469854580_image_4.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469738149_1705469854580_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a7672c9413402ebab73674",
    "name": "externallmg_1705469738416_1705469854580_image_5.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469738416_1705469854580_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a7672c9413402ebab73675",
    "name": "externallmg_1705469738609_1705469854580_image_6.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469738609_1705469854580_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a7672c9413402ebab73676",
    "name": "externallmg_1705469738942_1705469854580_image_7.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469738942_1705469854580_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a7672c9413402ebab73677",
    "name": "externallmg_1705469739386_1705469854580_image_8.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469739386_1705469854580_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65a7672c9413402ebab73678",
  "name": "externalimg_1705469739687_1705469854580_image_9.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externalimg_1705469739687_1705469854580_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab73679",
  "name": "externalimg_1705469739960_1705469854580_image_10.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externalimg_1705469739960_1705469854580_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a7672c9413402ebab7367a",
  "name": "externalimg_1705469740362_1705469854580_image_11.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externalimg_1705469740362_1705469854580_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a767509413402ebab73729",
  "name": "externalimg_1705469770913_1705469886819_image_0.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externalimg_1705469770913_1705469886819_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a767509413402ebab7372a",
  "name": "externalimg_1705469771260_1705469886819_image_1.jpeg",
  "path": "cases/65a20ada02c44c777bb30b08/
externalimg_1705469771260_1705469886819_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65a767509413402ebab7372b",
    "name": "externallmg_1705469771535_1705469886819_image_2.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469771535_1705469886819_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab7372c",
    "name": "externallmg_1705469772001_1705469886819_image_3.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469772001_1705469886819_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab7372d",
    "name": "externallmg_1705469772344_1705469886819_image_4.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469772344_1705469886819_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab7372e",
    "name": "externallmg_1705469772555_1705469886819_image_5.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469772555_1705469886819_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab7372f",
    "name": "externallmg_1705469772870_1705469886820_image_6.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469772870_1705469886820_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73730",
```

```
    "name": "externallmg_1705469773273_1705469886820_image_7.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469773273_1705469886820_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73731",
    "name": "externallmg_1705469773721_1705469886820_image_8.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469773721_1705469886820_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73732",
    "name": "externallmg_1705469774004_1705469886820_image_9.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469774004_1705469886820_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73733",
    "name": "externallmg_1705469774115_1705469886820_image_10.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469774115_1705469886820_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73734",
    "name": "externallmg_1705469774625_1705469886820_image_11.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469774625_1705469886820_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73735",
    "name": "externallmg_1705469775156_1705469886820_image_12.jpeg",
```



```

    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469775156_1705469886820_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a767509413402ebab73736",
    "name": "externallmg_1705469775329_1705469886820_image_13.jpeg",
    "path": "cases/65a20ada02c44c777bb30b08/
externallmg_1705469775329_1705469886820_image_13.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65a4bc6102c44c777bb4c810",
    "note": "Pending for documents informed and list of documents required sent to
jagdish sir",
    "taskId": "65a20ada02c44c777bb30b22",
    "createdAt": "2024-01-15T05:02:25.742Z"
  }
],
"createdAt": "2024-01-13T04:00:26.529Z",
"updatedAt": "2024-01-17T05:36:16.181Z",
"__v": 0,
"invoiceId": "65a20ada02c44c777bb30b0b",
"addressForMap": "",
"updatedBy": "648fcad91b499c2d52dc86f3"
}

```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			