

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b800"
    },
    "type": "CREDITOFFICER",
    "_id": "6527e518d040066d2c568dd4",
    "firstName": "Mugdha",
    "lastName": "Desai",
    "mobileNo": "",
    "workMobileNo": "8591526340",
    "email": "1mugdha.desai@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1342000",
    "discussWithPerson": "Mugdha",
    "expectedFees": 671,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b800",
  "branchCode": "000073",
  "type": "BRANCH",
  "name": "SME Centre Borivali (West)",
  "email": "sbi.15781@sbi.co.in",
  "mobileNo": "022-28954966",
  "alternateMobileNo": "",
  "address": "SME Centre Borivali (15521) 101, 1st floor,
Landmark Building, S. V. Road, Near Petrol Pump, Borivali (West), Mumbai – 400 092,
State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-SMECCC BORIVALI",
  "fax": "022-28909092",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "657157794999312746cdc402",
  "role": "MAKER + RATE VERIFIER",
  "firstName": "Komal",
  "email": "pawarkomal580@gmail.com",
```

```
"lastName": "pawar",
"mobileNo": "7447457799",
"designation": "Rate Verifier +Maker",
"shortName": "KP",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.296696648026348",
  "longitude": "72.85601075461167"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85601075461167,
    19.296696648026348
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-15",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
```

```
"value": "Unit",
"label": "Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Goddeo",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Thane ",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane ",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Satya Sai Industrial Estate ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```



```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near Tirupati Gas Godown, Fatak Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
```

```
"key": "newSurveyNumber",
"value": "49",
"label": true
},
"hisNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "2 & 4",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "9",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401105",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhayander (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"flooring": {
  "value": "IndustrialFlooring",
  "label": "Industrial Flooring"
},
"doors": {
  "value": "MS_Rolling_Shutter",
  "label": "MS Rolling Shutter"
},
"windows": {
  "value": "M.S._Grill_Fixed_Windows",
  "label": "M.S. Grill Fixed Windows"
},
"fittings": {
  "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
  "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shree Ram Nagar ",
```

```

    "west": "Sonal Industries ",
    "south": "Road ",
    "east": "Ramshankar Fabrication "
  },
  "asPerDocumentAgreement": {
    "north": "Industrial Estate ",
    "west": "Road ",
    "south": "Web Converted ",
    "east": "Supertech Industries "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of approved plan is not provided & not verified. ",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "1. As per site inspection, Gala No. 9 & 9A are internally amalgamated to form a single unit having single entrance. \n<br />\n2. As per Site Inspection, Actual Total Carpet Area - 1,791.00 Sq. Ft for Amalgamated Gala No. 9 & 9A is more than Built Up Area 1,175.00 Sq. Ft. mentioned in the documents. We have considered area mentioned in the documents. \n<br />\n3. The said valuation is of Gala No. 9 only. ",
  "depreciationPercentage": "50.400000000000006",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "10992",
  "depreciatedBuildingRate": "991.9999999999999"
},
"igrRate": {
  "propertyName": "Industrial",
  "rate": "109600",

```

```
"landRate": "33300",
"igrImage": "cases/65a23f8e02c44c777bb3c3a5/igr_1706165465314_Image.png",
"squareMeterGuideLineRate": "109600.00",
"squareFeetGuideLineRate": "10182.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "60.5",
  "rate": "7382.00",
  "squareMeterGuideLineRate": "79462.00",
  "squareFeetGuideLineRate": "7382.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MBMC Norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Average "
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in Develop area ",
  "negativeFactorsOfAffectMarketValue": "No "
},
"siteMeasurement": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Parking ",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1996",
"fullDate": "1/1/1996"
},
"planningArea": {
"value": "Industrial",
"label": "Industrial"
},
"typeOfStructure": {
"value": "Steel_Framed",
"label": "Steel Framed"
},
"typeOfFoundation": {
"value": "load_bearings",
"label": "Load Bearing"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
}
```

```
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "0",
  "label": "No"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
```



```
"label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "50",
"estimatedAge": "22",
"ageOfBuilding": "28",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "Ground",
"noOfLifts": "-",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1175.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Deed Of Declaration"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65a23f8e02c44c777bb3c3a5/
routeMap_1706329140806_Image.png",
    "routeLat": "19.297603",
    "routeLng": "72.855230",
    "stationName": "Bhayander ",
    "routeDistance": "1.8 Km "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ]
  },
}
```

```
"type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "sk63fj",
    "name": "sk63fj",
    "image": "cases/65a23f8e02c44c777bb3c3a5/
routeMap_1706328883628_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "12915600.00",
  "finalValue": "12915600.00",
  "distressValuePercentage": "80",
```

```
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8673850.00",
  "selectedBuildUpValue": "1175.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65a605ab02c44c777bb6044f",
      "name": "externallmg_1705379148878_1705378949371_image_14.jpeg",
      "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379148878_1705378949371_image_14.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65a605ab02c44c777bb60452",
      "name": "externallmg_1705379164893_1705378949371_image_17.jpeg",
      "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379164893_1705378949371_image_17.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65a605ab02c44c777bb6044d",
      "name": "externallmg_1705379134939_1705378949371_image_12.jpeg",
      "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379134939_1705378949371_image_12.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [
    {
      "status": false,
      "_id": "65a605ab02c44c777bb60443",
      "name": "externallmg_1705379087694_1705378949370_image_2.jpeg",
      "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379087694_1705378949370_image_2.jpeg",
      "orientation": "landscape"
    }
  ],
  "societyNameBoardImage": [
    {
      "status": false,
      "_id": "65a605ab02c44c777bb60442",
      "name": "externallmg_1705379075999_1705378949370_image_1.jpeg",
```

```
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379075999_1705378949370_image_1.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "65a605ab02c44c777bb6044e",
    "name": "Working Area",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379141038_1705378949371_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65a605ab02c44c777bb6044a",
    "name": "Working Area",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379121175_1705378949371_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65a605ab02c44c777bb60448",
    "name": "Working Area",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379113963_1705378949371_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65a605ab02c44c777bb60447",
    "name": "Working Area",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379107049_1705378949371_image_6.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10556",
    "max": "16000"
  },
  "builtUpRateRange": {
```

```
"min": "9596",
"max": "14546"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```



```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1175.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65a23f8e02c44c777bb3c3a5",
"ownerName": "Shri. Labubhai J. Goti Proprietor of M/s. S. Kumar Industries ",
"ownerPhoneNo": "9323112123",
"appAddress": "Gala no. 9 Ground Floor Satya Sai Industrial Estate Mouje Goddev
Bhayander East Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Deed Of Declaration",
      "value": "60ae1246aa6d152c1801b2e7"
    }
  },
  "inputs": {
    "documentDate": "12/12/1998"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "210138",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
document_1705131807924_1705131920823_Gala_no_9_Labubhai_Goti.pdf",
    "fileName":
"document_1705131807924_1705131920823_Gala_no_9_Labubhai_Goti.pdf"
  },
  {
    "documentType": {
      "value": "60ae126aaa6d152c1801b38b",
      "label": "Property Tax Bill"
    },
    "inputs": {
      "documentDate": "30/04/2023",
      "nameOfApprovingAuthority": {
        "value": "Mira_Bhayander_Municipal_Corporation",
        "label": "Mira Bhayander Municipal Corporation"
      },
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "S Kumar Industries ",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "E010027109014"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "105954",
    "path": "cases/65a23f8e02c44c777bb3c3a5/document_1706327634616_document_
1706160795169_1706160920852_PTGALA_NO_9_1.pdf",
    "fileName": "document_1706327634616_document_1706160795169_17061609208
52_PTGALA_NO_9_1.pdf"
  },
  {
    "documentType": {
      "value": "6077c791395bc80714864a30",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "16/01/2024",
```

```
"number": {
  "value": "CA_No",
  "label": "CA No"
},
"CA_No": "152984970"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1706505253192_EBGala_99ALight_Bill_1.pdf",
"path": "cases/65a23f8e02c44c777bb3c3a5/
document_1706505253192_EBGala_99ALight_Bill_1.pdf",
"id": "712653",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Mon Jan 29 2024 10:44:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1294aa6d152c1801b44b",
    "label": "Agreement For Re-Sale"
  },
  "inputs": {
    "documentDate": "04/02/1994",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "M/s. Satyasai Enterprises",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Shri. Labubhai J. Goti Proprietor of M/s. S. Kumar Industries"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706595372377_Gala_No_9.pdf",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
document_1706595372377_Gala_No_9.pdf",
  "id": "127090",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Tue Jan 30 2024 11:46:12 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006330",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
```

```
{
  "id": "282511",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Jan 13 2024 13:15:18 GMT+0530 (India Standard Time)"
},
"owners": [
  {
    "name": "Shri. Labubhai J. Goti Proprietor of M/s. S. Kumar Industries ",
    "phone": "9323112123",
    "ownershipShare": "",
    "email": "",
    "id": "984187"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Working Area",
    "length": "",
    "length1": "51",
    "length2": "2",
    "width": "",
    "width1": "34",
    "width2": "9",
    "totalArea": "1778.04",
    "images": [],
    "finalArea": "1778.04",
    "extraAreas": []
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Deed Of Declaration",
      "value": "60ae1246aa6d152c1801b2e7"
    }
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "109.16",
"totalAreaDocument": "1175",
"docBuiltpupPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "864725"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65b206a90a3af9757a58b035",
  "property": "Industrial",
  "area": "550",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "8000000",
  "expectedRate": "14545.45",
  "builtUpExpectedRate": "8000000",
  "image": "cases/65a23f8e02c44c777bb3c3a5/
indicator_1706165383890_Image.png",
  "squareMeter": "51.10",
  "id": "643824"
},
{
  "printlnReport": true,
  "_id": "65b206a90a3af9757a58b036",
  "property": "Industrial ",
  "area": "175",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
```

```
    "expectedPrice": "2400000",
    "expectedRate": "13714.29",
    "builtUpExpectedRate": "2400000",
    "image": "cases/65a23f8e02c44c777bb3c3a5/
indicator_1706165398480_Image.png",
    "squareMeter": "16.26",
    "id": "599230"
  },
  {
    "printlnReport": true,
    "_id": "65b206a90a3af9757a58b037",
    "property": "Industrial",
    "area": "990",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "source": "Index_no.2",
    "expectedPrice": "9500000",
    "expectedRate": "9595.96",
    "builtUpExpectedRate": "9500000",
    "image": "cases/65a23f8e02c44c777bb3c3a5/
indicator_1706165421456_Image.jpeg",
    "squareMeter": "91.97",
    "id": "888217"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a605ab02c44c777bb60440",
    "name": "externalImg_1705378874064_1705378965105_image_0.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externalImg_1705378874064_1705378965105_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60441",
    "name": "externalImg_1705379065890_1705378949365_image_0.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externalImg_1705379065890_1705378949365_image_0.jpeg",
    "orientation": "landscape"
  },
]
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60442",
  "name": "externallmg_1705379075999_1705378949370_image_1.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379075999_1705378949370_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60443",
  "name": "externallmg_1705379087694_1705378949370_image_2.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379087694_1705378949370_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60444",
  "name": "externallmg_1705379092228_1705378949371_image_3.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379092228_1705378949371_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60445",
  "name": "externallmg_1705379096479_1705378949371_image_4.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379096479_1705378949371_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60446",
  "name": "externallmg_1705379100744_1705378949371_image_5.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379100744_1705378949371_image_5.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60447",
    "name": "externallmg_1705379107049_1705378949371_image_6.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379107049_1705378949371_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60448",
    "name": "externallmg_1705379113963_1705378949371_image_7.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379113963_1705378949371_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60449",
    "name": "externallmg_1705379117690_1705378949371_image_8.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379117690_1705378949371_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb6044a",
    "name": "externallmg_1705379121175_1705378949371_image_9.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379121175_1705378949371_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb6044b",
    "name": "externallmg_1705379126593_1705378949371_image_10.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379126593_1705378949371_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "65a605ab02c44c777bb6044c",
  "name": "externallmg_1705379131124_1705378949371_image_11.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379131124_1705378949371_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb6044d",
  "name": "externallmg_1705379134939_1705378949371_image_12.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379134939_1705378949371_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb6044e",
  "name": "externallmg_1705379141038_1705378949371_image_13.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379141038_1705378949371_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb6044f",
  "name": "externallmg_1705379148878_1705378949371_image_14.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379148878_1705378949371_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65a605ab02c44c777bb60450",
  "name": "externallmg_1705379155350_1705378949371_image_15.jpeg",
  "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379155350_1705378949371_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "65a605ab02c44c777bb60451",
    "name": "externallmg_1705379158223_1705378949371_image_16.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379158223_1705378949371_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60452",
    "name": "externallmg_1705379164893_1705378949371_image_17.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379164893_1705378949371_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60453",
    "name": "externallmg_1705379165123_1705378949371_image_18.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379165123_1705378949371_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65a605ab02c44c777bb60454",
    "name": "externallmg_1705379168778_1705378949371_image_19.jpeg",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
externallmg_1705379168778_1705378949371_image_19.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Gala No. 9.pdf",
    "filename": "1706165300724_Gala_No_9.pdf",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165300724_Gala_No_9.pdf",
    "size": "11907656",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
```

```
    "originalname": "IGR-01.pdf",
    "filename": "1706165300988_IGR01.pdf",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165300988_IGR01.pdf",
    "size": "150764",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1706165300999_IGR02.pdf",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165300999_IGR02.pdf",
    "size": "150694",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1706165301003_IGR03.pdf",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165301003_IGR03.pdf",
    "size": "151023",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=LAHU.xlsx",
    "filename": "1706165301007_Summary_NewLAHU.xlsx",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165301007_Summary_NewLAHU.xlsx",
    "size": "3114031",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "EB-Gala 9-9A-Light Bill (1).pdf",
    "filename": "1706165301060_EBGala_99ALight_Bill_1.pdf",
    "path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165301060_EBGala_99ALight_Bill_1.pdf",
    "size": "435381",
    "createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "PT-GALA NO 9 (1).pdf",
```

```
"filename": "1706165301067_PTGALA_NO_9_1.pdf",
"path": "cases/65a23f8e02c44c777bb3c3a5/
processingDocuments/1706165301067_PTGALA_NO_9_1.pdf",
"size": "367119",
"createdAt": "Thu Jan 25 2024 12:18:21 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"lastName": "Kajvilkar",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "65a6190402c44c777bb661a1",
"note": "Pending for OC, CC, Plan, Maintenance Bill, Property Tax Bill, Electricity
Bills informed to Sunil.",
"taskId": "65a2478402c44c777bb3da35",
"createdAt": "2024-01-16T05:49:56.802Z"
}
],
"createdAt": "2024-01-13T07:45:18.423Z",
"updatedAt": "2024-01-30T06:16:18.661Z",
"__v": 0,
"invoiceId": "65a23f8e02c44c777bb3c3ae",
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Industrial Gala No. 9, Ground Floor, Satya Sai Industrial Estate , New/
Current Survey No. 49, Hissa No. 2 & 4, Near Tirupati Gas Godown, Fatak Road,
Village - Goddeo, Bhayander (East), Taluka - Thane , District - Thane , Thane , 401105,
State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Sunil Taniwade ",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "(Supervisor) ",
"siteVisitContactNo": "8082172609",
"buildingServicesRate": "2000",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Deed Of Declaration",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 1175.00",
"flatRate": "12000",
"landOtherRate": "10000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "Working Area",
"carpetTotal": "1778.04",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "2133.65",
"finalCarpetArea": "1778.04",
"finalSalableArea": "2347.01",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
```

```

    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Tue Jan 30 2024 09:17:33 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-15"
}

```

Name	Length	Width	Total
Composition :			
Working Area	51'2"	34'9"	1778.04
Other Composition :			