

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231249",
    "firstName": "Vidya",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8850557384"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "17000000",
    "discussWithPerson": "Vidya",
    "expectedFees": 8500,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",

```

```
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    }
  },

```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.05236269175969",
  "longitude": "73.07286125786567"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07286125786567,
    19.05236269175969
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "15/01/2024 04:00 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "19000",
}
```

```
"lumpsumValue": "19600000",
"rateMax": "21000",
"areaType": {
  "Name": "Carpet",
  "Value": "Carpet",
  "name": "Carpet",
  "value": "Carpet"
}
},
"compositionFlatType": {
  "value": "2.5BHK",
  "label": "2.5 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kharghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "13",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "57, Sector - 20",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Twins Co-Op. Hsg. Soc. Ltd. ",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B, Twins ",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 210",
  "label": false
},
"suburb": {
```

```
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "Navi Mumbai",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"label": "Teak Wood Door Frame With Flush Shutters",
"value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
},
"windows": {
"label": "Powder coated Aluminum sliding windows",
"value": "Powder_coated_Aluminum_sliding_windows"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"label": "Cement Plastering + POP Finish",
"value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "Navi Mumbai Municipal Corporation",
"value": "NMMC"
},
}
```

```
"asPerActualAgreement": {
  "north": "flat no 1303",
  "west": "lift",
  "south": "flat no 1301",
  "east": "Flat no 1305"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "22.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "675",
  "depreciatedCostOfConstruction": "18325.00",
  "depreciatedBuildingRate": "2325"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "107100",
  "landRate": "44400",
  "igrImage": "cases/65a502f902c44c777bb56459/igr_1705384121217_Image.png",
  "squareMeterGuideLineRate": "117810.00",
  "squareFeetGuideLineRate": "10945.00"
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "85",
  "rate": "9922.00",
  "squareFeetGuideLineRate": "9922.00",
  "squareMeterGuideLineRate": "106799.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Allotted Podium Level Stilt Car Parking Space bearing No. 6A",
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2009",
  "fullDate": "1/1/2009"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
```

```
"value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "15",
"flatFloorNo": "13",
"noOfLifts": "02",
"noOfDwellingUnitsInBuilding": "06"
},
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "wardrobesRate": "15000.00",
  "totalwardrobesRate": "525000",
  "wardrobesQty": "35.00",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "18666750.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "18141750.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```



```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11787336.00",
  "selectedBuildUpValue": "1188.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "18222",
    "max": "19500"
  },
  "builtUpRateRange": {
    "min": "15186",
    "max": "16250"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
    "title": "Total",
    "quantity": "",
    "ratePerUnit": "",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "990.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65a502f902c44c777bb56459",
"ownerName": "Vivek Mohan Thakare",
"ownerPhoneNo": "9702861282",
"appAddress": "flat no. 1302 13 th floor B wing Bldg plot no. 57 sector no. 20 . village
kharghar ",
"remark": "bankar vidya madam Vastukala+Yogesh Vankar",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e1",
```

```
"label": "Agreement To Sale"
},
"inputs": {
  "documentDate": "05/01/2024",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mrs. Neha Tushar Andhare & Mr. Tushar Gajanan Andhare",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mr. Vivek Mohanrao Thakare & Mrs. Kalyani Vivek Thakare",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "306 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "947535",
"path": "cases/65a502f902c44c777bb56459/document_1705312929554_1705313045586_Vivek_M_Thakare_sbi_Rbo_sanpada.pdf",
"fileName": "document_1705312929554_1705313045586_Vivek_M_Thakare_sbi_Rbo_sanpada.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/03/2007",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / BP / ATPO / 570"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName": "document_1705388235873_document_1705312929554_17053130455
86_Vivek_M_Thakare_sbi_Rbo_sanpada.pdf",
    "path": "cases/65a502f902c44c777bb56459/document_1705388235873_document_
1705312929554_1705313045586_Vivek_M_Thakare_sbi_Rbo_sanpada.pdf",
    "id": "189310",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Tue Jan 16 2024 12:27:16 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "006359",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "613240",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jan 15 2024 15:33:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Vivek Mohanrao Thakare & Mrs. Kalyani Vivek Thakare",
    "phone": "9702861282",
    "ownershipShare": "",
    "email": "",
    "id": "637063"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "65a5717402c44c777bb5f18d",
    "area": "1248",
    "providedByName": "Vivek Mohan Thakare",
    "providedByContactNo": "9702861282"
  },
  {
```



```
"areaType": {
  "label": "Carpet",
  "value": "Carpet"
},
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "65a5717402c44c777bb5f18e",
"area": "980",
"providedByName": "Vivek Mohan Thakare",
"providedByContactNo": "9702861282"
}],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "990676",
    "name": "Living Room",
    "length": "13.75",
    "length1": "13",
    "length2": "9",
    "width": "13.58",
    "width1": "13",
    "width2": "7",
    "totalArea": "186.77",
    "images": [],
    "extraAreas": [],
    "finalArea": "186.77"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "13.58",
    "length1": "13",
    "length2": "7",
    "width": "7.75",
    "width1": "7",
    "width2": "9",
```

```
"totalArea": "105.27",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "65a6454302c44c777bb6d6be",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "7.00",
    "length1": "7",
    "length2": "00",
    "width": "3.75",
    "width1": "3",
    "width2": "9",
    "totalArea": "26.25"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "65a645a902c44c777bb6d7d6",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "14.50",
    "length1": "14",
    "length2": "6",
    "width": "3.50",
    "width1": "3",
    "width2": "6",
    "totalArea": "50.75"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "65a645bf02c44c777bb6d85e",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "4.42",
    "length1": "4",
    "length2": "5",
```

```
    "width": "2.83",
    "width1": "2",
    "width2": "10",
    "totalArea": "12.51"
  }
],
"finalArea": "194.77999999999997"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.25",
  "length1": "6",
  "length2": "3",
  "width": "17.50",
  "width1": "17",
  "width2": "6",
  "totalArea": "109.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "109.37"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "11.50",
  "length1": "11",
  "length2": "6",
  "width": "18.92",
  "width1": "18",
  "width2": "11",
  "totalArea": "217.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "217.54"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "14.00",
  "length1": "14",
  "length2": "00",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "149.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "149.33"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "33.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.58"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "12.92",
  "width1": "12",
```

```
"width2": "11",
"totalArea": "50.59",
"images": [],
"extraAreas": [],
"finalArea": "50.59"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "30.90",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.90"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Pooja Room",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "12.33",
  "width1": "12",
  "width2": "4",
  "totalArea": "118.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "118.19"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
}
```

```
    },
    "id": "9",
    "name": "Balcony",
    "length": "48.00",
    "length1": "48",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "48.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "48.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "732447",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "1188",
    "squareMeterArea": "110.37",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65a6196e02c44c777bb662d4",
    "property": "3BHK 3Baths Flat/Apartment for Sale in Unique Twins Tower CHS, Sector 20 Kharghar, Navi Mumbai,"
```

```
"area": "950",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "17500000.00",
"expectedRate": "18421.05",
"builtUpExpectedRate": "15350.88",
"image": "cases/65a502f902c44c777bb56459/
indicator_1705383816861_Image.png",
"squareMeter": "88.26",
"id": "777433"
},
{
  "printlnReport": true,
  "_id": "65a6196e02c44c777bb662d5",
  "property": "3BHK 3Baths Flat/Apartment for Sale in Unique Twins Tower CHS,
Sector 20 Kharghar, Navi Mumbai, Mumbai",
  "area": "1000",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "19500000.00",
  "expectedRate": "19500.00",
  "builtUpExpectedRate": "16250.00",
  "image": "cases/65a502f902c44c777bb56459/
indicator_1705383840926_Image.png",
  "squareMeter": "92.90",
  "id": "868035"
},
{
  "printlnReport": true,
  "_id": "65a6196e02c44c777bb662d6",
  "property": "3BHK 3Baths Flat/Apartment for Sale in Unique Twins Tower CHS,
Sector 20 Kharghar, Navi Mumbai, Mumbai",
  "area": "1000",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "18500000.00",
  "expectedRate": "18500.00",
```

```
"builtUpExpectedRate": "15416.67",
"image": "cases/65a502f902c44c777bb56459/
indicator_1705383968514_Image.png",
"squareMeter": "92.90",
"id": "340103"
},
{
  "printlnReport": true,
  "_id": "65a6196e02c44c777bb662d7",
  "property": "3 BHK 1620 Sq-ft Flat For Sale Kharghar, Navi Mumbai",
  "area": "1125.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "20500000.00",
  "expectedRate": "18222.22",
  "builtUpExpectedRate": "15185.19",
  "image": "cases/65a502f902c44c777bb56459/
indicator_1705384035564_Image.png",
  "squareMeter": "104.52",
  "id": "123304"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1e0",
    "name": "externalImg_1705341546982_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externalImg_1705341546982_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1e1",
    "name": "externalImg_1705341548797_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externalImg_1705341548797_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "65a572a302c44c777bb5f1e2",
  "name": "externallmg_1705341551837_image.jpeg",
  "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341551837_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a572a302c44c777bb5f1e3",
  "name": "externallmg_1705341552847_image.jpeg",
  "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341552847_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a572a302c44c777bb5f1e4",
  "name": "externallmg_1705341555852_image.jpeg",
  "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341555852_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a572a302c44c777bb5f1e5",
  "name": "externallmg_1705341558852_image.jpeg",
  "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341558852_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a572a302c44c777bb5f1e6",
  "name": "externallmg_1705341559530_image.jpeg",
  "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341559530_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65a572a302c44c777bb5f1e7",
    "name": "externallmg_1705341562333_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341562333_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1e8",
    "name": "externallmg_1705341564342_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341564342_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1e9",
    "name": "externallmg_1705341566082_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341566082_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1ea",
    "name": "externallmg_1705341568202_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341568202_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1eb",
    "name": "externallmg_1705341570667_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341570667_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1ec",
```

```
    "name": "externallmg_1705341573447_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341573447_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1ed",
    "name": "externallmg_1705341575252_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341575252_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1ee",
    "name": "externallmg_1705341577342_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341577342_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1ef",
    "name": "externallmg_1705341579512_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341579512_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1f0",
    "name": "externallmg_1705341582982_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externallmg_1705341582982_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1f1",
    "name": "externallmg_1705341583752_image.jpeg",
```

```
    "path": "cases/65a502f902c44c777bb56459/
externalImg_1705341583752_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1f2",
    "name": "externalImg_1705341587227_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externalImg_1705341587227_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a572a302c44c777bb5f1f3",
    "name": "externalImg_1705341589187_image.jpeg",
    "path": "cases/65a502f902c44c777bb56459/
externalImg_1705341589187_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-15T10:03:37.412Z",
"updatedAt": "2024-01-16T10:01:01.121Z",
"__v": 0,
"invoiceId": "65a502f902c44c777bb56462",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1302, 13th Floor, Wing - B, Twins , Twins Co-Op.
Hsg. Soc. Ltd. , Plot No. 57, Sector - 20, Village - Kharghar, Navi Mumbai, Taluka -
Panvel , District - Raigad , PIN - 410 210, State - Maharashtra, India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Vivek Mohan Thakare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

```

"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9702861282",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 3 Toilet +
Pooja Room + Balcony",
"carpetTotal": "1139.05",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 990.00",
"flatRate": "15500",
"landOtherRate": "12500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "1374.64",
"finalCarpetArea": "1249.67",
"finalSalableArea": "1512.10",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1200.00\nBalcony Area in Sq. Ft.
= 49.00\n\n",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "110.62",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'9"	13'7"	186.77
Passage	13'7"	7'9"	105.27
Kitchen	6'3"	17'6"	109.37

Bedroom	11'6"	18'11"	217.54
Bedroom	14'00"	10'8"	149.33
Toilet	5'2"	6'6"	33.58
Toilet	3'11"	12'11"	50.59
Toilet	7'5"	4'2"	30.90
Pooja Room	9'7"	12'4"	118.19
Balcony	48'00"	1'00"	48.00
Other Composition :			