

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65a785daebcd536a2b79cb4a"
    },
    "type": "CREDITOFFICER",
    "_id": "65a785daebcd536a2b79cb4c",
    "firstName": "Santosh",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8454840855",
    "email": "santoshkumar6@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65a785daebcd536a2b79cb4a",
  "name": "Diamond Branch Surat",
  "branchCode": "64422",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "m1.dbs@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Office No H001 & H004, Ground Floor, Tower H, Surat Diamond Bourse
Dream City, Khajod. Surat 395007 Surat Gujrat"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "655da0ac5586e008159055e7",
  "zoneName": "GUjrat"
},
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
```

```
"_id": "60f949ce45132d6a6bddbcc3",
"role": "SITEENGINEER",
"firstName": "Tushar ",
"email": "tusharbhuwad90@gmail.com",
"lastName": "Bhuwad",
"mobileNo": "9082053889",
"designation": "",
"shortName": "TSB",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.133941178497324",
  "longitude": "72.85732692922409"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "17/01/2024 01:42 pm"
    },
    {
      "dateTime": "17/01/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mogra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "B",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Mumbai Suburban District",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vaastu - Siddhi",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Behind Manish Park",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Rajmata Jijabai Road, Pump House ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shree Vastu Enclave",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "26/2 & 25/2",
```



```
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "371, 375 to 379",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "604",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K/E",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 093",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  }
},
```

```
"flooring": {
  "value": "Vitrified_tiles_flooring",
  "label": "Vitrified tiles flooring"
},
"doors": {
  "value": "Teak_wood_door_frame_with_flush_shutters",
  "label": "Teak wood door frame with flush shutters"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "company_ownership",
    "label": "company ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road / Vaastu Shilp Building",
    "west": "Internal Road / Vastu Shubh Building",
```

```
"south": "Vaastu Pooja",
"east": "Adarsh Janseva CHSL "
},
"asPerDocumentAgreement": {
  "north": "By the property of MHADA",
  "west": "By the property of Smt. Jane Catherine Gomes",
  "south": "By the property of Salesette Parsi Panchayat",
  "east": "By the property of Mr. Patel"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  }
}
```

```
},
"monthlyRent": "0000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Account No. 151649765",
"meterCardHolderName": "M/s. Paladiya Brothers And Company",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
}
```

```
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
}
```

```
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "11",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "988.00",
```

```
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Index- II"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65a78cc1ebcd536a2b79dee1/
routeMap_1705656532918_Image.png",
    "routeLat": "19.128639",
    "routeLng": "72.858389",
    "stationName": "Andheri",
    "routeDistance": "1.9 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "wiadt6",
      "name": "wiadt6",
      "image": "cases/65a78cc1ebcd536a2b79dee1/
routeMap_1705656139281_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```



```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "988.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65aa09bd9c967c12c91dddcb",
      "name": "externalimg_r_1705642429622_IMG20240118125200.jpg",
      "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705642429622_IMG20240118125200.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
```

```
    "_id": "65aa09bd9c967c12c91dddc2",
    "name": "externalimg_r_1705642429588_IMG20240118124454.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705642429588_IMG20240118124454.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65aa09b39c967c12c91dddac",
    "name": "externalimg_r_1705642419183_IMG20240118125238.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705642419183_IMG20240118125238.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc5",
    "name": "externalimg_r_1705642429595_IMG20240118124804.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705642429595_IMG20240118124804.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e3e",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705655970931_TimePhoto_20240119_114241.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e3f",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externalimg_r_1705655970927_TimePhoto_20240119_114235.jpg",
    "orientation": "portrait"
  }
]
```

```
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e42",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970940_TimePhoto_20240119_114254.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e43",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970942_TimePhoto_20240119_114301.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e44",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970944_TimePhoto_20240119_114305.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc1",
    "name": "Living Room",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429582_IMG20240118124412.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "988.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65a78cc1ebcd536a2b79dee1",
"ownerName": "Paladiya Brothers & Co.",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9820020912",
"contactPersonName": "Hetal Paladiya",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Paladiya Brothers & Co.",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "406632"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Owner",
"fullAddress": "Residential Flat No. 604, 6th Floor, Building No B, Wing - A, Vaastu - Siddhi, Shree Vastu Enclave, Behind Manish Park, Rajmata Jijabai Road, Pump House , Village - Mogra, Municipality Ward No. K/E, Andheri (East), Taluka - Andheri, District - Mumbai Suburban District, Mumbai, PIN - 400 093, State - Maharashtra, India",
```



```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "15/06/2005",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Anuman Developers",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "M/s. Paladiya Brothers & Co.",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "6112/2005"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "276138",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
document_1705479327850_VASTU_SIDDHI_AGREEMENT_COPY.pdf",
    "fileName":
"document_1705479327850_VASTU_SIDDHI_AGREEMENT_COPY.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "12/01/2004",
      "nameOfApprovingAuthority": {
        "value": "Municipal_Corporation_Of_Greater_Mumbai",
        "label": "Municipal Corporation Of Greater Mumbai"
      },
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "CE / 7301 / WS / AK"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1705663260822_Commencement_Certificate.pdf",
"path": "cases/65a78cc1ebcd536a2b79dee1/
document_1705663260822_Commencement_Certificate.pdf",
"id": "814501",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Jan 19 2024 16:51:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b337",
    "label": "Full Occupation Certificate"
  },
  "inputs": {
    "documentDate": "09/08/2006",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 7301 / WS / AK"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1705663356918_OC.pdf",
"path": "cases/65a78cc1ebcd536a2b79dee1/document_1705663356918_OC.pdf",
"id": "184497",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Jan 19 2024 16:52:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
  "inputs": {
    "documentDate": "15/06/2005",
    "from": {
```

```
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Anuman Developers",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Paladiya Brothers & Co.",
  "number": {
    "value": "Registration_No",
    "label": "Registration No"
  },
  "Registration_No": "6112/2005"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1705663618231_INDEX.pdf",
"path": "cases/65a78cc1ebcd536a2b79dee1/
document_1705663618231_INDEX.pdf",
"id": "927887",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Jan 19 2024 16:56:58 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "006405",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "409297",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Jan 17 2024 13:46:01 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "704547",
  "name": "Passage",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "14.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Living Room",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "23.25",
  "width1": "23",
  "width2": "3",
  "totalArea": "224.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "224.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Dining",
  "length": "11.42",
  "length1": "11",
  "length2": "5",
```

```
"width": "7.25",
"width1": "7",
"width2": "3",
"totalArea": "82.77",
"images": [],
"extraAreas": [],
"finalArea": "82.77"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "14.17",
  "width1": "14",
  "width2": "2",
  "totalArea": "93.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "93.26"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "13.83",
  "width1": "13",
  "width2": "10",
  "totalArea": "137.18",
  "images": [],
  "extraAreas": [],
  "finalArea": "137.18"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "31.01",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "18.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "5.42",
  "length1": "5",
  "length2": "5",
  "width": "3.42",
  "width1": "3",
```

```
"width2": "5",
"totalArea": "18.51",
"images": [],
"extraAreas": [],
"finalArea": "18.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Bedroom",
  "length": "13.67",
  "length1": "13",
  "length2": "8",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "157.17",
  "images": [],
  "finalArea": "157.17",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "30.03",
  "images": [],
  "finalArea": "30.03",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "10",
    "name": "Bedroom",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "14.17",
    "width1": "14",
    "width2": "2",
    "totalArea": "138.12",
    "images": [],
    "extraAreas": [],
    "finalArea": "138.12"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "780520",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "988",
    "squareMeterArea": "91.79",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBUILTUPPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09b39c967c12c91ddda9",
```



```
    "name": "externallmg_1705642419191_Screenshot_2024011812503878_3d9111e2d3171bf4882369f490c087b4.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_1705642419191_Screenshot_2024011812503878_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09b39c967c12c91dddac",
    "name": "externallmg_r_1705642419183_IMG20240118125238.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_r_1705642419183_IMG20240118125238.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddbd",
    "name": "externallmg_r_1705642429572_IMG20240118124151.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_r_1705642429572_IMG20240118124151.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91ddd0",
    "name": "externallmg_r_1705642429585_IMG20240118124419.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_r_1705642429585_IMG20240118124419.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91ddd1",
    "name": "externallmg_r_1705642429582_IMG20240118124412.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_r_1705642429582_IMG20240118124412.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91ddd2",
```

```
    "name": "externallmg_r_1705642429588_IMG20240118124454.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429588_IMG20240118124454.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc3",
    "name": "externallmg_r_1705642429592_IMG20240118124745.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429592_IMG20240118124745.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc5",
    "name": "externallmg_r_1705642429595_IMG20240118124804.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429595_IMG20240118124804.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc6",
    "name": "externallmg_r_1705642429605_IMG20240118125142.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429605_IMG20240118125142.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc7",
    "name": "externallmg_r_1705642429602_IMG20240118124812.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429602_IMG20240118124812.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc8",
    "name": "externallmg_r_1705642429609_IMG20240118125149.jpg",
```

```
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429609_IMG20240118125149.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddc9",
    "name": "externallmg_r_1705642429618_IMG20240118125153.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429618_IMG20240118125153.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddca",
    "name": "externallmg_r_1705642429613_IMG20240118125151.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429613_IMG20240118125151.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09bd9c967c12c91dddcb",
    "name": "externallmg_r_1705642429622_IMG20240118125200.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642429622_IMG20240118125200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09d59c967c12c91dde06",
    "name": "externallmg_r_1705642452455_IMG20240119103833.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642452455_IMG20240119103833.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa09d59c967c12c91dde07",
    "name": "externallmg_r_1705642452381_IMG20240119103824.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705642452381_IMG20240119103824.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65aa3ea39c967c12c91e6e3c",
  "name": "externallmg_r_1705655970924_externallmg_r_1705642429585_IMG2024
0118124419.jpg",
  "path": "cases/65a78cc1ebcd536a2b79dee1/externallmg_r_1705655970924_extern
allmg_r_1705642429585_IMG20240118124419.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65aa3ea39c967c12c91e6e3e",
  "name": "externallmg_r_1705655970931_TimePhoto_20240119_114241.jpg",
  "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970931_TimePhoto_20240119_114241.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65aa3ea39c967c12c91e6e3f",
  "name": "externallmg_r_1705655970927_TimePhoto_20240119_114235.jpg",
  "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970927_TimePhoto_20240119_114235.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65aa3ea39c967c12c91e6e40",
  "name": "externallmg_r_1705655970935_TimePhoto_20240119_114244.jpg",
  "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970935_TimePhoto_20240119_114244.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65aa3ea39c967c12c91e6e41",
  "name": "externallmg_r_1705655970938_TimePhoto_20240119_114249.jpg",
  "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970938_TimePhoto_20240119_114249.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e42",
    "name": "externallmg_r_1705655970940_TimePhoto_20240119_114254.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970940_TimePhoto_20240119_114254.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e43",
    "name": "externallmg_r_1705655970942_TimePhoto_20240119_114301.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970942_TimePhoto_20240119_114301.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e44",
    "name": "externallmg_r_1705655970944_TimePhoto_20240119_114305.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970944_TimePhoto_20240119_114305.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65aa3ea39c967c12c91e6e45",
    "name": "externallmg_r_1705655970946_TimePhoto_20240119_114313.jpg",
    "path": "cases/65a78cc1ebcd536a2b79dee1/
externallmg_r_1705655970946_TimePhoto_20240119_114313.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65a9f95f9c967c12c91da1a0",
  "note": "Given Approx Value Rs. 1.70 to Rs. 1.75 Crs.",
  "taskId": "65a78cc1ebcd536a2b79defe",
  "createdAt": "2024-01-19T04:23:59.629Z"
}
],
"createdAt": "2024-01-17T08:16:01.145Z",
"updatedAt": "2024-01-20T05:07:10.011Z",
"__v": 0,
"invoiceId": "65a78cc1ebcd536a2b79dee7",
"addressForMap": "",
"updatedBy": "60f91b6f344e052188ffd1fc",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Passage + Dining +
3 Toilet",
"carpetTotal": "946.2399999999999",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "1135.49",
"finalCarpetArea": "946.24",
"finalSalableArea": "1135.49",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Index- II",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 988.00",
"reportGeneratedDate": "Sat Jan 20 2024 09:26:31 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-01-18",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
```

```

    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Passage	3'10"	3'10"	14.69
Living Room	9'8"	23'3"	224.75
Dining	11'5"	7'3"	82.77
Kitchen	6'7"	14'2"	93.26
Bedroom	9'11"	13'10"	137.18
Toilet	3'11"	7'11"	31.01
Toilet	5'00"	3'9"	18.75
Passage	5'5"	3'5"	18.51
Bedroom	13'8"	11'6"	157.17
Toilet	3'11"	7'8"	30.03
Bedroom	9'9"	14'2"	138.12
Other Composition :			