

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "652e3ee4316e1359cebed68e"
    },
    "type": "CREDITOFFICER",
    "_id": "652e3ee4316e1359cebed690",
    "firstName": "Siddharth",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "8657798653",
    "email": "brmgr1756@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3462750",
    "discussWithPerson": "Siddharth",
    "expectedFees": 1731.375,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "652e3ee4316e1359cebed68e",
  "name": "Andheri East Seepz Branch",
  "branchCode": "1756",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "brmgr1756@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 4 & 5, Options PrimoBuilding , Plot no 21, MIDC Andheri East
Mumbai 400093"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.120481680426384",
  "longitude": "72.87337807116539"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87337807116539,
    19.120481680426384
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "17/01/2024 06:09 pm"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Marol",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "4",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Sai Jyot Lahuji Salve Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sainath Nagar, Pocket No. 7, C-Cross Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "M.I.D.C",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "29, 44, 45 & 46",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "704",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```

```
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": []
```



```
"_id": "65a7c3c0ebcd536a2b7ab613",
"ownerName": "Mr. Narendra Nandkumar Vardam & Mr. Nilesh Nandkumar Vardam",
"ownerPhoneNo": "8657798653",
"appAddress": "Flat no 704 7 th floor Bldg no 4 Shree Sai Jyot Lahuji Salve Co-op
HSG Soc Ltd Sai Nagar Pocket no 7 C-Cross Road MIDC Andheri East 400093",
"remark": "Structural report required ",
"documents": [],
"caseNumber": "006408",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "263285",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 17 2024 17:40:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Narendra Nandkumar Vardam & Mr. Nilesh Nandkumar Vardam",
    "phone": "8657798653",
    "ownershipShare": "",
    "email": "",
    "id": "850824"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af593",
    "name": "externalImg_1705554076584_externalImg_1705385985172_17053861009
18_image_0.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554076584_externalI
mg_1705385985172_1705386100918_image_0.jpeg",
    "orientation": "portrait"
  }
],
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af594",
    "name": "externallmg_1705554076625_externallmg_1705386005747_1705386121205_image_0.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076625_externallmg_1705386005747_1705386121205_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af595",
    "name": "externallmg_1705554076667_externallmg_1705386007545_1705386121205_image_1.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076667_externallmg_1705386007545_1705386121205_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af596",
    "name": "externallmg_1705554076680_externallmg_1705386007887_1705386121205_image_2.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076680_externallmg_1705386007887_1705386121205_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af597",
    "name": "externallmg_1705554076703_externallmg_1705386009312_1705386121205_image_3.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076703_externallmg_1705386009312_1705386121205_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af598",
    "name": "externallmg_1705554076725_externallmg_1705386010541_1705386121205_image_4.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076725_externall
```

```
mg_1705386010541_1705386121205_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b09debcd536a2b7af599",
  "name": "externallmg_1705554076739_externallmg_1705386011207_17053861212
05_image_5.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076739_externall
mg_1705386011207_1705386121205_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b09debcd536a2b7af59a",
  "name": "externallmg_1705554076753_externallmg_1705386011882_17053861212
05_image_6.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076753_externall
mg_1705386011882_1705386121205_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b09debcd536a2b7af59b",
  "name": "externallmg_1705554076764_externallmg_1705386049074_17053861631
86_image_0.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076764_externall
mg_1705386049074_1705386163186_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b09debcd536a2b7af59c",
  "name": "externallmg_1705554076779_externallmg_1705386050468_17053861631
86_image_1.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076779_externall
mg_1705386050468_1705386163186_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65a8b09debcd536a2b7af59d",
    "name": "externallmg_1705554076798_externallmg_1705386051687_17053861631
86_image_2.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076798_externall
mg_1705386051687_1705386163186_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af59e",
    "name": "externallmg_1705554076812_externallmg_1705386052896_17053861631
86_image_3.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076812_externall
mg_1705386052896_1705386163186_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af59f",
    "name": "externallmg_1705554076830_externallmg_1705386054547_17053861631
86_image_4.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554076830_externall
mg_1705386054547_1705386163186_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b09debcd536a2b7af5a0",
    "name": "externallmg_r_1705554076610_externallmg_1705385985992_170538610
0918_image_1.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_r_1705554076610_extern
allmg_1705385985992_1705386100918_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af64e",
    "name": "externallmg_1705554095270_externallmg_1705386067896_17053861631
86_image_12.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095270_externall
mg_1705386067896_1705386163186_image_12.jpeg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af64f",
  "name": "externallmg_1705554095303_externallmg_1705386069691_1705386163186_image_13.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095303_externallmg_1705386069691_1705386163186_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af650",
  "name": "externallmg_1705554095329_externallmg_1705386011207_1705386121205_image_5.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095329_externallmg_1705386011207_1705386121205_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af651",
  "name": "externallmg_1705554095356_externallmg_1705386011882_1705386121205_image_6.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095356_externallmg_1705386011882_1705386121205_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af652",
  "name": "externallmg_1705554095369_externallmg_1705386049074_1705386163186_image_0.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095369_externallmg_1705386049074_1705386163186_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af653",
  "name": "externallmg_1705554095385_externallmg_1705386050468_17053861631
```

```
86_image_1.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554095385_external
mg_1705386050468_1705386163186_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af654",
  "name": "externalImg_1705554095401_externalImg_1705386051687_17053861631
86_image_2.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554095401_external
mg_1705386051687_1705386163186_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af655",
  "name": "externalImg_1705554095416_externalImg_1705386052896_17053861631
86_image_3.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554095416_external
mg_1705386052896_1705386163186_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af656",
  "name": "externalImg_1705554095440_externalImg_1705386054547_17053861631
86_image_4.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554095440_external
mg_1705386054547_1705386163186_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af657",
  "name": "externalImg_1705554095461_externalImg_1705386056177_17053861631
86_image_5.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externalImg_1705554095461_external
mg_1705386056177_1705386163186_image_5.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af658",
    "name": "externallmg_1705554095486_externallmg_1705386057922_1705386163186_image_6.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095486_externallmg_1705386057922_1705386163186_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af659",
    "name": "externallmg_1705554095507_externallmg_1705386059666_1705386163186_image_7.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095507_externallmg_1705386059666_1705386163186_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af65a",
    "name": "externallmg_1705554095579_externallmg_1705386061381_1705386163186_image_8.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095579_externallmg_1705386061381_1705386163186_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af65b",
    "name": "externallmg_1705554095652_externallmg_1705386062886_1705386163186_image_9.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095652_externallmg_1705386062886_1705386163186_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65a8b0afebcd536a2b7af65c",
    "name": "externallmg_1705554095671_externallmg_1705386064466_1705386163186_image_10.jpeg",
    "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095671_externall
```

```
mg_1705386064466_1705386163186_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65a8b0afebcd536a2b7af65d",
  "name": "externallmg_1705554095715_externallmg_1705386066946_1705386163186_image_11.jpeg",
  "path": "cases/65a7c3c0ebcd536a2b7ab613/externallmg_1705554095715_externallmg_1705386066946_1705386163186_image_11.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-17T12:10:40.625Z",
"updatedAt": "2024-01-18T05:01:35.865Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Structural Report No. 704, 7th Floor, Building No 4, Shree Sai Jyot Lahuji Salve Co-Op. Hsg. Soc. Ltd. , CTS No. 29, 44, 45 & 46, Sainath Nagar, Pocket No. 7, C-Cross Road, M.I.D.C, Village - Marol, Andheri (East), Mumbai",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Narendra Nandkumar Vardam & Mr. Nilesh Nandkumar Vardam",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8657798653"
}
```


Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			