

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80d"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f33",
    "firstName": "Tushar M",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-7506188320"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Tushar M",
    "expectedFees": null,
    "quotedAmount": "90000"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80d",
  "branchCode": "000086",
  "type": "BRANCH",
  "name": "Wagle Ind. Est. Branch",
  "email": "sbi.01053@sbi.co.in",
  "mobileNo": "022-25817818",
  "alternateMobileNo": "",
  "address": "Regional Business Office, Region-II, Wagle Ind. Area, Plot No. B-35, 2nd
Floor, Wagle Circle, Thane (West) - 400 604, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - WAGLE ESTATE",
  "fax": "25817831 / 32",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.09046168696473",
  "longitude": "72.83455163842122"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83455163842122,
    19.09046168696473
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-19",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vile Parle (West)",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2A1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Santacruz (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "20(Part), TPS VI",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Dheeraj Heritage Premises Co-Op. Hsg. Soc. Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S. V. Road, Daulat Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```



```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1609A (Part)",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "9",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 054",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_Framed_with_Glass_Door",
    "label": "Teak Wood Door Framed with Glass Door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
```

```

},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Slum_Rehabilitation_Authority",
    "label": "Slum Rehabilitation Authority"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Modi Hyundai Showroom ",
    "west": "Santacruz Bus Depot ",
    "south": "Sane Guruji Road ",
    "east": "S. V. Road "
  },
  "asPerDocumentAgreement": {
    "north": "Partly by Final Plot No. 21(Part) & Partly by Plot No. 20",
    "west": "By Final Plot No. 20",
    "south": "By 18.29 M. Wide Road ",
    "east": "By 27.44 Wide S.V.Road "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  },
},

```

```

"asPerDocument": {
  "north": "Details not available ",
  "east": "Details not available ",
  "south": "Details not available ",
  "west": "Details not available "
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "At the time of site visit Shop Nos. 8 & 9 are internally merged with separate entrance but can be easily demarcated separately. WC/Bath and Pantry in Shop No. 8 and Working area in Shop No.9. It is used by The Pratap Co-Op. Bank Ltd. ",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed that the construction is as per sanctioned plan. \n\n",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "i)At the time of inspection, Shop No. 8 & 9 is internally merged having Separate entrances. Both the Shops can be easily demarcated. The said valuation is only for Shop No. 9. It is used by The Pratatp Co- Op. Bank Ltd. For the purpose of valuation, we have considered the area as per Agreement for Sale of Shop No. 9. <br /> ii)Occupancy Certificate granted for shopping user on Lower Ground, Ground and 1st Floor. Office users at upper floors. The shop under valuation is located on First Floor.<br /> ",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "48028",
  "depreciatedBuildingRate": "2128"
},
"igrRate": {
  "propertyName": "Shop",
  "rate": "306200",
  "landRate": "116770",
  "igrImage": "cases/65aa121f9c967c12c91e08a4/igr_1707211210798_Image.png",
  "squareMeterGuideLineRate": "306200.00",
  "squareFeetGuideLineRate": "28447.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "84",
  "rate": "25631.00",
  "squareFeetGuideLineRate": "25631.00",
  "squareMeterGuideLineRate": "275891.00"

```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "34,000 Expected rental per month ",
  "assessmentNo": "Bill No. HW1204611010000",
  "taxPaidHolderName": "Dheeraj Heritage Premises Co-Op. Hsg. Soc. Ltd.\n",
  "taxAmount": "01.04.2023 To 30.09.2023 = Rs. 75,58,014.00<br /> 01.10.2023 To  
31.03.2024 = Rs. 75,58,014.00<br /> Total Rs. 1,51,16,028.00",
  "electricityServiceConnectionNo": "Bill No. 100221134717 ",
  "meterCardHolderName": "Heritage Housing Dev. Pvt. Ltd. ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per SRA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
```

```
"label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
}
```



```
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "59"
},
"finalPlinthArea": {
  "area": "255.60",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65aa121f9c967c12c91e08a4/
routeMap_1707222444836_Image.png",
    "routeLat": "19.089889",
    "routeLng": "72.837417",
    "stationName": "Santacruz ",
    "routeDistance": "1.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "32xaju",
      "name": "32xaju",

```

```
    "image": "cases/65aa121f9c967c12c91e08a4/
routeMap_1707222340040_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "10229964.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "10229964.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Feb 07 2024 09:23:51 GMT+0530 (India Standard Time)",
  "number": "2304844",
  "dayCount": "1",
  "monthCount": "66",
```

```
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6551284.00",
  "selectedBuildUpValue": "255.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65ab8af48babf21ac5da9bba",
      "name": "externallmg_1705740715140_1705740684391_image_2.jpeg",
      "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740715140_1705740684391_image_2.jpeg",
```

```
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bb9",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740635553_1705740684391_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbe",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740842835_1705740684392_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc2",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740887818_1705740684392_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc0",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740878114_1705740684392_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc6",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740948709_1705740684392_image_14.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbc",
    "name": "Working Area",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740782390_1705740684392_image_4.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "42188",
    "max": "72858"
  },
  "builtUpRateRange": {
    "min": "35157",
    "max": "60715"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "213.00",
empanelmentNo": [
"SME/TCC/2021-22/86/3"
],
isAdvanceInvoice": true,
```

```
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65aa121f9c967c12c91e08a4",
"ownerName": "Shri. Bajrang C. Singh",
"ownerPhoneNo": "7045161756",
"appAddress": "Shop No. 9, 1st floor, Bldg. No. 2A1, Dheeraj Heritage, Daulat Nagar,
TPS VI, Santacruz (West), Mumbai - 400054",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "15/07/2006",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Uday Pratap Singh ",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Shri. Bajrang C. Singh & Ms. Shanti G. Singh ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "5933 / 2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "216461",
    "path": "cases/65aa121f9c967c12c91e08a4/
document_1707217035980_Agreement_for_sale.pdf",
    "fileName": "document_1707217035980_Agreement_for_sale.pdf"
  },
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b328",
      "label": "Death Certificate"
    },
  },
}
```

```

"inputs": {
  "documentDate": "19/04/2021",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Ms. Shanti G. Singh "
},
"isHardCopy": false,
"displayStatus": false,
"id": "650363",
"path": "cases/65aa121f9c967c12c91e08a4/
document_1707217087592_Death_Certificate.pdf",
"fileName": "document_1707217087592_Death_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "01/10/2008",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "remark": " For shopping user on Lower Ground, Ground and 1st Floor. Office
users at upper floors.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 635 / HW / GL / AP / 2A"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "572016",
  "path": "cases/65aa121f9c967c12c91e08a4/document_1707217163770_OC.pdf",
  "fileName": "document_1707217163770_OC.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {

```

```
"documentDate": "17/10/2000",
"nameOfApprovingAuthority": {
  "value": "Slum_Rehabilitation_Authority_(SRA)",
  "label": "Slum Rehabilitation Authority (SRA)"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "SRA / ENG / 635 / HW / GL / AP / 2A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707217242353_Agreement_for_sale.pdf",
"path": "cases/65aa121f9c967c12c91e08a4/
document_1707217242353_Agreement_for_sale.pdf",
"id": "804294",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Feb 06 2024 16:30:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "08/08/2012",
    "remark": " issued by Dheeraj Heritage Premises Co-Op. Hsg. Soc. Ltd",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Shri. Bajrang C. Singh & Ms. Shanti G. Singh",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "003"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "584140",
  "path": "cases/65aa121f9c967c12c91e08a4/
document_1707217399324_Share_Certificate.pdf",
  "fileName": "document_1707217399324_Share_Certificate.pdf"
},
}
```

```
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "100221134717 dated 12.12.2023 in the name of Heritage Housing Dev. Pvt.
Ltd. issued by Adani Electricity "
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1707217516609_Electricity_Bill.pdf",
  "path": "cases/65aa121f9c967c12c91e08a4/
document_1707217516609_Electricity_Bill.pdf",
  "id": "891574",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Feb 06 2024 16:35:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "GST-D / 3700 / 23-24 dated 01.01.2024 in the name of Shri. Bajrang C.
Singh & Ms. Shanti G. Singh issued by Dheeraj Heritage Premises Co-Op. Hsg. Soc.
Ltd"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1707218270421_Maintanance_Bill.pdf",
  "path": "cases/65aa121f9c967c12c91e08a4/
document_1707218270421_Maintanance_Bill.pdf",
  "id": "724925",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Feb 06 2024 16:47:50 GMT+0530 (India Standard Time)"
},
{
```

```
"documentType": {
  "value": "60ae124daa6d152c1801b306",
  "label": "Property Tax"
},
"inputs": {
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "HW1204611010000 for the year 2023-24 issued by BMC."
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707218699213_Property_Tax.pdf",
"path": "cases/65aa121f9c967c12c91e08a4/
document_1707218699213_Property_Tax.pdf",
"id": "150598",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Feb 06 2024 16:54:59 GMT+0530 (India Standard Time)"
}
],
"gstNo": "",
"caseNumber": "006442",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "139440",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 19 2024 11:39:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Bajrang C. Singh",
    "phone": "7045161756",
    "ownershipShare": "",
    "email": "",
    "id": "168179"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "141139",
  "name": "Working Area",
  "length": "11.75",
  "length1": "11",
  "length2": "9",
  "width": "17.92",
  "width1": "17",
  "width2": "11",
  "totalArea": "210.52",
  "images": [],
  "extraAreas": [],
  "finalArea": "210.52"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Sale Agreement",
      "value": "60ae128faa6d152c1801b437"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "19.79",
    "totalAreaDocument": "213",
    "docBultupPercentage": "20",
    "docFinalBultUp": "255.60",
    "docFinalBultUpSquareMeter": "23.75",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "305236"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65c1fa3d6635d840ef5f5de2",
```

```
"property": "Shop",
"area": "256",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"source": "Index_no.2",
"expectedPrice": "9000000.00",
"expectedRate": "35156.25",
"builtUpExpectedRate": "9000000.00",
"image": "cases/65aa121f9c967c12c91e08a4/
indicator_1707210959191_Image.png",
"squareMeter": "23.78",
"id": "372086"
},
{
  "printlnReport": true,
  "_id": "65c1fa3d6635d840ef5f5de3",
  "property": "Shop",
  "area": "700",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "42500000",
  "expectedRate": "60714.29",
  "builtUpExpectedRate": "42500000",
  "image": "cases/65aa121f9c967c12c91e08a4/
indicator_1707211048048_Image.png",
  "squareMeter": "65.03",
  "id": "471968"
},
{
  "printlnReport": true,
  "_id": "65c1fa3d6635d840ef5f5de4",
  "property": "Shop",
  "area": "252",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "12500000",
  "expectedRate": "49603.17",
  "builtUpExpectedRate": "12500000",
```



```
    "image": "cases/65aa121f9c967c12c91e08a4/
indicator_1707211083180_Image.png",
    "squareMeter": "23.41",
    "id": "809275"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bb7",
    "name": "externalimg_1705740603988_1705740706615_image_0.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externalimg_1705740603988_1705740706615_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bb8",
    "name": "externalimg_1705740567039_1705740684389_image_0.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externalimg_1705740567039_1705740684389_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bb9",
    "name": "externalimg_1705740635553_1705740684391_image_1.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externalimg_1705740635553_1705740684391_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bba",
    "name": "externalimg_1705740715140_1705740684391_image_2.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externalimg_1705740715140_1705740684391_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "65ab8af48babf21ac5da9bbb",
    "name": "externallmg_1705740740194_1705740684392_image_3.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740740194_1705740684392_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbc",
    "name": "externallmg_1705740782390_1705740684392_image_4.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740782390_1705740684392_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbd",
    "name": "externallmg_1705740817826_1705740684392_image_5.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740817826_1705740684392_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbe",
    "name": "externallmg_1705740842835_1705740684392_image_6.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740842835_1705740684392_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bbf",
    "name": "externallmg_1705740859885_1705740684392_image_7.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740859885_1705740684392_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc0",
```

```
    "name": "externallmg_1705740878114_1705740684392_image_8.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740878114_1705740684392_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc1",
    "name": "externallmg_1705740878946_1705740684392_image_9.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740878946_1705740684392_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc2",
    "name": "externallmg_1705740887818_1705740684392_image_10.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740887818_1705740684392_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc3",
    "name": "externallmg_1705740915138_1705740684392_image_11.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740915138_1705740684392_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc4",
    "name": "externallmg_1705740923445_1705740684392_image_12.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740923445_1705740684392_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc5",
    "name": "externallmg_1705740938813_1705740684392_image_13.jpeg",
```

```
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740938813_1705740684392_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc6",
    "name": "externallmg_1705740948709_1705740684392_image_14.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740948709_1705740684392_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc7",
    "name": "externallmg_1705740976737_1705740684392_image_15.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705740976737_1705740684392_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc8",
    "name": "externallmg_1705741008308_1705740684392_image_16.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705741008308_1705740684392_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bc9",
    "name": "externallmg_1705741023313_1705740684392_image_17.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705741023313_1705740684392_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65ab8af48babf21ac5da9bca",
    "name": "externallmg_1705741028264_1705740684392_image_18.jpeg",
    "path": "cases/65aa121f9c967c12c91e08a4/
externallmg_1705741028264_1705740684392_image_18.jpeg",
```

```
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)- bajrang.xlsx",
    "filename": "1707211369173_Calculation_2_bajrang.xlsx",
    "path": "cases/65aa121f9c967c12c91e08a4/
processingDocuments/1707211369173_Calculation_2_bajrang.xlsx",
    "size": "16092",
    "createdAt": "Tue Feb 06 2024 14:52:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1707211369176_reference_report.pdf",
    "path": "cases/65aa121f9c967c12c91e08a4/
processingDocuments/1707211369176_reference_report.pdf",
    "size": "8514337",
    "createdAt": "Tue Feb 06 2024 14:52:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - bajrang.xlsx",
    "filename": "1707211369900_Summary__bajrang.xlsx",
    "path": "cases/65aa121f9c967c12c91e08a4/
processingDocuments/1707211369900_Summary__bajrang.xlsx",
    "size": "5880452",
    "createdAt": "Tue Feb 06 2024 14:52:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
    },
    "workType": "RATE_VERIFY",
```

```
"display": true,
"status": true,
"_id": "65b1eb0209f5e9474b4efb70",
"note": "Value shared with Prayush",
"taskId": "65ab74ec8babf21ac5da7046",
"createdAt": "2024-01-25T05:00:50.926Z"
},
{
  "createdBy": {
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "65bc6dd36635d840ef593b1b",
  "note": "Project report pending - Prayush",
  "taskId": "65ab74ec8babf21ac5da7046",
  "createdAt": "2024-02-02T04:21:39.867Z"
}
],
"createdAt": "2024-01-19T06:09:35.085Z",
"updatedAt": "2024-02-07T04:56:03.718Z",
"__v": 0,
"invoiceId": "65aa121f9c967c12c91e08b5",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Shop No. 9, 1st Floor, Building No 2A1, Dheeraj Heritage
Premises Co-Op. Hsg. Soc. Ltd, Plot No. 20(Part), TPS VI, CTS No. 1609A (Part), S. V.
Road, Daulat Nagar, Village - Vile Parle (West), Taluka - Andheri , District - Mumbai
Suburban , Santacruz (West), PIN - 400 054, State - Maharashtra, Country - India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Vasudev Raj ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Bank Manager ",
"siteVisitContactNo": "9821828421",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Sale Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 213.00",
"flatRate": "48700",
"landOtherRate": "45900",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "210.52",
"extendOfSiteRemark": "",
"finalBuiltupArea": "231.57",
"finalCarpetArea": "210.52",
"finalSalableArea": "254.73",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "Working Area",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
```

```
"leaseDate": ""
}
},
"reportGeneratedDate": "Tue Feb 06 2024 16:09:36 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-19"
}
```

Name	Length	Width	Total
Composition :			
Working Area	11'9"	17'11"	210.52
Other Composition :			