

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "652695d5703d7c40db9b3b77",
    "firstName": "Vishant ",
    "lastName": "Verma",
    "mobileNo": "",
    "workMobileNo": "9507000088",
    "email": "1cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6727660",
    "discussWithPerson": "Vishant ",
    "expectedFees": 3363.83,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
```

```
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.919421776263327",
  "longitude": "73.19226626857616"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.19226626857616,
    18.919421776263327
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "23/01/2024 09:36 am"
    },
    {
      "dateTime": "23/01/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-24",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Bhokarpada",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Artemis",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "NH 4",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Hiranandani Fortune City",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "67",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Panvel",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Maharashtra_Industrial_Development_Corporation",
  "label": "Maharashtra Industrial Development Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Open Plot",
  "west": "Amenity Area",
  "south": "Selene Hiranandani Fortune City",
  "east": "Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No.3219
Dated 13.10.2017 issued by Maharashtra Industrial Development Corporation",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Village - Bhokarpada",
  "rate": "56700",
  "landRate": "4750",
  "igrImage": "cases/65ae34598babf21ac5db5142/igr_1705999771187_Image.png",
  "squareMeterGuideLineRate": "62370.00",
  "squareFeetGuideLineRate": "5794.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "56700.00",
  "squareMeterGuideLineRate": "62370.00",
  "squareFeetGuideLineRate": "5794.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "50000",
  "assessmentNo": "Details not available",
```

```
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MIDC / MSRDC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Single Car Parking at P1 Level No. 286",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
```

```
"year": "2021",
"fullDate": "1/1/2021"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Part_Occupancy_Certificate",
  "label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "36",
"flatFloorNo": "11",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```



```
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
},
"routeMapImg": "cases/65ae34598babf21ac5db5142/
routeMap_1706092974034_Image.png",
"routeLat": "18.914083",
"routeLng": "73.194917",
"stationName": "Panvel",
"routeDistance": "16.6 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "ahfen",
    "name": "ahfen",
    "image": "cases/65ae34598babf21ac5db5142/
routeMap_1706092869836_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
```

```
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "19955000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "19955000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9332340.00",
  "selectedBuildUpValue": "1688.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b0ea04b53a231df751a23d",
      "name":
"externallmg_1706093058993_WhatsApp_Image_20240124_at_34908_PM_2.jpeg",
      "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093058993_WhatsApp_Image_20240124_at_34908_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65b0ea04b53a231df751a23e",
      "name":
"externallmg_1706093059122_WhatsApp_Image_20240124_at_34908_PM.jpeg",
      "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059122_WhatsApp_Image_20240124_at_34908_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65b0ea04b53a231df751a241",
      "name":
"externallmg_1706093059371_WhatsApp_Image_20240124_at_34909_PM.jpeg",
      "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059371_WhatsApp_Image_20240124_at_34909_PM.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a249",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059967_WhatsApp_Image_20240124_at_34912_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a245",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059705_WhatsApp_Image_20240124_at_34911_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a246",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059762_WhatsApp_Image_20240124_at_34911_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a247",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059836_WhatsApp_Image_20240124_at_34911_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a248",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059899_WhatsApp_Image_20240124_at_34912_PM_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "65b0ea04b53a231df751a244",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059641_WhatsApp_Image_20240124_at_34910_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a243",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059553_WhatsApp_Image_20240124_at_34910_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a242",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059503_WhatsApp_Image_20240124_at_34910_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a23f",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059227_WhatsApp_Image_20240124_at_34909_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b0ea04b53a231df751a240",
    "name": "Living Room",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059320_WhatsApp_Image_20240124_at_34909_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": null,
    "max": null
  }
},
```

```
"builtUpRateRange": {
  "min": null,
  "max": null
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1535.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65ae34598babf21ac5db5142",
"ownerName": "Sundar Narayan & Gouri Sundar",
"ownerPhoneNo": "8652288515",
"appAddress": "flat no. 1103 . 13 th floor Bldg . Artemis'at Hiranadani fortune city
village Bhokarpada panvel ",
"remark": "Bankar vishant sir ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
```

```
"documentDate": "24/11/2017",
"from": {
  "value": "Developers",
  "label": "Developers"
},
"Developers": "Persipina Developers Private Limited",
"to": {
  "value": "Allottee",
  "label": "Allottee"
},
"Allottee": "Sundar Narayan & Gouri Sundar",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "7922/2017"
},
"isHardCopy": false,
"displayStatus": true,
"id": "165436",
"path": "cases/65ae34598babf21ac5db5142/
document_1705915437362_1705915560035_20230925105327.pdf",
"fileName": "document_1705915437362_1705915560035_20230925105327.pdf"
},
{
  "documentType": {
    "value": "60ae1285aa6d152c1801b40d",
    "label": "Car Parking Allotment Letter"
  },
  "inputs": {
    "documentDate": "14/02/2023",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "N.A."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706091052365_91532.pdf",
  "path": "cases/65ae34598babf21ac5db5142/
document_1706091052365_91532.pdf",
  "id": "253236",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Jan 24 2024 15:40:52 GMT+0530 (India Standard Time)"
},
```

```
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "27/07/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P52000001381"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706091167302_P52000001381.pdf",
  "path": "cases/65ae34598babf21ac5db5142/
document_1706091167302_P52000001381.pdf",
  "id": "432902",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Jan 24 2024 15:42:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/10/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Industrial_Development_Corporation",
      "label": "Maharashtra Industrial Development Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MIDC / R.O. / Thane - 1 / Bldg. Plans Approval / 3219 / 2017"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "534757",
```

```
"path": "cases/65ae34598babf21ac5db5142/document_1706091272306_cc.pdf",
"fileName": "document_1706091272306_cc.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "13/10/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Industrial_Development_Corporation",
      "label": "Maharashtra Industrial Development Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "3219"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706091324979_Floor_Plan.pdf",
  "path": "cases/65ae34598babf21ac5db5142/
document_1706091324979_Floor_Plan.pdf",
  "id": "599955",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Jan 24 2024 15:45:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1250aa6d152c1801b316",
    "label": "Part Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "05/05/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_State_Road_Development_Corporation_Limited_",
      "label": "Maharashtra State Road Development Corporation Limited "
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MSRDC / SPA / ITP - 1 / Plot No. 18 / Part O.C. / 2021 / 512"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1706091392733_oc.pdf",
"path": "cases/65ae34598babf21ac5db5142/document_1706091392733_oc.pdf",
"id": "160001",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Jan 24 2024 15:46:33 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006491",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
{
  "id": "168405",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Mon Jan 22 2024 14:54:41 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Sundar Narayan & Gouri Sundar",
  "phone": "8652288515",
  "ownershipShare": "",
  "email": "",
  "id": "704208"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "882366",
  "name": "Living Room",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "23.50",
  "width1": "23",
  "width2": "6",
  "totalArea": "399.50",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "399.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "12.25",
  "length1": "12",
  "length2": "3",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "104.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "104.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "22.92",
  "width1": "22",
  "width2": "11",
  "totalArea": "87.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "87.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
```

```
"length": "14.42",
"length1": "14",
"length2": "5",
"width": "10.92",
"width1": "10",
"width2": "11",
"totalArea": "157.38",
"images": [],
"extraAreas": [],
"finalArea": "157.38"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "45.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "14.42",
  "length1": "14",
  "length2": "5",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "157.38",
  "images": [],
  "extraAreas": [],
  "finalArea": "157.38"
```



```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "8.58",
  "width1": "8",
  "width2": "7",
  "totalArea": "45.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "59.94",
  "images": [],
  "extraAreas": [],
  "finalArea": "59.94"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "14.42",
  "length1": "14",
```

```
"length2": "5",
"width": "18.00",
"width1": "18",
"width2": "00",
"totalArea": "259.50",
"images": [],
"extraAreas": [],
"finalArea": "259.50"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "4",
  "length2": "00",
  "length": "4.00",
  "width1": "14",
  "width2": "00",
  "width": "14.00",
  "totalArea": "56.00",
  "percentageBeforeTotal": "56.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "56"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  }
}
```

```
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length1": "5",
"length2": "00",
"length": "5.00",
"width1": "6",
"width2": "00",
"width": "6.00",
"totalArea": "30.00",
"percentageBeforeTotal": "30.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "30"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "3",
  "length2": "00",
  "length": "3.00",
  "width1": "5",
  "width2": "00",
  "width": "5.00",
  "totalArea": "15.00",
  "percentageBeforeTotal": "15.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15"
}
```

```
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "142.61",
    "totalAreaDocument": "1535",
    "docBultupPercentage": "10",
    "docFinalBultUp": "1688.50",
    "docFinalBultUpSquareMeter": "156.87",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "191289"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": false,
    "_id": "65af7e048babf21ac5dc8d28",
    "property": "Hiranandani Fortune City, Panvel",
    "area": "1487",
    "bultUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "21000000",
    "expectedRate": "14122.39",
    "bultUpExpectedRate": "12838.54",
    "image": "cases/65ae34598babf21ac5db5142/indicator_1705998022397_Image.png",
    "squareMeter": "138.15",
    "id": "659601"
  },
  {
    "printlnReport": false,
```

```
  "_id": "65af7e048babf21ac5dc8d29",
  "property": "Hiranandani Fortune City, Panvel",
  "area": "1167",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "13500000",
  "expectedRate": "11568.12",
  "builtUpExpectedRate": "10516.48",
  "image": "cases/65ae34598babf21ac5db5142/
indicator_1705998727245_Image.png",
  "squareMeter": "108.42",
  "id": "647869"
},
{
  "printlnReport": false,
  "_id": "65af7e048babf21ac5dc8d2a",
  "property": "Hiranandani Fortune City",
  "area": "1170",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "17500000",
  "expectedRate": "14957.26",
  "builtUpExpectedRate": "13597.51",
  "image": "cases/65ae34598babf21ac5db5142/
indicator_1705999655947_Image.png",
  "squareMeter": "108.70",
  "id": "328247"
},
{
  "printlnReport": false,
  "_id": "65af7e048babf21ac5dc8d2b",
  "property": "Hiranandani Fortune City, Panvel",
  "area": "1149",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "17500000",
  "expectedRate": "15230.64",
```

```
    "builtUpExpectedRate": "13846.03",
    "image": "cases/65ae34598babf21ac5db5142/
indicator_1705999685012_Image.png",
    "squareMeter": "106.75",
    "id": "343694"
  },
  {
    "printlnReport": false,
    "_id": "65af7e048babf21ac5dc8d2c",
    "property": "Hiranandani Fortune City",
    "area": "1481.66",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "17731420",
    "expectedRate": "11967.27",
    "builtUpExpectedRate": "10879.31",
    "image": "cases/65ae34598babf21ac5db5142/
indicator_1705999735516_Image.png",
    "squareMeter": "137.65",
    "id": "470377"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a23d",
    "name":
"externalImg_1706093058993_WhatsApp_Image_20240124_at_34908_PM_2.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externalImg_1706093058993_WhatsApp_Image_20240124_at_34908_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a23e",
    "name":
"externalImg_1706093059122_WhatsApp_Image_20240124_at_34908_PM.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externalImg_1706093059122_WhatsApp_Image_20240124_at_34908_PM.jpeg",
    "orientation": "landscape"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a23f",
  "name":
"externallmg_1706093059227_WhatsApp_Image_20240124_at_34909_PM_1.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059227_WhatsApp_Image_20240124_at_34909_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a240",
  "name":
"externallmg_1706093059320_WhatsApp_Image_20240124_at_34909_PM_2.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059320_WhatsApp_Image_20240124_at_34909_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a241",
  "name":
"externallmg_1706093059371_WhatsApp_Image_20240124_at_34909_PM.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059371_WhatsApp_Image_20240124_at_34909_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a242",
  "name":
"externallmg_1706093059503_WhatsApp_Image_20240124_at_34910_PM_1.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059503_WhatsApp_Image_20240124_at_34910_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a243",
  "name":
"externallmg_1706093059553_WhatsApp_Image_20240124_at_34910_PM_3.jpeg",
```

```
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059553_WhatsApp_Image_20240124_at_34910_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a244",
    "name":
"externallmg_1706093059641_WhatsApp_Image_20240124_at_34910_PM.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059641_WhatsApp_Image_20240124_at_34910_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a245",
    "name":
"externallmg_1706093059705_WhatsApp_Image_20240124_at_34911_PM_1.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059705_WhatsApp_Image_20240124_at_34911_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a246",
    "name":
"externallmg_1706093059762_WhatsApp_Image_20240124_at_34911_PM_3.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059762_WhatsApp_Image_20240124_at_34911_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b0ea04b53a231df751a247",
    "name":
"externallmg_1706093059836_WhatsApp_Image_20240124_at_34911_PM.jpeg",
    "path": "cases/65ae34598babf21ac5db5142/
externallmg_1706093059836_WhatsApp_Image_20240124_at_34911_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "65b0ea04b53a231df751a248",
  "name":
"externalImg_1706093059899_WhatsApp_Image_20240124_at_34912_PM_2.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externalImg_1706093059899_WhatsApp_Image_20240124_at_34912_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a249",
  "name":
"externalImg_1706093059967_WhatsApp_Image_20240124_at_34912_PM.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externalImg_1706093059967_WhatsApp_Image_20240124_at_34912_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b0ea04b53a231df751a24a",
  "name":
"externalImg_1706093060132_WhatsApp_Image_20240124_at_34913_PM.jpeg",
  "path": "cases/65ae34598babf21ac5db5142/
externalImg_1706093060132_WhatsApp_Image_20240124_at_34913_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "6491.xlsx",
    "filename": "1706093822830_6491.xlsx",
    "path": "cases/65ae34598babf21ac5db5142/
processingDocuments/1706093822830_6491.xlsx",
    "size": "2797461",
    "createdAt": "Wed Jan 24 2024 16:27:05 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-22T09:24:41.373Z",
"updatedAt": "2024-01-24T11:26:58.276Z",
```

```
"__v": 0,
"invoiceId": "65ae34598babf21ac5db514b",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1103, 11th Floor, Artemis, Hiranandani Fortune
City, NH 4, Village - Bhokarpada, Panvel, Taluka - Panvel, District - Raigad, Navi
Mumbai, PIN Code - 410 206, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Sayali",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "9920666603",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1535.00",
"flatRate": "13000",
"landOtherRate": "10200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"builtupPercentage": "10",
"carpetTotal": "1316.06",
"extendOfSiteRemark": "MOFA Carpet Area in Sq. Ft. = 1478.00\n\nRERA Carpet
Area in Sq. Ft. = 1406.00\nDeck / Balcony Area in Sq. Ft. = 129.00\nTotal Carpet Area
in Sq. Ft. = 1535.00\n(Area as per Agreement for Sale)",
"finalBuiltupArea": "1558.77",
"finalCarpetArea": "1417.06",
"finalSalableArea": "1714.64",
```

```

"otherCarpetTotal": "86.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 1316.00\nTerrace Area in Sq. Ft.
= 56.00\nFlowerbed Area in Sq. Ft. = 30.00\nDry Balcony Area in Sq. Ft. = 15.00\nTotal
Carpet Area in Sq. Ft. = 1417.00\n(Area as per Actual Site Measurement)",
"toBeAdded": "",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + 3 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "101.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Wed Jan 24 2024 15:23:34 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-24"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'00"	23'6"	399.50
Kitchen	12'3"	8'6"	104.12
Passage	3'10"	22'11"	87.85
Bedroom	14'5"	10'11"	157.38
Toilet	5'4"	8'6"	45.33
Bedroom	14'5"	10'11"	157.38

Toilet	5'3"	8'7"	45.06
Toilet	5'3"	11'5"	59.94
Bedroom	14'5"	18'00"	259.50
Other Composition :			
Terrace Area	4'00"	14'00"	56.00
Flowered Area	5'00"	6'00"	30.00
Dry Balcony Area	3'00"	5'00"	15.00