

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "659e41f902c44c777bae2b5f",
    "firstName": "Monika",
    "lastName": "Shrivastav",
    "mobileNo": "",
    "workMobileNo": "9970456210",
    "email": "5cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "95.00000",
    "discussWithPerson": "Anagha",
    "expectedFees": 0.0475,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": ""
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.223172820820885",
  "longitude": "72.96218065092232"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.96218065092232,
    19.223172820820885
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "25/01/2024 03:27 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-26T18:58:10.374Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-27",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "15000",
  "lumpsumValue": "9500000",
  "rateMax": "17000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Majiwade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mahavir Millennium Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Next To Garden Enclaves, Vasant Vihar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
```



```
"key": "street2",
"value": "Pokhran Road No. 2",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "ISRA ",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "280/1(Part), 280/4(Part), 289/2(Part), 415(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "803",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 610",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
```

```
    "label": "Aluminium Open Windows",
    "value": "Aluminium_Open_Windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering+_POP_Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Dharm Veer Nagar Road ",
    "west": "Mission Dr. Marg ",
    "south": "Siddhanchal CHSL ",
    "east": "Garden Enclave "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
}
```

```
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be
assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "22.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "630",
  "depreciatedCostOfConstruction": "17370.00",
  "depreciatedBuildingRate": "2170"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "144500",
  "landRate": "56200",
  "igrImage": "cases/65b212190a3af9757a58db59/igr_1706338951124_Image.png",
  "squareMeterGuideLineRate": "151725.00",
  "squareFeetGuideLineRate": "14096.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "85",
  "rate": "12765.00",
  "squareFeetGuideLineRate": "12765.00",
  "squareMeterGuideLineRate": "137396.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
```

```
"label": "Yes",
"value": "Yes"
},
"carParking": "Stilt Car Parking Space ",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2009",
  "fullDate": "1/1/2009"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
```



```
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "15",
"flatFloorNo": "8",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "688.80",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65b212190a3af9757a58db59/
routeMap_1706347846503_Image.png",
    "routeLat": "19.223096",
    "routeLng": "72.962783",
    "stationName": "Thane ",
    "routeDistance": "7.7 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "jakp5",
      "name": "jakp5",
      "image": "cases/65b212190a3af9757a58db59/
routeMap_1706347681474_Image.png"
```

```
}
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "9970380.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "9970380.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Jan 27 2024 15:43:23 GMT+0530 (India Standard Time)",
  "number": "2304694",
  "dayCount": "7",
  "monthCount": "396",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8792532.00",
  "selectedBuildUpValue": "688.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b3ffc8f9cb492acff98fdb",
      "name": "externalImg_1706295218307_image.jpeg",
      "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295218307_image.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65b3ffc8f9cb492acff98fd3",
    "name": "Living Room",
    "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295194937_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b3ffc8f9cb492acff98fd7",
    "name": "Living Room",
    "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295204862_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b3ffc8f9cb492acff98fd6",
    "name": "Living Room",
    "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295202017_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b3ffc8f9cb492acff98fdd",
    "name": "Living Room",
    "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295225837_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b3ffc8f9cb492acff98fde",
    "name": "Living Room",
    "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295227937_image.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "65b3ffc8f9cb492acff98fd9",
      "name": "Living Room",
      "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295212812_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b3ffc8f9cb492acff98fdf",
      "name": "Living Room",
      "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295229132_image.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b3ffc8f9cb492acff98fdb",
      "name": "Living Room",
      "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295218307_image.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16199",
    "max": "23404"
  },
  "builtUpRateRange": {
    "min": "13499",
    "max": "19504"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "574.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65b212190a3af9757a58db59",
"ownerName": "Varsha Vasant Salunkhe, Pratik Vasant Salunkhe & Richa Ajit Padte",
"ownerPhoneNo": "9833655510",
"appAddress": "flat no. 803 . 8th floor isara Bldg mahavir millennium co. op housing
soc Ltd. vasant vihar village Majiwade thane",
"remark": "bamkar \nmadam. vanaja Dasi madam \nmobile. 9987462258",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "25/01/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Jagruti Manoj Thakker & Mr. Manoj Lalji Thakkar ",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Varsha Vasant Salunkhe, Pratik Vasant Salunkhe & Richa Ajit
Padte",
      "number": {
        "value": "No",
```

```
    "label": "No"
  },
  "No": "1088 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "168894",
"path": "cases/65b212190a3af9757a58db59/
document_1706168853185_25565.pdf",
"fileName": "document_1706168853185_25565.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/09/2009",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "2002 / 81 / TMC / TDD / 878"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1706344996718_document_1706168853185_25565.pdf",
"path": "cases/65b212190a3af9757a58db59/
document_1706344996718_document_1706168853185_25565.pdf",
"id": "891546",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Jan 27 2024 14:13:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006572",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "631130",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 25 2024 13:17:37 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Varsha Vasant Salunkhe, Pratik Vasant Salunkhe & Richa Ajit Padte",
    "phone": "9833655510",
    "ownershipShare": "",
    "email": "",
    "id": "840538"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "65b3fec3f9cb492acff98f82",
    "area": "590",
    "providedByName": "varsha Vasant salunke",
    "providedByContactNo": "9833655510"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "14.92",
    "width1": "14",
    "width2": "11",
    "totalArea": "145.44",
    "images": [],
    "extraAreas": [],
    "finalArea": "145.44"
  }
]
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "24.84",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "65b4c675f9cb492acffab108",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "11.08",
      "length1": "11",
      "length2": "1",
      "width": "2.92",
      "width1": "2",
      "width2": "11",
      "totalArea": "32.33"
    },
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "65b4c692f9cb492acffab11d",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "11.42",
      "length1": "11",
      "length2": "5",
      "width": "7.25",
      "width1": "7",
```

```
    "width2": "3",
    "totalArea": "82.77"
  }
],
"finalArea": "139.94"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "6.83",
  "width1": "6",
  "width2": "10",
  "totalArea": "66.06",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "_id": "65b4c77bf9cb492acffab4b2",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "4.42",
      "length1": "4",
      "length2": "5",
      "width": "7.50",
      "width1": "7",
      "width2": "6",
      "totalArea": "33.12"
    }
  ],
  "finalArea": "99.18"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "3",
"name": "Kitchen",
"length": "1.33",
"length1": "1",
"length2": "4",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "5.11",
"images": [],
"extraAreas": [],
"finalArea": "5.11"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "13.67",
  "width1": "13",
  "width2": "8",
  "totalArea": "91.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "91.11"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "12.42",
  "length1": "12",
  "length2": "5",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "40.35",
  "images": [],
```

```
"finalArea": "40.35",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "7.58",
  "width1": "7",
  "width2": "7",
  "totalArea": "27.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.17"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "32.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.35"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },

```



```
"name": {
  "label": "Flower Bed Area",
  "value": "Flower_Bed_Area"
},
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "0",
"length1": "1",
"length2": "7",
"length": "1.58",
"width1": "7",
"width2": "10",
"width": "7.83",
"totalArea": "12.40",
"percentageBeforeTotal": "12.40",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "12.4"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "53.33",
  "totalAreaDocument": "574",
  "docBultupPercentage": "20",
  "docFinalBultUp": "688.80",
  "docFinalBultUpSquareMeter": "63.99",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "754047"
}
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65b4aa97f9cb492acffa5ff8",
    "property": "Residential Flat",
    "area": "470",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "11000000",
    "expectedRate": "23404.26",
    "builtUpExpectedRate": "19503.55",
    "image": "cases/65b212190a3af9757a58db59/
indicator_1706338739651_Image.png",
    "squareMeter": "43.66",
    "id": "823786"
  },
  {
    "printlnReport": true,
    "_id": "65b4d54bf9cb492acffae327",
    "property": "Residential Flat",
    "area": "690",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "15000000",
    "expectedRate": "21739.13",
    "builtUpExpectedRate": "18115.94",
    "image": "cases/65b212190a3af9757a58db59/
indicator_1706338786147_Image.png",
    "squareMeter": "64.10",
    "id": "736613"
  },
  {
    "printlnReport": true,
    "_id": "65b4aa97f9cb492acffa5ffa",
    "property": "Residential Flat",
    "area": "463",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
```

```
"areaType": "Carpet",
"source": "Index_no.2",
"expectedPrice": "7500000",
"expectedRate": "16198.70",
"builtUpExpectedRate": "13498.92",
"image": "cases/65b212190a3af9757a58db59/
indicator_1706338817844_Image.png",
"squareMeter": "43.01",
"id": "504793"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b3ffc8f9cb492acff98fce",
"name": "externalimg_1706295182572_image.jpeg",
"path": "cases/65b212190a3af9757a58db59/
externalimg_1706295182572_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b3ffc8f9cb492acff98fcf",
"name": "externalimg_1706295184943_image.jpeg",
"path": "cases/65b212190a3af9757a58db59/
externalimg_1706295184943_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b3ffc8f9cb492acff98fd0",
"name": "externalimg_1706295188895_image.jpeg",
"path": "cases/65b212190a3af9757a58db59/
externalimg_1706295188895_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b3ffc8f9cb492acff98fd1",
"name": "externalimg_1706295191087_image.jpeg",
"path": "cases/65b212190a3af9757a58db59/
externalimg_1706295191087_image.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd2",
  "name": "externallmg_1706295194864_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295194864_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd3",
  "name": "externallmg_1706295194937_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295194937_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd4",
  "name": "externallmg_1706295196048_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295196048_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd5",
  "name": "externallmg_1706295201295_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295201295_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd6",
  "name": "externallmg_1706295202017_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externallmg_1706295202017_image.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd7",
  "name": "externalImg_1706295204862_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295204862_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd8",
  "name": "externalImg_1706295206832_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295206832_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fd9",
  "name": "externalImg_1706295212812_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295212812_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fda",
  "name": "externalImg_1706295215827_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295215827_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fdb",
  "name": "externalImg_1706295218307_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295218307_image.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fdc",
  "name": "externalImg_1706295224332_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295224332_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fdd",
  "name": "externalImg_1706295225837_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295225837_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fde",
  "name": "externalImg_1706295227937_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295227937_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b3ffc8f9cb492acff98fdf",
  "name": "externalImg_1706295229132_image.jpeg",
  "path": "cases/65b212190a3af9757a58db59/
externalImg_1706295229132_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Agreement for sale Final.docx",
    "filename": "1706348013190_Agreement_for_sale_Final.docx",
    "path": "cases/65b212190a3af9757a58db59/
processingDocuments/1706348013190_Agreement_for_sale_Final.docx",
    "size": "43833",
    "createdAt": "Sat Jan 27 2024 15:03:33 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "62fe044a48a26047e6552796"
},
{
  "originalname": "Calculation Sheet NEW.xlsx",
  "filename": "1706348013609_Calculation_Sheet_NEW.xlsx",
  "path": "cases/65b212190a3af9757a58db59/
processingDocuments/1706348013609_Calculation_Sheet_NEW.xlsx",
  "size": "2218515",
  "createdAt": "Sat Jan 27 2024 15:03:33 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-25T07:47:37.462Z",
"updatedAt": "2024-01-27T10:23:15.457Z",
"__v": 0,
"invoiceId": "65b212190a3af9757a58db62",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 803, 8th Floor, Wing - ISRA , Mahavir Millennium
Co-Op. Hsg. Soc. Ltd. , Next To Garden Enclaves, Vasant Vihar, Pokhran Road No. 2,
Village - Majiwade, Taluka - Thane , District - Thane , Thane (West), PIN - 400 610,
State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Pratik Vasant Salunkhe",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9833655510",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"carpetTotal": "580.65",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "12.40",
"siteVisitDate": "2024-01-26",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
```

```
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 574.00",
"flatRate": "18000",
"landOtherRate": "15200",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "652.35",
"finalCarpetArea": "593.05",
"finalSalableArea": "717.59",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 581.00\nFlower Bed Area in Sq.
Ft. = 12.00\n\n",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "12.40",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Jan 27 2024 12:45:17 GMT+0530 (India Standard Time)"
}
```


Name	Length	Width	Total
Composition :			
Living Room	9'9"	14'11"	145.44
Passage	4'1"	6'1"	24.84
Passage	9'8"	6'10"	66.06
Kitchen	1'4"	3'10"	5.11
Bedroom	6'8"	13'8"	91.11
Bedroom	12'5"	3'3"	40.35
Toilet	3'7"	7'7"	27.17
Toilet	2'10"	11'5"	32.35
Other Composition :			
Flower Bed Area	1'7"	7'10"	12.40