

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fb"
    },
    "type": "CREDITOFFICER",
    "_id": "64d1d9dad9f3034f301dcff",
    "firstName": "Prabhat Bhajbai",
    "lastName": "Bhajbai",
    "mobileNo": "",
    "workMobileNo": "9820021086",
    "email": "Prabhat@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "78.00000",
    "discussWithPerson": "Prabhat Bhajbai",
    "expectedFees": 0.039,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fb",
  "branchCode": "000068",
  "type": "BRANCH",
  "name": "RBO Sanpada",
  "email": "sme.navimum@sbi.co.in",
  "mobileNo": "022-27759215",
  "alternateMobileNo": "",
  "address": "SMEC VASHI, E/202, 2nd Floor, Sanpada Rly. Station Complex, Navi
Mumbai - 400 705, State - Maharashtra, Country - India.\n\n",
  "ledgerName": "STATE BANK OF INDIA - RBO SANPADA",
  "fax": "022-27752206",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Bhor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
```

```
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.03712736204217",
  "longitude": "73.09486941453896"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09486941453896,
    19.03712736204217
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-29",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-20",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Kalamboli (GES)",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "7",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Bhoomi Gardenia Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "17",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "601",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 410 218",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "CIDCO",
"label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Wing - B",
"west": "Roadpali Sports Ground",
"south": "Roadpali Park Ave Road",
"east": "Wing - F"
},
"asPerDocumentAgreement": {
"north": "Plot No. 5 & 6",
"west": "Plot No. 4",
"south": "Lay bye & 20.0 Mtrs. Wide Road",
"east": "Plot No. 9"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Occupancy Certificate Document No. CIDCO /
BP - 2889 / TPO (NM & K) / 2014 / 810 dated 21.08.2014 issued by CIDCO",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "15",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "14625",
"depreciatedBuildingRate": "2125"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "96200",
"landRate": "29300",
"igrImage": "cases/65b216e70a3af9757a58e5c1/igr_1706519525223_Image.png",
"squareMeterGuideLineRate": "101010.00",
"squareFeetGuideLineRate": "9384.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "90",
"rate": "8718.00",
"squareFeetGuideLineRate": "8718.00",
"squareMeterGuideLineRate": "93839.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "17,000/- Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
```

```
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Mr. Satyavan Jagdale",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2014",
```

```
"fullDate": "1/1/2014"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "50",
"ageOfBuilding": "10",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "1",
"noOfFloors": "14",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "696.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65b216e70a3af9757a58e5c1/
routeMap_1706520212720_Image.png",
    "routeLat": "19.037448",
    "routeLng": "73.094513",
    "stationName": "Mansarovar",
    "routeDistance": "3.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "a6ezfc",
      "name": "a6ezfc",
      "image": "cases/65b216e70a3af9757a58e5c1/
routeMap_1706520157146_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8482500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8482500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jan 29 2024 16:02:31 GMT+0530 (India Standard Time)",
  "number": "2304717",
  "dayCount": "14",
  "monthCount": "419",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6067728.00",
  "selectedBuildUpValue": "696.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b47a2ff9cb492acff99826",
      "name": "externallmg_1706326574705_IMG_20240126_49272.jpg",
      "path": "cases/65b216e70a3af9757a58e5c1/externallmg_1706326574705_IMG_20240126_49272.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65b47a4af9cb492acff99872",
      "name": "externallmg_1706326602156_IMG_20240126_49707.jpg",
      "path": "cases/65b216e70a3af9757a58e5c1/externallmg_1706326602156_IMG_20240126_49707.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65b47a4af9cb492acff99883",
```

```
    "name": "externallmg_1706326602192_IMG_20240126_57876.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602192_IMG_20240126_57876.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff9982a",
    "name": "externallmg_r_1706326574426_IMG20240126104232.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_r_1706326574426_IMG20240126104232.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff99822",
    "name": "externallmg_1706326574695_IMG_20240126_44192.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574695_IMG_20240126_44192.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff99819",
    "name": "externallmg_1706326574344_IMG_20240126_47725.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574344_IMG_20240126_47725.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff9981a",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574349_IMG_20240126_54766.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff9981e",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574689_IMG_20240126_539.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a2ff9cb492acff99821",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574693_IMG_20240126_5569.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff99874",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602160_IMG_20240126_50673.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff99878",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602169_IMG_20240126_52391.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff9987b",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602179_IMG_20240126_53560.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff9987e",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602183_IMG_20240126_55855.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff9987a",
    "name": "Living Room",
```

```
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602176_IMG_20240126_53303.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff9987f",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602187_IMG_20240126_56126.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b47a4af9cb492acff99881",
    "name": "Living Room",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602190_IMG_20240126_56835.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0",
    "max": "14946"
  },
  "builtUpRateRange": {
    "min": "0",
    "max": "12455"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "580.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65b216e70a3af9757a58e5c1",
"ownerName": "Mrs. Madhuri Vinod Havale & Mr. Vinod Vasant Havale",
"ownerPhoneNo": "9320195318",
"appAddress": "flat no. 601 . 6th floor. A wing Bhoomi Gardrnia co. op housing society
Ltd plot no. 7 . sector no. 17 kalmboli ",
"remark": "SSI Gokul Rahor \n8169938785",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "21/01/2024",
      "from": {
        "value": "The_Sellers",
        "label": "The Sellers"
      },
      "The_Sellers": "Mr. Rajesh M. Banka",
      "to": {
        "value": "The_Purchasers",
        "label": "The Purchasers"
      },
      "The_Purchasers": "Mrs. Madhuri Vinod Havale & Mr. Vinod Vasant Havale",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "1097/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
```

```
"id": "532024",
"path": "cases/65b216e70a3af9757a58e5c1/
document_1706169849757_1706169975603_1706167330517.pdf",
"fileName": "document_1706169849757_1706169975603_1706167330517.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2011",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "CIDCO / ATPO / 1128"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1706521784313_157885.pdf",
"path": "cases/65b216e70a3af9757a58e5c1/
document_1706521784313_157885.pdf",
"id": "716243",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Mon Jan 29 2024 15:19:44 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/08/2014",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
}
```

```
    "Document_No": "CIDCO / BP - 2889 / TPO (NM & K) / 2014 / 810"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706521860996_174913.pdf",
  "path": "cases/65b216e70a3af9757a58e5c1/
document_1706521860996_174913.pdf",
  "id": "926500",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Mon Jan 29 2024 15:21:01 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1257aa6d152c1801b335",
    "label": "Society Registration Certificate"
  },
  "inputs": {
    "documentDate": "07/02/2017",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "-"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706521924654_204232.pdf",
  "path": "cases/65b216e70a3af9757a58e5c1/
document_1706521924654_204232.pdf",
  "id": "532722",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Mon Jan 29 2024 15:22:04 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006575",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "119274",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 25 2024 13:38:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
```

```
"name": "Mrs. Madhuri Vinod Havale & Mr. Vinod Vasant Havale",
"phone": "9320195318",
"ownershipShare": "",
"email": "",
"id": "970501"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "714480",
  "name": "Living Room",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "16.33",
  "width1": "16",
  "width2": "4",
  "totalArea": "159.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "159.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "32.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.58"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "26.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "1.00",
  "length1": "1",
  "length2": "00",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "3.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "3.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
```

```
"width": "6.75",
"width1": "6",
"width2": "9",
"totalArea": "59.06",
"images": [],
"extraAreas": [],
"finalArea": "59.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "10.83",
  "length1": "10",
  "length2": "10",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "107.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "107.43"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "11.75",
  "length1": "11",
  "length2": "9",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "120.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.44"
},
{
  "measurementType": {
```



```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "20.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.78"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "24.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.69"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    }
  },
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "4",
  "length2": "10",
  "length": "4.83",
  "width1": "9",
  "width2": "6",
  "width": "9.50",
  "totalArea": "45.92",
  "percentageBeforeTotal": "45.92",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "45.92"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "7",
  "length": "2.58",
  "width1": "6",
  "width2": "8",
  "width": "6.67",
  "totalArea": "17.22",
  "percentageBeforeTotal": "17.22",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "17.22"
},
{
  "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "9",
  "length2": "9",
  "length": "9.75",
  "width1": "2",
  "width2": "7",
  "width": "2.58",
  "totalArea": "25.19",
  "percentageBeforeTotal": "25.19",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "25.19"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "6",
  "length2": "4",
  "length": "6.33",
  "width1": "2",
  "width2": "10",
  "width": "2.83",
  "totalArea": "17.94",
```

```
"percentageBeforeTotal": "17.94",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "17.94"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "53.88",
  "totalAreaDocument": "580",
  "docBultupPercentage": "20",
  "docFinalBultUp": "696.00",
  "docFinalBultUpSquareMeter": "64.66",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "538688"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65b76befe1e7bf61f3d1c0ef",
  "property": "Residential Flat",
  "area": "665",
  "bultUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "9500000",
  "expectedRate": "14285.71",
  "bultUpExpectedRate": "11904.76",
  "image": "cases/65b216e70a3af9757a58e5c1/
indicator_1706519122961_Image.png",
```

```
"squareMeter": "61.78",
"id": "379675"
},
{
  "printlnReport": true,
  "_id": "65b76befe1e7bf61f3d1c0f1",
  "property": "4900000",
  "area": "347",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "4900000",
  "expectedRate": "14121.04",
  "builtUpExpectedRate": "11767.53",
  "image": "cases/65b216e70a3af9757a58e5c1/
indicator_1706519403507_Image.jpeg",
  "squareMeter": "32.24",
  "id": "124843"
},
{
  "printlnReport": false,
  "_id": "65b76f8ee1e7bf61f3d1d070",
  "property": "Residential Flat",
  "area": "347",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4950000",
  "expectedRate": "14265.13",
  "builtUpExpectedRate": "11887.61",
  "image": "cases/65b216e70a3af9757a58e5c1/
indicator_1706520462473_Image.png",
  "squareMeter": "32.24",
  "id": "180019"
},
{
  "printlnReport": false,
  "_id": "65b77f81e1e7bf61f3d20c3a",
  "property": "Residential Flat",
  "area": "736",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "https://www.99acres.com/",
"expectedPrice": "11100000",
"expectedRate": "15081.52",
"builtUpExpectedRate": "12567.93",
"image": "cases/65b216e70a3af9757a58e5c1/
indicator_1706524545749_Image.png",
"squareMeter": "68.38",
"id": "367580"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b47a2ff9cb492acff99817",
"name": "externallmg_1706326574334_IMG_20240126_44773.jpg",
"path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574334_IMG_20240126_44773.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b47a2ff9cb492acff99818",
"name": "externallmg_1706326574338_IMG_20240126_46806.jpg",
"path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574338_IMG_20240126_46806.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b47a2ff9cb492acff99819",
"name": "externallmg_1706326574344_IMG_20240126_47725.jpg",
"path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574344_IMG_20240126_47725.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b47a2ff9cb492acff9981a",
"name": "externallmg_1706326574349_IMG_20240126_54766.jpg",
"path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574349_IMG_20240126_54766.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9981b",
  "name": "externallmg_1706326574354_IMG_20240126_59166.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574354_IMG_20240126_59166.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9981c",
  "name": "externallmg_1706326574357_IMG_20240126_110432.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574357_IMG_20240126_110432.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9981d",
  "name": "externallmg_1706326574662_Screenshot_2024012610431640_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/externallmg_1706326574662_Screens
hot_2024012610431640_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9981e",
  "name": "externallmg_1706326574689_IMG_20240126_539.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574689_IMG_20240126_539.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9981f",
  "name": "externallmg_1706326574690_IMG_20240126_5184.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574690_IMG_20240126_5184.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff99820",
  "name": "externallmg_1706326574691_IMG_20240126_5480.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574691_IMG_20240126_5480.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff99821",
  "name": "externallmg_1706326574693_IMG_20240126_5569.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574693_IMG_20240126_5569.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff99822",
  "name": "externallmg_1706326574695_IMG_20240126_44192.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574695_IMG_20240126_44192.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff99823",
  "name": "externallmg_1706326574698_IMG_20240126_46216.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574698_IMG_20240126_46216.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff99824",
  "name": "externallmg_1706326574700_IMG_20240126_48489.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574700_IMG_20240126_48489.jpg",
  "orientation": "landscape"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a2ff9cb492acff99825",
    "name": "externallmg_1706326574703_IMG_20240126_48940.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574703_IMG_20240126_48940.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a2ff9cb492acff99826",
    "name": "externallmg_1706326574705_IMG_20240126_49272.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326574705_IMG_20240126_49272.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a2ff9cb492acff99827",
    "name": "externallmg_r_1706326574390_IMG20240126104226.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_r_1706326574390_IMG20240126104226.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a2ff9cb492acff99828",
    "name": "externallmg_r_1706326574591_IMG20240126162339.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_r_1706326574591_IMG20240126162339.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a2ff9cb492acff99829",
    "name": "externallmg_r_1706326574509_IMG20240126162335.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_r_1706326574509_IMG20240126162335.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a2ff9cb492acff9982a",
  "name": "externallmg_r_1706326574426_IMG20240126104232.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_r_1706326574426_IMG20240126104232.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff99872",
  "name": "externallmg_1706326602156_IMG_20240126_49707.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602156_IMG_20240126_49707.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff99873",
  "name": "externallmg_1706326602159_IMG_20240126_50168.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602159_IMG_20240126_50168.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff99874",
  "name": "externallmg_1706326602160_IMG_20240126_50673.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602160_IMG_20240126_50673.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff99875",
  "name": "externallmg_1706326602163_IMG_20240126_51443.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602163_IMG_20240126_51443.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99876",
    "name": "externallmg_1706326602165_IMG_20240126_51827.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602165_IMG_20240126_51827.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99877",
    "name": "externallmg_1706326602167_IMG_20240126_52117.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602167_IMG_20240126_52117.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99878",
    "name": "externallmg_1706326602169_IMG_20240126_52391.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602169_IMG_20240126_52391.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99879",
    "name": "externallmg_1706326602175_IMG_20240126_52658.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602175_IMG_20240126_52658.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff9987a",
    "name": "externallmg_1706326602176_IMG_20240126_53303.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602176_IMG_20240126_53303.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65b47a4af9cb492acff9987b",
  "name": "externallmg_1706326602179_IMG_20240126_53560.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602179_IMG_20240126_53560.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff9987c",
  "name": "externallmg_1706326602180_IMG_20240126_54408.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602180_IMG_20240126_54408.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff9987d",
  "name": "externallmg_1706326602181_IMG_20240126_55479.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602181_IMG_20240126_55479.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff9987e",
  "name": "externallmg_1706326602183_IMG_20240126_55855.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602183_IMG_20240126_55855.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b47a4af9cb492acff9987f",
  "name": "externallmg_1706326602187_IMG_20240126_56126.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602187_IMG_20240126_56126.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65b47a4af9cb492acff99880",
    "name": "externallmg_1706326602188_IMG_20240126_56436.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602188_IMG_20240126_56436.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99881",
    "name": "externallmg_1706326602190_IMG_20240126_56835.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602190_IMG_20240126_56835.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99882",
    "name": "externallmg_1706326602191_IMG_20240126_57323.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602191_IMG_20240126_57323.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99883",
    "name": "externallmg_1706326602192_IMG_20240126_57876.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602192_IMG_20240126_57876.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99884",
    "name": "externallmg_1706326602195_IMG_20240126_58289.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externallmg_1706326602195_IMG_20240126_58289.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a4af9cb492acff99885",
```

```
    "name": "externalImg_1706326602198_IMG_20240126_58631.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externalImg_1706326602198_IMG_20240126_58631.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b47a53f9cb492acff998bb",
    "name": "externalImg_1706326611530_IMG_20240126_59511.jpg",
    "path": "cases/65b216e70a3af9757a58e5c1/
externalImg_1706326611530_IMG_20240126_59511.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "A 601 Floor plan.pdf",
    "filename": "1706519549157_A_601_Floor_plan.pdf",
    "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549157_A_601_Floor_plan.pdf",
    "size": "342897",
    "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "A- 601 Typical Plan.pdf",
    "filename": "1706519549165_A_601_Typical_Plan.pdf",
    "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549165_A_601_Typical_Plan.pdf",
    "size": "206910",
    "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR.pdf",
    "filename": "1706519549171_AGR.pdf",
    "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549171_AGR.pdf",
    "size": "31992662",
    "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externalImg_1706326574662_Screenshot_2024012610431640_3d
```

```
9111e2d3171bf4882369f490c087b4.jpg",
  "filename": "1706519549823_externallmg_1706326574662_Screenshot_202401261
0431640_3d9111e2d3171bf4882369f490c087b4.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/processingDocuments/1706519549823
_externallmg_1706326574662_Screenshot_2024012610431640_3d9111e2d3171bf488
2369f490c087b4.jpg",
  "size": "1198792",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1706326574509_IMG20240126162335.jpg",
  "filename":
"1706519549847_externallmg_r_1706326574509_IMG20240126162335.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/processingDocuments/1706519549847
_externallmg_r_1706326574509_IMG20240126162335.jpg",
  "size": "1666467",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "externallmg_r_1706326574591_IMG20240126162339.jpg",
  "filename":
"1706519549892_externallmg_r_1706326574591_IMG20240126162339.jpg",
  "path": "cases/65b216e70a3af9757a58e5c1/processingDocuments/1706519549892
_externallmg_r_1706326574591_IMG20240126162339.jpg",
  "size": "1362840",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1706519549925_IGR01.pdf",
  "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549925_IGR01.pdf",
  "size": "163201",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1706519549931_IGR02.pdf",
  "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549931_IGR02.pdf",
  "size": "159382",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1706519549935_IGR03.pdf",
  "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549935_IGR03.pdf",
  "size": "157001",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=MADHURI.xlsx",
  "filename": "1706519549940_Summary_NewMADHURI.xlsx",
  "path": "cases/65b216e70a3af9757a58e5c1/
processingDocuments/1706519549940_Summary_NewMADHURI.xlsx",
  "size": "2279397",
  "createdAt": "Mon Jan 29 2024 14:42:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65b4be5ff9cb492acffa9f20",
    "note": "Required approved plan.",
    "taskId": "65b22de6e589274e62e05f43",
    "createdAt": "2024-01-27T08:27:11.099Z"
  }
],
"createdAt": "2024-01-25T08:08:07.720Z",
"updatedAt": "2024-01-29T10:39:10.992Z",
"__v": 0,
"invoiceId": "65b216e70a3af9757a58e5c7",
```



```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 601, 6th Floor, Wing - A, Bhoomi Gardenia Co-op.
Hsg. Soc. Ltd., Plot No. 7, Sector 17, Village - Kalamboli (GES), Taluka - Panvel, District
- Raigad, Navi Mumbai, PIN Code - 410 218, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Ankit Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Agent's Office Staff",
"siteVisitContactNo": "9372798776",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 580.00",
"flatRate": "15000",
"landOtherRate": "12500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": ""
  }
}
```

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Passage + 2 Toilet",
"carpetTotal": "554.06",
"otherCarpetTotal": "106.27",
"builtupPercentage": "20",
"finalBuiltupArea": "792.40",
"finalCarpetArea": "660.33",
"finalSalableArea": "871.64",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "106.27",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 554.00\nBalcony Area in Sq. Ft.
= 106.00\nTotal Carpet Area in Sq. Ft. = 660.00\n(Area as per Actual Site
Measurement)",
"reportGeneratedDate": "Mon Jan 29 2024 14:48:10 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-20"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'9"	16'4"	159.25
Passage	8'6"	3'10"	32.58
Passage	3'00"	8'9"	26.25
Passage	1'00"	3'7"	3.58
Kitchen	8'9"	6'9"	59.06
Bedroom	10'10"	9'11"	107.43
Bedroom	11'9"	10'3"	120.44
Toilet	5'8"	3'8"	20.78

Toilet	3'9"	6'7"	24.69
<hr/>			
Other Composition :			
<hr/>			
Balcony Area	4'10"	9'6"	45.92
<hr/>			
Balcony Area	2'7"	6'8"	17.22
<hr/>			
Balcony Area	9'9"	2'7"	25.19
<hr/>			
Balcony Area	6'4"	2'10"	17.94
<hr/>			