

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "1sbi.14677@sbi.co.in",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "54.00000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 0.027,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
  "lastName": "Acharya",
  "mobileNo": "9867664219",
```

```

    "designation": "",
    "shortName": "JA",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      "title": {

```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.002621292377434",
  "longitude": "73.12359076626213"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.12359076626213,
    19.002621292377434
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "27/01/2024 04:03 pm"
    },
    {
      "dateTime": "27/01/2024 12:00 am"
    },
    {
      "dateTime": "27/01/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-27",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-27",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "New Panvael",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "36 to 39, 128 & 129",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hrishikesh Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "10",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Hrishikesh Apartment",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "01",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "New Panvel (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "label": "Ceramic Tile Flooring",
    "value": "CeramicTileFlooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Meera Kunj CHSL / Murari Ekta CHSL",
    "south": "Road / Shree Ganesh Vinayak Building",
    "east": "Road No. 8 "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "C WING",
      "west": "STAIRCAS",
```

```
    "south": "R NO2",
    "east": "BUILDING"
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"compositeRate": {
  "remark": "As per actual site measurement, the Carpet area is 436.00 Sq. Ft. and
Built-up area mentioned in the agreement is 625.00 Sq. Ft. The loading on carpet to
built-up is 43%, hence, we have adjusted the rate accordingly.",
  "depreciationPercentage": "33",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9375",
  "depreciatedBuildingRate": "1675"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "95900",
  "landRate": "43900",
  "igrImage": "cases/65b4c35ef9cb492acffaa9a1/igr_1706524243157_Image.png",
  "squareMeterGuideLineRate": "95900.00",
  "squareFeetGuideLineRate": "8909.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "78",
  "rate": "7847.00",
  "squareFeetGuideLineRate": "7847.00",
  "squareMeterGuideLineRate": "84460.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
```

```
"label": "Middle Class"
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "label": "Tenant Occupied",
  "value": "Tenant_Occupied"
},
"monthlyRent": "12,000 (Expected rental income per month)",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  }
},
```

```
"carParking": "Open Parking Space",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2002",
  "fullDate": "1/1/2002"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
}
```

```
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "0",
  "label": "No"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "38",
"ageOfBuilding": "22",
"noOfBasement": "0",
```



```
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "2",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "625.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65b4c35ef9cb492acffaa9a1/
routeMap_1706505759445_Image.png",
    "routeLat": "19.002722",
    "routeLng": "73.123500",
    "stationName": "Panvel Junction",
    "routeDistance": "1.9 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "cbo4rl",
      "name": "cbo4rl",
      "image": "cases/65b4c35ef9cb492acffaa9a1/
routeMap_1706505461995_Image.png"
    }
  ]
},
```

```
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5859375.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "5859375.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jan 29 2024 17:08:25 GMT+0530 (India Standard Time)",
  "number": "2304720",
  "dayCount": "17",
  "monthCount": "422",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4904375.00",
  "selectedBuildUpValue": "625.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b72a49e1e7bf61f3d0dd31",
      "name":
"externalmg_1706502729639_WhatsApp_Image_20240129_at_095800.jpeg",
      "path": "cases/65b4c35ef9cb492acffaa9a1/
externalmg_1706502729639_WhatsApp_Image_20240129_at_095800.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "65b72a3fe1e7bf61f3d0dce0",
    "name":
"externallmg_1706502719718_WhatsApp_Image_20240129_at_095804_3.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502719718_WhatsApp_Image_20240129_at_095804_3.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd2e",
    "name":
"externallmg_1706502729618_WhatsApp_Image_20240129_at_095800_1.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729618_WhatsApp_Image_20240129_at_095800_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd36",
    "name": "Living Room",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729661_WhatsApp_Image_20240129_at_095802_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd37",
    "name": "Living Room",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729663_WhatsApp_Image_20240129_at_095802_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd3b",
    "name": "Living Room",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729673_WhatsApp_Image_20240129_at_095803_3.jpeg",
```

```
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9167",
    "max": "14643"
  },
  "builtUpRateRange": {
    "min": "8334",
    "max": "12203"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "625.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65b4c35ef9cb492acffaa9a1",
"ownerName": "Mr. Anand Nana Birare",
"ownerPhoneNo": "8879921889",
"appAddress": "flat no. c 001 Ground floor Hrishikesh chs Ltd plot no. 36.37..38
```

```
sector no. 10 New panvel ",
"remark": "ssl pawan sir 8928874274",
"documents": [
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "16/01/2024",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mr. Rakesh Ranjan Poddar",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Anand Nana Birare & Mrs. Anita Nana Birare",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "1005-2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "203050",
  "path": "cases/65b4c35ef9cb492acffaa9a1/document_1706345253538_1706345380701_Hrishikesh_C001_Agreement_For_Sale.pdf",
  "fileName": "document_1706345253538_1706345380701_Hrishikesh_C001_Agreement_For_Sale.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "06/12/2000",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_Ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "EE (BP) / ATPO / 2809"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1706509583725_CC.pdf",
"path": "cases/65b4c35ef9cb492acffaa9a1/document_1706509583725_CC.pdf",
"id": "776314",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Jan 29 2024 11:56:23 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "14/02/2002",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra ltd."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "EE (BP) / ATPO / 1178 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1706509643314_OC.pdf",
"path": "cases/65b4c35ef9cb492acffaa9a1/document_1706509643314_OC.pdf",
"id": "675928",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Mon Jan 29 2024 11:57:23 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006600",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "138687",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
"datetime": "Sat Jan 27 2024 14:18:30 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mr. Anand Nana Birare",
    "phone": "8879921889",
    "ownershipShare": "",
    "email": "",
    "id": "257817"
  },
  {
    "name": "Mrs. Anita Nana Birare",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "255492"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "341338",
    "name": "Living Room",
    "length": "9.92",
    "length1": "9",
    "length2": "11",
    "width": "13.75",
    "width1": "13",
    "width2": "9",
    "totalArea": "136.35",
    "images": [],
    "extraAreas": [],
    "finalArea": "136.35"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Passage",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "2.92",
"width1": "2",
"width2": "11",
"totalArea": "29.17",
"images": [],
"extraAreas": [],
"finalArea": "29.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "83.85",
  "images": [],
  "extraAreas": [],
  "finalArea": "83.85"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "52.22",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "52.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "97.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "97.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "12.00",
  "images": [],
  "finalArea": "12.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "6.92",
```

```
"length1": "6",
"length2": "11",
"width": "3.58",
"width1": "3",
"width2": "7",
"totalArea": "24.78",
"images": [],
"extraAreas": [],
"finalArea": "24.78"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Built_Up",
  "squareMeterArea": "58.06",
  "totalAreaDocument": "625",
  "docBuiltpupPercentage": "",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "975144"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65b77e59e1e7bf61f3d205b0",
  "property": "Residential Flat",
  "area": "550",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "7500000",
"expectedRate": "13636.36",
"builtUpExpectedRate": "11363.64",
"image": "cases/65b4c35ef9cb492acffaa9a1/indicator_1706524105751_Image.png",
"squareMeter": "51.10",
"id": "965924"
},
{
  "printlnReport": true,
  "_id": "65b77e59e1e7bf61f3d205b1",
  "property": "Residential Flat",
  "area": "630",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "8500000",
  "expectedRate": "13492.06",
  "builtUpExpectedRate": "11243.39",
  "image": "cases/65b4c35ef9cb492acffaa9a1/indicator_1706524131453_Image.png",
  "squareMeter": "58.53",
  "id": "645518"
},
{
  "printlnReport": true,
  "_id": "65b77e59e1e7bf61f3d205b2",
  "property": "Residential Flat",
  "area": "600",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "source": "Nobroker.com",
  "expectedPrice": "5000000",
  "expectedRate": "8333.33",
  "builtUpExpectedRate": "5000000",
  "image": "cases/65b4c35ef9cb492acffaa9a1/indicator_1706524159133_Image.png",
  "squareMeter": "55.74",
  "id": "513300"
},
{
  "printlnReport": true,
  "_id": "65b77e59e1e7bf61f3d205b3",
  "property": "Residential Flat",
```



```
"area": "560",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "Housing.Com",
"expectedPrice": "8200000",
"expectedRate": "14642.86",
"builtUpExpectedRate": "12202.38",
"image": "cases/65b4c35ef9cb492acffaa9a1/indicator_1706524176721_Image.png",
"squareMeter": "52.03",
"id": "662847"
}
],
"externallImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b72a3fe1e7bf61f3d0dce0",
"name":
"externallmg_1706502719718_WhatsApp_Image_20240129_at_095804_3.jpeg",
"path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502719718_WhatsApp_Image_20240129_at_095804_3.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b72a3fe1e7bf61f3d0dce1",
"name":
"externallmg_1706502719723_WhatsApp_Image_20240129_at_095759_1.jpeg",
"path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502719723_WhatsApp_Image_20240129_at_095759_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65b72a49e1e7bf61f3d0dd2d",
"name":
"externallmg_1706502729613_WhatsApp_Image_20240129_at_095759.jpeg",
"path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729613_WhatsApp_Image_20240129_at_095759.jpeg",
"orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd2e",
    "name":
"externallmg_1706502729618_WhatsApp_Image_20240129_at_095800_1.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729618_WhatsApp_Image_20240129_at_095800_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd2f",
    "name":
"externallmg_1706502729628_WhatsApp_Image_20240129_at_095800_2.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729628_WhatsApp_Image_20240129_at_095800_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd30",
    "name":
"externallmg_1706502729634_WhatsApp_Image_20240129_at_095800_3.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729634_WhatsApp_Image_20240129_at_095800_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd31",
    "name":
"externallmg_1706502729639_WhatsApp_Image_20240129_at_095800.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729639_WhatsApp_Image_20240129_at_095800.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd32",
    "name":
"externallmg_1706502729645_WhatsApp_Image_20240129_at_095801_1.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729645_WhatsApp_Image_20240129_at_095801_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd33",
    "name":
"externallmg_1706502729649_WhatsApp_Image_20240129_at_095801_2.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729649_WhatsApp_Image_20240129_at_095801_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd34",
    "name":
"externallmg_1706502729653_WhatsApp_Image_20240129_at_095801.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729653_WhatsApp_Image_20240129_at_095801.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd35",
    "name":
"externallmg_1706502729657_WhatsApp_Image_20240129_at_095802_1.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729657_WhatsApp_Image_20240129_at_095802_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd36",
    "name":
"externallmg_1706502729661_WhatsApp_Image_20240129_at_095802_2.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729661_WhatsApp_Image_20240129_at_095802_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b72a49e1e7bf61f3d0dd37",
```

```
    "name":
"externallmg_1706502729663_WhatsApp_Image_20240129_at_095802_3.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729663_WhatsApp_Image_20240129_at_095802_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd38",
  "name":
"externallmg_1706502729666_WhatsApp_Image_20240129_at_095802.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729666_WhatsApp_Image_20240129_at_095802.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd39",
  "name":
"externallmg_1706502729669_WhatsApp_Image_20240129_at_095803_1.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729669_WhatsApp_Image_20240129_at_095803_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3a",
  "name":
"externallmg_1706502729671_WhatsApp_Image_20240129_at_095803_2.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729671_WhatsApp_Image_20240129_at_095803_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3b",
  "name":
"externallmg_1706502729673_WhatsApp_Image_20240129_at_095803_3.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729673_WhatsApp_Image_20240129_at_095803_3.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3c",
  "name":
"externallmg_1706502729675_WhatsApp_Image_20240129_at_095803.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729675_WhatsApp_Image_20240129_at_095803.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3d",
  "name":
"externallmg_1706502729678_WhatsApp_Image_20240129_at_095804_1.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729678_WhatsApp_Image_20240129_at_095804_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3e",
  "name":
"externallmg_1706502729680_WhatsApp_Image_20240129_at_095804_2.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729680_WhatsApp_Image_20240129_at_095804_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a49e1e7bf61f3d0dd3f",
  "name":
"externallmg_1706502729682_WhatsApp_Image_20240129_at_095804.jpeg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502729682_WhatsApp_Image_20240129_at_095804.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b72a65e1e7bf61f3d0dd70",
  "name": "externallmg_1706502757708_Screenshot_20240129_084807.jpg",
  "path": "cases/65b4c35ef9cb492acffaa9a1/
externallmg_1706502757708_Screenshot_20240129_084807.jpg",
```

```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1706524259313_AGR.pdf",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
processingDocuments/1706524259313_AGR.pdf",
    "size": "10231356",
    "createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1706524259538_CC.pdf",
    "path": "cases/65b4c35ef9cb492acffaa9a1/
processingDocuments/1706524259538_CC.pdf",
    "size": "487154",
    "createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1706502729657_WhatsApp_Image_20240129_at_095802_1.jpeg",
    "filename": "1706524259548_externallmg_1706502729657_WhatsApp_Image_202
40129_at_095802_1.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/processingDocuments/1706524259548_
externallmg_1706502729657_WhatsApp_Image_20240129_at_095802_1.jpeg",
    "size": "157941",
    "createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1706502729666_WhatsApp_Image_20240129_at_095802.jpeg",
    "filename": "1706524259551_externallmg_1706502729666_WhatsApp_Image_202
40129_at_095802.jpeg",
    "path": "cases/65b4c35ef9cb492acffaa9a1/processingDocuments/1706524259551_
externallmg_1706502729666_WhatsApp_Image_20240129_at_095802.jpeg",
    "size": "152593",
    "createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {

```

```
"originalname": "externallmg_1706502757708_Screenshot_20240129_084807.jpg",
"filename":
"1706524259554_externallmg_1706502757708_Screenshot_20240129_084807.jpg",
"path": "cases/65b4c35ef9cb492acffaa9a1/processingDocuments/1706524259554_
externallmg_1706502757708_Screenshot_20240129_084807.jpg",
"size": "1193865",
"createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "OC.pdf",
"filename": "1706524259584_OC.pdf",
"path": "cases/65b4c35ef9cb492acffaa9a1/
processingDocuments/1706524259584_OC.pdf",
"size": "362352",
"createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=ANAND.xlsx",
"filename": "1706524259590_Summary_NewANAND.xlsx",
"path": "cases/65b4c35ef9cb492acffaa9a1/
processingDocuments/1706524259590_Summary_NewANAND.xlsx",
"size": "2959137",
"createdAt": "Mon Jan 29 2024 16:00:59 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-27T08:48:30.701Z",
"updatedAt": "2024-01-29T11:45:47.961Z",
"__v": 0,
"invoiceId": "65b4c35ef9cb492acffaa9aa",
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 01, Ground Floor, Wing - C, Hrishikesh Co-op. Hsg.
Soc. Ltd., Hrishikesh Apartment, Plot No. 36 to 39, 128 & 129, Sector 10, Village - New
Panvel, New Panvel (East), Taluka - Panvel, District - Raigad, PIN - 410 206, State -
Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
```

```
"contactPersonName": "Mr. Anand Nana Birare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "8879921889",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "435.74",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 625.00",
"builtupPercentage": "10",
"finalBuiltupArea": "479.31",
"finalCarpetArea": "435.74",
"finalSalableArea": "527.25",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Mon Jan 29 2024 10:24:51 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-27",
"buildingServicesRate": "2500",
"flatRate": "10200",
"landOtherRate": "7700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
```



```

    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	9'11"	13'9"	136.35
Passage	10'00"	2'11"	29.17
Bedroom	8'9"	9'7"	83.85
Kitchen	7'10"	6'8"	52.22
Bedroom	10'3"	9'6"	97.37
Toilet	3'0"	4'0"	12.00
Toilet	6'11"	3'7"	24.78
Other Composition :			