

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
}
```

```

"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {

```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.193463848827854",
  "longitude": "72.95229247821014"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.95229247821014,
19.193463848827854
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-30",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-30",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Panchpakhadi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Thane",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "D",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aashiyana",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "62 B/2 & 131 B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "906",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 606",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ten X - Under Construction Building",
    "west": "Pipeline & Road",
    "south": "Open Plot",
    "east": "Raymond Ten X"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
```

```
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per Approved Plan, the composition of flat is 1 Bedroom
+ Living Room + Kitchen + 1 Toilet.",
"dateOfIssusApprovePlan": " Copy of Approved Building Plan Document No. V.P. No.
S04 / 0016 /09 - TMC / TD - DP / 3746 / 21 Dated 03.11.2021 issued by Thane
Municipal Corporation",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal Site Inspection,
Measurement & Internal Photographs of the property. Details about the work progress
status has been provided by Customer Relationship Manager - Ms. Pranali (Contact No.
022 - 68685500)",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "124100",
  "landRate": "52100",
  "igrImage": "cases/65b79b1be1e7bf61f3d28e8f/igr_1706592951349_Image.png",
  "squareMeterGuideLineRate": "130305.00",
  "squareFeetGuideLineRate": "12106.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "124100.00",
  "squareMeterGuideLineRate": "130305.00",
  "squareFeetGuideLineRate": "12106.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
```

```
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"monthlyRent": "24,000/- Expected rental income per month after completion",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
```

```
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
}
```

```
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "9",
```



```
"noOfLifts": "5",
"noOfDwellingUnitsInBuilding": "14"
},
"finalPlinthArea": {
  "area": "354.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65b79b1be1e7bf61f3d28e8f/
routeMap_1706690716730_Image.png",
    "routeLat": "19.212880",
    "routeLng": "72.965322",
    "stationName": "Thane",
    "routeDistance": "4.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "891fs",
      "name": "891fs",
      "image": "cases/65b79b1be1e7bf61f3d28e8f/
routeMap_1706690625864_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```

```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9660000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "9660000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
```

```
"label": "RCC Plinth",
"floorsCompleted": "Complete",
"percentage": "5",
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "24",
"percentage": "40",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "24",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "24",
"percentage": "7.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "24",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "24",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"door": {
"label": "Door",
"floorsCompleted": "24",
"percentage": "2.50",
"isHideFloor": false,
```

```
"status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "24",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "24",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "24",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "24",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "24",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "5",
  "percentage": "2.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "96.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4287945.00",
  "selectedBuildUpValue": "354.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b8ff846635d840ef558878",
      "name": "externalimg_r_1706622834815_1706622958953_image_1.jpg",
      "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalimg_r_1706622834815_1706622958953_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65b8ff846635d840ef558879",
      "name": "externalimg_r_1706622841262_1706622958953_image_3.jpg",
      "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalimg_r_1706622841262_1706622958953_image_3.jpg",
      "orientation": "landscape"
    }
  ]
},
],
```

```
"externalPhotos": [
  {
    "status": false,
    "_id": "65b8ff846635d840ef55887a",
    "name": "externalmg_r_1706622827598_1706622958953_image_0.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalmg_r_1706622827598_1706622958953_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b8ff846635d840ef55887c",
    "name": "externalmg_r_1706622846506_1706622958953_image_4.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalmg_r_1706622846506_1706622958953_image_4.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "31988",
    "max": "32609"
  },
  "builtUpRateRange": {
    "min": "29080",
    "max": "29645"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```



```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "322.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65b79b1be1e7bf61f3d28e8f",
"ownerName": "Mr. Nitesh Amar Mhatre & Mrs. Tejasvi Nitesh Mhatre",
"ownerPhoneNo": "7276813714",
"appAddress": "Flat no. 906, 9th Floor, Wing - A, Aashiyana Project, Village -
Panchpakhadi, Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "28/12/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Raymond Limited",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Nitesh Amar Mhatre & Mrs. Tejasvi Nitesh Mhatre",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "32033/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
```

```
"id": "113539",
"path": "cases/65b79b1be1e7bf61f3d28e8f/
document_1706531594717_1706531726257_Racpc_GHatkopar_Nitesh_Mhatre.pdf",
"fileName":
"document_1706531594717_1706531726257_Racpc_GHatkopar_Nitesh_Mhatre.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "06/06/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51700045709"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1706692757004_P51700045709.pdf",
  "path": "cases/65b79b1be1e7bf61f3d28e8f/
document_1706692757004_P51700045709.pdf",
  "id": "931197",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Jan 31 2024 14:49:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "V.P. No. S04 / 0016 /09 - TMC / TDD / 3746 / 21"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "103781",
  "path": "cases/65b79b1be1e7bf61f3d28e8f/document_1706692785726_cc.pdf",
  "fileName": "document_1706692785726_cc.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "13/11/2021",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "V.P. No. S04 / 0016 /09 - TMC / TD - DP / 3746 / 21"
},
  "isHardCopy": false,
  "displayStatus": true,
  "id": "439887",
  "path": "cases/65b79b1be1e7bf61f3d28e8f/document_1706692813092_plan1.pdf",
  "fileName": "document_1706692813092_plan1.pdf"
},
{
  "documentType": {
    "value": "60ae1272aa6d152c1801b3b4",
    "label": "MHADA Offer Letter"
  },
  "inputs": {
    "documentDate": "20/07/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "remark": "in the name of Nitesh Amar Mhatre",
    "number": {
      "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "N.A."
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1706693375065_122303.pdf",
"path": "cases/65b79b1be1e7bf61f3d28e8f/
document_1706693375065_122303.pdf",
"id": "290610",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Wed Jan 31 2024 14:59:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006622",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "927041",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jan 29 2024 18:03:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Nitesh Amar Mhatre & Mrs. Tejasvi Nitesh Mhatre",
    "phone": "7276813714",
    "ownershipShare": "",
    "email": "",
    "id": "103376"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "29.91",
  "totalAreaDocument": "322",
  "docBuiltupPercentage": "10",
  "docFinalBuiltUp": "354.20",
  "docFinalBuiltUpSquareMeter": "32.91",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "293136"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65b88ad695b2d34ce374c722",
    "property": "Raymond Ashiyana, Thane West",
    "area": "322",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "square_yards",
    "expectedPrice": "10300000",
    "expectedRate": "31987.58",
    "builtUpExpectedRate": "29079.62",
    "image": "cases/65b79b1be1e7bf61f3d28e8f/
indicator_1706592539654_Image.png",
    "squareMeter": "29.91",
    "id": "506084"
  },
  {
    "printlnReport": true,
    "_id": "65b88ad695b2d34ce374c723",
    "property": "Raymond Ashiyana, Thane West",
    "area": "322",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Property._Waa_2",
```

```
    "expectedPrice": "10500000",
    "expectedRate": "32608.70",
    "builtUpExpectedRate": "29644.27",
    "image": "cases/65b79b1be1e7bf61f3d28e8f/
indicator_1706592632004_Image.png",
    "squareMeter": "29.91",
    "id": "130434"
  },
  {
    "printlnReport": true,
    "_id": "65b88ad695b2d34ce374c724",
    "property": "Raymond Ashiyana, Thane West",
    "area": "322",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "https://www.Propertyipistol.com/",
    "expectedPrice": "10500000",
    "expectedRate": "32608.70",
    "builtUpExpectedRate": "29644.27",
    "image": "cases/65b79b1be1e7bf61f3d28e8f/
indicator_1706592740649_Image.png",
    "squareMeter": "29.91",
    "id": "975899"
  },
  {
    "printlnReport": true,
    "_id": "65b88ad695b2d34ce374c725",
    "property": "Raymond Ashiyana, Thane West",
    "area": "322",
    "builtUpPercentage": "10",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Middle",
    "source": "Housing.Com",
    "expectedPrice": "10500000",
    "expectedRate": "32608.70",
    "builtUpExpectedRate": "29644.27",
    "image": "cases/65b79b1be1e7bf61f3d28e8f/
indicator_1706592791493_Image.png",
    "squareMeter": "29.91",
    "id": "115974"
  }
}
```

```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b8ff846635d840ef558878",
    "name": "externallmg_r_1706622834815_1706622958953_image_1.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externallmg_r_1706622834815_1706622958953_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b8ff846635d840ef558879",
    "name": "externallmg_r_1706622841262_1706622958953_image_3.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externallmg_r_1706622841262_1706622958953_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b8ff846635d840ef55887a",
    "name": "externallmg_r_1706622827598_1706622958953_image_0.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externallmg_r_1706622827598_1706622958953_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b8ff846635d840ef55887b",
    "name": "externallmg_r_1706622837751_1706622958953_image_2.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externallmg_r_1706622837751_1706622958953_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b8ff846635d840ef55887c",
    "name": "externallmg_r_1706622846506_1706622958953_image_4.jpg",
    "path": "cases/65b79b1be1e7bf61f3d28e8f/
externallmg_r_1706622846506_1706622958953_image_4.jpg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65b8ff626635d840ef558869",
      "name": "externalImg_r_1706622811446_1706622944649_image_0.png",
      "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalImg_r_1706622811446_1706622944649_image_0.png",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65b8ff626635d840ef55886a",
      "name": "externalImg_r_1706622811650_1706622944649_image_1.jpg",
      "path": "cases/65b79b1be1e7bf61f3d28e8f/
externalImg_r_1706622811650_1706622944649_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "Calculation.xlsx",
      "filename": "1706689953945_Calculation.xlsx",
      "path": "cases/65b79b1be1e7bf61f3d28e8f/
processingDocuments/1706689953945_Calculation.xlsx",
      "size": "1831112",
      "createdAt": "Wed Jan 31 2024 14:02:34 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "60f915d3f3dd69653a592199",
        "role": "MAKER + RATE VERFIER + CHEAKER",
        "firstName": "Shobha",
        "lastName": "Kuperkar",
        "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
    }
  ]
}
```



```
    "status": true,
    "_id": "65b88bad95b2d34ce374cb43",
    "note": "Rate verification done, site visit pending.",
    "taskId": "65b7a622e1e7bf61f3d29cce",
    "createdAt": "2024-01-30T05:39:57.532Z"
  }
],
"createdAt": "2024-01-29T12:33:31.617Z",
"updatedAt": "2024-01-31T10:19:47.130Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 906, 9th Floor, Wing - A, Aashiyana, Plot No. D,
Village - Panchpakhadi, Thane (West), Taluka - Thane, District - Thane, Thane, PIN
Code - 400 606, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Pranali",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "2268685500",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 322.00",
"flatRate": "30000",
"landOtherRate": "27000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Wed Jan 31 2024 14:07:27 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-01-30",
```

```

"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": ""

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			