

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6576c5389e3cbd4940a7af54",
    "firstName": "Nitin ",
    "lastName": "Padvi",
    "mobileNo": "",
    "workMobileNo": "9422539583",
    "email": "nitin.padvi@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Nitin ",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC- Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "SITEENGINEER",
  "firstName": "Abhiraj",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.552916006726434",
  "longitude": "73.94024226788613"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.94024226788613,
    18.552916006726434
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "3/02/2024 09:18 am"
    },
    {
      "dateTime": "3/02/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-07",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kharadi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A-1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Haveli",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rakshak Nagar Gold",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```



```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "4/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "405",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 411 014",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Pune",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_"
```

```
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Pune_Municipal_Corporation",
    "label": "Pune Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Prakash Gold",
    "west": "Tanishq Society",
    "south": "Road",
    "east": "Road"
  },
  "asPerDocumentAgreement": {
    "north": "S. No. 39",
    "west": "S. No. 7 (Part)",
    "south": "S. No. 7",
    "east": "S. No. 4"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  }
}
```

```
    },
    "asPerDocument": {
      "north": "",
      "east": "",
      "south": "",
      "west": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "28.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9030.5",
  "depreciatedBuildingRate": "1930.5"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "71490",
  "landRate": "26610",
  "igrImage": "cases/65bd1ff86635d840ef5aaead/igr_1706937292704_Image.png",
  "squareMeterGuideLineRate": "71490.00",
  "squareFeetGuideLineRate": "6642.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "81",
  "rate": "5849.00",
  "squareFeetGuideLineRate": "5849.00",
  "squareMeterGuideLineRate": "62963.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "15,000/- Expected rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per Pune Municipal Corporation norms",
"tenantName": "Mrs. Shraddha Dasore,",
"maintenanceOfFlat": "Good"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
}
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
}
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
}
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
}
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
}
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "19",
"totalLifeBuilding": "60",
"estimatedAge": "41",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
```



```
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "786.00",
  "areaType": "Saleable",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Any Other Document"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65bd1ff86635d840ef5aaead/
routeMap_1708061389132_Image.png",
    "routeLat": "18.55269",
    "routeLng": "73.94037",
    "stationName": "Hadapsar (Pune)",
    "routeDistance": "4.00 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "nh7sbd",
      "name": "nh7sbd",
      "image": "cases/65bd1ff86635d840ef5aaead/
routeMap_1708061312517_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
```

```
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7098366.00",
"finalValue": "7098366.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Feb 16 2024 15:10:07 GMT+0530 (India Standard Time)",
  "number": "2305003",
  "dayCount": "9",
  "monthCount": "225",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "4597314.00",
"selectedBuildUpValue": "786.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65cef23819837c7e5fdc7b76",
"name":
"externalImg_1708061239439_WhatsApp_Image_20240216_at_104325_AM.jpeg",
"path": "cases/65bd1ff86635d840ef5aaead/
externalImg_1708061239439_WhatsApp_Image_20240216_at_104325_AM.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "65cef23819837c7e5fdc7b75",
  "name":
"externallmg_1708061239333_WhatsApp_Image_20240216_at_104324_AM.jpeg",
  "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239333_WhatsApp_Image_20240216_at_104324_AM.jpeg",
  "orientation": "landscape"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b79",
    "name":
"externallmg_1708061239761_WhatsApp_Image_20240216_at_104327_AM.jpeg",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239761_WhatsApp_Image_20240216_at_104327_AM.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b73",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239236_WhatsApp_Image_20240216_at_104321_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b74",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239252_WhatsApp_Image_20240216_at_104322_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b77",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239587_WhatsApp_Image_20240216_at_104326_AM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b78",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239718_WhatsApp_Image_20240216_at_104327_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b7a",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239911_WhatsApp_Image_20240216_at_104328_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b7b",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239952_WhatsApp_Image_20240216_at_104330_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b7c",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061240060_WhatsApp_Image_20240216_at_104330_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cef23819837c7e5fdc7b7d",
    "name": "Living Room",
    "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061240132_WhatsApp_Image_20240216_at_104332_AM.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "9375",
"max": "11333"
},
"builtUpRateRange": {
  "min": "7813",
  "max": "9445"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "786.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65bd1ff86635d840ef5aaead",
"ownerName": "Lt. Rohit Prakash",
"ownerPhoneNo": "9953805150",
"appAddress": "A ,1 \n405 Rakshak Nagar\nKharadi \nPune 411014",
"remark": "All documents in Mumbai id ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
```

```
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "05/10/2005",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Raviraj Kothari Developers",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Lt. Rohit Prakash",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "8469/2005"
},
"isHardCopy": false,
"displayStatus": true,
"id": "834321",
"path": "cases/65bd1ff86635d840ef5aaead/
document_1706893289321_199511.pdf",
"fileName": "document_1706893289321_199511.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "29/10/2002",
    "nameOfApprovingAuthority": {
      "value": "Pune_Municipal_Corporation",
      "label": "Pune Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "1142"
  },
  "isHardCopy": false,
  "displayStatus": true,
}
```

```
    "id": "834042",
    "path": "cases/65bd1ff86635d840ef5aaead/
document_1706931856922_AGREEMENT_0001_21.pdf",
    "fileName": "document_1706931856922_AGREEMENT_0001_21.pdf"
  }
],
"caseNumber": "006720",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "955133",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Feb 02 2024 22:31:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Lt. Rohit Prakash",
    "phone": "9953805150",
    "ownershipShare": "",
    "email": "",
    "id": "150982"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "126147",
    "name": "Living Room",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "13.67",
    "width1": "13",
    "width2": "8",
    "totalArea": "133.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "133.25"
  },

```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "",
  "length1": "7",
  "length2": "8",
  "width": "",
  "width1": "13",
  "width2": "9",
  "totalArea": "105.42",
  "images": [],
  "finalArea": "105.42",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "2.75",
  "width1": "2",
  "width2": "9",
  "totalArea": "11.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
```

```
"width": "10.75",
"width1": "10",
"width2": "9",
"totalArea": "115.56",
"images": [],
"extraAreas": [],
"finalArea": "115.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "16.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "6.42",
  "width1": "6",
  "width2": "5",
  "totalArea": "23.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.53"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "11.33",
  "length1": "11",
  "length2": "4",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "121.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "121.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "28.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
```

```
"width2": "00",
"totalArea": "18.00",
"images": [],
"extraAreas": [],
"finalArea": "18.00"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "58.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "58.78",
  "percentageBeforeTotal": "58.78",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```



```
    },
    "id": "254416",
    "selectAreaTypeDocument": "Saleable",
    "totalAreaDocument": "786",
    "squareMeterArea": "73.02",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65bdcc106635d840ef5afe6b",
    "property": "2BHK Flat for Sale in Raviraj Rakshaknagar Gold, Pandhari Nagar,
Pune",
    "area": "750.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "https://www.99acres.com/",
    "expectedPrice": "7500000.00",
    "expectedRate": "10000.00",
    "builtUpExpectedRate": "8333.33",
    "image": "cases/65bd1ff86635d840ef5aaead/
indicator_1706936871189_Image.png",
    "squareMeter": "69.68",
    "id": "979921"
  },
  {
    "printlnReport": true,
    "_id": "65bdcc106635d840ef5afe6c",
    "property": "2 BHK Flat For Sale Rakshak Nagar Gold, Pune",
    "area": "800",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "7500000",
    "expectedRate": "9375.00",
```

```
"builtUpExpectedRate": "7812.50",
"image": "cases/65bd1ff86635d840ef5aaead/
indicator_1706936987731_Image.png",
"squareMeter": "74.32",
"id": "118912"
},
{
  "printlnReport": true,
  "_id": "65bdcc106635d840ef5afe6d",
  "property": "2 BHK Flat For Sale Rakshak Nagar Gold, Kharadi, Pune",
  "area": "600",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6800000.00",
  "expectedRate": "11333.33",
  "builtUpExpectedRate": "9444.44",
  "image": "cases/65bd1ff86635d840ef5aaead/
indicator_1706937029225_Image.png",
  "squareMeter": "55.74",
  "id": "839030"
},
{
  "printlnReport": true,
  "_id": "65bdcc106635d840ef5afe6e",
  "property": "2 BHK For Sale in Rakshak Nagar Gold, Kharadi, Pune",
  "area": "750.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "7800000",
  "expectedRate": "10400.00",
  "builtUpExpectedRate": "8666.67",
  "image": "cases/65bd1ff86635d840ef5aaead/
indicator_1706937063399_Image.png",
  "squareMeter": "69.68",
  "id": "616467"
},
{
  "printlnReport": false,
  "_id": "65cef38619837c7e5fdc8288",
  "property": "Rakshak Nagar Gold",
```

```
"area": "786",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "magic_bricks",
"expectedPrice": "6900000",
"expectedRate": "8778.63",
"builtUpExpectedRate": "6900000",
"image": "cases/65bd1ff86635d840ef5aaead/
indicator_1708061574209_Image.png",
"squareMeter": "73.02",
"id": "452355"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65cef23819837c7e5fdc7b73",
"name":
"externalImg_1708061239236_WhatsApp_Image_20240216_at_104321_AM.jpeg",
"path": "cases/65bd1ff86635d840ef5aaead/
externalImg_1708061239236_WhatsApp_Image_20240216_at_104321_AM.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65cef23819837c7e5fdc7b74",
"name":
"externalImg_1708061239252_WhatsApp_Image_20240216_at_104322_AM.jpeg",
"path": "cases/65bd1ff86635d840ef5aaead/
externalImg_1708061239252_WhatsApp_Image_20240216_at_104322_AM.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65cef23819837c7e5fdc7b75",
"name":
"externalImg_1708061239333_WhatsApp_Image_20240216_at_104324_AM.jpeg",
"path": "cases/65bd1ff86635d840ef5aaead/
externalImg_1708061239333_WhatsApp_Image_20240216_at_104324_AM.jpeg",
"orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cef23819837c7e5fdc7b76",
  "name":
"externallmg_1708061239439_WhatsApp_Image_20240216_at_104325_AM.jpeg",
  "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239439_WhatsApp_Image_20240216_at_104325_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cef23819837c7e5fdc7b77",
  "name":
"externallmg_1708061239587_WhatsApp_Image_20240216_at_104326_AM.jpeg",
  "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239587_WhatsApp_Image_20240216_at_104326_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cef23819837c7e5fdc7b78",
  "name":
"externallmg_1708061239718_WhatsApp_Image_20240216_at_104327_AM_1.jpeg",
  "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239718_WhatsApp_Image_20240216_at_104327_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cef23819837c7e5fdc7b79",
  "name":
"externallmg_1708061239761_WhatsApp_Image_20240216_at_104327_AM.jpeg",
  "path": "cases/65bd1ff86635d840ef5aaead/
externallmg_1708061239761_WhatsApp_Image_20240216_at_104327_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cef23819837c7e5fdc7b7a",
  "name":
"externallmg_1708061239911_WhatsApp_Image_20240216_at_104328_AM.jpeg",
```

```
    "path": "cases/65bd1ff86635d840ef5aaead/  
externallmg_1708061239911_WhatsApp_Image_20240216_at_104328_AM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65cef23819837c7e5fdc7b7b",  
    "name":  
"externallmg_1708061239952_WhatsApp_Image_20240216_at_104330_AM_1.jpeg",  
    "path": "cases/65bd1ff86635d840ef5aaead/  
externallmg_1708061239952_WhatsApp_Image_20240216_at_104330_AM_1.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65cef23819837c7e5fdc7b7c",  
    "name":  
"externallmg_1708061240060_WhatsApp_Image_20240216_at_104330_AM.jpeg",  
    "path": "cases/65bd1ff86635d840ef5aaead/  
externallmg_1708061240060_WhatsApp_Image_20240216_at_104330_AM.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65cef23819837c7e5fdc7b7d",  
    "name":  
"externallmg_1708061240132_WhatsApp_Image_20240216_at_104332_AM.jpeg",  
    "path": "cases/65bd1ff86635d840ef5aaead/  
externallmg_1708061240132_WhatsApp_Image_20240216_at_104332_AM.jpeg",  
    "orientation": "landscape"  
  }  
],  
"externalDocuments": [],  
"processingDocuments": [],  
"leadRemarks": [],  
"audioRemarks": [],  
"remarks": [],  
"createdAt": "2024-02-02T17:01:44.896Z",  
"updatedAt": "2024-02-16T09:41:59.770Z",  
"__v": 0,  
"assignmentType": {  
  "value": "Retail",  
  "label": "Retail"
```

```
},
"fullAddress": "Residential Flat No. 405, 4th Floor, Building No A-1, Rakshak Nagar
Gold, Village - Kharadi, Pune, Taluka - Haveli, District - Pune, PIN Code - 411 014,
State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mrs. Shraddha Dasore, ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "9420075757",
"buildingServicesRate": "2700",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Any Other Document",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 786.00",
"flatRate": "9800",
"landOtherRate": "7100",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
```

```

},
"builtupPercentage": "20",
"carpetTotal": "573.35",
"extendOfSiteRemark": "Saleable Built up Area in Sq. Ft. = 748.00\nTerrace Area in Sq. Ft. = 38.00 (50% of Terrace Area i.e. 75.00 Sq. Ft.)\nTotal Saleable Built up Area in Sq. Ft. = 786.00\n(Area as per Agreement for Sale)",
"finalBuiltupArea": "758.56",
"finalCarpetArea": "632.13",
"finalSalableArea": "910.27",
"otherCarpetTotal": "58.78",
"salablePercentage": "20",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 573.00\nBalcony Area in Sq. Ft. = 59.00\nTotal Carpet Area in Sq. Ft. = 632.00\n(Area as per Actual Site Measurement)",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Passage + 2 Toilet",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "58.78",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Fri Feb 16 2024 11:52:45 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-07"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'9"	13'8"	133.25
Kitchen	7'8"	13'9"	105.42
Passage	4'2"	2'9"	11.46
Bedroom	10'9"	10'9"	115.56
Passage	4'5"	3'8"	16.19
Toilet	3'8"	6'5"	23.53
Bedroom	11'4"	10'9"	121.83
Toilet	7'8"	3'8"	28.11
Passage	6'00"	3'00"	18.00

Other
Composition :

Balcony Area	7'8"	7'8"	58.78
--------------	------	------	-------
