

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
    "firstName": "Priyanka",
    "email": "thane@vastukala.org",
    "lastName": "Pawar",
    "mobileNo": "8928414480",
    "shortName": "PCP",
    "workWithDocumentMaker": "627222afafd7d55eddeddd82"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65829f7c65d49d78457ec7be",
    "role": "SITEENGINEER",
    "firstName": "Vaibhav",
    "email": "vaib1234b@gmail.com",
    "lastName": "Bhagat",
    "mobileNo": "8779534609",
    "designation": "Bachlore Of Engireeing",
    "shortName": "Vaibhav",
    "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "627222afafd7d55eddeddd82",
    "role": "FRONTDESK",
    "firstName": "Pratibha",
    "email": "shilvanta_pratibha@yahoo.co.in",
    "lastName": "Shilvantha",
    "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.099700920053166",
  "longitude": "73.25235953819528"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-06T18:59:04.595Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-06",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "20000",
  "lumpsumValue": "8200000",
  "rateMax": "22000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chinchavli, Airoli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "AL-5-5",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Garden View Apartment Owners Association",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "16",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Acharya Vinobha Bhave Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "AL-5/5/15",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "267 Part & 268 Part",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 708",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_with_POP_false_Ceiling",
  "label": "Cement Plastering with POP false Ceiling"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Building No. AL-5/6",
    "west": "Row Houses",
    "south": "Building No. AL-5/4",
    "east": "Acharya Vinobha Bhave Road"
  },
  "asPerDocumentAgreement": {
    "north": "15.00 Mtr wide Road",
    "west": "15.00 AL-I & AL-4 Type Apartments",
    "south": "7.00 Mtr wide Road",
    "east": "10.00 Mtr wide Road"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Row House No. 13",
      "east": "Staircase",
```

```
    "south": "Row House No. 16",
    "west": "Row House No. 14"
  },
  "asPerDocument": {
    "north": "",
    "east": "",
    "south": "",
    "west": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per site inspection, 1BHK flat converted into 2BHK Flat.
",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "No",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "As per site inspection, 1BHK flat converted into 2BHK Flat. ",
  "depreciationPercentage": "51",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "18225",
  "depreciatedBuildingRate": "1225"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "113300",
  "landRate": "43400",
  "igrImage": "cases/65c081956635d840ef5d0c3e/igr_1707981639552_Image.png",
  "squareMeterGuideLineRate": "96305.00",
  "squareFeetGuideLineRate": "8947.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "66",
  "rate": "7276.00",
  "squareFeetGuideLineRate": "7276.00",
  "squareMeterGuideLineRate": "78317.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
```

```
"label": "Medium"
},
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "Rs. 17,000.00 Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "Mr. Avinash / Rented Since – 1 Year",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "value": "No",
    "label": "No"
  }
},
```

```
"carParking": "Open Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1990",
  "fullDate": "1/1/1990"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
}
```

```
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "26",
"ageOfBuilding": "34",
"noOfBasement": "0",
```



```
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "3",
"flatFloorNo": "3",
"noOfLifts": "0",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "441.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65c081956635d840ef5d0c3e/
routeMap_1707988205337_Image.png",
    "routeLat": "19.149078",
    "routeLng": "72.995124",
    "stationName": "Airoli",
    "routeDistance": "1.5 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ehob7",
      "name": "ehob7",
      "image": "cases/65c081956635d840ef5d0c3e/
routeMap_1707988063995_Image.png"
    }
  ]
},
```

```
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8037225.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "8037225.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3208716.00",
  "selectedBuildUpValue": "441.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65c280c06635d840ef6008cc",
      "name": "externallmg_1707245750831_image.jpeg",
      "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245750831_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65c280c06635d840ef6008cd",
      "name": "externallmg_1707245754153_image.jpeg",
```

```
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245754153_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c280c06635d840ef6008ce",
    "name": "externallmg_1707245754491_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245754491_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c280c06635d840ef6008c9",
    "name": "externallmg_1707245746628_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245746628_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c280c06635d840ef6008c6",
    "name": "externallmg_1707245744396_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245744396_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c280c06635d840ef6008c3",
    "name": "externallmg_1707245742836_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245742836_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c280c06635d840ef6008cc",
    "name": "externallmg_1707245750831_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245750831_image.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20703",
    "max": "23247"
  },
  "builtUpRateRange": {
    "min": "18821",
    "max": "21135"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "441.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65c081956635d840ef5d0c3e",
"ownerName": "Mr. Vivek Kumar Singh & Mrs. Priti Kumari",
"ownerPhoneNo": "8340747962",
"fullAddress": "Residential Flat No. AL-5/5/15, 3rd Floor, Building No AL-5-5, Garden
```

View Apartment Owners Association, Plot No. 1, Sector 16, Acharya Vinobha Bhave Road, Village - Chinchavli, Airoli, Gut No. 267 Part & 268 Part, Taluka - Thane, District - Thane, Navi Mumbai, PIN Code - 400 708, State - Maharashtra, India",

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/02/2024",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Sasi Chandran Naduvath",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Vivek Kumar Singh & Mrs. Priti Kumari",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "2811 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1707986809261_SALE_AGREEMENT.pdf",
    "path": "cases/65c081956635d840ef5d0c3e/
document_1707986809261_SALE_AGREEMENT.pdf",
    "id": "878756",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Thu Feb 15 2024 14:16:49 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006750",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
```

```
"id": "394648",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Mon Feb 05 2024 12:05:01 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Vivek Kumar Singh & Mrs. Priti Kumari",
"phone": "8340747962",
"ownershipShare": "",
"email": "",
"id": "970939"
}
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
"_id": "65c2800a6635d840ef60087c",
"area": "346",
"providedByName": "Mr. Vivek Kumar Singh & Mrs. Priti Kumari",
"providedByContactNo": "8340747962"
}
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "1",
"name": "Living Room",
"length": "11.00",
"length1": "11",
"length2": "00",
"width": "12.00",
"width1": "12",
"width2": "00",
```

```
"totalArea": "132.00",
"images": [],
"extraAreas": [],
"finalArea": "132.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "39.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "72.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "3",
"name": "Bedroom",
"length": "15.00",
"length1": "15",
"length2": "00",
"width": "5.00",
"width1": "5",
"width2": "00",
"totalArea": "75.00",
"images": [],
"extraAreas": [],
"finalArea": "75.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "9.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Bathroom",
  "length": "",
  "length1": "2",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "8.00",
  "images": [],
```

```
"finalArea": "8.00",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "40.97",
    "totalAreaDocument": "441",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "746300"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65cde6dfd93fe4510d516e2f",
    "property": "Residential Flat",
    "area": "450",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "9500000",
    "expectedRate": "21111.11",
    "builtUpExpectedRate": "9500000",
    "image": "cases/65c081956635d840ef5d0c3e/
indicator_1707992758015_Image.png",
    "squareMeter": "41.81",
    "id": "823949"
  },
  {
    "printlnReport": true,
    "_id": "65cdbb4fd93fe4510d50c3ba",
    "property": "Residential Flat",
    "area": "441",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "Nobroker.com",
    "expectedPrice": "8300000",
    "expectedRate": "18820.86",
    "builtUpExpectedRate": "8300000",
    "image": "cases/65c081956635d840ef5d0c3e/
indicator_1707981548763_Image.png",
    "squareMeter": "40.97",
    "id": "651655"
  },
  {
    "printlnReport": true,
    "_id": "65cde6dfd93fe4510d516e31",
    "property": "Residential Flat",
    "area": "247",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
```

```
"areaType": "Built_Up",
"source": "Index_no.2",
"expectedPrice": "4950000",
"expectedRate": "20040.49",
"builtUpExpectedRate": "4950000",
"image": "cases/65c081956635d840ef5d0c3e/
indicator_1707992692679_Image.jpeg",
"squareMeter": "22.95",
"id": "428691"
},
{
  "printlnReport": false,
  "_id": "65cde8eed93fe4510d517a86",
  "property": "Residential Flat",
  "area": "388",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "8200000",
  "expectedRate": "21134.02",
  "builtUpExpectedRate": "17611.68",
  "image": "cases/65c081956635d840ef5d0c3e/
indicator_1707993325763_Image.png",
  "squareMeter": "36.05",
  "id": "946249"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c280c06635d840ef6008c2",
    "name": "externalImg_1707245742085_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externalImg_1707245742085_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c280c06635d840ef6008c3",
    "name": "externalImg_1707245742836_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
externalImg_1707245742836_image.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c4",
  "name": "externallmg_1707245743081_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245743081_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c5",
  "name": "externallmg_1707245743706_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245743706_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c6",
  "name": "externallmg_1707245744396_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245744396_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c7",
  "name": "externallmg_1707245744586_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245744586_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c8",
  "name": "externallmg_1707245746036_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245746036_image.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008c9",
  "name": "externalimg_1707245746628_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externalimg_1707245746628_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008ca",
  "name": "externalimg_1707245746903_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externalimg_1707245746903_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008cb",
  "name": "externalimg_1707245747751_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externalimg_1707245747751_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008cc",
  "name": "externalimg_1707245750831_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externalimg_1707245750831_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008cd",
  "name": "externalimg_1707245754153_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externalimg_1707245754153_image.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008ce",
  "name": "externallmg_1707245754491_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245754491_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008cf",
  "name": "externallmg_1707245756101_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245756101_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c280c06635d840ef6008d0",
  "name": "externallmg_1707245757061_image.jpeg",
  "path": "cases/65c081956635d840ef5d0c3e/
externallmg_1707245757061_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "externallmg_1707245746903_image.jpeg",
    "filename": "1707981663221_externallmg_1707245746903_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981663221_externallmg_1707245746903_image.jpeg",
    "size": "415595",
    "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1707245747751_image.jpeg",
    "filename": "1707981663567_externallmg_1707245747751_image.jpeg",
    "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981663567_externallmg_1707245747751_image.jpeg",
    "size": "216392",
    "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1707981663783_IGR01.pdf",
  "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981663783_IGR01.pdf",
  "size": "151476",
  "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1707981663941_IGR02.pdf",
  "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981663941_IGR02.pdf",
  "size": "144735",
  "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1707981664105_IGR03.pdf",
  "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981664105_IGR03.pdf",
  "size": "156243",
  "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "SALE AGREEMENT.pdf",
  "filename": "1707981664307_SALE_AGREEMENT.pdf",
  "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981664307_SALE_AGREEMENT.pdf",
  "size": "2429053",
  "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=VIVEK.xlsx",
  "filename": "1707981666906_Summary_NewVIVEK.xlsx",
  "path": "cases/65c081956635d840ef5d0c3e/
processingDocuments/1707981666906_Summary_NewVIVEK.xlsx",
  "size": "3908705",
  "createdAt": "Thu Feb 15 2024 12:51:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65c4c08ad93fe4510d466200",
    "note": "Pending for value confirmation",
    "taskId": "65c0819f6635d840ef5d0cff",
    "createdAt": "2024-02-08T11:52:42.917Z"
  }
],
"createdAt": "2024-02-05T06:35:01.705Z",
"updatedAt": "2024-02-15T10:40:40.703Z",
"__v": 0,
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Vivek Kumar Singh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8340747962",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage",
"carpetTotal": "272.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-02-06",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
```

```

"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 441.00",
"flatRate": "19500",
"landOtherRate": "17000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"finalBuiltupArea": "381.70",
"finalCarpetArea": "347.00",
"finalSalableArea": "419.87",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Feb 15 2024 12:54:19 GMT+0530 (India Standard Time)"
}

```

Name	Length	Width	Total
Composition :			

Living Room	11'00"	12'00"	132.00
Kitchen	13'00"	3'00"	39.00
Bedroom	12'00"	6'00"	72.00
Bedroom	15'00"	5'00"	75.00
WC	3'00"	3'00"	9.00
Bathroom	2'0"	4'0"	8.00
Passage	2'00"	6'00"	12.00
Other Composition :			