

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b2b9fa191f7b344b00aaa5"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b0f",
    "email": "bom14510@mahabank.co.in",
    "firstName": "Sapna ",
    "mobileNo": "",
    "workMobileNo": "9898499411",
    "lastName": "Tekwani"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Sapna ",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b2b9fa191f7b344b00aaa5",
  "name": "SAMB Fort",
  "branchCode": "",
  "mobileNo": "9028199476",
  "alternateMobileNo": "",
  "email": "bom1447@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Janmangal, 4th Floor, 45/47, Mumbai Samachar Marg, \nFort, Mumbai -
400 001."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65829f7c65d49d78457ec7be",
    "role": "SITEENGINEER",
    "firstName": "Vaibhav",
    "email": "vaib1234b@gmail.com",
    "lastName": "Bhagat",
    "mobileNo": "8779534609",
    "designation": "Bachlore Of Engireeing",
    "shortName": "Vaibhav",
    "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": []
},
"clientType": {
```

```
"label": "BANK",
"value": "BANK"
},
"location": {
  "latitude": "19.05258276331388",
  "longitude": "73.0719393797573"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0719393797573,
    19.05258276331388
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "6/02/2024 06:26 pm"
    },
    {
      "dateTime": "6/02/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-07T17:52:31.534Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "4500",
  "lumpsumValue": "30000000",
  "rateMax": "5000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kharghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  }
}
```

```
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "205",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Park View",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "19",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
```

```
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
```

```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1,2,3,4,5,6,7,8",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```



```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
```

```
"value": "VerifiedTileFlooring"
},
"doors": {
  "label": "Teak Wood Door Frame With Flush Shutters",
  "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
},
"windows": {
  "label": "Aluminium Sliding Window ",
  "value": "Aluminium_Sliding_Window_"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "plot no 206 devki angan chsl",
    "west": "shanikrupa apartments ",
    "south": "morbi gaon garden",
    "east": "plot no 170,171 ,road 12 mt"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
```

```
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
}
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
}
```

```
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Poor",
  "value": "Poor"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Poor",
  "value": "Poor"
},
"maintenanceOfTheBuilding": {
  "label": "Poor",
  "value": "Poor"
},
"visibleDamageInBuilding": {
  "label": "Yes",
  "value": "1"
},
}
```

```
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "04",
"flatFloorNo": "",
"noOfLifts": "01",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "02"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```



```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65c217af6635d840ef5fbac4",
"ownerName": "Rajendra Vitthal Shinde ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 1,2,3,4,5,6,7,8,Park View,Plot no 205,Sector 19,Murbi
Village,Kharghar,Navi Mumbai ",
"remark": "Cont Person Sapana Madam Bankar \nMob no ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65c217af6635d840ef5fbac4/
document_1707218798845_1707218936448_SmRi52SKPbN92nLY816.pdf",
    "fileName":
"document_1707218798845_1707218936448_SmRi52SKPbN92nLY816.pdf",
    "id": "269537",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Feb 06 2024 16:57:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    }
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65c217af6635d840ef5fbac4/
document_1707218838048_1707218975627_DocScanner_6_Feb_2024_1247.pdf",
    "fileName":
"document_1707218838048_1707218975627_DocScanner_6_Feb_2024_1247.pdf",
    "id": "167844",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Feb 06 2024 16:57:43 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "006795",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "848749",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 06 2024 16:57:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rajendra Vitthal Shinde ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "926094"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "65c3c1efd93fe4510d445e4b",
    "area": "624",
    "providedByName": "bank",
    "providedByContactNo": "23"
  }
]
```

```
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "454267",
    "name": "Living Room",
    "length": "50.00",
    "length1": "50",
    "length2": "00",
    "width": "30.00",
    "width1": "30",
    "width2": "00",
    "totalArea": "1500.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1500.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c3c279d93fe4510d445e7d",
    "name": "externalImg_1707328112216_image.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externalImg_1707328112216_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c3c279d93fe4510d445e7e",
    "name": "externalImg_1707328112968_image.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externalImg_1707328112968_image.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c3c279d93fe4510d445e7f",
    "name": "externallmg_1707328113580_image.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707328113580_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c3c279d93fe4510d445e80",
    "name": "externallmg_1707328113737_image.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707328113737_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c3c279d93fe4510d445e81",
    "name": "externallmg_1707328113896_image.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707328113896_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4845bd93fe4510d455f24",
    "name":
"externallmg_1707377755476_WhatsApp_Image_20240208_at_10617_PM_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755476_WhatsApp_Image_20240208_at_10617_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4845bd93fe4510d455f25",
    "name":
"externallmg_1707377755492_WhatsApp_Image_20240208_at_10617_PM_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755492_WhatsApp_Image_20240208_at_10617_PM_2.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4845bd93fe4510d455f26",
  "name":
"externallmg_1707377755500_WhatsApp_Image_20240208_at_10617_PM_3.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755500_WhatsApp_Image_20240208_at_10617_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4845bd93fe4510d455f27",
  "name":
"externallmg_1707377755507_WhatsApp_Image_20240208_at_10618_PM.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755507_WhatsApp_Image_20240208_at_10618_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4845bd93fe4510d455f28",
  "name":
"externallmg_1707377755509_WhatsApp_Image_20240208_at_10604_PM_1.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755509_WhatsApp_Image_20240208_at_10604_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4845bd93fe4510d455f29",
  "name":
"externallmg_1707377755511_WhatsApp_Image_20240208_at_10604_PM_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755511_WhatsApp_Image_20240208_at_10604_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4845bd93fe4510d455f2a",
  "name":
"externallmg_1707377755513_WhatsApp_Image_20240208_at_10605_PM_1.jpeg",
```

```
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755513_WhatsApp_Image_20240208_at_10605_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4845bd93fe4510d455f2b",
    "name":
"externallmg_1707377755514_WhatsApp_Image_20240208_at_10605_PM_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755514_WhatsApp_Image_20240208_at_10605_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4845bd93fe4510d455f2c",
    "name":
"externallmg_1707377755516_WhatsApp_Image_20240208_at_10605_PM.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755516_WhatsApp_Image_20240208_at_10605_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4845bd93fe4510d455f2d",
    "name":
"externallmg_1707377755525_WhatsApp_Image_20240208_at_10606_PM_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755525_WhatsApp_Image_20240208_at_10606_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fb4",
    "name":
"externallmg_1707377755961_WhatsApp_Image_20240208_at_10606_PM_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377755961_WhatsApp_Image_20240208_at_10606_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "65c48470d93fe4510d455fb5",
    "name":
"externallmg_1707377776077_WhatsApp_Image_20240208_at_10606_PM.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776077_WhatsApp_Image_20240208_at_10606_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fb6",
    "name":
"externallmg_1707377776121_WhatsApp_Image_20240208_at_10607_PM_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776121_WhatsApp_Image_20240208_at_10607_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fb7",
    "name":
"externallmg_1707377776124_WhatsApp_Image_20240208_at_10607_PM_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776124_WhatsApp_Image_20240208_at_10607_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fb8",
    "name":
"externallmg_1707377776126_WhatsApp_Image_20240208_at_10607_PM_3.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776126_WhatsApp_Image_20240208_at_10607_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fb9",
    "name":
"externallmg_1707377776128_WhatsApp_Image_20240208_at_10607_PM.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776128_WhatsApp_Image_20240208_at_10607_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fba",
    "name":
"externallmg_1707377776130_WhatsApp_Image_20240208_at_10608_PM_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776130_WhatsApp_Image_20240208_at_10608_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fbb",
    "name":
"externallmg_1707377776135_WhatsApp_Image_20240208_at_10608_PM_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776135_WhatsApp_Image_20240208_at_10608_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fbc",
    "name":
"externallmg_1707377776137_WhatsApp_Image_20240208_at_10608_PM.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776137_WhatsApp_Image_20240208_at_10608_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c48470d93fe4510d455fbd",
    "name":
"externallmg_1707377776139_WhatsApp_Image_20240208_at_10609_PM_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377776139_WhatsApp_Image_20240208_at_10609_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4847fd93fe4510d456051",
```

```
    "name":
"externallmg_1707377791543_WhatsApp_Image_20240208_at_10609_PM_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791543_WhatsApp_Image_20240208_at_10609_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456052",
  "name":
"externallmg_1707377791547_WhatsApp_Image_20240208_at_10609_PM.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791547_WhatsApp_Image_20240208_at_10609_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456053",
  "name":
"externallmg_1707377791551_WhatsApp_Image_20240208_at_10610_PM_1.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791551_WhatsApp_Image_20240208_at_10610_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456054",
  "name":
"externallmg_1707377791554_WhatsApp_Image_20240208_at_10610_PM_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791554_WhatsApp_Image_20240208_at_10610_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456055",
  "name":
"externallmg_1707377791558_WhatsApp_Image_20240208_at_10610_PM.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791558_WhatsApp_Image_20240208_at_10610_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456056",
  "name":
"externallmg_1707377791560_WhatsApp_Image_20240208_at_10611_PM_1.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791560_WhatsApp_Image_20240208_at_10611_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456057",
  "name":
"externallmg_1707377791563_WhatsApp_Image_20240208_at_10611_PM_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791563_WhatsApp_Image_20240208_at_10611_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456058",
  "name":
"externallmg_1707377791565_WhatsApp_Image_20240208_at_10611_PM_3.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791565_WhatsApp_Image_20240208_at_10611_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d456059",
  "name":
"externallmg_1707377791567_WhatsApp_Image_20240208_at_10611_PM.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791567_WhatsApp_Image_20240208_at_10611_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c4847fd93fe4510d45605a",
  "name":
"externallmg_1707377791569_WhatsApp_Image_20240208_at_10612_PM_1.jpeg",
```

```
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377791569_WhatsApp_Image_20240208_at_10612_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c484e1d93fe4510d45643a",
    "name":
"externallmg_1707377889525_WhatsApp_Image_20240208_at_130104.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889525_WhatsApp_Image_20240208_at_130104.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c484e1d93fe4510d45643b",
    "name":
"externallmg_1707377889528_WhatsApp_Image_20240208_at_130105_2.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889528_WhatsApp_Image_20240208_at_130105_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c484e1d93fe4510d45643c",
    "name":
"externallmg_1707377889532_WhatsApp_Image_20240208_at_130105.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889532_WhatsApp_Image_20240208_at_130105.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c484e1d93fe4510d45643d",
    "name":
"externallmg_1707377889535_WhatsApp_Image_20240208_at_130106_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889535_WhatsApp_Image_20240208_at_130106_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65c484e1d93fe4510d45643e",
  "name":
"externallmg_1707377889537_WhatsApp_Image_20240208_at_130106_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889537_WhatsApp_Image_20240208_at_130106_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c484e1d93fe4510d45643f",
  "name":
"externallmg_1707377889540_WhatsApp_Image_20240208_at_130106.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889540_WhatsApp_Image_20240208_at_130106.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c484e1d93fe4510d456440",
  "name":
"externallmg_1707377889543_WhatsApp_Image_20240208_at_130107_1.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889543_WhatsApp_Image_20240208_at_130107_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c484e1d93fe4510d456441",
  "name":
"externallmg_1707377889546_WhatsApp_Image_20240208_at_130107_2.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889546_WhatsApp_Image_20240208_at_130107_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c484e1d93fe4510d456442",
  "name":
"externallmg_1707377889548_WhatsApp_Image_20240208_at_130107.jpeg",
  "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889548_WhatsApp_Image_20240208_at_130107.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c484e1d93fe4510d456443",
    "name":
"externallmg_1707377889551_WhatsApp_Image_20240208_at_130108_1.jpeg",
    "path": "cases/65c217af6635d840ef5fbac4/
externallmg_1707377889551_WhatsApp_Image_20240208_at_130108_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "65c48434d93fe4510d455dd1",
    "note": "Revised (Task Reopen)",
    "taskId": "65c22c046635d840ef5ffc51",
    "createdAt": "2024-02-08T07:35:16.263Z"
  }
],
"createdAt": "2024-02-06T11:27:43.700Z",
"updatedAt": "2024-02-08T07:38:09.685Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1,2,3,4,5,6,7,8, Basement Floor, Park View, Plot
No. 205, Sector 19, Village - Kharghar, Navi Mumbai, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
```

```

"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Rajendra Vitthal Shinde ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1500",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2024-02-07"

```

}

Name	Length	Width	Total
Composition :			
Living Room	50'00"	30'00"	1500.00
Other Composition :			