

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b934"
    },
    "type": "CREDITOFFICER",
    "_id": "658a785ab7b4df714dab9af8",
    "firstName": "Ajay",
    "lastName": "Gawande",
    "mobileNo": "",
    "workMobileNo": "9820670780",
    "email": "ajay.gawande@jansewabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3500000",
    "discussWithPerson": "Ajay",
    "expectedFees": 1750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b934",
  "branchCode": "000001",
  "type": "BRANCH",
  "name": "Andheri (West) Branch",
  "email": "jssblaw@mtnl.net.in",
  "mobileNo": "02226206985",
  "alternateMobileNo": "",
  "address": "Shop No. 11 & 12, Rukmini Purushottam CHSL, J.P. Road, Near
Navarnag Cinema Bus Stop, Andheri (West), Mumbai - 400 058, State - Maharashtra,
Country - India. ",
  "ledgerName": "JANSEVA SAHAKARI BANK Andheri (West) Branch",
  "fax": " ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21005661389661",
  "longitude": "72.8444003240744"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.8444003240744,
19.21005661389661
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-08",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-08",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Magathane",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Borivali",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chintamani Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shree Sadguru Nagar, Sant Gora Kumbhar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Devipada",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "34, Hissa No. 6",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "208, 208/1 to 13 & 217/1 to 58 & 218, 218/1 to 32",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Varadvinayak CHSL",
    "west": "Road / Sahyadri Building",
    "south": "Morya CHSL",
    "east": "Mitratwa SRA CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "Survey No. 34, Hissa No. 7, 2",
    "west": "Survey No. 34, Hissa No. 5",
    "south": "Survey No. 34, Hissa No. 3",
    "east": "Survey No. 45, Hissa No. 4"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",

```

```
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "16000",
  "depreciatedBuildingRate": "2500"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "156390",
  "landRate": "69980",
  "igrImage": "cases/65c21e6b6635d840ef5fcc10/igr_1707462076189_Image.png",
  "squareMeterGuideLineRate": "156390.00",
  "squareFeetGuideLineRate": "14529.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "81",
  "rate": "13004.00",
  "squareFeetGuideLineRate": "13004.00",
  "squareMeterGuideLineRate": "139972.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
```

```
"label": "Owner Occupied"
},
"monthlyRent": "8,000/- Expected rental income per month",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "CA No. 152253167",
"meterCardHolderName": "Ravindra Tanu Juvale",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per SRA / MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Not Provided",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Average",
  "label": "Average"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "0",
  "label": "No"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_Possession_Letter",
  "label": "As per Possession Letter"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
```



```
"area": "240.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Possession Letter"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65c21e6b6635d840ef5fcc10/
routeMap_1707473649630_Image.png",
    "routeLat": "19.223556",
    "routeLng": "72.867250",
    "stationName": "Borivali",
    "routeDistance": "2.7 km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "jtovk1",
      "name": "jtovk1",
      "image": "cases/65c21e6b6635d840ef5fcc10/
routeMap_1707473407968_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```

```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3840000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "3840000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Feb 09 2024 17:52:42 GMT+0530 (India Standard Time)",
  "number": "2304894",
  "dayCount": "14",
  "monthCount": "116",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3120960.00",
"selectedBuildUpValue": "240.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "65c4b5ddd93fe4510d463769",
"name": "externalImg_1707390281926_1707390383288_image_7.jpeg",
"path": "cases/65c21e6b6635d840ef5fcc10/
externalImg_1707390281926_1707390383288_image_7.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "65c4b5ddd93fe4510d463765",
"name": "externalImg_1707390259110_1707390383288_image_3.jpeg",
"path": "cases/65c21e6b6635d840ef5fcc10/
externalImg_1707390259110_1707390383288_image_3.jpeg",
"orientation": "portrait"
}
]
```

```
],
"externalPhotos": [
  {
    "status": false,
    "_id": "65c4b5ddd93fe4510d463767",
    "name": "externallmg_1707390265790_1707390383288_image_5.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390265790_1707390383288_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c4b5ddd93fe4510d46376d",
    "name": "externallmg_1707390321306_1707390383288_image_11.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390321306_1707390383288_image_11.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375c",
    "name": "Living Room",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390298026_1707390410111_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375d",
    "name": "Living Room",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390311252_1707390410111_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c4b5ddd93fe4510d463762",
    "name": "Living Room",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390242995_1707390383286_image_0.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "status": false,
  "_id": "65c4b5ddd93fe4510d463764",
  "name": "Living Room",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390255213_1707390383288_image_2.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "17778",
    "max": "19395"
  },
  "builtUpRateRange": {
    "min": "14815",
    "max": "17632"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "240.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"invoices": [],
"paymentId": [],
"_id": "65c21e6b6635d840ef5fcc10",
"ownerName": "Shri. Ravindra Tanu Juvale",
"ownerPhoneNo": "9892491265",
"appAddress": "Flat no 204 Chintamani CHS Ltd Shree Sadguru Nagar Devipada
Borivali East Near Fish Market 400066",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1258aa6d152c1801b339",
      "label": "Possession Letter"
    },
    "inputs": {
      "documentDate": "02/10/2005",
      "remark": "In the name of Shri. Ravind Juvale issued by Shree Sadguru
Enterprises , Builders & Developers"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "902746",
    "path": "cases/65c21e6b6635d840ef5fcc10/document_1707220330080_170722046
4997_Ravindra_javal_agreement_5_pages.pdf",
    "fileName": "document_1707220330080_1707220464997_Ravindra_javal_agreeme
nt_5_pages.pdf"
  },
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/08/1992",
      "from": {
        "value": "The_Developer",
        "label": "The Developer"
      },
      "The_Developer": "Shriyut Jagdish Vamanrao Rane Initiator Shree. Saadguru
Enterprises",
      "to": {
        "value": "The_Tenant",
        "label": "The Tenant"
      },
      "The_Tenant": "Shri. Ravindra Tanu Juvale",
      "number": {
```

```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "-",
},
"isHardCopy": false,
"displayStatus": true,
"id": "957226",
"path": "cases/65c21e6b6635d840ef5fcc10/
document_1707220430337_1707220567308_Ravindra_javal_Jsb_Andheri_West.pdf",
"fileName":
"document_1707220430337_1707220567308_Ravindra_javal_Jsb_Andheri_West.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "16/06/2017",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 9585 / BP (WS) / AR"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "263659",
  "path": "cases/65c21e6b6635d840ef5fcc10/document_1707220497468_170722063
7409_Ravindra_Customer_Bldg_Occupation_Certificate.pdf",
  "fileName": "document_1707220497468_1707220637409_Ravindra_Customer_Bld
g_Occupation_Certificate.pdf"
},
{
  "documentType": {
    "label": "Electricity Bill",
    "value": "6077c791395bc80714864a30"
  },
  "inputs": {
    "documentDate": "27/02/2024",
    "number": {
```

```
    "value": "CA_No",
    "label": "CA No"
  },
  "CA_No": "152253167"
},
"isHardCopy": false,
"displayStatus": false,
"id": "844004",
"path": "cases/65c21e6b6635d840ef5fcc10/
document_1707220529654_1707220668717_ProcessDownloadPDF.pdf",
"fileName":
"document_1707220529654_1707220668717_ProcessDownloadPDF.pdf"
}
],
"caseNumber": "006797",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "322986",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 06 2024 17:26:27 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Ravindra Tanu Juvele",
    "phone": "9892491265",
    "ownershipShare": "",
    "email": "",
    "id": "804266"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "736888",
    "name": "Living Room",
    "length": "7.92",
    "length1": "7",
    "length2": "11",
```

```
"width": "11.92",
"width1": "11",
"width2": "11",
"totalArea": "94.34",
"images": [],
"extraAreas": [],
"finalArea": "94.34"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
  "totalArea": "56.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "56.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "23.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.83"
}
],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1258aa6d152c1801b339",
      "label": "Possession Letter"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "485925",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "240",
    "squareMeterArea": "22.3",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65c5ce28d93fe4510d473d0b",
    "property": "Sadguru Nagar Devipada, Borivali East",
    "area": "225",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "Middle",
    "source": "Nobroker.com",
    "expectedPrice": "3800000",
    "expectedRate": "16888.89",
    "builtUpExpectedRate": "3800000",
    "image": "cases/65c21e6b6635d840ef5fcc10/
indicator_1707461674273_Image.png",
    "squareMeter": "20.90",
    "id": "577422"
  },
  {
    "printlnReport": true,
```

```
"_id": "65c5ce28d93fe4510d473d0c",
"property": "Sadguru Nagar, Borivali East",
"area": "225",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "6",
"source": "https://www.99acres.com/",
"expectedPrice": "4000000",
"expectedRate": "17777.78",
"builtUpExpectedRate": "14814.81",
"image": "cases/65c21e6b6635d840ef5fcc10/
indicator_1707461796942_Image.png",
"squareMeter": "20.90",
"id": "494222"
},
{
  "printlnReport": true,
  "_id": "65c5ce28d93fe4510d473d0d",
  "property": "Sadguru Nagar Devipada, Borivali East",
  "area": "380",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "6700000",
  "expectedRate": "17631.58",
  "builtUpExpectedRate": "6700000",
  "image": "cases/65c21e6b6635d840ef5fcc10/
indicator_1707461857705_Image.png",
  "squareMeter": "35.30",
  "id": "911484"
},
{
  "printlnReport": true,
  "_id": "65c5ce28d93fe4510d473d0e",
  "property": "Siddhesha CHSL. Sadguru Nagar, Borivali East",
  "area": "240",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "Ground",
```

```
    "source": "Index_no.2",
    "expectedPrice": "4000000",
    "expectedRate": "16666.67",
    "builtUpExpectedRate": "4000000",
    "image": "cases/65c21e6b6635d840ef5fcc10/
indicator_1707461958957_Image.png",
    "squareMeter": "22.30",
    "id": "533978"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375b",
    "name": "externallmg_1707390274987_1707390410111_image_0.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390274987_1707390410111_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375c",
    "name": "externallmg_1707390298026_1707390410111_image_1.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390298026_1707390410111_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375d",
    "name": "externallmg_1707390311252_1707390410111_image_2.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390311252_1707390410111_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46375e",
    "name": "externallmg_1707390323580_1707390410111_image_3.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390323580_1707390410111_image_3.jpeg",
    "orientation": "portrait"
  }
]
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65c4b5ddd93fe4510d46375f",
      "name": "externallmg_1707390338293_1707390410111_image_4.jpeg",
      "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390338293_1707390410111_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65c4b5ddd93fe4510d463760",
      "name": "externallmg_1707390344346_1707390410111_image_5.jpeg",
      "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390344346_1707390410111_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65c4b5ddd93fe4510d463761",
      "name": "externallmg_1707390359583_1707390410111_image_6.jpeg",
      "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390359583_1707390410111_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65c4b5ddd93fe4510d463762",
      "name": "externallmg_1707390242995_1707390383286_image_0.jpeg",
      "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390242995_1707390383286_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "65c4b5ddd93fe4510d463763",
      "name": "externallmg_1707390251618_1707390383288_image_1.jpeg",
      "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390251618_1707390383288_image_1.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d463764",
  "name": "externallmg_1707390255213_1707390383288_image_2.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390255213_1707390383288_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d463765",
  "name": "externallmg_1707390259110_1707390383288_image_3.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390259110_1707390383288_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d463766",
  "name": "externallmg_1707390259113_1707390383288_image_4.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390259113_1707390383288_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d463767",
  "name": "externallmg_1707390265790_1707390383288_image_5.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390265790_1707390383288_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d463768",
  "name": "externallmg_1707390275587_1707390383288_image_6.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390275587_1707390383288_image_6.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c4b5ddd93fe4510d463769",
    "name": "externallmg_1707390281926_1707390383288_image_7.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390281926_1707390383288_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46376a",
    "name": "externallmg_1707390291423_1707390383288_image_8.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390291423_1707390383288_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46376b",
    "name": "externallmg_1707390297187_1707390383288_image_9.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390297187_1707390383288_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46376c",
    "name": "externallmg_1707390304006_1707390383288_image_10.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390304006_1707390383288_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c4b5ddd93fe4510d46376d",
    "name": "externallmg_1707390321306_1707390383288_image_11.jpeg",
    "path": "cases/65c21e6b6635d840ef5fcc10/
externallmg_1707390321306_1707390383288_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "65c4b5ddd93fe4510d46376e",
  "name": "externalImg_1707390337906_1707390383288_image_12.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externalImg_1707390337906_1707390383288_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65c4b5ddd93fe4510d46376f",
  "name": "externalImg_1707390345257_1707390383288_image_13.jpeg",
  "path": "cases/65c21e6b6635d840ef5fcc10/
externalImg_1707390345257_1707390383288_image_13.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1698490711305_1697100715004_Calculation.xlsx",
    "filename": "1707462176004_1698490711305_1697100715004_Calculation.xlsx",
    "path": "cases/65c21e6b6635d840ef5fcc10/processingDocuments/1707462176004_
1698490711305_1697100715004_Calculation.xlsx",
    "size": "2927508",
    "createdAt": "Fri Feb 09 2024 12:33:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65c5c4d5d93fe4510d47144c",
    "note": "Rate verification done",
  }
]
```

```
"taskId": "65c220336635d840ef5fd2c8",
"createdAt": "2024-02-09T06:23:17.621Z"
}
],
"createdAt": "2024-02-06T11:56:27.740Z",
"updatedAt": "2024-02-09T12:25:49.522Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 204, 2nd Floor, Building No 1, Wing - E,
Chintamani Co-op. Hsg. Soc. Ltd., Shree Sadguru Nagar, Sant Gora Kumbhar Road,
Devipada, Village - Magathane, Borivali (East), Taluka - Borivali, District - Mumbai
Suburban, PIN - 400 066, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Ravindra Tanu Juvalie",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9892491265",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Possession Letter",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 240.00",
"flatRate": "16000",
"landOtherRate": "13500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "Living Room + Kitchen + Toilet",
"carpetTotal": "174.17",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "209.00",
```

```

"finalCarpetArea": "174.17",
"finalSalableArea": "209.00",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	7'11"	11'11"	94.34
Kitchen	4'8"	12'00"	56.00
Toilet	3'11"	6'1"	23.83
Other Composition :			