

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231052",
    "firstName": "amol Kamble",
    "email": "0_default_amol.kamble@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9967776684"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "52855",
    "discussWithPerson": "amol Kamble",
    "expectedFees": 26.427500000000002,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
```

```
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"checker": {
  "_id": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg",
  "firstName": "Shyam",
  "lastName": "Kajvilkar",
  "shortName": "SK",
  "email": "shyam@vastukala.org",
  "designation": "",
  "mobileNo": "9765074720",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.196230143028224",
  "longitude": "72.96575896442842"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.96575896442842,
    19.196230143028224
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-11",
      "remark": "mrunali "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-10",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Panchpakahdi",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "340",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sumeet Enclave Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sant Dnyaneshwar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Banacha Pada",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "1402",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400602",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "ItalianMarbleFlooring",
    "label": "Italian Marble Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Thane_Municipal_Corporation",
  "label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Oasis Royal",
  "west": "Asha Apartment",
  "south": "Amrutraj CHSL",
  "east": "Sand Dnyaneshwar Marg"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "As Occupancy Certificate is available, we assumed that
the construction is as per approved plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "18",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "21014",
"depreciatedBuildingRate": "2214"
},
"igrRate": {
"propertyName": "Residential ",
"rate": "146400",
"landRate": "56000",
"igrImage": "cases/65c49b21d93fe4510d45a75b/igr_1709122661682_Image.png",
"squareMeterGuideLineRate": "161040.00",
"squareFeetGuideLineRate": "14961.00"
},
"igrFinalRate": {
"floorRatePercentage": "10",
"depreciationPercentage": "88",
"rate": "13790.00",
"squareMeterGuideLineRate": "148435.00",
"squareFeetGuideLineRate": "13790.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "N.A.",
"assessmentNo": "Property Tax No. 20230148",
"taxPaidHolderName": "M/s. Vedant Construction on behalf of P.O.A.H. Shri. Ramesh
Maruti Bhekare",
```

```
"taxAmount": "24,015/-",
"electricityServiceConnectionNo": "Electricity Bill Consumer No. 000011716962",
"meterCardHolderName": "Mr. Bhagwan Mahadeo Sambre",
"undividedAreaOfLandAsPerSaleDeed": "N.A.",
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "N.A."
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
```

```
"fullDate": "1/1/2012"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "48",
"ageOfBuilding": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "15",
"flatFloorNo": "14",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1340.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65c49b21d93fe4510d45a75b/
routeMap_1709122755062_Image.png",
    "routeLat": "19.196041",
    "routeLng": "72.965759",
    "stationName": "Thane",
    "routeDistance": "2.2 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "3cpdpg",
      "name": "3cpdpg",
      "image": "cases/65c49b21d93fe4510d45a75b/
routeMap_1709122711756_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "23472638.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "23472638.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Feb 28 2024 18:33:09 GMT+0530 (India Standard Time)",
  "number": "2305219",
  "dayCount": "24",
  "monthCount": "441",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "18484116.00",
  "selectedBuildUpValue": "1340.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65c863bdd93fe4510d4aa335",
      "name": "externallmg_r_1707631510194_1707631649331_image_1.jpg",
      "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631510194_1707631649331_image_1.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65c863bdd93fe4510d4aa332",
      "name": "externallmg_r_1707631515949_1707631649331_image_3.jpg",
      "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631515949_1707631649331_image_3.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65c863bdd93fe4510d4aa33f",
```

```
    "name": "externallmg_r_1707631540973_1707631649331_image_13.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631540973_1707631649331_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa340",
    "name": "externallmg_r_1707631543087_1707631649331_image_14.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631543087_1707631649331_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa334",
    "name": "externallmg_r_1707631507706_1707631649331_image_0.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631507706_1707631649331_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa333",
    "name": "externallmg_r_1707631512992_1707631649331_image_2.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631512992_1707631649331_image_2.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa33e",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631538768_1707631649331_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa33c",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631530853_1707631649331_image_9.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa33d",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631535533_1707631649331_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa33a",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631528884_1707631649331_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa338",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631518307_1707631649331_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65c863bdd93fe4510d4aa339",
    "name": "Living Room",
    "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631525874_1707631649331_image_7.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20000",
    "max": "22222"
  },
  "builtUpRateRange": {
    "min": "12326",
    "max": "18519"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1117.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3",
  "SME/TCC/221/13"
],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65c49b21d93fe4510d45a75b",
"ownerName": "Mr. Bhagwan Mahadeo Sambre",
"ownerPhoneNo": "7507745722",
"appAddress": "FLAT no - 1402, 14th floor, Bldg no B 1, sumeet enclave,
panchpakhadi, dhaneshwar road, Thane West ",
"remark": "mrunali ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/09/2010",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      }
    }
  }
]
```

```
    },
    "Promoter": "M/s. Vedant Construction",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Bhagwan Mahadeo Sambre",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "7470/2010"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709120839423_AGRFLAT_NO_1402.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
document_1709120839423_AGRFLAT_NO_1402.pdf",
  "id": "961981",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Feb 28 2024 17:17:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/03/2012",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "V. P. No. 2005 / 91 / TMC / TDD / 385 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709120892934_Occupancy_Certificate.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
document_1709120892934_Occupancy_Certificate.pdf",
  "id": "374901",
  "uploadedBy": "60eeaeddf3dd69653a581316",
```

```
"createdAt": "Wed Feb 28 2024 17:18:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/01/2024",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "657"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709120932955_2298454.pdf",
"path": "cases/65c49b21d93fe4510d45a75b/
document_1709120932955_2298454.pdf",
"id": "705366",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Feb 28 2024 17:18:53 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124daa6d152c1801b306",
    "label": "Property Tax"
  },
  "inputs": {
    "documentDate": "01/04/2023",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "20230148"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1709120981212_Property_Tax.pdf",
"path": "cases/65c49b21d93fe4510d45a75b/
document_1709120981212_Property_Tax.pdf",
```

```
"id": "292564",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Feb 28 2024 17:19:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "20/03/2010",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "V. P. No. 2005 / 91 / TMC / TDD / 823"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709121098756_CC.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/document_1709121098756_CC.pdf",
  "id": "233209",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Wed Feb 28 2024 17:21:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "06/12/2023",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "000011716962"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1709122091775_Electricity_Bill.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
document_1709122091775_Electricity_Bill.pdf",
```

```
"id": "427673",
"uploadedBy": "60eeaeddf3dd69653a581316",
"createdAt": "Wed Feb 28 2024 17:38:11 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006841",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
{
"id": "891185",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Thu Feb 08 2024 14:43:05 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Bhagwan Mahadeo Sambre",
"phone": "7507745722",
"ownershipShare": "",
"email": "",
"id": "231976"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
}
},
{id": "918609",
"name": "Passage",
"length": "3.25",
"length1": "3",
"length2": "3",
"width": "7.50",
"width1": "7",
"width2": "6",
"totalArea": "24.37",
"images": [],
"extraAreas": [],
"finalArea": "24.37"
}
],
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"name": "Living Room",
"length": "11.67",
"length1": "11",
"length2": "8",
"width": "18.42",
"width1": "18",
"width2": "5",
"totalArea": "214.86",
"images": [],
"extraAreas": [],
"finalArea": "214.86"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "10.25",
  "width1": "10",
  "width2": "3",
  "totalArea": "97.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "97.37"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "",
  "length1": "8",
  "length2": "2",
  "width": "",
```

```
"width1": "7",
"width2": "4",
"totalArea": "59.89",
"images": [],
"finalArea": "59.89",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "4.75",
  "length1": "4",
  "length2": "9",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "31.27",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.27"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "8.25",
  "length1": "8",
  "length2": "3",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "39.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
```



```
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "13.33",
  "width1": "13",
  "width2": "4",
  "totalArea": "122.22",
  "images": [],
  "extraAreas": [],
  "finalArea": "122.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "12.25",
  "width1": "12",
  "width2": "3",
  "totalArea": "133.73",
  "images": [],
  "extraAreas": [],
  "finalArea": "133.73"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Dining",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
```

```
"totalArea": "71.69",
"images": [],
"extraAreas": [],
"finalArea": "71.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "17.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Balcony",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "18.08",
  "width1": "18",
  "width2": "1",
  "totalArea": "43.70",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.70"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "18.08",
  "width1": "18",
  "width2": "1",
  "totalArea": "43.70",
  "images": [],
  "extraAreas": [],
  "finalArea": "43.70"
}
```

```
"id": "11",
"name": "Balcony",
"length": "5.67",
"length1": "5",
"length2": "8",
"width": "16.00",
"width1": "16",
"width2": "00",
"totalArea": "90.67",
"images": [],
"extraAreas": [],
"finalArea": "90.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Balcony",
  "length": "2.42",
  "length1": "2",
  "length2": "5",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
  "totalArea": "13.90",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.90"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Balcony",
  "length": "",
  "length1": "2",
  "length2": "5",
  "width": "",
  "width1": "3",
  "width2": "9",
  "totalArea": "9.06",
  "images": [],
```

```
"finalArea": "9.06",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "14",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
  "width": "14.33",
  "width1": "14",
  "width2": "4",
  "totalArea": "179.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "179.17"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "755293",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1117",
    "squareMeterArea": "103.77",
    "docFinalBuiltUp": "1340.4",
    "docFinalBuiltUpSquareMeter": "124.524",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65df23939a876858ab3127c8",
    "property": "Residential Flat",
    "area": "1000",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "20000000",
    "expectedRate": "20000.00",
    "builtUpExpectedRate": "16666.67",
    "image": "cases/65c49b21d93fe4510d45a75b/
indicator_1709122424697_Image.png",
    "squareMeter": "92.90",
    "id": "383833"
  },
  {
    "printlnReport": true,
    "_id": "65df23939a876858ab3127c9",
    "property": "Residential Flat",
    "area": "850",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "Nobroker.com",
    "expectedPrice": "17500000",
    "expectedRate": "20588.24",
    "builtUpExpectedRate": "17156.86",
    "image": "cases/65c49b21d93fe4510d45a75b/
indicator_1709122451521_Image.png",
    "squareMeter": "78.97",
    "id": "488007"
  },
  {
    "printlnReport": true,
    "_id": "65df3e5d9a876858ab3180b0",
    "property": "Residential Flat",
    "area": "305",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
```

```
"areaType": "Built_Up",
"source": "Index_no.2",
"expectedPrice": "5300000",
"expectedRate": "12325.58",
"builtUpExpectedRate": "5300000",
"image": "cases/65c49b21d93fe4510d45a75b/
indicator_1709129108851_Image.jpeg",
"squareMeter": "28.34",
"id": "755383"
},
{
  "printlnReport": true,
  "_id": "65df3e5d9a876858ab3180b1",
  "property": "Residential Flat",
  "area": "1350",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "30000000",
  "expectedRate": "22222.22",
  "builtUpExpectedRate": "18518.52",
  "image": "cases/65c49b21d93fe4510d45a75b/
indicator_1709129186136_Image.png",
  "squareMeter": "125.42",
  "id": "356894"
},
{
  "printlnReport": true,
  "_id": "65df3e5d9a876858ab3180b2",
  "property": "Residential Flat",
  "area": "986",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Nobroker.com",
  "expectedPrice": "21600000",
  "expectedRate": "21906.69",
  "builtUpExpectedRate": "18255.58",
  "image": "cases/65c49b21d93fe4510d45a75b/
indicator_1709129228320_Image.png",
  "squareMeter": "91.60",
  "id": "224046"
}
```

```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa332",
    "name": "externalimg_r_1707631515949_1707631649331_image_3.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631515949_1707631649331_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa333",
    "name": "externalimg_r_1707631512992_1707631649331_image_2.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631512992_1707631649331_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa334",
    "name": "externalimg_r_1707631507706_1707631649331_image_0.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631507706_1707631649331_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa335",
    "name": "externalimg_r_1707631510194_1707631649331_image_1.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631510194_1707631649331_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa336",
    "name": "externalimg_r_1707631522739_1707631649331_image_6.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631522739_1707631649331_image_6.jpg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa337",
  "name": "externallmg_r_1707631520264_1707631649331_image_5.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631520264_1707631649331_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa338",
  "name": "externallmg_r_1707631518307_1707631649331_image_4.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631518307_1707631649331_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa339",
  "name": "externallmg_r_1707631525874_1707631649331_image_7.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631525874_1707631649331_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33a",
  "name": "externallmg_r_1707631528884_1707631649331_image_8.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631528884_1707631649331_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33b",
  "name": "externallmg_r_1707631532772_1707631649331_image_10.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631532772_1707631649331_image_10.jpg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33c",
  "name": "externallmg_r_1707631530853_1707631649331_image_9.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631530853_1707631649331_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33d",
  "name": "externallmg_r_1707631535533_1707631649331_image_11.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631535533_1707631649331_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33e",
  "name": "externallmg_r_1707631538768_1707631649331_image_12.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631538768_1707631649331_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa33f",
  "name": "externallmg_r_1707631540973_1707631649331_image_13.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631540973_1707631649331_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65c863bdd93fe4510d4aa340",
  "name": "externallmg_r_1707631543087_1707631649331_image_14.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
externallmg_r_1707631543087_1707631649331_image_14.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c863bdd93fe4510d4aa341",
    "name": "externalimg_r_1707631544890_1707631649331_image_15.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631544890_1707631649331_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c86370d93fe4510d4aa321",
    "name": "externalimg_r_1707631466994_1707631611766_image_0.png",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631466994_1707631611766_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c86370d93fe4510d4aa322",
    "name": "externalimg_r_1707631469388_1707631611766_image_2.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631469388_1707631611766_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65c86370d93fe4510d4aa323",
    "name": "externalimg_r_1707631467261_1707631611766_image_1.jpg",
    "path": "cases/65c49b21d93fe4510d45a75b/
externalimg_r_1707631467261_1707631611766_image_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR-FLAT NO. 1402.pdf",
    "filename": "1709125265209_AGRFLAT_NO_1402.pdf",
    "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125265209_AGRFLAT_NO_1402.pdf",
    "size": "6260502",
    "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
    },
    {
      "originalname": "CC.pdf",
      "filename": "1709125265341_CC.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/processingDocuments/1709125265341_CC.pdf",
      "size": "164164",
      "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Electricity Bill.pdf",
      "filename": "1709125265348_Electricity_Bill.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/processingDocuments/1709125265348_Electricity_Bill.pdf",
      "size": "515687",
      "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "externallmg_r_1707631467261_1707631611766_image_1.jpg",
      "filename":
"1709125265368_externallmg_r_1707631467261_1707631611766_image_1.jpg",
      "path": "cases/65c49b21d93fe4510d45a75b/processingDocuments/1709125265368_externallmg_r_1707631467261_1707631611766_image_1.jpg",
      "size": "2540719",
      "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "externallmg_r_1707631469388_1707631611766_image_2.jpg",
      "filename":
"1709125265428_externallmg_r_1707631469388_1707631611766_image_2.jpg",
      "path": "cases/65c49b21d93fe4510d45a75b/processingDocuments/1709125265428_externallmg_r_1707631469388_1707631611766_image_2.jpg",
      "size": "2495844",
      "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "IGR-01.pdf",
      "filename": "1709125265491_IGR01.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/processingDocuments/1709125265491_IGR01.pdf",
      "size": "144282",
      "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1709125265496_IGR02.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125265496_IGR02.pdf",
  "size": "149488",
  "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1709125265502_IGR03.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125265502_IGR03.pdf",
  "size": "151691",
  "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Maintenance Bill.jpg",
  "filename": "1709125265507_Maintenance_Bill.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125265507_Maintenance_Bill.jpg",
  "size": "2672842",
  "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Occupancy Certificate.pdf",
  "filename": "1709125265586_Occupancy_Certificate.pdf",
  "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125265586_Occupancy_Certificate.pdf",
  "size": "239478",
  "createdAt": "Wed Feb 28 2024 18:31:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Maintenance Bill.jpg",
  "filename": "1709125279573_Maintenance_Bill.jpg",
  "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279573_Maintenance_Bill.jpg",
  "size": "2672842",
  "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
```

```
    },
    {
      "originalname": "Occupancy Certificate.pdf",
      "filename": "1709125279635_Occupancy_Certificate.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279635_Occupancy_Certificate.pdf",
      "size": "239478",
      "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "OTHER DOCUMENTS.pdf",
      "filename": "1709125279643_OTHER_DOCUMENTS.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279643_OTHER_DOCUMENTS.pdf",
      "size": "7798088",
      "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Prev Report - Flat No. 1402.pdf",
      "filename": "1709125279812_Prev_Report__Flat_No_1402.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279812_Prev_Report__Flat_No_1402.pdf",
      "size": "2147879",
      "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Property Tax.pdf",
      "filename": "1709125279858_Property_Tax.pdf",
      "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279858_Property_Tax.pdf",
      "size": "2761472",
      "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    },
    {
      "originalname": "Summary New=Flat No. 1402.xlsx",
      "filename": "1709125279917_Summary_NewFlat_No_1402.xlsx",
      "path": "cases/65c49b21d93fe4510d45a75b/
processingDocuments/1709125279917_Summary_NewFlat_No_1402.xlsx",
      "size": "5385283",
      "createdAt": "Wed Feb 28 2024 18:31:20 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  }
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "65d08bfa52bb6a0e76c6f89a",
    "note": "Pending for value confirmation",
    "taskId": "65cf0fe619837c7e5fdd111b",
    "createdAt": "2024-02-17T10:35:38.832Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65df395a9a876858ab317867",
    "note": "documents update (Task Reopen)",
    "taskId": "65c5e780d93fe4510d47ba35",
    "createdAt": "2024-02-28T13:47:06.500Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    }
  }
]
```

```
},
  "workType": "MAKER",
  "display": true,
  "status": true,
  "_id": "65df396d9a876858ab31790e",
  "note": "Documents update (Task Reopen)",
  "taskId": "65cf0fe619837c7e5fdd111b",
  "createdAt": "2024-02-28T13:47:25.382Z"
}
],
"createdAt": "2024-02-08T09:13:05.993Z",
"updatedAt": "2024-02-28T14:09:16.586Z",
"__v": 0,
"gstNo": "",
"uniqueNo": "",
"updatedBy": "60eeaeddf3dd69653a581316",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 1402, 14th Floor, Sumeet Enclave Co-op. Hsg. Soc. Ltd., Plot No. 340, Sant Dnyaneshwar Road, Banacha Pada, Village - Panchpakahdi, Thane (West), Taluka - Thane, District - Thane, Thane, 400602, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mr. Ashwin Kumar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Neighbour",
"siteVisitContactNo": "8669734017",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet + Dining + 5 Balcony",
"carpetTotal": "1148.28",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "1377.94",
"finalCarpetArea": "1148.28",
"finalSalableArea": "1515.73",
"salablePercentage": "10",
"toBeAdded": "",
```

```

"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1117.00",
"buildingServicesRate": "2700",
"flatRate": "21500",
"landOtherRate": "18800",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Feb 28 2024 17:03:13 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-02-10",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

Name	Length	Width	Total
Composition :			
Passage	3'3"	7'6"	24.37
Living Room	11'8"	18'5"	214.86
Kitchen	9'6"	10'3"	97.37



Toilet	8'2"	7'4"	59.89
Toilet	4'9"	6'7"	31.27
Passage	8'3"	4'9"	39.19
Bedroom	9'2"	13'4"	122.22
Bedroom	10'11"	12'3"	133.73
Dining	7'9"	9'3"	71.69
Balcony	2'1"	8'3"	17.19
Balcony	2'5"	18'1"	43.70
Balcony	5'8"	16'00"	90.67
Balcony	2'5"	5'9"	13.90
Balcony	2'5"	3'9"	9.06
Bedroom	12'6"	14'4"	179.17
Other Composition :			