

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b909"
    },
    "type": "CREDITOFFICER",
    "_id": "65c7231ed93fe4510d49aa58",
    "firstName": "Sandeep Singh ",
    "lastName": "Singh ",
    "mobileNo": "",
    "workMobileNo": "9654346846",
    "email": "LCBbo090210@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Sandeep Singh ",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b909",
  "branchCode": "000025",
  "type": "BRANCH",
  "name": "Mumbai Large Corporate Branch",
  "email": "atulhazare@yahoo.com",
  "mobileNo": "022-22042094,",
  "alternateMobileNo": "",
  "address": "11th Floor, Dalamal House, Jamnalal Bajaj Marg, Nariman Point, Mumbai
- 400 021, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "657157794999312746cdc402",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Komal",
  "email": "pawarkomal580@gmail.com",
```

```
"lastName": "pawar",
"mobileNo": "7447457799",
"designation": "Rate Verifier +Maker",
"shortName": "KP",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.11598697835367",
  "longitude": "72.85914681851864"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85914681851864,
    19.11598697835367
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "Cont Person Satish Diwate 9819518214"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
```

```
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-16",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gundavali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Greenwoods Co. Op. Hsg. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sir M. V. Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Andheri Kurla Road ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "H",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "274",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400093",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_with_POP_false_Ceiling",
    "label": "Cement Plastering with POP false Ceiling"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "UpperClass",
    "label": "Upper Class"
  }
},
```

```
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Compound ",
  "west": "I - Wing ",
  "south": "Internal Road ",
  "east": "Open"
},
"asPerDocumentAgreement": {
  "north": "Partly Land bearing CTS No. 251 & 242",
  "west": "by property bearing CTS No. 273",
  "south": "Partly by CTS No. 275, 276 & 277 & others ",
  "east": "Partly Land bearing CTS No. 283 & 284"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy certificate is received may be assumed
that the construction is as per sanctioned plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "N.A."
```

```
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "31286",
  "depreciatedBuildingRate": "2086"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "246660",
  "landRate": "124680",
  "igrImage": "cases/65c72664d93fe4510d49b0f6/igr_1708145747460_Image.png",
  "squareMeterGuideLineRate": "246660.00",
  "squareFeetGuideLineRate": "22915.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "83",
  "rate": "20989.00",
  "squareFeetGuideLineRate": "20989.00",
  "squareMeterGuideLineRate": "225923.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "I_Class",
    "label": "I Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "35,000/- per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM Norms ",
  "tenantName": "Mr. Shailesh Kumar Shahu",
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Parking ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
    "fullDate": "1/1/2007"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
```

```
"label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "17",
"totalLifeBuilding": "60",
"estimatedAge": "43",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "9",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "891.60",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
```



```
    "routeMapImg": "cases/65c72664d93fe4510d49b0f6/
routeMap_1709039606933_Image.png",
    "routeLat": "19.116528",
    "routeLng": "72.858917",
    "stationName": "Western Express Highway",
    "routeDistance": "260 Mtrs. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ti5a0j",
      "name": "ti5a0j",
      "image": "cases/65c72664d93fe4510d49b0f6/
routeMap_1709039472593_Image.png"
    },
    {
      "id": "fb273",
      "name": "fb273",
      "image": "cases/65c72664d93fe4510d49b0f6/
routeMap_1709039486349_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "23245498.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "7294375",
"finalValue": "23245498.00",
"purchaseValueDocument": {
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "679230",
  "path": "cases/65c72664d93fe4510d49b0f6/document_1707550156243_1707550297748_Agreement_for_sale_Sanjeev_Reniwal_102H_Green_Woods.pdf",
  "fileName": "document_1707550156243_1707550297748_Agreement_for_sale_Sanjeev_Reniwal_102H_Green_Woods.pdf",
  "documentDate": "30/01/2010",
  "amount": "6935000",
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "M/s. Bapa & Rashi Developers ",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Sanjeev Reniwal",
  "number": {
    "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "3148 / 2010"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Feb 29 2024 11:14:49 GMT+0530 (India Standard Time)",
  "number": "2305225",
  "dayCount": "4",
  "monthCount": "447",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "18713792.00",
  "selectedBuildUpValue": "891.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65cf789e52bb6a0e76c582a2",
      "name": "externallmg_1708095642794_1708095783995_image_11.jpeg",
      "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095642794_1708095783995_image_11.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65cf789e52bb6a0e76c58299",
      "name": "externallmg_1708095638008_1708095783995_image_2.jpeg",
      "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095638008_1708095783995_image_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65cf789e52bb6a0e76c582a4",
      "name": "externallmg_1708095644278_1708095783995_image_13.jpeg",
      "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095644278_1708095783995_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65cf789e52bb6a0e76c582a5",
      "name": "externallmg_1708095644527_1708095783995_image_14.jpeg",
      "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095644527_1708095783995_image_14.jpeg",
      "orientation": "landscape"
    }
  ],
  "parkingImages": [
    {
```

```
    "status": false,
    "_id": "65cf789e52bb6a0e76c58298",
    "name": "externallmg_1708095637623_1708095783995_image_1.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095637623_1708095783995_image_1.jpeg",
    "orientation": "landscape"
  }
],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829a",
    "name": "externallmg_1708095638338_1708095783995_image_3.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095638338_1708095783995_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829c",
    "name": "externallmg_1708095639778_1708095783995_image_5.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095639778_1708095783995_image_5.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "65cf786352bb6a0e76c5824e",
    "name": "Living Room",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095583527_1708095726132_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cf786352bb6a0e76c58250",
    "name": "Living Room",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095584475_1708095726132_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cf786352bb6a0e76c58252",
```

```
    "name": "Living Room",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095585550_1708095726132_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cf786352bb6a0e76c58255",
    "name": "Living Room",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095586550_1708095726132_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cf786352bb6a0e76c58257",
    "name": "Living Room",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095587415_1708095726132_image_11.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "30552",
    "max": "33180"
  },
  "builtUpRateRange": {
    "min": "25461",
    "max": "27650"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
```

```
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "743.00",
"empanelmentNo": [
  "REF:ZO: SAMD:1138"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "ATTACHSIGN",
"invoices": [],
"paymentId": [],
"_id": "65c72664d93fe4510d49b0f6",
"ownerName": "Mr. Sanjeev Reniwal",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 102.1st floor,H-wing,Building No 1,Greens Woods, Sir M.V
Road,Chakala Andheri East ",
"remark": "Cont Person Satish Diwate 9819518214",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "30/01/2010",
      "amount": "6935000",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Bapa & Rashi Developers ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Sanjeev Reniwal",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "3148 / 2010"
    }
  },

```

```
"isHardCopy": false,
"displayStatus": true,
"id": "679230",
"path": "cases/65c72664d93fe4510d49b0f6/document_1707550156243_1707550297748_Agreement_for_sale_Sanjeev_Reniwal_102H_Green_Woods.pdf",
"fileName": "document_1707550156243_1707550297748_Agreement_for_sale_Sanjeev_Reniwal_102H_Green_Woods.pdf"
},
{
  "documentType": {
    "label": "Share Certificate ",
    "value": "60ae1264aa6d152c1801b371"
  },
  "inputs": {
    "documentDate": "21/11/2010",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "239"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "274457",
  "path": "cases/65c72664d93fe4510d49b0f6/document_1707550225069_1707550366756_Share_Certificate_Sanjeev_Reniwal_102H_Green_Woods.pdf",
  "fileName": "document_1707550225069_1707550366756_Share_Certificate_Sanjeev_Reniwal_102H_Green_Woods.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "inputs": {
    "documentDate": "14/02/2007",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CE / 8289 / WS / AK"
  },
}
```

```
"isHardCopy": false,
"displayStatus": true,
"id": "732443",
"path": "cases/65c72664d93fe4510d49b0f6/document_1707550263081_1707550404945_Occupation_Certificate_Sanjeev_Reniwal_102H_Green_Woods.pdf",
"fileName": "document_1707550263081_1707550404945_Occupation_Certificate_Sanjeev_Reniwal_102H_Green_Woods.pdf"
},
{
  "documentType": {
    "label": "Maintenance Bill",
    "value": "60ae125eaa6d152c1801b353"
  },
  "inputs": {
    "documentDate": "31/01/2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "339920",
  "path": "cases/65c72664d93fe4510d49b0f6/document_1707550279822_1707550422348_Society_Maintenance_BillJan_24_to_Mar_24_Sanjeev_Reniwal_102H_Green_Woods.pdf",
  "fileName": "document_1707550279822_1707550422348_Society_Maintenance_BillJan_24_to_Mar_24_Sanjeev_Reniwal_102H_Green_Woods.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "05/01/2005",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "CE / 8289 / WS / AK"
},
"isHardCopy": false,
"displayStatus": true,
"id": "861453",
"path": "cases/65c72664d93fe4510d49b0f6/document_1707550295650_170755043
```

```
8436_Car_Parking_Sanjeev_Reniwal_102H_Green_Woods.pdf",
  "fileName": "document_1707550295650_1707550438436_Car_Parking_Sanjeev_Reniwal_102H_Green_Woods.pdf"
},
{
  "documentType": {
    "value": "60ae126faa6d152c1801b3a3",
    "label": "Parking Allotment Letter"
  },
  "inputs": {
    "documentDate": "25/04/2010"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "910396",
  "path": "cases/65c72664d93fe4510d49b0f6/document_1707983748237_OC_2.pdf",
  "fileName": "document_1707983748237_OC_2.pdf"
}
],
"caseNumber": "006892",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "823580",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 10 2024 13:01:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sanjeev Reniwal",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "120997"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "930816",
"name": "Living Room",
"length": "10.42",
"length1": "10",
"length2": "5",
"width": "18.00",
"width1": "18",
"width2": "0",
"totalArea": "187.50",
"images": [],
"extraAreas": [],
"finalArea": "187.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "71.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "71.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "72.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "72.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "120.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "21.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
```



```
"length": "5.42",
"length1": "5",
"length2": "5",
"width": "3.00",
"width1": "3",
"width2": "00",
"totalArea": "16.25",
"images": [],
"extraAreas": [],
"finalArea": "16.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "35.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "10.00",
  "length1": "10",
  "length2": "0",
  "width": "15.25",
  "width1": "15",
  "width2": "3",
  "totalArea": "152.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "152.50"
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "36.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.25"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "69.03",
    "totalAreaDocument": "743",
    "docBuiltpPercentage": "20",
    "docFinalBUILTUp": "891.60",
    "docFinalBUILTUpSquareMeter": "82.83",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "641243"
  }
],
"images": [],
"indicatorArr": [
```

```
{
  "printlnReport": true,
  "_id": "65d03cee52bb6a0e76c5c493",
  "property": "Flat",
  "area": "850",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "27000000",
  "expectedRate": "31764.71",
  "builtUpExpectedRate": "26470.59",
  "image": "cases/65c72664d93fe4510d49b0f6/
indicator_1708145462822_Image.png",
  "squareMeter": "78.97",
  "id": "131791"
},
{
  "printlnReport": true,
  "_id": "65d03cee52bb6a0e76c5c494",
  "property": "Flat",
  "area": "750",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "23500000",
  "expectedRate": "31333.33",
  "builtUpExpectedRate": "26111.11",
  "image": "cases/65c72664d93fe4510d49b0f6/
indicator_1708145517456_Image.png",
  "squareMeter": "69.68",
  "id": "719174"
},
{
  "printlnReport": true,
  "_id": "65d03cee52bb6a0e76c5c495",
  "property": "Flat",
  "area": "719",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
```

```
    "expectedPrice": "23500000",
    "expectedRate": "32684.28",
    "builtUpExpectedRate": "27236.90",
    "image": "cases/65c72664d93fe4510d49b0f6/
indicator_1708145550921_Image.png",
    "squareMeter": "66.80",
    "id": "556845"
  },
  {
    "printlnReport": true,
    "_id": "65d03cee52bb6a0e76c5c496",
    "property": "Flat",
    "area": "759.5",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "25200000",
    "expectedRate": "33179.72",
    "builtUpExpectedRate": "27649.77",
    "image": "cases/65c72664d93fe4510d49b0f6/
indicator_1708145642306_Image.png",
    "squareMeter": "70.56",
    "id": "279899"
  },
  {
    "printlnReport": true,
    "_id": "65d03cee52bb6a0e76c5c497",
    "property": "Flat",
    "area": "746.26",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "22800000",
    "expectedRate": "30552.35",
    "builtUpExpectedRate": "25460.35",
    "image": "cases/65c72664d93fe4510d49b0f6/
indicator_1708145683922_Image.png",
    "squareMeter": "69.33",
    "id": "499774"
  }
],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c5824c",
  "name": "externallmg_1708095583299_1708095726132_image_0.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095583299_1708095726132_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c5824d",
  "name": "externallmg_1708095583335_1708095726132_image_1.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095583335_1708095726132_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c5824e",
  "name": "externallmg_1708095583527_1708095726132_image_2.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095583527_1708095726132_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c5824f",
  "name": "externallmg_1708095583890_1708095726132_image_3.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095583890_1708095726132_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c58250",
  "name": "externallmg_1708095584475_1708095726132_image_4.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095584475_1708095726132_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf786352bb6a0e76c58251",
    "name": "externallmg_1708095584948_1708095726132_image_5.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095584948_1708095726132_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf786352bb6a0e76c58252",
    "name": "externallmg_1708095585550_1708095726132_image_6.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095585550_1708095726132_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf786352bb6a0e76c58253",
    "name": "externallmg_1708095585951_1708095726132_image_7.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095585951_1708095726132_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf786352bb6a0e76c58254",
    "name": "externallmg_1708095586258_1708095726132_image_8.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095586258_1708095726132_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf786352bb6a0e76c58255",
    "name": "externallmg_1708095586550_1708095726132_image_9.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095586550_1708095726132_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65cf786352bb6a0e76c58256",
  "name": "externallmg_1708095587007_1708095726132_image_10.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095587007_1708095726132_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf786352bb6a0e76c58257",
  "name": "externallmg_1708095587415_1708095726132_image_11.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095587415_1708095726132_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf789e52bb6a0e76c58297",
  "name": "externallmg_1708095637485_1708095783995_image_0.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095637485_1708095783995_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf789e52bb6a0e76c58298",
  "name": "externallmg_1708095637623_1708095783995_image_1.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095637623_1708095783995_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cf789e52bb6a0e76c58299",
  "name": "externallmg_1708095638008_1708095783995_image_2.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095638008_1708095783995_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65cf789e52bb6a0e76c5829a",
    "name": "externallmg_1708095638338_1708095783995_image_3.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095638338_1708095783995_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829b",
    "name": "externallmg_1708095638653_1708095783995_image_4.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095638653_1708095783995_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829c",
    "name": "externallmg_1708095639778_1708095783995_image_5.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095639778_1708095783995_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829d",
    "name": "externallmg_1708095640204_1708095783995_image_6.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095640204_1708095783995_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829e",
    "name": "externallmg_1708095641222_1708095783995_image_7.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095641222_1708095783995_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c5829f",
```



```
    "name": "externallmg_1708095641633_1708095783995_image_8.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095641633_1708095783995_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a0",
    "name": "externallmg_1708095642047_1708095783995_image_9.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095642047_1708095783995_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a1",
    "name": "externallmg_1708095642160_1708095783995_image_10.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095642160_1708095783995_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a2",
    "name": "externallmg_1708095642794_1708095783995_image_11.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095642794_1708095783995_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a3",
    "name": "externallmg_1708095643297_1708095783995_image_12.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095643297_1708095783995_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a4",
    "name": "externallmg_1708095644278_1708095783995_image_13.jpeg",
```

```
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095644278_1708095783995_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a5",
    "name": "externallmg_1708095644527_1708095783995_image_14.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095644527_1708095783995_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a6",
    "name": "externallmg_1708095644813_1708095783995_image_15.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095644813_1708095783995_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a7",
    "name": "externallmg_1708095645172_1708095783995_image_16.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095645172_1708095783995_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a8",
    "name": "externallmg_1708095645806_1708095783995_image_17.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095645806_1708095783995_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cf789e52bb6a0e76c582a9",
    "name": "externallmg_1708095646152_1708095783995_image_18.jpeg",
    "path": "cases/65c72664d93fe4510d49b0f6/
externallmg_1708095646152_1708095783995_image_18.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65cf783952bb6a0e76c58225",
  "name": "externalImg_1708095545128_1708095690872_image_0.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externalImg_1708095545128_1708095690872_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65cf783952bb6a0e76c58226",
  "name": "externalImg_1708095545159_1708095690872_image_1.jpeg",
  "path": "cases/65c72664d93fe4510d49b0f6/
externalImg_1708095545159_1708095690872_image_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65d03ce752bb6a0e76c5c45b",
    "note": "Value given for confirmation",
    "taskId": "65c739c3d93fe4510d49da19",
    "createdAt": "2024-02-17T04:58:15.446Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
```

```
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "65e06e4b1ec0d12578d886d5",
  "note": "purchase value (Task Reopen)",
  "taskId": "65dde0a5e333566c7d31933f",
  "createdAt": "2024-02-29T11:45:15.253Z"
}
],
"createdAt": "2024-02-10T07:31:48.930Z",
"updatedAt": "2024-02-29T11:50:32.467Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 102, 1st Floor, Building No 1, Wing - H,
Greenwoods Co. Op. Hsg. Ltd. , Sir M. V. Road, Andheri Kurla Road , Village -
Gundavali, Andheri (East), Mumbai, PIN - 400093, State - Maharashtra, India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "64de0528ccaf1e7b7f65b92e",
"contactPersonName": "Sandeep Bodhe",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0773839508",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 743.00",
"flatRate": "32000",
"landOtherRate": "29200",
```

```

"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Passage +
2 Toilet",
"carpetTotal": "712.21",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "854.65",
"finalCarpetArea": "712.21",
"finalSalableArea": "940.12",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Thu Feb 29 2024 18:29:28 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-02-16"
}

```

Name	Length	Width	Total
Composition :			

Living Room	10'5"	18'0"	187.50
Dining	8'2"	8'9"	71.46
Kitchen	9'00"	8'00"	72.00
Bedroom	12'0"	10'0"	120.00
Passage	5'0"	4'3"	21.25
Passage	5'5"	3'00"	16.25
Toilet	7'0"	5'0"	35.00
Bedroom	10'0"	15'3"	152.50
Toilet	5'0"	7'3"	36.25

Other
Composition :