

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "30000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
}
],
}
```

```
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.04872066300783",
  "longitude": "72.9075609644526"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Borla",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Chembur",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "One Meraki",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Motibaug",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "V. N. Purav Marg",
  "label": false
},
}
```

```
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. R. K. Studio",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A & B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "619/14, 619/15, 619/21A & 619/21B",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400071",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65c74a9bd93fe4510d4a1a24",
"ownerName": "M/s. Meraki Habitats LLP",
```



```
"ownerPhoneNo": "9820620783",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Basement Floor, Wing
- A & B, One Meraki, Opp. R. K. Studio, CTS No. 619/14, 619/15, 619/21A & 619/21B,
Motibaug, V. N. Purav Marg, Village - Borla, Taluka - Kurla, District - Mumbai Suburban,
Chembur, 400071",
"remark": "8th LIE Report",
"documents": [
  {
    "documentType": {
      "value": "641d4da529e5586db05ed8e8",
      "label": "CA Certificate"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1707559572426_COPM__One_Meraki__Wing_A__Wing_B
__Residential_Tower_1_311223.pdf",
    "path": "cases/65c74a9bd93fe4510d4a1a24/document_1707559572426_COPM__O
ne_Meraki__Wing_A__Wing_B__Residential_Tower_1_311223.pdf",
    "id": "614795",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Sat Feb 10 2024 15:36:19 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "006895",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "511235",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 10 2024 15:36:19 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Meraki Habitats LLP",
    "phone": "9820620783",
    "ownershipShare": "",
    "email": "",
    "id": "994217"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e80",
    "name": "externalImg_1707559813132_IMG20240207WA0095.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalImg_1707559813132_IMG20240207WA0095.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e81",
    "name": "externalImg_1707559813150_IMG20240207WA0096.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalImg_1707559813150_IMG20240207WA0096.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e82",
    "name": "externalImg_1707559813167_IMG20240207WA0097.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalImg_1707559813167_IMG20240207WA0097.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e83",
    "name": "externalImg_1707559813181_IMG20240207WA0098.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalImg_1707559813181_IMG20240207WA0098.jpg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e84",
    "name": "externalimg_1707559813194_IMG20240207WA0099.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813194_IMG20240207WA0099.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e85",
    "name": "externalimg_1707559813208_IMG20240207WA0100.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813208_IMG20240207WA0100.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e86",
    "name": "externalimg_1707559813222_IMG20240207WA0101.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813222_IMG20240207WA0101.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e87",
    "name": "externalimg_1707559813227_IMG20240207WA0102.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813227_IMG20240207WA0102.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e88",
    "name": "externalimg_1707559813234_IMG20240207WA0103.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813234_IMG20240207WA0103.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e89",
    "name": "externalimg_1707559813244_IMG20240207WA0104.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813244_IMG20240207WA0104.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e8a",
    "name": "externalimg_1707559813257_IMG20240207WA0105.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813257_IMG20240207WA0105.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e8b",
    "name": "externalimg_1707559813267_IMG20240207WA0106.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813267_IMG20240207WA0106.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65c74b85d93fe4510d4a1e8c",
    "name": "externalimg_1707559813282_IMG20240207WA0107.jpg",
    "path": "cases/65c74a9bd93fe4510d4a1a24/
externalimg_1707559813282_IMG20240207WA0107.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-10T10:06:19.405Z",
"updatedAt": "2024-02-10T10:10:13.354Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
```

"contactPersonName": "Mr. Akshay Patani",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9820620783"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			